

INSURANCE

INS. CASE OWNER:

Ernest CC 4/AXA1801 3977, AUBURN

LKK:

IDAC:

Surveyor:

D/ram

DOI:

ASSIGNMENT

6/6/18

Date / Time:

21/7/18

Registered in Merimen:

21/7/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

510 7513K

Name of Insured:

TEAMS-UPS SERVICES PTE

Insured Tel No.:

HP:

Excess Sec II :\$S

25000

D.O.A:

10/8/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

How long with

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

10 476085

Policy No.:

921650670

Make / Model:

HYUNDAI

Place of Accident:

BT ROAD EAST WUE 3

OI GIA REPORT: YES / NO

YES

TP GIA REPORT: YES / NO

YES

Insured Liability:

%

Final ? Yes / No

YES

YM 8123L



INSRS:

WSP:

Tel:

Liability:

RMKS:

pitstop



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

21/8/18
TH

YM 8123L

CHB 7513K - F

OI rear-ended to TP.

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$S

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with: IDAM

Email

Call

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28. Ass. Lia:

Repair Cost:

\$S

749.00

Loss of Rental (LOR):

\$S

(days)

Loss of Use (LOU):

\$S

200.00 (\$100 x 2 days)

Loss of Income (LOI):

\$S

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

\$S

Medical:

\$S

Disbursement:

\$S

(e.g. Tow/ Independent)

Legal Cost

\$S

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

\$S

949.00

Global Sum \$S:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$S

949.00

Name 1:

WIS AUTOMOTIVE SERVICES PTE LTD

Payee 2: (Strike if N.A.)

\$S

Name 2:

Payee 3: (Strike if N.A.)

\$S

Name 3:

COPY SENT
12/10/18

08/11/13 wel
ASS BY:

REF: AXA

13977 / Aub3

ASSIGNMENT

From: Date: 6/8/18

Estimated Cost:

On ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: YM 8123L

at Workshop m/s Pitstop Barley

of 17 Kaki Bkt Rd 4 # 01-58

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res: Yes or No

Lum Sum: p/p % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: YM8123L Yr Regn: 2008, Feb

Type: M.Car / M.Cycle / Bus / Van / ☒ Corn / Taxi / Prime Mover /

Truck / Trailer or

Make: ~~Maz~~ Isuzu NPR c.c 2999

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 429287. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JAANPR85LT71019A6

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: 7.00 R16.

R: 7.00 R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kenda.

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 06/08/18

Survey held at Pitstop.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AXA.

COE Expiry: 17/02/23.

LIS - 9 700.00 (Red: B 200.00 / 22 %)

MV: 26K

PV: 21.5K

Nett: A.7K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/AXA18013973/ub3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 01-08-2018		
		Code : AXA2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 7513K	Veh. Inspected	YM 8123L	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	01/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/07/2018	Inspection Date		
Survey held at	PITSTOP GARAGE BLK 51, UBI AVE 1 #01-29 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. E) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Thia Thia

Repair Quotation

Client: AXA Insurance (Motor Claim Department)
Address: 8 Shenton Way, #24-01 AXA Tower, Singapore 068811
Attention: Motor Claim Department
Contact No:
Fax No: 6880 4740
Email:

Date: 30/7/2018
Veh No: YM8123L
Veh Model: ISUZU NPR85LUSY
Mileage:

Service Advisor		Payment Terms	Quotation Validity
Name:	Muhammad Idram	Due Upon Receipt	7 days
Contact No:	87483825		
Email:	muhammad.idram@pitstop.com.sg		
Fax No:	68449463		

S/No	Description	Price	Actions		Remarks
1	Underrun Protection Device <i>Bed</i>	\$500.00	Accept	Reject	<input checked="" type="checkbox"/>
2	Labour to dismantle and refix above parts	\$100.00	Accept	Reject	<input checked="" type="checkbox"/>
3	Labour to spray the above parts	\$100.00	Accept	Reject	<input checked="" type="checkbox"/>
4	Labour to realign the tailgate	\$200.00	Accept	Reject	<input checked="" type="checkbox"/>
Remark: *We will advise if further supplementary items are necessary*					
Estimated Days of Repair:	5 Working Day	Sub-Total	\$900.00	Gst	\$63.00
		Total	\$963.00		

*The above is based on initial assessment. We will advise further if there is supplementary repair.
**Quotation for cash repair only, not for insurance claims

Customer Signature / Date

(To accept this quotation, please sign & return)

Company Stamp

*Adrian King. 96893735.
P/P 06/08/18. \$100
02 days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Entire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0662C
Vehicle Details	
Vehicle No.:	YM8123L
Vehicle to be Exported:	Yes
Intended De-registration Date:	06 Aug 2018
Vehicle Make:	ISUZU
Vehicle Model:	NPR85LU5Y
Primary Colour:	Blue
Manufacturing Year:	2007
Engine No.:	4JJ1508291
Chassis No.:	JAANPR85L77101946
Maximum Power Output:	-
Open Market Value:	\$28,977.00
Original Registration Date:	18 Feb 2008
First Registration Date:	18 Feb 2008
Transfer Count:	2
Actual ARF Paid:	\$1,449.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Registration Particulars	
COE Expiry Date:	17 Feb 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$23,496.00
COE Rebate Amount:	\$21,300.00
Total Rebate Amount:	\$21,300.00
Remarks	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 06 Aug 2018

OK

CHEAPEST CAR INSURANCE RENEWAL

Compare
10+ Insurers

GET A CHEAPER QUOTE NOW!

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Honda Stream RS2 1.8A

\$2800 Downpayment Monthly
From \$738 Onwards. Lowest
3.68%P.A@Gv Cars Financing
Call Cheryl Ho @ 9611 5242

- * Free VICOM evaluation
- * Free grooming and 6 months maintenance
- * In-house workshop ensures quality service
- * Member of SYTA and hire purchase association
- * 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Save Searches
 Print

Sort by Date Posted 20 results/page

3 vehicles

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection	Isuzu npr85	Any	Any	2008	Any	Any	Any	Available
	<input type="checkbox"/> Isuzu NPR85 (COE till 01/2023) Fuel Type: Diesel For More Information, Please Contact.	\$28,000	\$6,250 /yr	28-Jan-2008	2,999 cc	-	Truck	Available
Period: 28-Mar-2018 Tags: 2008 Isuzu NPR85, Isuzu NPR85, Isuzu, NPR85, Used Isuzu								
	<input type="checkbox"/> Isuzu NPR85 (COE till 06/2028) Fuel Type: Diesel New 10 Year COE: Selling Cheap. Full Servicing Done. Trade In And Loan Available. Call Now. Don't Miss.	\$52,800	\$5,370 /yr	06-Jun-2008	2,999 cc	-	Truck	Available
Period: 10-Jul-2018 Tags: 2008 Isuzu NPR85, Isuzu NPR85, Isuzu, NPR85, Used Isuzu								
	<input type="checkbox"/> Isuzu NPR85 (COE till 06/2023) Fuel Type: Diesel New 5 Years COE! Only \$578/Month! In House Finance Available! High Trade In Available Too! Hurry Down To View And Test The Vehicle! Well Maintained No Repair Needed 14 Ft Box Lorry!	\$27,800	\$5,730 /yr	13-Jun-2008	2,999 cc	-	Truck	Available
Period: 01-Aug-2018 Tags: 2008 Isuzu NPR85, Isuzu NPR85, Isuzu, NPR85, Used Isuzu								

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

Print Received Message

This mail is associated with :

*YM8123L (C0474085)
[SHB7513K]
TP
REDINA TRADING PTE LTD
Jul 10 2018 4:00PM
[TRANS-CAB SERVICES PTE LTD]
Pittetop Bartley

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 28/08/2018 22:17 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$949.00) - YM8123L - Claim Handler: Ernest Tay

Approved: 949.00.

LETTER OF DEMAND

Our Ref: WTS-YM8123L-20180813

Date: 16-08-2018

Without Prejudice

AXA Insurance (Motor Claim Department)
8 Shenton Way, #24-01 AXA Tower
Singapore 068811

Attn: Motor Claims Department

ACCIDENT INVOLVING YM8123L & SHB7513K (YOUR INSURED) 10/07/2018 @ ALONG BT
BATOK EAST AVENUE 3 SLIP RD INTO BT BATOK AVENUE 6

Dear Sir/Mdm,

We would like to append our losses as follows:


	<u>Amount (\$)</u>
1. Lump Sum Repair Cost	700.00
2. Loss of Use (2 days * \$100)	200.00
7% GST	49.00
Total	949 .00

Enclosed: Copy of Repair Cost Pro Forma Invoice, GIA Report, Original Tax Invoice with and Original Discharge Voucher for your perusal and kind attention.

Kindly look into the matter and revert to us soonest possible.

Thank You,

Yours Faithfully,


Muhammad Idram

DID: 68449-449

Fax: 68449-463

HP: 87489825

Email: muhammad.idram@pitstop.com.sg



Thin Thin (LKKAUTO)

From: Thin Thin (LKKAUTO)
Sent: Friday, 12 October 2018 7:10 PM
To: 'claims@transcab.com.sg'
Cc: CS A Team; 'carrisalee@ava-ins.com'; 'icewong@ava-ins.com'; 'ireneng@ava-ins.com'; 'foonghon@ava-ins.com'
Subject: ACCIDENT INVOLVING SHB 7513K AND YM 8123L ALONG BUKIT BATOK EAST AVE 3 ON 10/07/2018

12 OCTOBER 2018

Transcab Taxi
Singapore

Dear Sir/Mdm,

OUR REF : CC4/AXA18013973/Aub3
YOUR REF : SHB 7513K

ACCIDENT INVOLVING SHB 7513K AND YM 8123L ALONG BUKIT BATOK EAST AVE 3 ON 10/07/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **WTS AUTOMOTIVE SERVICES PTE LTD** acting on behalf of the owner of YM 8123L against your motor insurance policy.

Basing on the circumstances of the accident reported by both parties, we are of the opinion that we cannot be absolved from liability.

We also wish to advise that there is an excess of S\$5,000.00 attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim. The applicability of the excess is as follows:

- (1) Any settlement equal to or above the excess, you shall be liable to make the payment of S\$5,000.00; or
- (2) Any settlement below the excess, you shall be liable for the amount settled.

AXA shall keep you informed of the third party claim settlement and thereafter kindly let AXA have the excess payment in your cheque payable to "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

Notwithstanding the excess being applied and/or received by AXA for the above subject matter, AXA expressly reserves all their rights under the policy to refund the excess payment in the event that there arises any known policy breach and or exclusion material to coverage.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to thinthin@lkkauto.com within 7 days from the date of this letter if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)

If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to AXA immediately. You may email it to cst@axa.com.sg or deliver it by hand to AXA's Customer Care Centre.

This letter should not be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2360 or email us at thinthin@lkkauto.com. Please quote our claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

THIN THIN HLAING
LKK Auto Consultants Pte Ltd
DID: 6841 2360
FAX: 6741 4108
Email: thinthin@lkkauto.com

This is a computer generated letter and no signature is required.

Cc Motor Claims Department
AXA Insurance Pte Ltd

AXA Insurance
(Discharge Voucher)

VEHICLE NO: YM8123L

This is to certify that WTS Automotive Services Pte Ltd has repaired the above mentioned vehicle to my satisfaction and I had taken delivery at

1600 am / pm on this date 13/08/2018

Yu Fei Fei 

Signature & Co. (If Applicable)

We hereby WTS Automotive Services Pte Ltd guarantee the workmanship of the repairs carried out on the accident portion of your vehicle.



redefining / insurance

CLAIM REF : C0474085
INSURED : TRANS-CAB SERVICES PTE LTD

DISCHARGE VOUCHER

We/I (REDINA TRADING PTE LTD. 198500662C) hereby agree to accept the sum of dollars [Nine Hundred and Forty Nine Only] (S\$ 949.00) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. SHB 7513K as a result of an accident along BUKIT BATOK EAST AVE 3 on 10/07/2018 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. YM 8123L.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. SHB 7513K in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SHB 7513K.

Dated this 15 day of October 2018

Claimant's Signature

:

Yu Fei Fei



NRIC no./ Company Stamp

:

65067992L

Occupation/ Business

:

service

Address

:

17 Bukit Batok ST22 (659587)

Telephone No.

:

85960906

Witness's Name

:

MUHAMMAD IDRIS ABUL RAHMAN

Witness's Signature

:

[Signature]

Witness's NRIC No.

:

S8325292L



Client:

AXA INSURANCE
8 SHENTON WAY, #24-01 AXA
TOWER, SINGAPORE 068811
Singapore 68811
Contact : 68804741
Email:

Tax Invoice :

Job Id:	Q15043
Service Advisor:	MUHAMMAD IDRAM
Invoice No:	#B201808-0170
Vehicle No:	YM8123L
Vehicle Model:	ISUZU NPR85LJ5Y
Date Time in:	14-Aug-2018 13:29:53
Invoice Date Time:	16-Aug-2018 16:38:52
Mileage:	0 KM

#	Item	Description	Quantity	Total
1	Package	Accident Case	1	\$0.00
2	Material / Labour	THIRD PARTY CLAIM - TP claim against 5H87513K - D.O.A : 10/07/2018	1.000	\$0.00
3	Material / Labour	THIRD PARTY CLAIM - UNDERRUN PROTECTION DEVICE	1.000	\$500.00
4	Material / Labour	LABOUR - LABOUR TO DISMANTLE AND REFIX ABOVE PARTS	1.000	\$100.00
5	Material / Labour	LABOUR - LABOUR TO SPRAY THE ABOVE PARTS	1.000	\$100.00

Remarks:

Sub Total: \$700.00
GST: \$49.00
Grand Total: \$749.00

Terms:

I acknowledge that the above works have been carried out to my satisfaction. For other works recommended but have not received my consent, I hereby indemnify WTS Automotive Services Pte Ltd against any/all claims by me or any third parties.

AXA INSURANCE / 16-Aug-2018 16:38:52

Please proceed payment to "WTS Automotive Services Pte Ltd"

For feedback on our service, please email us at admin@pitstop.com.sg. We will respond as soon as possible.

17 Kaki Bukit Road 4, #01-58/59/60/61/62, Bartley BizCentre, Singapore 417809 | P: +65 68-449-449

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING


Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Jul 2018		31 Jul 2018 15:47 Edit Adj Rpt	S\$700.00 Edit Estimates	S\$700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K								
Main Claimant:	REDINA TRADING PTE LTD , Co. Reg. No.: 198500662C								
Vehicle Reg. No.:	YM8123L	Date of Loss:	10/07/2018 16:00 - :59 [124 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0474085	Policy/Cover Note No.:	P1680520 (Third Party Only)						
Vehicle Reg. No. (Insured):	SHB7513K	Policy No. (Claimant):							
		Excess:	S\$5,000.00						
Repairer:	WTS Automotive Services Pte Ltd (HQ) 17 Kaki Bukit Road 4 #01-58/59/60/61/62, Bartley Biz Centre, 417809 Kaki Bukit - Tel: 6844 9449 / 6844 9456								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Stacey Ng - 6880 4351]								
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 10/08/2018]								
Driver/Custodian (Insured):	CHAN LAY WENG (58 / Male), NRIC: 51423194C								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AXA_SG (28/08/2018): Alert - Adj Mandate Approved (S\$949.00) - YM8123L - Claim Handler: Ernest Tay AXA_SG (21/08/2018): C0474085 - PLS UPLOAD IA AXA_SG (31/07/2018): New TP Assignment - C0474085/P1680520 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***YM8123L (C0474085)**
[SHB7513K]
TP
REDINA TRADING PTE LTD
Jul 10 2018 4:00PM
[TRANS-CAB SERVICES PTE LTD]
WTS Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Thumbnail Print
Photos/Images			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	14/08/18 15:06	General View	1	Load JPG Print
2	14/08/18 15:06	General View	1	Load JPG Print
3	14/08/18 15:06	General View	1	Load JPG Print
4	14/08/18 15:06	General View	1	Load JPG Print
5	14/08/18 15:06	General View	1	Load JPG Print
6	14/08/18 15:06	General View	1	Load JPG Print
7	14/08/18 15:06	General View	1	Load JPG Print
8	14/08/18 15:06	General View	1	Load JPG Print
9	14/08/18 15:06	General View	1	Load JPG Print
10	14/08/18 15:06	General View	1	Load JPG Print
11	14/08/18 15:06	General View	1	Load JPG Print
12	14/08/18 15:06	General View	1	Load JPG Print
13	14/08/18 15:06	General View	1	Load JPG Print
14	14/08/18 15:06	General View	1	Load JPG Print
15	14/08/18 15:06	General View	1	Load JPG Print
16	14/08/18 15:06	General View	1	Load JPG Print
17	14/08/18 15:06	Reinspection Photo	1	Load JPG Print
18	14/08/18 15:06	Reinspection Photo	1	Load JPG Print
19	14/08/18 15:06	Reinspection Photo	1	Load JPG Print
20	14/08/18 15:06	Reinspection Photo	1	Load JPG Print
21	14/08/18 15:06	Reinspection Photo	1	Load JPG Print
Documentation			1 per page <input type="checkbox"/>	
No	Finalized On	AXA Insurance Pte Ltd (HQ)		
1	31/07/18 08:51	EMAIL	1	Load PDF Print
2	31/07/18 08:51	Accident Photo	1	Load PDF Print
3	31/07/18 08:51	YM8123L TP quotation latest	1	Load PDF Print
4	31/07/18 08:51	GIA REPORT OF YM8123L (TP) 1	1	Load PDF Print
5	31/07/18 08:51	GIA REPORT OF YM8123L (TP)	1	Load PDF Print
6	31/07/18 08:51	GIA REPORT OF SHB7513K (INSD)	1	Load PDF Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	27/08/18 13:52	Mark Estimate	1	Load PDF Print
2	27/08/18 14:31	Immediate Advice	1	Load PDF Print
3	17/10/18 15:41	WORKSHOP INVOICE	1	Load PDF Print
4	17/10/18 15:41	AUTHORISATION TO ACT FORM	1	Load PDF Print
5	17/10/18 15:41	DISCHARGE VOUCHER	1	Load PDF Print

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
6	17/10/18 15:41	LOD	 Load PDF	
7	17/10/18 15:41	LETTER TO OI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SHB7513K (Insd veh)	Model:	ISUZU NPR66L 4.3 D (M)
	YM8123L (TP veh)		
Date of Accident:	10/07/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$		963.00
Final Repair Cost	:	\$		749.00
Loss of Use	:	\$		200.00
Rental (if any)	:	\$		0.00
LTA / GIA Search Fee	:	\$		0.00
Others:	:	\$		0.00
	:	\$		
Final Settlement Sum	:	\$		949.00

2.00 days at \$100.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability _____ 100 _____ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	WTS Automotive Services Pte Ltd	:	\$ 949.00
2)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

17 Oct
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18013973/AUB3Q2

Date: 17/10/2018

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant Vehicle
No : YM8123L

Insured Vehicle No :

SHB7513K

Date of Loss: 10/07/2018

Nature of Claim:

TP

Claim No: C0474085

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YM8123L

Make & Model: ISUZU NPR66L, 4.3 D (M)

Reg. Date: 18/02/2008 (Man. Year: 2007)

Colour: White

Engine Capacity: 2999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 4JJ1508291

Chassis No: JAANPR85L77101946

Odometer: 429287 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 7.00 R16

Front Left Side: Kenda 6 mm

Front Right Side: Kenda 6 mm

Rear Tyre Size:

7.00 R16

Rear Left Side:

Kenda 6 mm

Rear Right Side:

Kenda 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	500.00	500.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	400.00	200.00	200.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	900.00	700.00	200.00	22.22
+ GST 7.00/7.00% (S\$)	63.00	49.00	14.00	22.22
Nett Amount (S\$)	963.00	749.00	214.00	22.22
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
Nett Liability (S\$)		949.00		

INSPECTION

Date of Assignment: 31/07/2018

Date Inspected: 06/08/2018 Inspected At:

Pitstop Bartley
17 Kaki Bukit Road 4, Bartley Biz Centre
#01-58
Singapore 417809

Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING**Manager:** THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Sep 2018)	
Parts:	N/A	ISUZU NPR66L 4.3 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YM8123L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*UNDERRUN PROTECTION DEVICE (CONSISTENT)	Bent	500.00 F	*500.00 F
					Total Parts (S\$)	500.00 500.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO DISMANTLE AND REFIX ABOVE PARTS	New	100.00	100.00
2	LABOUR TO SPRAY THE ABOVE PARTS	New	100.00	100.00
3	LABOUR TO REALIGN THE TAILGATE	New	200.00	0.00
Gross Labour Cost (S\$)			400.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >