

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its
repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : **Yes** or **No**GIA / PR Seen: _____ Consistent? : **Yes** or **No**Est. Repairs: _____ days Res.: **Yes** or **No**Lum Sum: _____ % 3 Val.: **Yes** or **No****CA / REV / REP. / 24 HRS**Vehicle: **IN / OUT**

Date: _____ Person Contacted: _____

Veh No: SLZ6299L Yr Regn: 2018 / MayType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 c.c. 1984Colour: Bronze A/C: Insured / Std / NI / NASp. Reading: 8259 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU222F45JA144728Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / STD A/Rim orTyre Size: F: 205/60 R16R: 205/60 R16**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /****TOYO / YOKO or** ContinentalFrontRearR/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 03/08/18Survey held at PremiumDes. of Damages Front / Rear / O/S / N/S / U/C / Rooftop orThe **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time _____ Action / Instruction

TP ~~At~~ At

Date/Time, File Pass to?

☐ : **Preli. Report**

1)

☐ : **Final Report**

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. \$

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)