15/5/2010

INS. CASE OWNER: CC3 /QBE1801 3977, Klp63 | LKK: | IDAC:

ASSIGNMENT

Surveyor: Kalvin DOI: 21/7/18 Date / Time : 21/7/18

Registered in Merimen:

Pre-assign / CCU / FTE

Insured Vehicle No. : SJM 8432Y Claim No. :

Name of Insured : Policy No. :

Insured Tel No. : HP: Make / Model :

Excess Sec II :S$ D.O.A : 20/7/18 Place of Accident :

Is driver the owner? (YES / NO) Nature of Accident :

If **NO**, Driver Name / Age : OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : (V/L: YES / NO) Insured Liability : % **Final ? Yes / No**

SH 8703E → → →

INSRS:	INSRS:	INSRS:	INSRS:
WSP: COLTE Ly.	WSP:	WSP:	WSP:
Tel :	Tel :	Tel :	Tel :
Liability :	Liability :	Liability :	Liability :
RMKS:	RMKS:	RMKS:	RMKS:

Date/ Time	
	SH 8703E-X SJM 8432Y-X

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	

Documentation Check List:	Handler	Typist
Notification ltr (if non-pickup)	☐	☐
After call ltr to OI:	☐	☐
Authorisation To Act:	☐	☐
Release Voucher:	☐	☐
Final Repair Bill:	☐	☐
Car Rental Invoice:	☐	☐
Towing Invoice	☐	☐
LTA / GIA :	☐	☐
Medical Bill:	☐	☐
PIR:	☐	☐
Mandate/Reject Instruction:	☐	☐
LOD	☐	☐
Payment Breakdown Form:		☐
Post-Repair Photos:	☐	☐
Others:	☐	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	S$	(days) Reduction: %	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with	Email ☐ Call ☐
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :
Repair Cost:	S$		
Loss of Rental (LOR):	S$	(days)	
Loss of Use (LOU):	S$	($ x days)	
Loss of Income (LOI):	S$	($ x days)	
LOR only ☐ LOU only ☐	LOR + LOU ☐	LOR + LO ☐ **[Tick only one]**	
GIA/LTA Search	S$		
Medical:	S$		1) Claim status: Normal/Reject/Private Settle
Disbursement:	S$	(e.g. Tow/ Independent)	2) Report Format:
Legal Cost	S$		3) Survey fee:
Total:	**S$**	**Global Sum S$:**	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	S$	Name 1:	
Payee 2: (Strike if N.A.)	S$	Name 2:	
Payee 3: (Strike if N.A.)	S$	Name 3:	

(08/11/13)

Surveyor: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SH 8703K Yr Regn: 20 Sep / 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Prius c.c 1798

Colour Blue A/C: Insted / Std / NI / NA

Sp.Reading 308292 T/Radio: Insted / Std / NI / NA

Eng/No: _____

C/No: JTDKB3F48035300679

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size; F: 195/65R15

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Westlake

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm
D.O.A.	30/7/18	D.O.I.	31/7/18

Survey held at CDHE (Loyang)

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or N/S Rr Lg.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	QBE
	PIP

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☐ : Final Report

Report Format : _____

Lump Sum / I.B.I: ($ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Survey Fee:	
Transportation:	
___S + RS___SI	
Photos	
Others	
TOTAL	

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainline : 65 6383 8280 Facsimile : 65 6280 9755
Workshops
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
504 Yishun Industrial Park A Singapore 768732

Date/Time 30.07.2018 14:36 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305193919

STOMER COMFORT TRANSPORTATION PTE LTD

/MS 7010045

STOMER NO. 383 SIN MING DRIVE

DRESS Singapore SINGAPORE 575717

65508755

– (R) (O)

(P)

SCOUNT CARD NO.

REGN NO.: SH 8703K	MILEAGE
MAKE : TOYOTA	FUEL E.....1/2.....F
MODEL PRIUS HYBRID(G4)	DATE/TIME IN 30.07.2018 10:55
YR OF MAN 20.09.2016	TARGET DATE
CHASSIS C JTDKB3FU803530679	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 30.07.2018
NATURE: 3P 30.07.2018

S/NO LABOR CODE DESCRIPTION



HECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

owledgement Slip

e:

lo.: SH 8703K CHIANG

cle No.:

e of Service Advisor

Signature/Date

e returned to Service Reception upon collection

Exit Pass

Vehicle No.: SH 8703K

Name of Service Advisor

Date

To be kept by Security Guard