

108/11/13

Surveyor: Kelvin

REF:

CS/QW180111000/K11b

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/IS/TPRES/ODRES/EVA/INV/MV

To Inspected Vehicle No: _____

at Workshop no/s: _____

of: _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or NoLum Sum: 1255 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH 91795 Yr Regn: 72, 2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai c.c. 1700Colour: Blue A/C: Insured / Std / Nil / NASp. Reading: 74121 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: 57PKB 754 8035 6027

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD Rim or

Tyre Size: F: 195/15R5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 1 mm L/Bal. 1 mmD.O.A. 70/7/8 D.O.I. 1/8/8Survey held at CDHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>SH 91795 - x</u>
<u>6/8/12</u>	<u>Checked P/L \$1255 / 2 hrs. (Red 1790.10, 5890)</u>
<u>7/8/12</u>	<u>double ref - close ref duplication</u>

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) GR - typist

Report Format:

TP

Lump Sum / I.B.I. (\$

1255)Days Of Repair: 2Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

3 x RS 51

Photos

Others

TOTAL