

ANS. REC. BY:

REP

ca1smo1801400 / Uq03n2

Special Instruction:

Surveyor

Matus

ASSIGNMENT (Office)

From (Person):

Irene Henry

of

SMO

Date/Time

1/8/18 @ 2:17pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8LU 7896H

Insured:

FBM9994E

at Workshop m/s

ZOOM AutoCenter

Tel:

9450 7920

of

15 Kelki Blvd Ave 4 #01-53

Policy No:

Claim No:

CMTD1803296/FW

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/07/2018

CA / REV / REP. / REV 24 HRS

Date/Time:

2:35 pm @ 1/8/18

Person Contacted:

Elin

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	8LU7896H - X
	FBM9994E - X
02/8/18 @ 10:30am	informed Gosh Pau Loop, we are pending estimate from repairer.
03/8/18 @ 10:36am	revised to Gosh Pau Loop by email.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18014001/Uqd3

50 RAFFLES PLACE
#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 01-08-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBM 9994E	Veh. Inspected	SLU 7896H
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1803296/FW	Excess (\$)	0.00
Assign From	IRENE HENRY	Assign Date	01/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	27/07/2018	Inspection Date	01/08/2018
Survey held at	15 KAKI BUKIT RD 4 #01-53		
Repairer	ZOOM AUTOWERKS PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1803296/FW

Date: 03rd August 2018

Our Ref: CS/SMO18014001/Uqd3

Without Prejudice

The Motor Claims Department
Sompo Insurance

Attn: Irene

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SLU 7896H


We thank you for the instruction on 01/08/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 01/08/2018 at the premises of M/s ZOOM AUTOWERKS and have the following to report:-

Workshop Estimate Amount	: S\$ <u>14,650.74</u>
Revised Estimate Amount	: S\$ <u>2,600.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the n/s body.



Comments/ Present Status:

Damages consistent.

Days of repair: 5 days.

We have NOT authorize repair.

Yours faithfully

Marcus Chua
Licensed Appraiser

Nivitha (LKK Auto)

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Wednesday, 1 August 2018 2:17 PM
To: assignments@lkkauto.com
Cc: admin-d@lkkauto.com; Teo, Grace
Subject: SOMPO REF: CMTD1803296/FW: Pre-Repair Inspection for SLU 7896 H // Accident on 27/07/2018 @ 12:25HR at along Yishun Avenue 1 Entrance/Exit to Estuary Condo involving Vehicle Number SLU 7896 H & FBM 9994 E
Attachments: SLU 7896 H.PDF

Hi,

Kindly assign your motor surveyor to conduct motor survey of the mentioned (SLU 7896H).

Please refer to the email correspondence below.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Zoom Autowerks [mailto:zoomautowerks@gmail.com]

Sent: Wednesday, 1 August, 2018 2:08 PM

To: Henry, Irene James <irene.henry@sompo.com.sg>

Cc: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>

Subject: Re: Pre-Repair Inspection for SLU 7896 H // Accident on 27/07/2018 @ 12:25HR at along Yishun Avenue 1 Entrance/Exit to Estuary Condo involving Vehicle Number SLU 7896 H & FBM 9994 E

Dear All,

Please arrange for LKK

On Wed, Aug 1, 2018, 13:42 Henry, Irene James <irene.henry@sompo.com.sg> wrote:

Our Reference: CMTD1803296/GPL

Your Reference: SLU 7896H

Date: 01st August 2018

Without Prejudice

M/S ZOOMS AUTOWERKS PTE LTD

Dear Sir

We refer to your Notice of Accident via email dated 01/08/2018.

Kindly re-direct your future motor claim requests to motosurvey@sompo.com.sg.

Please be informed that Pau Loong is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Ma Chin Fook (North area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: claimsreport

Sent: Wednesday, 1 August, 2018 9:51 AM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Subject: Pre-Repair Inspection for SLU 7896 H // Accident on 27/07/2018 @ 12:25HR at along Yishun Avenue 1 Entrance/Exit to Estuary Condo involving Vehicle Number SLU 7896 H & FBM 9994 E

Dear Vivien,

D18MTMC01003316

FYNA

Best Regards

Angel Tan

Claims Division

D: 6329 5222 | T: 6461 6555 | F: 6221 3147

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

 Please consider the environment before printing this email



From: Zoom Autowerks [<mailto:zoomautowerks@gmail.com>]

Sent: Wednesday, 1 August, 2018 9:14 AM

To: claimsreport <claimsreport@sompo.com.sg>

Subject: Pre-Repair Inspection for SLU 7896 H // Accident on 27/07/2018 @ 12:25HR at along Yishun Avenue 1 Entrance/Exit to Estuary Condo involving Vehicle Number SLU 7896 H & FBM 9994 E

Dear Sir/Madam,

We are instructed by Lee Jiunn Shan to notify you of a road traffic accident on 27/07/2018 at about 12:25HR at along Yishun Avenue 1 Entrance/Exit to Estuary Condo involving our client's vehicle registration number SLU 7896 H

and vehicle registration number FBM 9994 E driven by your insured at the material time.

A copy of the Singapore Accident Statement/Traffic Police Report filed is enclosed. As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated time, our client shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

Kindly arrange survey at Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53, Singapore 4178 08.

Warmest Regards,

Elin Cai

Zoom Autowerks Pte Ltd

130 Bedok Reservoir Road

#08-1339 Singapore 470130

☎9450 7920

✉zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 3 August 2018 10:36 AM
To: 'Henry, Irene James'; assignments; Gnoh, Pau Loong
Cc: 'Teo, Grace'; SUR
Subject: RE: SOMPO REF: CMTD1803296/FW: Pre-Repair Inspection for SLU 7896 H // Accident on 27/07/2018 @ 12:25HR at along Yishun Avenue 1 Entrance/Exit to Estuary Condo involving Vehicle Number SLU 7896 H & FBM 9994 E
Attachments: CSSMO18014001Uqd3.pdf

Dear Gnoh,

Enclosed herewith preliminary advice of SLU 7896H.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 2 August 2018 10:30 AM
To: 'Henry, Irene James' <irene.henry@sompo.com.sg>; assignments <assignments@lkkauto.com>; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>
Cc: 'Teo, Grace' <grace.teo@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SOMPO REF: CMTD1803296/FW: Pre-Repair Inspection for SLU 7896 H // Accident on 27/07/2018 @ 12:25HR at along Yishun Avenue 1 Entrance/Exit to Estuary Condo involving Vehicle Number SLU 7896 H & FBM 9994 E

Dear Mr Gnoh,

Please be informed that we have inspected the vehicle SLU 7896H on 01/08/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 1 August 2018 2:40 PM
To: 'Henry, Irene James' <irene.henry@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Teo, Grace' <grace.teo@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SOMPO REF: CMTD1803296/FW: Pre-Repair Inspection for SLU 7896 H // Accident on 27/07/2018 @ 12:25HR at along Yishun Avenue 1 Entrance/Exit to Estuary Condo involving Vehicle Number SLU 7896 H & FBM 9994 E

Dear Sir/Mdm,

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 2 August 2018 10:30 AM
To: 'Henry, Irene James'; assignments; 'Gnoh, Pau Loong'
Cc: 'Teo, Grace'; SUR
Subject: RE: SOMPO REF: CMTD1803296/FW: Pre-Repair Inspection for SLU 7896 H // Accident on 27/07/2018 @ 12:25HR at along Yishun Avenue 1 Entrance/Exit to Estuary Condo involving Vehicle Number SLU 7896 H & FBM 9994 E

Dear Mr Gnoh,

Please be informed that we have inspected the vehicle SLU 7896H on 01/08/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 1 August 2018 2:40 PM
To: 'Henry, Irene James' <irene.henry@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Teo, Grace' <grace.teo@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SOMPO REF: CMTD1803296/FW: Pre-Repair Inspection for SLU 7896 H // Accident on 27/07/2018 @ 12:25HR at along Yishun Avenue 1 Entrance/Exit to Estuary Condo involving Vehicle Number SLU 7896 H & FBM 9994 E

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Henry, Irene James [<mailto:irene.henry@sompo.com.sg>]
Sent: Wednesday, 1 August 2018 2:17 PM
To: assignments@lkkauto.com
Cc: admin-d@lkkauto.com; Teo, Grace <grace.teo@sompo.com.sg>
Subject: SOMPO REF: CMTD1803296/FW: Pre-Repair Inspection for SLU 7896 H // Accident on 27/07/2018 @ 12:25HR at along Yishun Avenue 1 Entrance/Exit to Estuary Condo involving Vehicle Number SLU 7896 H & FBM 9994 E

Hi,

Kindly assign your motor surveyor to conduct motor survey of the mentioned (SLU 7896H).

Please refer to the email correspondence below.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4635G
Vehicle Details	
Vehicle No.:	SLU7896H
Vehicle to be Exported:	No
Intended De-registration Date:	03 Aug 2018
Vehicle Make:	KIA
Vehicle Model:	FORTE K3 1.6A
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	G4FGHH680510
Chassis No.:	KNAFJ411MJ5744368
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$11,759.00
Original Registration Date:	14 Dec 2017
First Registration Date:	14 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$11,759.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Dec 2027
PARF Rebate Amount:	\$8,819.00
Intended COE Rebate Details	
COE Expiry Date:	13 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,791.00
COE Rebate Amount:	\$43,797.00
Total Rebate Amount:	\$52,616.00

The information contained herein is correct as at 03 Aug 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/07/2018 16:40
Date Of Accident	27/07/2018 12:25
Exact Location Of Accident	YISHUN AVE 1 ENTRANCE/EXIT OF ESTUARY CONDO
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU7896H
Insured/Policyholder	
Name Of Registered Owner	LEE JIUNN SHAN
NRIC No	S7614635G
Email Address	VINCENTLEE_1212@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97647894
Alternative Phone No	OTHERS-97647894

Vehicle Particulars

Manufacturer	KIA
Model	FORTE K3-1.6 EX (A)
Exact Purpose for which vehicle was being used at time of accident	GOING FOR LUNCH
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700089519
Cover Note Number	

Driver

Name of Driver	LEE JIUNN SHAN
NRIC No	S7614635G
Date Of Birth	13/05/1976
Occupation	OUTDOOR
Date Of Driving Pass	14/11/2002
Driving Experience	15 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97647894
Fax Number	
Contact Number	OTHERS-97647894
E Mail Address	VINCENTLEE_1212@HOTMAIL.COM

Address 11 SEMBAWANG CRESCENT #08-21
 Postcode 757058
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 4
 Passenger 1 NAME: : MICHELLE YEO
 GENDER: : FEMALE
 Passenger 2 NAME: : TAN YU QIN
 GENDER: : MALE
 Passenger 3 NAME: : LESLIE LIEW
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name YISHUN SOUTH NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 32 YISHUN ST 81 , POSTCODE: 768456 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-8522999 - FAX NO: 68522239
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT VIDEO WITH POLICE

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBM9994E
 Vehicle Make/Model/Colour HONDA GREY
 Details Of Properties
 Vehicle Category MOTORCYCLE

Name of Driver	SITI NUR HAFISAH BINTE SENIN
NRIC/Passport Number	S9509632H
Contact Number	97850346
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	SITI NUR HAFISAH BINTE SENIN
Approximate Age	
Injuries Sustain	LEG INJURY
Injured person in which vehicle?	FBM9994E
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time: 27/07/18
 1616

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Refer to police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180727/2079

Police Station Of Origin
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

1 of 3

Report No: T/20180727/2079

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 27/07/2018 15:20	Vide Report No.: F/20180727/0116	Station Diary No. 57
---	-------------------------------------	-------------------------

Informant's Particulars

Name of Informant LEE JIUNN SHAN		Address 11 SEMBAWANG CRESCENT #08-21 SINGAPORE 757058	
ID Type / ID No.: NRIC NO / S7614635G		Contact No.: Home/Office: Mobile: 97647894	
Nationality SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 42	Date of Birth: 13/05/1976	Type of Informant: Driver
Race Chinese		Language English	Institution / School Name:
Occupation: Engineer		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Attended by Police:	Drink Drive: No	Date/Time of Accident: 27/07/2018 12:25	Type of Location: Straight Road
Location: Along Road 1 YISHUN AVENUE 1				
Along Yishun Ave 1 towards Seletar West Link, outside of entrance/exit of Estuary Condo				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Between moving vehicle - Side to Side.				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
FBM9994E	Motorcycle	HONDA		Grey	Slightly Damaged	0
SLU7896H	Car	KIA	FORTE K3 1.6A	Blue	Slightly Damaged	3

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLU7896H	AIG ASIA PACIFIC INSURANCE PTE LTD.	1700089519	14/12/2017	13/12/2018



**SINGAPORE
POLICE FORCE**



T/20180727/2079

2 of 3

Report No: T/20180727/2079

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	SITI NUR HAFISAH BTE SENIN	ID No.	S9509632H
Related Vehicle	FBM9994E (Motorcycle)	Contact No.	97850346
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LEE JIUNN SHAN	ID No.	S7614635G
Related Vehicle	SLU7896H (Car)	Contact No.	97647894
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 27/07/2018 at around 12.25pm, I was driving along Yishun Ave 1 on the 2nd lane of a 3 lane road. Upon approaching the entrance of the Estuary condo, I noticed that there were vehicle queuing on the extreme left lane to enter the said condo. As I wanted to turn left at the next junction, I decided to signal left and change to the extreme left lane upon passing by the entrance of the said condo.

Suddenly, a motorbike had exit from the said condo while I was already changing to the left lane. As my view was blocked by the vehicles entering the condo, I did not managed to avoid the collision and as such the said motorbike has hit onto the left side of my car. The rider had then fell down and hurt herself. I then called for the ambulance. Minutes later, the ambulance and Traffic Police came to my scene. The rider was then conveyed by the ambulance. The Traffic Police officer had then gave me a case card and advised me to lodge a Police report.



**SINGAPORE
POLICE FORCE**



T/20180727/2079

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

3 of 3

Report No. T/20180727/2079

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sr Staff Sgt ELRENO BIN SUBARI	
Signature Of Interpreter: Not applicable	
Officer In Charge Of Case: TP / GIT / SI NG CHWEE THENG Contact No.: 65476397	

Signature Of Informant:	
Date/Time: 27/07/2018 15:20	
Classification Of Case:	

Authentication Stamp
NP168



ZOOM AUTOWERKS PTE LTD

832 Sims Avenue, Eunosville

#12-884 Singapore 400832

Tel: 4507920

* zoomautowerks@gmail.com

D.O.A : 27 JULY 2018
 OWNER : LEE JIUNN SHAN
 REG NO. : SLU 7896 H
 MAKE/MODEL : KIA FORTE K3

Not Allowed
den
2/5 #2600
1/8/18
Sday.

02 August 2018

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Front fender -L/H	\$ 12 522.50 X
1	Front fender inner shield	\$ 17 86.90 X
1	Front wheel hub	\$ 17 195.00 X
1	Front wheel bearing	\$ 17 155.00 X
1	Front shock absorber	\$ 17 282.00 X
1	Front knuckle arm	\$ 17 325.00 X
1	Front knuckle arm bearing	\$ 17 182.00 X
1	Front lower arm	\$ 17 295.00 X
1	Front door -L/H	\$ 2 785.00 X
1	Front door lock	\$ 17 207.00 X
1	Front door weatherstrip	\$ 17 190.00 X
1	Rear door -L/H	\$ 2 780.00 X
1	Rear door lock	\$ 17 300.00 X
1	Rear door regulator	\$ 17 453.00 X
1	Rear door regulator motor	\$ 17 351.00 X
1	Rear door weatherstrip	\$ 17 172.00 X
1	Rear bumper	\$ 2 658.00 X
1	Rear bumper side retainer	\$ 17 38.50 X
1	Rocker panel L/H	\$ 503.00 789.60 X
1	Rear wheel hub with bearing	\$ 17 289.50 X
1	Rear shock absorber	\$ 17 221.60 X
		\$ 7,278.60
	Less 10%	\$ 727.86
		\$ 6,550.74

c/f: \$ 6,550.74

<u>SPECIAL NETT ITEMS</u>			
1	Front fender inner shield clip (1 set)	\$ 47	45.00 X
1	Front tyre	\$ 11	350.00 X
1	Front sport rim	\$ 11	650.00 X
1	Rear bumper clip (1 set)	\$ 11	45.00 X
1	Rear tyre	\$ 11	350.00 X
1	Rear sport rim	\$ 47	650.00 #50
		\$	2,090.00

<u>S/N</u>	<u>LABOUR CHARGES</u>		
1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00 20
2	To remove and refit front undercarriage.	\$ 11	250.00 X
3	To remove and refit rear undercarriage.	\$ 11	350.00 X
4	To conduct wheel alignment.	\$	180.00 60
5	To remove, replace door damaged parts and transfer all fittings.	\$ 11	350.00 X
6	To apply undercoating.	\$	200.00 50
7	Panel beating.	\$	2,400.00 800
8	To re-spray painting on the affected areas.	\$	2,200.00 1200
		\$	6,010.00

GRAND TOTAL :

\$ 14,650.74

3280.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18014001/Uqd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 06-08-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBM 9994E	Veh. Inspected	SLU 7896H
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1803296/FW	Excess (\$)	0.00
Assign From	IRENE HENRY	Assign Date	01/08/2018

2. Vehicle Particulars & Condition

Make & Model	KIA CERATO K3 (A)	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KNAFJ411MJ5744368	Colour	BLUE
Odometer	19450	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	NEXEN	8 mm
L/H Front Tyre	195/65 R15	NEXEN	8 mm
R/H Rear Tyre	195/65 R15	NEXEN	8 mm
L/H Rear Tyre	195/65 R15	NEXEN	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/07/2018	Inspection Date	01/08/2018
Survey held at	15 KAKI BUKIT RD 4 #01-53		
Repairer	ZOOM AUTOWERKS PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 7896H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER -L/H	TO REPAIR SEE LABOUR	522.50	-
1	FRONT FENDER INNER SHIELD	NOT NECESSARY	86.90	-
1	FRONT WHEEL HUB	NOT NECESSARY	195.00	-
1	FRONT WHEEL BEARING	NOT NECESSARY	155.00	-
1	FRONT SHOCK ABSORBER	NOT NECESSARY	282.00	-
1	FRONT KNUCKLE ARM	NOT NECESSARY	325.00	-
1	FRONT KNUCKLE ARM BEARING	NOT NECESSARY	182.00	-
1	FRONT LOWER ARM	NOT NECESSARY	295.00	-
1	FRONT DOOR -L/H	TO REPAIR SEE LABOUR	785.00	-
1	FRONT DOOR LOCK	NOT NECESSARY	207.00	-
1	FRONT DOOR WEATHERSTRIP	NOT NECESSARY	190.00	-
1	REAR DOOR -L/H	TO REPAIR SEE LABOUR	780.00	-
1	REAR DOOR LOCK	NOT NECESSARY	300.00	-
1	REAR DOOR REGULATOR	NOT NECESSARY	453.00	-
1	REAR DOOR REGULATOR MOTOR	NOT NECESSARY	351.00	-
1	REAR DOOR WEATHERSTRIP	NOT NECESSARY	172.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	658.00	-
1	REAR BUMPER SIDE RETAINER	NOT NECESSARY	38.50	-
1	ROCKER PANEL L/H	BADLY DENTED	789.60	789.60
1	REAR WHEEL HUB WITH BEARING	NOT NECESSARY	289.50	-
1	REAR SHOCK ABSORBER	NOT NECESSARY	221.60	-
	LESS 10% DISCOUNT		-727.86	-78.96
			6,550.74	710.64
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NOT NECESSARY	45.00	-
1	FRONT TYRE (SN)	NOT NECESSARY	350.00	-
1	FRONT SPORT RIM (SN)	NOT NECESSARY	650.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	45.00	-
1	REAR TYRE (SN)	NOT NECESSARY	350.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SPORT RIM (SN)	CUT	650.00	450.00
			2,090.00	450.00
	LABOUR			
	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING.		80.00	20.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE .	NOT NECESSARY	250.00	-
	TO REMOVE AND REFIT REAR UNDERCARRIAGE .	NOT NECESSARY	350.00	-
	TO CONDUCT WHEEL ALIGNMENT .		180.00	60.00
	TO REMOVE,REPLACE DOOR DAMAGED PARTS AND TRANSFER ALL FITTINGS.	NOT NECESSARY	350.00	-
	TO APPLY UNDERCOATING.		200.00	50.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER -L/H,FRONT DOOR -L/H ,REAR DOOR -L/H AND REAR BUMPER .		2,400.00	800.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		2,200.00	1,200.00
			6,010.00	2,130.00
	GRAND TOTAL		14,650.74	3,290.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CS/SMO18014001/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.