

ASS. REC. BY:

REF:

CS3/AG18014007/ U24d3

Special Instruction:

Surveyor:
Munir

Munir

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

10:21am @ 1/8/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8KU 7277G

Insured:

YP 7597T

at Workshop m/s

Bizfolio Motor

Tel:

G244 4464

of

Blk 9002, Tampines 81-93 # 01-34

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/07/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

10:21am @ 1/8/18

Person Contacted:

Julian

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction	(X) Estimate
	8KU 7277G - X	
	YP 7597T	
2/8/18	Dismantled.	
6/8/18	After Repair	

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TR / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKU 72776
 at Workshop m/s Bizb/1.0 01-34
 of 9002
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKU 72776 Yr Regn: Aug 1205
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: mazda c.c. 1998
 Colour: brown A/C: Insured / Std / NI / NA
 Sp. Reading: 12882 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JM6CW107170124963
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or continental

Front		Rear	
R/Bal. <u>6</u>	mm	R/Bal. <u>6</u>	mm
L/Bal. <u>6</u>	mm	L/Bal. <u>6</u>	mm
D.O.A. _____		D.O.I. <u>1/8/18</u>	

Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear & Rear. w/ screen shattered
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No further. PAS.

15/8/18 submit RR report

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

180

20

200

Your password will expire in 12 days. [Click here to change it.](#)

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying

To: assignments@lkkauto.com, Admin A

Cc: Fong, Andy-SY

Sent: 1/8/2018 10:01:19 AM

Attachments:  SKU7277G VS YP7597T.TIF  YP7597T VS SKU7277G.tif

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.


NEO & LIM
*Advocates and Solicitors
Commissioner for Oaths
Notary Public*
IVY NEO QUEE ENG
**151 CHIN SWEE ROAD #14-04
MANHATTAN HOUSE
SINGAPORE 169876
TEL: 67338800
FAX: 67338801
EMAIL: neonlim@singnet.com.sg
UEN: 53131342E**
YOUR REF:
OUR REF:
DATE:
NQE.AN.7.18.6081
31/7/2018
**AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way, #07-16
Singapore 079120**
**Attn: Motor Claims Department
(By Fax No.64153727 only)**
Dear Sirs
PRE-REPAIR INSPECTION NOTICE

We act for Lee Hul Lin the owner and/or driver of motor vehicle no.SKU7277G, which was involved in an accident at PIE (Tuas) after Eng Neo exit LP1125 on 26 July 2018, 22.30 hours.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. YP75971 for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at Bizfollo Motor Trading (Block 9002 Tampines St.93 #01-34 Singapore 528836- Juliana @ 62444464).

If we do not hear from you within the next 2 working days, we shall deem that you have waived the requirement for the pre-repair inspection.

Yours faithfully

Cc: Bizfollo Motor Trading
(Yr Ref:SKU7277G)



NEO & LIM

*Advocates and Solicitors
Commissioner for Oaths
Notary Public*

IVY NEO QUEE ENG

151 CHIN SWEE ROAD #14-04
MANHATTAN HOUSE
SINGAPORE 169876
TEL: 67338800
FAX: 67338801
EMAIL: neonlim@singnet.com.sg
UEN: 53131342E

YOUR REF:

OUR REF:

2109685109SG003
NQE.AN.7.18.6081

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way, #07-16
Singapore 079120

Attn: Motor Claims Department
(By Fax No.64153727 only)

Dear Sirs

PRE-REPAIR INSPECTION NOTICE

We refer to your email of 31 July 2018.

Our client is not agreeable to your nominated panel of surveyors.

Our client nominated panel of surveyors are as follows:

1. Patrick Ng Kong Beng
2. Jayson Liew Leong San
3. Loi Boon Juan
4. Ang Guea Kiang
5. Matthew Ng Yong Chin
6. Ong Poh Meng
7. Tan Chin Suan
8. Lee
9. Philip Foo

Please contact our Ms. Angela at 67338800 or email us at neonlim@singnet.com.sg for the PRI. If we do not hear from you within 2 days of this letter, we shall deem that you have agreed that the surveyor appointed by our client shall be our single joint expert for this matter.

Yours faithfully

Cc: Bizfolio Motor Trading
(Yr Ref:SKUX2776)

DATE:

31/7/2018




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG18014007/Uz4d3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 01-08-2018		
		Code : AIG		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	YP 7597T	Veh. Inspected	SKU 7277G	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	CHIN LEE YING	Assign Date	01/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	26/07/2018	Inspection Date	01/08/2018	
Survey held at	-			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/07/2018 10:01
Date Of Accident	26/07/2018 22:30
Exact Location Of Accident	PIE (TUAS) AFTER ENG NEO EXIT LP1125
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU7277G
Insured/Policyholder	
Name Of Registered Owner	LEE HUI LIN
NRIC No	S1654503A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96257283
Alternative Phone No	OTHERS-96257283

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA 5
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100424785-02
Cover Note Number	

Driver

Name of Driver	WONG KENG YAK
NRIC No	S1553446Z
Date Of Birth	05/01/1962
Occupation	INDOOR
Date Of Driving Pass	30/03/2008
Driving Experience	10 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96920049
Fax Number	
Contact Number	
EEmail Address	WONGKENGYAK@GMAIL.COM

Address	23 HILLVIEW AVENUE #10-01 S6969557
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP7597T
Vehicle Make/Model/Colour	LORRY/ WHITE
Details Of Properties	NIL
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LIM KIA KHEE
NRIC/Passport Number	S8093205M
Contact Number	94650041
Address	NIL
	NIL
Postcode	NIL
Insurance Company Name	
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



28 24 2018

Accident Sketch Plan Pg. 1

SKETCH PLAN



A - SKU7277G

B - YP7597T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The incident happened at approximately 10.30 pm, on the second lane along PIE towards Tuas after Top New exit. on 26th July 2018.	
I was driving along PIE (Tuas), on the second lane from the left and was heading towards BKE. Traffic was heavy and there were a few cars filtering into my lane ahead of me, after Top New exit.	
They cut into 4-5 cars ahead of me. Suddenly, the car in front of me abruptly applied his brakes. I reacted instinctively and also applied my breaks. I then heard a loud bang from the rear of my car and noticed that my rear windscreen had shattered.	
The driver of truck YP7597T (who slammed) into my car from behind and I drove to the road shoulder on the left, and we were parked near lamp post 1126. I exchanged particulars with Mr Lim Kia Khee, took photos and drove off thereafter.	
<p>AGG Ins.</p> <p>Policy No. <u>SKU7277G</u></p> <p>Date of Accident <u>26.7.2018</u></p> <p><input type="checkbox"/> Reporting Only</p> <p><input type="checkbox"/> Own Damage Claim</p> <p><input type="checkbox"/> Third Party Claim</p> <p><input checked="" type="checkbox"/> Other Workshop</p> <p><u>Yeow Koon Motor</u></p> <p><u>Spray painting</u></p>	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

NRIC & DL Pg. 1



NRIC & DL Pg. 1

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg 20 Mar 2008



Licence No: S1553446Z

NP 428A

5533942



NRIC No: S1553446Z



Date of issue
03-11-2015

Address

23 HILLVIEW AVENUE
#10-01
SINGAPORE 669557

15 FEB 2018
MALAYSIA RESIDATION
BANGKUNAN SULTAN ISKANDAR
VISIT PASS
Reg. 11, Imm. Regs. 63
Permitted to enter and remain
in West Malaysia and Sabah
for thirty (30) days
on social visit only from
the date shown above.

16 FEB 2018
MALAYSIA RESIDATION
BANGKUNAN SULTAN ISKANDAR
VISIT PASS
Reg. 11, Imm. Regs. 63
Permitted to enter and remain
in West Malaysia and Sabah
for thirty (30) days
on social visit only from
the date shown above.

08 JUN 2018
MALAYSIA RESIDATION
KL INTERNATIONAL
VISIT PASS
Reg. 11, Imm. Regs. 63
Permitted to enter and remain
in West Malaysia and Sabah
for thirty (30) days
on social visit only from
the date shown above.

09 JUN 2018
MALAYSIA RESIDATION
KL INTERNATIONAL
VISIT PASS
Reg. 11, Imm. Regs. 63
Permitted to enter and remain
in West Malaysia and Sabah
for thirty (30) days
on social visit only from
the date shown above.

27 JUL 2018
MALAYSIA RESIDATION
KL INTERNATIONAL
VISIT PASS
Reg. 11, Imm. Regs. 63
Permitted to enter and remain
in West Malaysia and Sabah
for thirty (30) days
on social visit only from
the date shown above.

27 JUL 2018
MALAYSIA RESIDATION
KL INTERNATIONAL
VISIT PASS
Reg. 11, Imm. Regs. 63
Permitted to enter and remain
in West Malaysia and Sabah
for thirty (30) days
on social visit only from
the date shown above.

VISAS



CERTIFICATE OF INSURANCE

MAZDA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Lee Hui Lin
 Period of Insurance : 13 Aug 2017 To 12 Aug 2018
 Engine No. : PE10237238
 Chassis No. : JM6CW1071F0121963

Vehicle No. : SKU7277G
 Policy No. : 2100424785-02
 Endorsement No. :
 Issued Date : 21 Jul 2017

ABOUT THE COVER

Make/Model : MAZDA 5 2.0 SKYACTIV
 Engine Capacity/Tonnage : 1,998.00 CC
 Driver Restriction : NA

Sum Insured : Market Value
 Off Peak Car : No

First Year of Registration : 2015
 Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade

Loss of Use (10 days) 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 109) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Lee Hui Lin - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Trans Eurokara Pte Ltd, Add 5 Ubi Close, Singapore 408605 63950899

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6330 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HONG LEONG FINANCE LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0503599190

ARF (AP) PTE LTD - MAZDA
 7 MAXWELL ROAD #01-100 ANNEX B MND COMPLEX
 SINGAPORE 069111

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Janile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SSPVKKU

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	SKU7277G
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover
Vehicle Attachment 1 :	With Sun Roof
Vehicle Scheme :	Normal
Vehicle Make :	MAZDA
Vehicle Model :	MAZDA5 5-DOOR WAGON 2.0L SP.6EAT SUNROOF
Chassis No. :	JM6CW1071F0121963
Propellant :	Petrol
Engine No. :	PE10237238
Engine Capacity :	1998 cc
Maximum Power Output :	111.0 kW (148 bhp)
Maximum Laden Weight :	2130 kg
Unladen Weight :	1535 kg
Year Of Manufacture :	2015
Original Registration Date :	13 Aug 2015
Lifespan Expiry Date :	-
COE Category :	E - Open Category
Quota Premium :	\$69,001.00
COE Expiry Date :	12 Aug 2025
Road Tax Expiry Date :	12 Aug 2019
PARF Eligibility Expiry Date :	12 Aug 2025
Inspection Due Date :	12 Aug 2020
Intended Transfer Date :	15 Aug 2018
CO2 Emission :	158.00 (g/km)
CEV/VES Rebate Utilised Amount :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

No Sittler. r

NO:

SKU 72776

Date:

	Rear windscreen	shopped —
	Rear windscreen moulding	see —
	Rear windscreen sealant	see —
	Rear windscreen inner seal	see —
	Tailgate	DD —
	Tailgate rear logo	see —
	Tailgate 'Mazda' emblem	see —
	Tailgate 'S' emblem	see —
	Tailgate Outer handle	see —
2 pcs	Tailgate reflectors	see —
	Tailgate weatherstrip	see —
	Tailgate rear wiper motor	11 X
	Rear windscreen solar film	see —
	Tailgate inner lock	Tw. —
	Rear licence plate withholder	Best
	Rear bumper	DD/see —
	Rear bumper clips	see —
2 pcs	Rear bumper side retainers	Best —
	Rear bumper beam	R X
	Rear end panel	R X
2 pcs	Tail lamps	see —
	Rear exhaust	R X
	Rear reverse camera	?

Sdy.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Aug 2018 Edit Reg		01 Aug 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Metaquip TC Industrial , Co. Reg. No.: NA								
Main Claimant:	-								
Vehicle Reg. No.:	SKU7277G	Date of Loss:	26/07/2018 00:00 - :59 [35 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2109685109SG	Policy/Cover Note No.:	0999994875 (Comprehensive)						
Vehicle Reg. No. (Insured):	YP7597T	Policy No. (Claimant):							
		Excess:							
Repairer:	Bizfolio Motor Trading (HQ) BLK 9002 TAMPINES ST 93 #01-34, 528836 Tampines - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 14/08/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (03/08/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




































Claim Documents



















































***SKU7277G (2109685109SG)**
[YP7597T]


















TP

-

Jul 26 2018 12:00AM
[Metaquip TC Industrial]
Bizfolio Motor Trading

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
2	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
3	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
4	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
5	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
6	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
7	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
8	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
9	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
10	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
11	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
12	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
13	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
14	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
15	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
16	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
17	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
18	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
19	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
20	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
21	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
22	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
23	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
24	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
25	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
26	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
27	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
28	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
29	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
30	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
31	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
32	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
33	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
34	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
35	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
36	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	
37	07/08/18 11:25	General View														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
39	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
40	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
41	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
42	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
43	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
44	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
45	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
46	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
47	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
48	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
49	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
50	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
51	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
52	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
53	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
54	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
55	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
56	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
57	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
58	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
59	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
60	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
61	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
62	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
63	07/08/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
64	07/08/18 11:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	07/08/18 11:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	07/08/18 11:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	07/08/18 11:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	07/08/18 11:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	07/08/18 11:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	07/08/18 11:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	07/08/18 11:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	07/08/18 11:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	07/08/18 11:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	07/08/18 11:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	07/08/18 11:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	07/08/18 11:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	07/08/18 11:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	07/08/18 11:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	07/08/18 11:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	07/08/18 11:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	07/08/18 11:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
91	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
93	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	07/08/18 11:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	03/08/18 10:48	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18014007/URD3E2

Date: 17/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994875
Claimant Vehicle No : SKU7277G **Insured Vehicle No :** YP7597T
 Date of Loss: 26/07/2018 Nature of Claim: TP Claim No: 2109685109SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU7277G**
 Make & Model: MAZDA 5 SP, 2.0 (A) Engine No: PE10237238
 Reg. Date: 13/08/2015 (Man. Year: 2015) Chassis No: JM6CW1071F0121963
 Colour: Brown Odometer: 128821 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 01/08/2018
 Date Inspected: 01/08/2018 Inspected At: Bizfolio Motor Trading (HQ)
 BLK 9002 TAMPINES ST 93 #01-34
 Singapore 528836
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Shattered	0.00 F	*- F
2	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*- F
3	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*- F
4	1		*REAR WINDSCREEN INNER SEAL	Necessary	0.00 F	*- F
5	1		*TAILGATE	Dented	0.00 F	*- F
6	1		*TAILGATE REAR LOGO	Necessary	0.00 F	*- F
7	1		*TAILGATE MAZDA EMBLEM	Necessary	0.00 F	*- F
8	1		*TAILGATE 5 EMBLEM	Necessary	0.00 F	*- F
9	1		*TAILGATE OUTER HANDLE	Cracked	0.00 F	*- F
10	2		*TAILGATE REFLECTORS	Cracked	0.00 F	*- F
11	1		*TAILGATE WEATHERSTRIP	Necessary	0.00 F	*- F
12	1		*TAILGATE REAR WIPER MOTOR	Not Necessary	0.00 F	*- F
13	1		*REAR WINDSCREEN SOLAR FILM	Necessary	0.00 F	*- F
14	1		*TAILGATE INNER LOCK	Twisted	0.00 F	*- F
15	1		*REAR LICENSE PLATE W/HOLDER	Bent	0.00 F	*- F
16	1		*REAR BUMPER	Dented / Deformed	0.00 F	*- F
17	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
18	2		*REAR BUMPER SIDE RETAINERS	Bent	0.00 F	*- F
19	1		*REAR BUMPER BEAM	Repair	0.00 F	*- F
20	1		*REAR END PANEL	Repair	0.00 F	*- F
21	2		*TAILLAMPS	Cracked	0.00 F	*- F
22	1		*REAR EXHAUST	Repair	0.00 F	*- F
23	1		*REAR REVERSE CAMERA	* Check	0.00 F	*- F
F=Franchise part.						
					Total Parts (S\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >