

22/03/2002

ASS. REC. BY:

REF:

01 EGI 18014010/Urb322

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGI

Date/Time:

1/8/18 @ 11:30am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 1234J

Insured:

GV502U

at Workshop m/s

Focus Auto

Tel:

6886 9097

of

No 1, Kuki Bldg Ave 6 #02-50

Policy No:

Claim No:

GV502U / SL / p1

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/07/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:39am @ 1/8/18

Person Contacted:

Laura

Vehicle

IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SKW 1234J - CB3 / AIG / 866 2565 / Sub 382

DOA: 5/2/2018

GV502U - CCG / EGI / 8565 / Uha392

DOA: 30/9/2018

Revert thru email

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

SRI/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TS / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW1234Jat Workshop m/s Focus

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IPAC Accident Report: _____ Consistent?: Yes or No

GLA / PR Seen: ✓ Consistent?: Yes or NoEst. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L1A50536

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKW1234JYr Regn: 7 / 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /Make: 1414 cerato k3c.c. 1591Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 25888

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAF 6411M J 5729379

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45-17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or nexen

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 30/7/18D.O.I. 1/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

11/8 contacted 4/5 @ 3100 with MR Wong.Red: 4289180, 481.

RECEIVED 03 AUG 2018

Date/Time, File Pass to?

1) Support

Date/Time, File Return to?

2) _____

Report Format: TPLump Sum / L.B. (\$) 3100Days Of Repair: 4Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS, \$ SI

Photos

Others

TOTAL

250250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18014010/Urd3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 01-08-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GV 502U	Veh. Inspected	SKW 1234J
Policy No.		Coverage (\$)	0.00
Claim No.	GV50U/SL/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	01/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	30/07/2018	Inspection Date	01/08/2018
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Wednesday, 1 August 2018 11:30 AM
To: 'admin-d@lkkauto.com'
Cc: 'ASSIGNMENTS@LKKAUTO.COM'
Subject: OI : GV502U / TP : SKW1234J/LKK / DOA : 30/07/2018
Attachments: GV502U - SAS.pdf; SKW 1234J - SAS.pdf; SKW 1234J - PRS FORM.pdf; Re: RE: ACCIDENT INVOLVING SKW1234J & GV502U ON 30/07/2018 ALONG BRADDEL... (23.8 KB)

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FOCUS AUTO PTE LTD,**

ADDRESS : NO 1 KAKI BUKIT AVE 6
#02-50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : LAURA / WONG @ 6886 9097

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and Inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9194
Tel.: +65 6829 9199
Fax: +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Friday, August 03, 2018 3:33 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: GV502U / TP : SKW1234J/LKK / DOA : 30/07/2018
Attachments: SKW 1234J .pdf

Dear Sir/ Madam,

Enclosed preliminary revised for **SKW 1234J**.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, August 01, 2018 11:42 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GV502U / TP : SKW1234J/LKK / DOA : 30/07/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Wednesday, 1 August 2018 11:30 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>
Subject: OI : GV502U / TP : SKW1234J/LKK / DOA : 30/07/2018

Dear Catherine/Nivitha,

ERGO

Date: 01.08.2018
Our Reference: GV 502U/SL/pl
Your Reference: SKW 1234J

To: FOCUS AUTO PTE LTD

Sent via Fax
or
Email

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SKW 1234J
Insured's Vehicle: GV 502U
Date Of Accident: 30.07.2018


We acknowledge receipt of your request for PRS on: 31.07.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input checked="" type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us todate.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GV502U/SL/pl
Our Ref: CS/EGI18014010/Urd3

The Motor Claims Department
ERGO Insurance Pte Ltd

Without Prejudice

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. SKW 1234J .

We thank you for the instruction on 01/08/2018.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 01/08/2018 at the premises of M/s FOCUS AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 5,991.80 .
Revised Estimate Amount	: S\$ 3,896.25 .
"Check" Items Amount	: S\$.
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:
The vehicle sustained damages
at the rear portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully

MARCUS CHUA
Automotive Assessor

MSME18098970 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 31/07/2018 16:11
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/07/2018 16:11
Date Of Accident	30/07/2018 17:55
Exact Location Of Accident	ALONG BRADDELL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW1234J
Insured/Policyholder	
Name Of Registered Owner	SUM KOK WEI
NRIC No	S9113482I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81280190
Alternative Phone No	OFFICE-81280190

Vehicle Particulars

Manufacturer	KIA
Model	K3
Exact Purpose for which vehicle was being used at time of accident	

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI18V09494/VPC/R00
Cover Note Number	

Driver

Name of Driver	SUM KOK WEI
NRIC No	S9113482I
Date Of Birth	26/03/1991
Occupation	INDOOR
Date Of Driving Pass	12/05/2011
Driving Experience	7 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81280190
Fax Number	
Contact Number	OFFICE-81280190
EEmail Address	NOEMAIL

Address 10A BRADDELL HILL #18-01
 Postcode 579720
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : CHEE
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 30/07/2018 AT 1754HRS, I WAS DRIVING VEHICLE A (SKW1234J) TRAVELLING ALONG BRADDELL ROAD. I WAS STUCK ON LANE 2, TRAFFIC WAS HEAVY. SUDDENLY, VEHICLE B (GV502U) WHICH WAS FROM BEHIND OF MY VEHICLE CANNOT MANAGED TO STOP IN TIME AND COLLIDED ONTO REAR OF MY VEHICLE CAUSING MY VEHICLE REAR PORTION BADLY DAMAGED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GV502U
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver GOH NGONG POO
 NRIC/Passport Number
 Contact Number 93424335
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SUM KOK WEI

Approximate Age

Injuries Sustain

Injured person in which vehicle? SKW1234J

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3482I
Vehicle Details	
Vehicle No.:	SKW1234J
Vehicle to be Exported:	No
Intended De-registration Date:	01 Aug 2018
Vehicle Make:	KIA
Vehicle Model:	CERATO K3 1.6A SUNROOF
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	G4FGGH673152
Chassis No.:	KNAFZ411MJ5729379
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$16,144.00
Original Registration Date:	25 Jul 2017
First Registration Date:	25 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$16,144.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jul 2027
PARF Rebate Amount:	\$12,108.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$38,428.00
Total Rebate Amount:	\$50,536.00

The information contained herein is correct as at 01 Aug 2018

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Free Car Valuation

Unsure of how much your car is worth?

Let us tell you how much is the value - no charges & no obligations!

Post an Advertisement

Sell it yourself! Advertise it at just


\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Low mileage, Immaculate condition,Cheapest Yet Nego!




Rare Beauty 2/14 Audi A6
Avant. 60k km Agent Unit. New \$240k, Now Only \$99.8k!
Kimhung Hegary & Co StarAd

ABWIN

ONE-STOP

MOTORING SOLUTIONS



Browse by Category

▼

Sort by Date Posted

▼

20 results/page

▼

6 vehicles

Kia Cerato

Advanced Search

Submit

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Kia Cerato

Any

Any


2017

Any

Any

Any

Available



Kia Cerato K3 1.6A Sunroof

\$91,800

\$9,130 /yr

11-Oct-2017

1,591 cc

10,263 km


Sedan

Available

Highest Specs K3 1.6A SX Model With Sunroof & Full Bodykits! 1 Owner, Fully Maintained & Service By C&C, Original Condition, High Parf Value, 10 Years Engine Warranty, Flexible Loan & Trade In Availab...

Posted: 26-Jul-2018

Tags: 2017 Kia Cerato, Kia Cerato, Kia, Cerato, Used Kia



Kia Cerato K3 1.6A EX

\$71,000

\$7,370 /yr

28-Apr-2017

1,591 cc

21,000 km


Sedan

Available

1 Careful Owner, Full Agent Serviced With Service Record, Stylish Design With Excellent Fuel Efficiency! R/T April '19. Very Well Maintained! Selling Cheap! In House And Bank Loan Available. Call For ...

Posted: 19-Jul-2018

Tags: 2017 Kia Cerato, Kia Cerato, Kia, Cerato, Used Kia



Kia Cerato K3 1.6A Sunroof

\$77,888

\$7,550 /yr

08-Nov-2017

1,591 cc

9,000 km


Sedan

Available

SX Highest Spec Model. With All Add-ons Available From C&C. Comes With 1 Free Agent Servicing And Warranty Till 2022. Also Comes With 470 Credits From C&C. Lowest Mileage. Use To Commute To And Fro Fr...

Posted: 06-Jul-2018

Tags: 2017 Kia Cerato, Kia Cerato, Kia, Cerato, Used Kia



Kia Cerato K3 1.6A

\$75,800

\$7,650 /yr

28-Aug-2017

1,591 cc

-

Sedan

Available

In Excellent Condition. Well Kept By Owner And Regularly Serviced. Comes In 7 Inch Motrex Touchscreen That Support Apple Car Play And Android Software. High Loan And Trade In Welcome. Call Now For Vie...

Posted: 02-Jul-2018

Tags: 2017 Kia Cerato, Kia Cerato, Kia, Cerato, Used Kia

Car Buying


Car Selling


Car Ownership

Car Aftermarket

On The Move

Lifestyle





Kia Cerato K3 1.6A Sunroof

\$84,000

\$8,460 /yr

24-Jul-2017

1,591 cc

18,500 km


Sedan

Available

Beautiful Model With Sunroof! 5 Year Warranty Plus 2 More Years Extended Warranty. Well Maintained By 1 Owner, Flexible Loan At Low Interst Rates, Trade In Welcome, Call To View Now!

Posted: 22-Jun-2018

Tags: 2017 Kia Cerato, Kia Cerato, Kia, Cerato, Used Kia



Kia Cerato K3 1.6A

\$72,800

\$7,280 /yr

11-Sep-2017

1,591 cc

10,000 km

Sedan

Available

EX Model! New Car Selling For \$87K! Buy This Unit For \$10,000 Off New Car Price! Only 9 Months Old, Well Taken Care, Low Mileage. Owner Selling Due To Migration. Original 5 Years Warranty Till 2022. V...

Posted: 05-Jun-2018

Tags: 2017 Kia Cerato, Kia Cerato, Kia, Cerato, Used Kia

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6886 9095 Email: focus.autopetltd@yahoo.com.sg

GST:201004495R RCB NO:201004495R

not Allowed
1/8/18
2/s # 3102/2
to be photo After rep
Atty.

M/S : ERGO Insurance Pte Ltd
5 Temasek Boulevard #04-01
Suntec Tower Five
Singapore 038985
TEL: (65)6829 9199 (Ext: 170) **FAX:** (65) 6829 9247
ATTN: Motor Claim Department
Your Ref No: SKW1234J
Claim Type: Third Party
Accident Date: 30-07-2018
TP Veh Reg No: GV502U

Estimate No: EST0000676
Date: 31 Jul 2018
Policy No: SI18V09494/VPC/R00
Veh Reg No: SKW1234J
Make/Model: KIA CERATO K3
Chassis No: KNAFZ411MJ5729379
Engine No: G4FGGH673152
Reg. Date: 25-07-2017

Estimate Repair Cost to Vehicle No :SKW1234J

PAGE:1/2

Description	U/Price	Quantity	List Price SS	Amount SS
SKW1234J KIA CERATO K3				
List Price				
1 Rear Boot	863.0000	1 PC	863.00	X
2 Rear Boot Lock	109.0000	1 PC	109.00	—
3 Rear Boot Lock Catch	17.0000	1 PC	17.00	X
4 Rear Boot Rubber	104.0000	1 PC	104.00	—
5 Rear Boot Emblem	24.0000	1 PC	24.00	—
6 Rear Boot Centre Logo	29.0000	1 PC	29.00	—
7 Rear End Panel	452.0000	1 PC	452.00	X
8 Rear End Panel Top Garnish	78.0000	1 PC	78.00	X
9 Rear End Panel Top Garnish Clipse	5.5000	3 PC	16.50	X
10 Rear Bumper	668.0000	1 PC	668.00	—
11 Rear Bumper Side Retainer	33.0000	2 PC	66.00	—
12 Rear Bumper Reinforcement	323.0000	1 PC	323.00	—
13 Rear Bumper Reinforcement Bracket	140.0000	2 PC	280.00	—
14 Rear Bumper Lower Bracket	14.0000	3 PC	42.00	—
15 Rear Bumper Lower Pad	347.0000	1 PC	347.00	—
16 Rear Bumper Clip	5.5000	5 PC	27.50	—
17 Rear Bumper Sensor	178.0000	2 PC	356.00	—
			3,802.00	2262.5
	Less 10%		380.20	3,421.80
Special Net				
18 Rear Bumper Spoiler	650.0000	1 PC	650.00	—
			650.00	650.00
Labour				
19 Panel Beating	920.0000	1 PC	920.00	5-20
20 Check Wiring	60.0000	1 PC	60.00	20
21 To Remove & Replace Bumper Sensor	60.0000	1 PC	60.00	50
22 To Spray Rust Proofing	60.0000	1 PC	60.00	20
23 Spray Painting	820.0000	1 PC	820.00	800-600
			1,920.00	1,920.00

234

2262.5

2036.25

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6886 9095 Email: focus.autopteltd@yahoo.com.sg

GST:201004495R RCB NO:201004495R

M/S : ERGO Insurance Pte Ltd
5 Temasek Boulevard #04-01
Suntec Tower Five
Singapore 038985

TEL: (65)6829 9199 (Ext: 170) FAX: (65) 6829 9247

ATTN: Motor Claim Department

Your Ref No: SKW1234J

Claim Type: Third Party

Accident Date: 30-07-2018

TP Veh Reg No: GV502U

Estimate No: EST0000676

Date: 31 Jul 2018

Policy No: SI18V09494/VPC/R00

Veh Reg No: **SKW1234J**

Make/Model: KIA CERATO K3

Chassis No: KNAFZ411MJ5729379

Engine No: G4FGGH673152

Reg. Date: 25-07-2017

Estimate Repair Cost to Vehicle No :SKW1234J

PAGE:2/2

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	SS 5,991.80

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND NINE HUNDRED NINETY ONE AND CENTS EIGHTY ONLY

For FOCUS AUTO PTE LTD

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18014010/Urd3e2

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 23-08-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GV 502U	Veh. Inspected	SKW 1234J
Policy No.		Coverage (\$)	0.00
Claim No.	GV502U/SL/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	01/08/2018

2. Vehicle Particulars & Condition

Make & Model	KIA CERATO K3 (A)	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KNAFZ411MJ5729379	Colour	GREY
Odometer	25858	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R17	NEXEN	6 mm
L/H Front Tyre	215/45 R17	NEXEN	6 mm
R/H Rear Tyre	215/45 R17	NEXEN	6 mm
L/H Rear Tyre	215/45 R17	NEXEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	30/07/2018	Inspection Date	01/08/2018
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 1234J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT	TO REPAIR SEE LABOUR	863.00	-
1	REAR BOOT LOCK	SHORTED	109.00	109.00
1	REAR BOOT LOCK CATCH	NOT NECESSARY	17.00	-
1	REAR BOOT RUBBER	TWISTED	104.00	104.00
1	REAR BOOT EMBLEM	NECESSARY	24.00	24.00
1	REAR BOOT CENTRE LOGO	NECESSARY	29.00	29.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	452.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	78.00	-
3	REAR END PANEL TOP GARNISH CLIPSE @\$5.50	NOT NECESSARY	16.50	-
1	REAR BUMPER	DENTED / DEFORMED	668.00	668.00
2	REAR BUMPER SIDE RETAINER @\$33.00	BENT	66.00	66.00
1	REAR BUMPER REINFORCEMENT	CRACKED	323.00	323.00
2	REAR BUMPER REINFORCEMENT BRACKET @\$140.00	BENT	280.00	280.00
3	REAR BUMPER LOWER BRACKET @\$14.00	TWISTED	42.00	42.00
1	REAR BUMPER LOWER PAD	DEFORMED / TWISTED	347.00	234.00
5	REAR BUMPER CLIP @\$5.50	NECESSARY	27.50	27.50
2	REAR BUMPER SENSOR @\$178.00	SHORTED	356.00	356.00
	LESS 10% DISCOUNT		-380.20	-226.25
			3,421.80	2,036.25
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER SPOILER (SN)	CRACKED	650.00	650.00
			650.00	650.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BOOT AND REAR END PANEL.		920.00	520.00
	CHECK WIRING.		60.00	20.00
	TO REMOVE & REPLACE BUMPER SENSOR.		60.00	50.00
	TO SPRAY RUST PROOFING.		60.00	20.00

Report Ref No. CS/EG18014010/Urd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING.		820.00	600.00
			1,920.00	1,210.00
	GRAND TOTAL		5,991.80	3,896.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,100.00

Report Ref No. CS/EG18014010/Urd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.