

ASS. REC. BY:

REF:

CS3/SMO18014013/D240302

Special Instruction:

Surveyor:

Bryan

ASSIGNMENT (Office)

From (Person):

Grace Leo

of

SMO

Date/Time:

31/7/18 @ 4:33pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBE 909D

Insured:

8KZ 7778B

at Workshop m/s

Speedy Motor

Tel:

6481 5567

of

31k 10 AMK Ind. Park 2A #05-21

Policy No:

Claim No:

CM7D1803265/7HE

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/07/2018

CA / REV / REP. / REV 24 HRS

Cup

H.O.D. Endorsement:

Date/Time:

10:49am 01/8/18

Person Contacted:

Ms. Tan

Vehicle IN/OUT

Date/Time	Action/Instruction	(X) Estimate
	FBE 909D - NA / INC 10617761/r	DoA: 2/8/2018
	8KZ 7778B - X	
	Dismantle parts : 02/08/2018	

REF:

ASSIGNMENT

COR Jan 2023

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **FBE 909 D** Yr Regn: **2013 Jan**Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Honda CB 1000** C.C. **998**Colour: **Multi-colour** A/C: Insured / Std / NI / NASp. Reading: **38904** T/Radio: Insured / Std / NI / NAEng/No: **8C60E2108070**C/No: **ZDCSC60C0CF066907**Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: **120/70 R17**R: **180/55 R17**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal. **3** mmR/Bal. **3** mm

L/Bal. mm

L/Bal. mm

D.O.A. **29/07/2018**D.O.I. **01/08/2018 @ 02:15 pm**Survey held at **Speedy Motor AMK**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

No visible damage.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Sampo PRS SKZ 7778B**1st inspection 01/08/2018****2nd - " - 02/08/2018****No repair range provided.**

* **No visible damage to TP bike. Reported that OI reversed. So should contact at TP tyre only. Haven say which side fault. Had to check on consistency of damage.**

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final ReportResurvey No. of Trip: **2**

Survey Fee:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

Transportation:

☐ : Interview (\$)

) Photos

Report Format: **PRS**☐ : Tech. Invs (\$)

) Others

Lump Sum / I.B.I: (\$)

☐ : Weekend (\$)

TOTAL

160**100****60**

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 31 July, 2018 4:33 PM
To: Tan Mei Ling; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Choo, Thelma; Henry, Irene James
Subject: CMTD1803265/THE - SUV(LKK)/ SKZ7778B & FBE909D ACC ON 29.07.18
Attachments: img-731152918.pdf

Our Reference : CMTD1803265/THE
Your Reference: JEQ/FBE909D/SM

Date: 31st July 2018

Without Prejudice
EMAIL ONLY

Attention:
M/S JUSEQUITY LAW COPORATION

Dear Mei Ling,

ACCIDENT INVOLVING SKZ7778B & FBE909D ON 29.07.2018

We refer to your email reply of today.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sampo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sampo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: meilinyu@gmail.com [mailto:meilinyu@gmail.com] **On Behalf Of** Tan Mei Ling

Sent: Tuesday, July 31, 2018 4:25 PM

To: Teo, Grace

Cc: Choo, Thelma; Henry, Irene James

Subject: Re: CMTD1803265/THE - PRI/ SKZ7778B & FBE909D ACC ON 29.07.18

Dear Sirs

We refer to your email of even date.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

- 1) **UNITED Appraisal And Management Pte Ltd**
- 2) **SK Auto Consultants**
- 3) **Chartered Auto Assessors**
- 4) **LCW APPRAISER PTE LTD**
- 5) **Sincere Appraisal Services**
- 6) **Pal's Appraisal Pte Ltd**
- 7) **Mc-Coy Appraiser Pte Ltd**
- 8) **CM Automotive Consultancy**

Please be informed that if the above is not agreeable by you, our client's motor vehicle is available for pre-repair inspection at the under-stated workshop:-

Speedy Motor Cycle Service Centre

Blk 10 Ang Mo Kio Industrial Park 2A

#05-21 Singapore 568047

Person In-Charge: Mr Lim Sam Hee at Tel: 6481 5567 / 9388 6867

Fax No. 6482 5567

*Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11.

On Tue, Jul 31, 2018 at 4:01 PM, Teo, Grace <grace.teo@sampo.com.sg> wrote:

Our Reference : CMTD1803265/THE

Your Reference: JEQ/FBE909D/SM

Without Prejudice

Attention:
M/S JUSEQUITY LAW COPORATION

Dear Mei Ling,

ACCIDENT INVOLVING SKZ7778B & FBE909D ON 29.07.2018

We refer to your Notice of Accident dated 31/07/2018.

Please be informed that Thelma Choo is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: meilinyu@gmail.com [mailto:meilinyu@gmail.com] **On Behalf Of** Tan Mei Ling

Sent: Tuesday, July 31, 2018 3:35 PM

To: Claims - Motor Survey

Subject: NOTICE OF ACCIDENT - FBE909D

Dear Sirs

Please see attached Notice of Accident.

--

Warmest Regards

Sent for and on behalf of

JusEquity Law Corporation
Advocates & Solicitors

Commissioner For Oaths

171 Chin Swee Road #02-06 CES Centre Singapore 169877

Main : (65) 6506 9339 | DID : (65) 6506 0945

Fax : (65) 6536 5368

Email : ml_tan@juseq.com.sg

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

--

Warmest Regards

Sent for and on behalf of

JusEquity Law Corporation

Advocates & Solicitors

Commissioner For Oaths

171 Chin Swee Road #02-06 CES Centre Singapore 169877

Main : (65) 6506 9339 | DID : (65) 6506 0945

Fax : (65) 6536 5368

Email : ml_tan@juseq.com.sg

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.



JusEquity Law Corporation

ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS

171 Chin Swee Road #02-06 CES Centre Singapore 169877
Telephone (65) 6536 9339, (65) 6253 1812, (65) 6397 2008, (65) 6533 2327
Fax : (65) 6253 0120 (Conveyancing) , (65) 6536 5368 (Litigation)
Email : juseq@singnet.com.sg Website: www.juseq.com.sg

Our Ref: JEQ/FBE909D/SM
Your Ref: **SKZ7778B**

31 July 2018

SOMPO INSURANCE SINGAPORE PTE LTD
50 Raffles Place #05-01
Singapore Land Tower
Singapore 048623

VIA FAX ONLY
(FAX NO. 6221 3147)

Dear Sir

ACCIDENT INVOLVING FBE909D & SKZ7778B ON 29.7.2018

We act for the owner of vehicle no. FBE909D.

We hereby notify you of a road traffic accident on 29/7/18 at about 1800 hours along Blk 456 Pasir Ris Drive 4 open space carpark involving our client's vehicle and vehicle registration no. SKZ7778B driven by your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know **within 2 working days of your receipt of this notice** whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully


Cc ZURAIDAH BINTE ISMAIL
60 Dakota Crescent
#06-207
Singapore 390060
(Vehicle No. SKZ7778B)

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8356F
Vehicle Details	
Vehicle No.:	FBE909D
Vehicle to be Exported:	No
Intended De-registration Date:	03 Aug 2018
Vehicle Make:	HONDA
Vehicle Model:	CB1000RA M
Primary Colour:	Multi-Colour
Manufacturing Year:	2012
Engine No.:	SC60E2108070
Chassis No.:	ZDCSC60C0CF066907
Maximum Power Output:	-
Open Market Value:	\$14,080.00
Original Registration Date:	25 Jan 2013
First Registration Date:	25 Jan 2013
Transfer Count:	1
Actual ARF Paid:	\$2,112.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jan 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,701.00
COE Rebate Amount:	\$760.00
Total Rebate Amount:	\$760.00

The information contained herein is correct as at 03 Aug 2018

OK

MOR118097854 / ETHOZ Protect Pte Ltd - Bukit Batok
 ENTRY DATE & TIME: 30/07/2018 12:18
 SUBMITTED BY: Jonathan Lim Kok Siong

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/07/2018 12:16
Date Of Accident	29/07/2018 18:00
Exact Location Of Accident	BLK 456 PASIR RIS DRIVE 4 OPEN SPACE CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBE909D
Insured/Policyholder	
Name Of Registered Owner	AHMAD FAHMI BIN ABDULLAH
NRIC No	S9038356F
Email Address	FAHMIGASOLYNNE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91868561
Alternative Phone No	OFFICE-91868561

Vehicle Particulars

Manufacturer	HONDA
Model	CB1000RA M

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTMC01004182
Cover Note Number	

Driver

Name of Driver	AHMAD FAHMI BIN ABDULLAH
NRIC No	S9038356F
Date Of Birth	19/10/1990
Occupation	INDOOR
Date Of Driving Pass	24/04/2017
Driving Experience	1 YEAR AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91868561
Fax Number	
Contact Number	OFFICE-91868561
Email Address	FAHMIGASOLYNNE@GMAIL.COM

Address BLK 437 TAMPINES STREET 43
#09-149
Postcode 520437
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1 NAME: : SITI NOR RABIAH ADAWIYAH BINTE MOHAMED ISMAIL
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name CHANGI N.P.C
Police Station Address ROAD: 9 SIMEI STREET 2, POSTCODE: 529914, COUNTRY: SINGAPORE
Police Station Contact TEL NO: - FAX NO:
Was notice of Intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKZ7778B
Vehicle Make/Model/Colour KIA SORENTO
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver SALLEH BIN FARAI BAJRAI
NRIC/Passport Number S7827838B
Contact Number 98710278
Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

SITI NOR RABIAH ADAWIYAH BINTE MOHAMED ISMAIL

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBE909D

Were seat belts worn?

NO

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

No visible damage to TP bike. Reported that OI reversed.
so should contact at TP tyre only. Never say which side fall.
Need to check on consistency of damage.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
SOMPO INSURANCE SINGAPORE PL		Ref: CS3/SMO18014013/Dz4d3e2		
50 RAFFLES PLACE #05-01/06		Date: 13-08-2018		
SINGAPORE LAND TOWER SINGAPORE 048623				
Code: SMO				
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SKZ 7778B	Veh. Inspected	FBE 909D	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1803265/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	31/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CB1000	c.c	998	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	ZDCSC60C0CF066907	Colour	MULTI COLOUR	
Odometer	38904 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70 R17	PIRELLI	3 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	180/55 R17	PIRELLI	3 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
NO VISIBLE DAMAGE TO TP BIKE. REPORTED THAT OI REVERSED. SO SHOULD CONTACT AT TP TYRE ONLY. NEVER SAY WHICH SIDE FALL. NEED TO CHECK ON CONSISTENCY OF DAMAGE.				
5. General Information				
Accident Date	29/07/2018	Inspect Date / Time	01/08/2018 (02:51 PM)	
Survey held at	SPEEDY MOTOR CYCLE SERVICE CENTRE BLK 10 ANG MO KIO IND.PARK 2A #05-21 SINGAPORE 568047			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

Report Ref No. CS3/SMO18014013/Dz4d3e2

Inspected By

ANG BRYAN TANI

Automotive Assessor / Investigator



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.