

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
SOMPO INSURANCE SINGAPORE PL			Ref:	CS3/SMO18014013/[Dz4d3e2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER SINGAPORE 048623				13-08-2018		
			Code:	SMO		
1. Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	SKZ 7778B	Veh. Inspected		FBE 909D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD1803265/THE	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		31/07/2018	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA CB1000	c.c		998	
	Engine No.	HIDDEN	Year of Reg.		2013	
	Chassis No.	ZDCSC60C0CF066907	Colour		MULTI COLOUR	
	Odometer	38904 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	120/70 R17	PIRELLI		3 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	180/55 R17	PIRELLI		3 mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
	NO VISIBLE DAMAGE TO TP BIKE. REPORTED THAT OI REVERSED. SO SHOULD CONTACT AT TP TYRE ONLY. NEVER SAY WHICH SIDE FALL. NEED TO CHECK ON CONSISTENCY OF DAMAGE.					
5.	5. General Information					
	Accident Date	29/07/2018	Inspect Date / Time		01/08/2018 (02:51 PM)	
	Survey held at	vey held at SPEEDY MOTOR CYCLE SERVICE CENTRE				
	BLK 10 ANG MO KIO IND.PARK 2A #05-21 SINGAPORE 568047					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				

Report Ref No. CS3/SMO18014013/Dz4d3e2

Inspected By

ANG BRYAN TANI

K.K.LAU CPT(RET)

Automotive Assessor / Investigator

BEng(Hons), B. Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.