

22/03/2002

ASS. REC. BY:

REF: CS3 / MSG / 8014020 / Tizad Ben Instruction:

Surveyor: Tauhiah ASSIGNMENT (Office)From (Person): Jasmine Lok of MSG Date/Time: 01/8/2018 @ 4:05pm

Estimated Cost: Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLR 5283F Insured: SLR 1514Rat Workshop m/s Groom Werkz Tel: 93954747of 48 Conang CrescentPolicy No: 29000740 Claim No: 565888

Sum Insured: Excess:

Make of Veh: D.O.A. 27/7/2018
(Client's Record)CA / REV / REP. / REV 24 HRS 'up'Date/Time: 5:50pm 01/8/18 Person Contacted: Vincent H.O.D. Endorsement: Vehicle IN ☒ OUT

Date/Time	Action/Instruction (X) Estimate
	SLR 5283F - X
	SLR 1514R - X
	After repair: 6/8/2018

(08/1/13) Wef

ASS. REC. BY:

Taylor

REF: MSIG

ASSIGNMENT

From: Date: 02/08/2018

Estimated Cost:

OP/TP WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: 8LR 5283R

at Workshop m/s

Groom Werkz

of

48 Cenang Crescent

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

12pm - 3pm


Make of Veh:

Vincent 93454747

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up

PRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

92R 5283E

Yr Regn:

Aug / 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Tucson

c.c

1999

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

20396

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

12M433 8134 5456 01708

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/60R17

R:

~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

2/8/18 3pm

Survey held at

Groomwerkz

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

NO G.I.A.

Estimated repair range \$5,000 - \$6,000

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

120

Transportation:

S + RS, SI

Photos

Others

10

TOTAL

130

Report Format: PRE.

Lump Sum / I.B.I. (\$))

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18014020/T1z4d3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 01-08-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLR 1514R	Veh. Inspected	SLR 5283R
Policy No.	29000740	Coverage (\$)	0.00
Claim No.	565888	Excess (\$)	0.00
Assign From	MERIMEN (JASMINE LOK)	Assign Date	01/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	27/07/2018	Inspection Date	02/08/2018
Survey held at	-		

5a. Remarks

<p>A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.</p> <p>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.</p> <p>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.</p>
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Jul 2018		01 Aug 2018 16:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	YIAN LI LING, ID: S8212919G, Tel: +6598416977, Email: LILING.YIAN@GMAIL.COM			
Main Claimant:	ALKA'S LOTUS, Co. Reg. No.: 53366234J			
Vehicle Reg. No.:	SLR5283E	Date of Loss:	27/07/2018 17:00 - :59 [11 Months and 9 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 565888	Policy/Cover Note No.:	29000740 (Comprehensive) Coverage: 31/07/2017 - 30/07/2018	
Vehicle Reg. No. (Insured):	SLR1514R	Policy No. (Claimant):		
		Excess:	S\$500.00	
Repairer:	Groom Werkz Services (HQ) 48 SENANG CRESCENT, 416615 Chai Chee - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 02/08/2018]			
Driver/Custodian (Insured):	YIAN LI LING (36 / Female), NRIC: S8212919G, Tel: +6598416977			
Adj Asg. Remarks:	Third Pre-Repair Survey. TP reject , please assigned LKK to be SJE. Liability - 100% Contact : Mr Vincent @ 9395 4747 (To call before going)			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

>[Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLR5283E		
Vehicle Type :	Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HYUNDAI		
Vehicle Model :	TL TUCSON 2.0 GLS AT 2WD		
Chassis No. :	KMHJ3813MJU560708		
Propellant :	Petrol		
Engine No. :	G4NAHU466891		
Engine Capacity :	1999 cc		
Maximum Power Output :	114.0 kW (152 bhp)		
Maximum Laden Weight :	2040 kg		
Unladen Weight :	1540 kg		
Year Of Manufacture :	2017		
Original Registration Date :	18 Aug 2017		
Lifespan Expiry Date :	-		
COE Category :	B - Car above 1600cc or 97kW (130bhp)		
Quota Premium :	\$50,001.00		
COE Expiry Date :	17 Aug 2027		
Road Tax Expiry Date :	17 Aug 2018		
PARF Eligibility Expiry Date :	17 Aug 2027		
Inspection Due Date :	17 Aug 2020		
Intended Transfer Date :	03 Aug 2018		
CO2 Emission :	182.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 17 Aug 2018. You may renew the road tax from 18 May 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 17 Aug 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 18 Aug 2018 to 17 Feb 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	606.00	-	606.00
Total Amount Payable :			631.00
Amount Payable (From 18 Aug 2018 to 17 Aug 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	1,212.00	-	1,212.00
Total Amount Payable :			1,237.00

You may print this page for reference.

OK

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	6234J
Vehicle Details	
Vehicle No.:	SLR5283E
Vehicle to be Exported:	No
Intended De-registration Date:	06 Aug 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	TL TUCSON 2.0 GLS AT 2WD
Primary Colour:	Brown
Manufacturing Year:	2017
Engine No.:	G4NAHU466891
Chassis No.:	KMHJ3813MJU560708
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	\$18,161.00
Original Registration Date:	18 Aug 2017
First Registration Date:	18 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$18,161.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Aug 2027
PARF Rebate Amount:	\$13,620.00
Intended COE Rebate Details	
COE Expiry Date:	17 Aug 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,001.00
COE Rebate Amount:	\$45,148.00
Total Rebate Amount:	\$58,768.00

The information contained herein is correct as at 06 Aug 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/07/2018 17:51
Date Of Accident	27/07/2018 17:15
Exact Location Of Accident	AYE(CITY) NEAR EXIT 11
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR5283E
Insured/Policyholder	
Name Of Registered Owner	ALKA'S LOTUS
Co Reg No	53366234J
Email Address	GAUTAMMAHEY@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98905300
Alternative Phone No	OFFICE-62884424

Vehicle Particulars

Manufacturer	HYUNDAI
Model	TUCSON-2.0 GLS (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093304338
Cover Note Number	18/08/2017 - 17/08/2018

Driver

Name of Driver	GAUTAM MAHEY
NRIC No	S9002626G
Date Of Birth	13/01/1990
Occupation	INDOOR
Date Of Driving Pass	29/11/2008
Driving Experience	9 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98905300
Fax Number	
Contact Number	
EMail Address	GAUTAMMAHEY@HOTMAIL.COM

Address	BLK 14 JOO SENG ROAD #17-101
Postcode	360014
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SYED NASEEM GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY VEHICLE WAS DRIVING ALONG THE RIGHT LANE OF AYE(CITY) NEAR EXIT 11. TRAFFIC WAS MODERATE. VEHICLES IN FRONT OF ME STOPPED, I ALSO STOPPED. SUDDENLY, I FELT A GREAT IMPACT FROM MY VEHICLE REAR PORTION AND VEHICLE B HAD HIT ONTO MY VEHICLE. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VEHICLE OWNER WILL RETRIEVE VIA PERSONAL PC
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR1514R
Vehicle Make/Model/Colour	VW POLO
Details Of Properties	FRONT PORTION
Vehicle Category	PRIVATE CAR
Name of Driver	YIAN LI LING
NRIC/Passport Number	S8212919G
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

1

Sketch Plan Pg. 1

NTUC Income Motor Service Centre

Vehicle No:

Report Date: 7/27/2018 Start Time: 6:02 PM

Report No: MT

D.O.A:

Make / Model:

Reporting Type:

End Time:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonable required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, law or court orders.



7/27/2018 18:02

Policyholder's Signature

Date & Time:

[Signature]

7/27/2018 18:02

Driver's Signature (If driver is not the policyholder)

Date & Time:

[Signature]

Reporting Centre Personnel's Signature

Name: Chen JunLiang

NRIC/ Fin No: S990765



Sketch Plan Pg. 2

SKETCH PLAN

AYE(CITY) NEAR EXIT 11

Vehicle A: SLR5283E	Vehicle B: SLR1514R	
---------------------	---------------------	--


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


MY VEHICLE WAS DRIVING ALONG THE RIGHT LANE OF AYE(CITY) NEAR EXIT 11. TRAFFIC WAS MODERATE. VEHICLES IN FRONT OF ME STOPPED, I ALSO STOPPED. SUDDENLY, I FELT A GREAT IMPACT FROM MY VEHICLE REAR PORTION AND VEHICLE B HAD HIT ONTO MY VEHICLE. NO ONE WAS INJURED.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 7/27/2018 18:02


 Driver's Signature (If driver is not the policyholder)
 Date & Time: 7/27/2018 18:02


 Reporting Centre Personnel's Signature
 Name: Chen JunLiang
 NRIC/ FIC No: S990765

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Jul 2018		01 Aug 2018 16:05 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	YIAN LI LING, ID: S8212919G, Tel: +6598416977, Email: LILING.YIAN@GMAIL.COM	
Main Claimant:	ALKA'S LOTUS, Co. Reg. No.: 53366234J	
Vehicle Reg. No.:	SLR5283E	Date of Loss: 27/07/2018 17:00 - :59 [11 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 565888	Policy/Cover Note No.: 29000740 (Comprehensive) Coverage: 31/07/2017 - 30/07/2018
Vehicle Reg. No. (Insured):	SLR1514R	Policy No. (Claimant):
		Excess: S\$500.00
Repairer:	Groom Werkz Services (HQ) 48 SENANG CRESCENT, 416615 Chai Chee - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 02/08/2018]	
Driver/Custodian (Insured):	YIAN LI LING (36 / Female), NRIC: S8212919G, Tel: +6598416977	
Adj Asg. Remarks:	Third Pre-Repair Survey. TP reject , please assigned LKK to be SJE. Liability - 100% Contact : Mr Vincent @ 9395 4747 (To call before going)	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SLR5283E (565888)**

[SLR1514R]

TP

ALKA'S LOTUS

Jul 27 2018 5:00PM

[YIAN LI LING]



















































Groom Werkz Services

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	31/07/18 16:05	Accident Statement <small>From:OD - Reg. No: SLR1514R, Claimant: YIAN LI LING</small>	Load HTM	

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
2	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
3	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
4	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
5	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
6	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
7	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
8	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
9	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
10	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
11	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
12	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
13	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
14	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
15	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
16	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
17	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
18	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
19	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
20	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
21	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
22	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
23	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
24	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
25	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
26	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
27	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
28	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
29	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
30	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
31	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
32	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>
33	03/08/18 10:54	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
35	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
36	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
37	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
38	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
39	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
40	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
41	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
42	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
43	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
44	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
45	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
46	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
47	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
48	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
49	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
50	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
51	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
52	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
53	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
54	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
55	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
56	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
57	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
58	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
59	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
60	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
61	03/08/18 10:54	General View	 Load JPG	<input checked="" type="checkbox"/>
62	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	08/08/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
84	08/08/18 18:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
85	08/08/18 18:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
86	08/08/18 18:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
87	08/08/18 18:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
88	08/08/18 18:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
89	08/08/18 18:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
90	08/08/18 18:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
91	08/08/18 18:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
92	08/08/18 18:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
93	08/08/18 18:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
94	08/08/18 18:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
95	08/08/18 18:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
96	08/08/18 18:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
97	08/08/18 18:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
98	08/08/18 18:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
99	08/08/18 18:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
100	08/08/18 18:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
101	08/08/18 18:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
102	08/08/18 18:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	31/07/18 15:58	E-FILE REPORT (SLR5283E)		Load PDF	
2	01/08/18 10:43	REJECTION REPLY TP & WE NOMINATED LKK TO BE SJE		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18014020/T1Z4D3E2

Date: 10/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29000740

Claimant Vehicle No : SLR5283E

Insured Vehicle No : SLR1514R

Date of Loss: 27/07/2018

Nature of Claim: TP Claim No: 565888

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR5283E

Make & Model: HYUNDAI TUCSON, 2.0 GLS (A)

Engine No: G4NAHU466891

Reg. Date: 18/08/2017 (Man. Year: 2017)

Chassis No: KMHJ3813MJU560708

Colour: Bronze

Odometer: 20396 km

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/60 R17

Rear Tyre Size: 225/60 R17

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 01/08/2018

Date Inspected: 02/08/2018 Inspected At: Groom Werkz Services (HQ)
48 SENANG CRESCENT
Singapore 416615

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Aug 2018)

Parts: M1-SUV HYUNDAI TUCSON 2.0 GLS (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLR5283E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >