

22/03/2001

ASS. REC. BY:

REF:

CSMSG18014042/ Ncd302

Special Instruction:

Survivor  
menmen

Naz

ASSIGNMENT (Office)

From (Person):

Muhd Ashik

of

MSG

Date/Time:

1/8/18 @ 4:07pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 2473P

Insured:

SDX 9939J

at Workshop m/s

E.M. Solution

Tel:

6456 0226

of

160 Sin Ming Drive # 03-18

Policy No:

B298 2617 DMV

Claim No:

566095

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31/07/2018

CA / REV / REP. / REV 24 HRS lup

H.O.D. Endorsement:

Date/Time:

11:04am @ 2/8/18

Person Contacted:

Josephine

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

GBH 2473P-X

SDX 9939J - CC3/AIG/2018G21/RSC4392

DOA: 21/09/2012

13/8/18 @ 3:34pm Informed Ashik, we are pending estimate from repairer.

Dismantle: 3/8/2018.

After repair: 6/8/2018

108.11.10

Surveyor

NAR

REF:

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: GBH 243P Yr Regn: 23 MAR 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA DYNA c.c. 2,982

Colour: SILVER A/C: Insured / Std / NI / NA

Sp. Reading: 11271 T/Radio: Insured / Std / NI / NA

Eng/No: FOA

C/No: JTFAT35Y60K210027

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 / 75 R15

R: 155 / R12 - C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 5 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 31/7/18 D.O.I. 2/8/18

Survey held at EMZ

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time \_\_\_\_\_ Action / Instruction \_\_\_\_\_

Estimated repair range \$4,000 - \$5,000

RECEIVED 27 NOV 2018

23/11/2018

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_) ) S + RS. SI

☐ : Interview (\$ \_\_\_\_\_) ) Photos

☐ : Tech. Invs (\$ \_\_\_\_\_) ) Others

☐ : Weekend (\$ \_\_\_\_\_) )

Report Format : PRG

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

TOTAL

120
10
130



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18014042/Nsd3

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 02-08-2018



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDX 9939J	Veh. Inspected	GBH 2473P
Policy No.	B2982617QMY	Coverage (\$)	0.00
Claim No.	566095	Excess (\$)	0.00
Assign From	MERIMEN (MUHD ASHIK)	Assign Date	02/08/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	31/07/2018	Inspection Date	02/08/2018
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Jul 2018		01 Aug 2018 16:07 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>			<b>[Created by insurer]</b>						
Insured:	<b>LAWRENCE LEE</b> , ID: S2199149Z								
Main Claimant:	<b>TT GLASS PTE LTD</b> , Co. Reg. No.: 201506192K								
Vehicle Reg. No.:	<b>GBH2473P</b>	Date of Loss:	31/07/2018 10:00 - :59 [4 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 566095</b>	Policy/Cover Note No.:	B2982617QMY (Comprehensive) Coverage: 11/06/2018 - 10/06/2019						
Vehicle Reg. No. (Insured):	<b>SDX9939J</b>	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	<b>E M Solution Pte Ltd (HQ)</b> 160 Sin Ming Drive,, #03-18, Sin Ming Autocity, 575722 Sin Ming - Tel: 64560226								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Muhd Ashik B Madi</b> - 6594 2548]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Imm.Advice due 02/08/2018]</b>								
Driver/Custodian (Insured):	LAWRENCE LEE (), NRIC: S2199149Z								
Adj Asg. Remarks:	Liability 100%, SJE disagree - assign LKK, Contact : Mr Bernard at 6456 0226 or HP 9101 8302								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## View Sent Message

This mail is associated with :

**\*GBH2473P (566095)**  
**[SDX9939J]**

TP

TT GLASS PTE LTD  
Jul 31 2018 10:00AM  
[LAWRENCE LEE]  
E M Solution Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on **03/08/2018 15:34 PM.**  
**To** MSI\_ASHIK  
**CC** sur@lkkauto.com  
**Subject** **VEHICLE GBH 2473P (YOUR REF: 566095)**

Dear Muhd Ashik,

Please be informed that we have inspected the vehicle GBH 2473P on 02/08/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan on behalf of Shirley  
LKK Auto Consultants Pte Ltd  
Tel: 6256 3561

### DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	6192K
<b>Vehicle Details</b>	
Vehicle No.:	GBH2473P
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1KD2790638
Chassis No.:	JTFAT35Y60K210027
Maximum Power Output:	-
Open Market Value:	\$27,084.00
Original Registration Date:	23 Mar 2018
First Registration Date:	23 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$1,355.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	22 Mar 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$34,730.00
COE Rebate Amount:	\$32,390.00
<b>Total Rebate Amount:</b>	<b>\$32,390.00</b>

The information contained herein is correct as at 23 Nov 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	31/07/2018 11:17
Date Of Accident	31/07/2018 10:45
Exact Location Of Accident	ANG MO KIO AVE 5 EXIT CTE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH2473P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TT GLASS PTE LTD
Co Reg No	201506192K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98287754

### Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150 5MT
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE

Are you claiming under your own insurance policy for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	M496583 (COMP)
Cover Note Number	

### Driver

Name of Driver	LIANG CHEONG HUAT
Passport No/FIN	G8004603R
Date Of Birth	26/08/1987
Occupation	OUTDOOR
Date Of Driving Pass	20/11/2007
Driving Experience	10 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	MOBILE +65-8878 7754
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	8 KAKI BUKIT AVE 4 #02-12 PREMIER @ KAKI BUKIT
Postcode	415875
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : TAN YOU YIK GENDER: : MALE
Passenger 2	NAME: : TAN CHEE KAR GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS DRIVING AT THE FILTER LANE FROM ANG MO KIO AVE 5 INTO CTE. IN FRONT VEHICLE BRAKED AND STOPPED. I ALSO BRAKED AND STOPPED. THEN SUDDENLY A CAR(SDX9939J) CAME FROM BEHIND, HIT ONTO THE REAR OF MY LORRY.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDX9939J
Vehicle Make/Model/Colour	MERCEDES BENZ CLA180
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	



Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN



IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for use in litigation with the Insurers and/or any applicable insurance contract and/or



IDAC KAKI BUKIT (VAC)  
23 Kaki Bukit Ave 4  
Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: yakb5@singnet.com.sg

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Jul 2018		01 Aug 2018 16:07 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:	LAWRENCE LEE, ID: S2199149Z		
Main Claimant:	TT GLASS PTE LTD, Co. Reg. No.: 201506192K		
Vehicle Reg. No.:	GBH2473P	Date of Loss:	31/07/2018 10:00 - :59 [4 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 566095	Policy/Cover Note No.:	B2982617QMY (Comprehensive) Coverage: 11/06/2018 - 10/06/2019
Vehicle Reg. No. (Insured):	SDX9939J	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	E M Solution Pte Ltd (HQ) 160 Sin Ming Drive,, #03-18, Sin Ming Autocity, 575722 Sin Ming - Tel: 64560226		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by <b>Muhd Ashik B Madi</b> - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Imm.Advice due 02/08/2018]		
Driver/Custodian (Insured):	LAWRENCE LEE (), NRIC: S2199149Z		
Adj Asg. Remarks:	Liability 100%, SJE disagree - assign LKK, Contact : Mr Bernard at 6456 0226 or HP 9101 8302		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.



















**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GBH2473P (566095)  
[SDX9939J]  
TP  
TT GLASS PTE LTD  
Jul 31 2018 10:00AM  
[LAWRENCE LEE]  
E M Solution Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser		<input checked="" type="checkbox"/>
Assessment Reports								1 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	01/08/18 17:53	Accident Statement From:OD - Reg. No: SDX9939J, Claimant: LAWRENCE LEE							Load HTM		
Photos/Images								3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	04/08/18 00:53	General View							Load JPG	<input checked="" type="checkbox"/>	
2	04/08/18 00:53	General View							Load JPG	<input checked="" type="checkbox"/>	
3	04/08/18 00:53	General View							Load JPG	<input checked="" type="checkbox"/>	
4	04/08/18 00:53	General View							Load JPG	<input checked="" type="checkbox"/>	
5	04/08/18 00:53	General View							Load JPG	<input checked="" type="checkbox"/>	
6	04/08/18 00:53	General View							Load JPG	<input checked="" type="checkbox"/>	
7	04/08/18 00:53	General View							Load JPG	<input checked="" type="checkbox"/>	
8	04/08/18 00:53	General View							Load JPG	<input checked="" type="checkbox"/>	
9	04/08/18 00:53	General View							Load JPG	<input checked="" type="checkbox"/>	
10	04/08/18 00:53	General View							Load JPG	<input checked="" type="checkbox"/>	
11	04/08/18 00:53	General View							Load JPG	<input checked="" type="checkbox"/>	
12	04/08/18 00:53	General View							Load JPG	<input checked="" type="checkbox"/>	
13	04/08/18 00:53	General View							Load JPG	<input checked="" type="checkbox"/>	
14	04/08/18 00:53	General View							Load JPG	<input checked="" type="checkbox"/>	
15	04/08/18 00:53	General View							Load JPG	<input checked="" type="checkbox"/>	
16	04/08/18 00:53	General View							Load JPG	<input checked="" type="checkbox"/>	
17	04/08/18 00:53	General View							Load JPG	<input checked="" type="checkbox"/>	
18	04/08/18 00:53	General View							Load JPG	<input checked="" type="checkbox"/>	
19	04/08/18 00:53	General View							Load JPG	<input checked="" type="checkbox"/>	
20	04/08/18 00:53	General View							Load JPG	<input checked="" type="checkbox"/>	
21	04/08/18 00:54	General View							Load JPG	<input checked="" type="checkbox"/>	
22	04/08/18 00:54	General View							Load JPG	<input checked="" type="checkbox"/>	
23	04/08/18 00:54	General View							Load JPG	<input checked="" type="checkbox"/>	
24	04/08/18 00:54	General View							Load JPG	<input checked="" type="checkbox"/>	
25	04/08/18 00:54	General View							Load JPG	<input checked="" type="checkbox"/>	
26	04/08/18 00:54	General View							Load JPG	<input checked="" type="checkbox"/>	
27	04/08/18 00:54	General View							Load JPG	<input checked="" type="checkbox"/>	
28	04/08/18 00:54	General View							Load JPG	<input checked="" type="checkbox"/>	
29	04/08/18 00:54	General View							Load JPG	<input checked="" type="checkbox"/>	
30	04/08/18 00:54	General View							Load JPG	<input checked="" type="checkbox"/>	
31	04/08/18 00:54	General View							Load JPG	<input checked="" type="checkbox"/>	
32	04/08/18 00:54	General View							Load JPG	<input checked="" type="checkbox"/>	
33	04/08/18 00:54	General View							Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	04/08/18 00:54	General View	 Load JPG	<input checked="" type="checkbox"/>
35	04/08/18 00:54	General View	 Load JPG	<input checked="" type="checkbox"/>
36	04/08/18 00:54	General View	 Load JPG	<input checked="" type="checkbox"/>
37	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	23/11/18 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	23/11/18 14:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	23/11/18 14:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	23/11/18 14:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	23/11/18 14:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	23/11/18 14:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	23/11/18 14:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	23/11/18 14:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	23/11/18 14:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	23/11/18 14:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	23/11/18 14:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	23/11/18 14:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	23/11/18 14:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	23/11/18 14:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	23/11/18 14:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	23/11/18 14:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	23/11/18 14:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	23/11/18 14:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	01/08/18 14:20	PRI from Vision Law LLC		Load PDF	
2	01/08/18 14:20	GBH2473P E-FILE REPORT		Load PDF	
3	01/08/18 14:20	Survey Disagree on SJE - assign LKK		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18014042/NCD3E2

Date: 29/11/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B2982617QMY

Claimant Vehicle No : GBH2473P

Insured Vehicle No : SDX9939J

Date of Loss: 31/07/2018

Nature of Claim: TP

Claim No: 566095

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: GBH2473P

Make &amp; Model: TOYOTA DYNA 150, 3.0 D 5MT (M)

Engine No: 1KD2790638

Reg. Date: 23/03/2018 (Man. Year: 2018)

Chassis No: JTFAT35Y60K210027

Colour: Silver

Odometer: 11271 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/75 R15

Rear Tyre Size: 155 R12C

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 01/08/2018

Date Inspected: 02/08/2018 Inspected At:

E M Solution Pte Ltd (HQ)  
160 Sin Ming Drive,, #03-18, Sin Ming  
Autocity  
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 29 Nov 2018)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBH2473P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >