

22/03/2002

SS. REC. BY:

REF:

CS/CY18014045/Tind3

Special Instruction:

Survivor:
Mennen

Taurich

ASSIGNMENT (Office)

From (Person):

Hung Shiang Yi

of

CTE

Date/Time:

1/8/18 04:26pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SLZ 828A

Insured:

SJS 97 822

at Workshop m/s

Borneo Motor

Tel:

6631 1860 / 9847 6171

of

2pendin Crescent Level 4

Policy No:

DMHCSN/16 847 51801

Claim No:

SNM18D03676C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/07/2018

CA / REV / REP. / REV 24 HRS

Cup

16-08-2018 @ after 10am

H.O.D. Endorsement:

Date/Time:

5:48pm 1/8/18

Person Contacted:

thomas

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

No caller called (3x)

SLZ 828A-X

SJS 97 822-X

7/9/18

Final fig \$ 2654.01 confirmed by email (Ref 1675-40, 38/1)

(08/11/13) wef

ASS. REC. BY: Tanjit

REF: CTI

ASSIGNMENT

From: _____ Date: 16/8/18

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MVTo Inspect Vehicle No: SLZ 828Aat Workshop m/s Borneo Motorof 2 penden Crescent level 4

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

after 10amMake of Veh: thomas

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLZ 828AYr Regn: 2018 JuneType: ☒ Car ☐ M.Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover ☐

Truck / Trailer or

Make: Toyotac.c. 1598Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 4085

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR 0331REH 604584004Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 2.5/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 16/8/18 @ 1550Survey held at Borneo PendaDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 07 SEP 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

2/9 - typistReport Format: merimenLump Sum / I.B.I: (\$) 2654.01Days Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

____ \$ + RS ____ \$

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18014045/T1vd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 02-08-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJS 9782Z	Veh. Inspected	SLZ 828A
Policy No.	DMHCSN1684751801	Coverage (\$)	0.00
Claim No.	SNM18D03676C02	Excess (\$)	0.00
Assign From	MERIMEN (HWANG SHIANG YI)	Assign Date	02/08/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	26/07/2018	Inspection Date	16/08/2018
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Aug 2018		01 Aug 2018 16:26 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	GOH SEW LAN, ID: S1379458H		
Vehicle Reg. No.:	SLZ828A	Date of Loss:	26/07/2018 11:00 - :59
Claim Type:	TP / SNM18D03676C02	Policy/Cover Note No.:	DMHCSN1684751801
Vehicle Reg. No. (Insured):	SJS9782Z	Policy No. (Claimant):	P2143808
		Excess:	S\$0.00
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Hwang Shiang Yi - 63896541]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/08/2018]		
Adj Asg. Remarks:	EST \$4632.47, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/07/2018 09:54
Date Of Accident	26/07/2018 11:00
Exact Location Of Accident	HAVELOCK ROAD INFRONT MINISTRY OF MANPOWER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ828A
Insured/Policyholder	
Name Of Registered Owner	GOH SEW LAN
NRIC No	S1379458H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98391857
Alternative Phone No	OTHERS-98391857
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA ALTIS ELEGANCE AUTO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P2143808
Cover Note Number	
Driver	
Name of Driver	WONG XIAN JIE DOMINIC
NRIC No	S8722798G
Date Of Birth	05/08/1987
Occupation	INDOOR
Date Of Driving Pass	14/01/2006
Driving Experience	12 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81283168
Fax Number	
Contact Number	
Email Address	DOMINICWONG1987@GMAIL.COM

Address	BLK 642 CHOA CHU KANG ST 64 #09-67
Postcode	680642
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : WONG LEAH KEONG GENDER: : MALE
Passenger 2	NAME: : GOH SEW LAN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

KINDLY REFER TO ATTACH POLICE REPORT NO.T/20180726/2162.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJS9782Z
Vehicle Make/Model/Colour	OPEL ASTRA (SILVER)
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TALITHA RAGHUNATHAN
NRIC/Passport Number	S8626662H
Contact Number	97353488 (OWNER)
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	GOH SEW LAN
Approximate Age	
Injuries Sustain	3 DAYS MC
Injured person in which vehicle?	SLZ828A
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	WONG XIAN JIE DOMINIC
Approximate Age	
Injuries Sustain	3 DAYS MC
Injured person in which vehicle?	SLZ828A
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 3

Name	WONG LEAH KEONG
Approximate Age	
Injuries Sustain	5 DAYS MC
Injured person in which vehicle?	SLZ828A
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 28/7/18

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

SKETCH PLAN

Hand-drawn sketch plan on a grid background. It shows a road layout with arrows indicating traffic flow. A vertical line is labeled "Haverlock Road". Two vehicles are marked: (A) SLZ 828A and (B) SJS 9782Z.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACH POLICE REPORT.

Important:


You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a **FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE** within the stipulated time frame from the day of the occurrence.

- | | |
|-------------------------------------|----------------------------------|
| <input type="checkbox"/> | - Reporting Only |
| <input type="checkbox"/> | - Claim OD |
| <input type="checkbox"/> | - Claim TP |
| <input checked="" type="checkbox"/> | - Claim OD/ TP at other workshop |

DECLARATION

I/WE declare the foregoing particulars are true in every respect.


 Policyholder's signature
 Date & Time


 28/7/18
 Driver's Signature
 (if driver not the policyholder)
 Date & Time


 Reporting Centre Personnel's Signature
 Name:
 Nric/Fin No.

INTERNAL INVOICE

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

New vehicle preparation PDI
***** For use by SMS PDI *****

10100001/NEWVEHIC

38025398

Mdm SL Goh
642 Choa Chua Kang Street 64
#09-67
Singapore 680642

04/07/2018

18	GEXGP2 S2	IRE171R 26/06/2018	SLZ0828A	1	32841	69INT/SLZ0828A
MR053REH604584044 12R0B72491 00 Raymond Seah L M --/--/---- 0.00 --/--/---- 0.00						

M D1068*-PLATINUM SHINEPRO
1 * PSEPRO PDI LABOUR FOR PLATINUM SHINE PDI
D1068D) Platinum Shine Glass Coating
1 * PSEPRO MAT PDI PLATINUM SHINE SET

0.00	GST: 0.00%	0.00
0.00		
0.00		0.00
0.00		

04/07/2018
09:54

SLZ0828A



SINGAPORE POLICE FORCE



T/20180726/2162

1 of 4

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

Report No. T/20180726/2162

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/07/2018 20:50	Vide Report No.:	Station Diary No.: 131
--	------------------	---------------------------

Informant's Particulars

Name of Informant: WONG XIAN JIE DOMINIC			Address: APT BLK 642 CHOA CHU KANG STREET 64 #09-67 SINGAPORE 680642		
ID Type / ID No.: NRIC NO / S8722798G			Contact No.: Home/Office: Mobile: 81283168		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 30	Date of Birth: 05/08/1987	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: LOGISTICS OPERATION			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 26/07/2018 11:00	Type of Location: Straight Road
Location: HAVELOCK ROAD AT TRAFFIC LIGHT IN FRONT OF MINISTRY OF MANPOWER				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJS9782Z	Car	OPEL	ASTRA	Silver	Slightly Damaged	1
SLZ828A	Car	TOYOTA	COROLLA	Silver	Slightly Damaged	3

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



SINGAPORE POLICE FORCE



T/20180726/2162

2 of 4

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

Report No. T/20180726/2162

CONTINUATION OF REPORT

Passenger			
Name	GOH SEW LAN	ID No.	S1379458H
Related Vehicle	SLZ828A (Car)	Contact No.	98391857
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	26/07/2018	Date Discharge	26/07/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	WONG XIAN JIE DOMINIC	ID No.	S8722798G
Related Vehicle	SLZ828A (Car)	Contact No.	81283168
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	26/07/2018	Date Discharge	26/07/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Passenger			
Name	WONG LEAH KEONG	ID No.	S1323345D
Related Vehicle	SLZ828A (Car)	Contact No.	96509878
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	26/07/2018	Date Discharge	26/07/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On the above mentioned date and time, I was travelling along the above mentioned location when I stopped at the traffic light in lane 3. I was the driver, my mother was sitting in the passenger seat while my father was sitting behind the driver's seat. The traffic light was still red when suddenly another vehicle, A Silver Opel, SJS 9782Z, hit onto the rear of my vehicle. I alighted the vehicle to assess the damage however my parents stayed in the car as they were in a state of shock. I met up with the other driver namely, Talitha Raghunathan NRIC S8626662H and she apologized for the accident. I managed to take some pictures of the damages for both vehicles. My vehicle had some damage on the rear bumper while the other vehicle had damage at its front bumper. The other driver informed me stating that the vehicle she was driving was a rental car and she handed me a contact number of a person from the rental company namely, Harry HP: 97353488. No Traffic Police or ambulance were at scene. We then drove off as we did not want to hog traffic.



**SINGAPORE
POLICE FORCE**



T/20180726/2162

3 of 4

Report No. T/20180726/2162

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

CONTINUATION OF REPORT

Both my parents and I then proceeded to Tan Tock Seng Hospital where my father was issued with 5 days MC while my mother and I were issued with 3 days MC each.

Hence, I am lodging this report for insurance purposes.



**SINGAPORE
POLICE FORCE**



T/20180726/2162

4 of 4

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

Report No. T/20180726/2162

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.



Signature Of Officer Recording The Report:

Signature: **SAIFUDDIN HAMMAD KHAILIL RIFDI BIN JEFFRY**

Signature Of Interpreter:

Signature: **Singapore Police Force**

Officer In Charge Of Case:
TP / GIA /
Staff Sgt WONG SIEU LUI
Contact No.: 65476151

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:

26/07/2018 20:50

Classification Of Case:



Co.Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631-1188

Account Detail		Account No	Customer Detail
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Mdm Goh Sew Lan 642 Choa Chua Kang Street 64 #09-67 Singapore 680642 Mobile: 96059878
		Document No	
		0	
		Document Date	
		30/07/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	GEXGPZ	S2	26/06/2018	SLZ0828A	966	33777	72/DS/SLZ0828A
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH604584044	1ZROB72491	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: <i>TP VEH: SJS 97822</i> <i>DATE OF ACC: 26.07.2018</i>				✓ 50 100.00
2	B	BP-LAB CHECK WIRING AND CONDUCT WATER TEST (NET T)				✓ 104.72
3	B	BP-LAB DRILL HOLE AND INSTALL REVERSE SENSOR (N ETT)				✓ 154.00
4	B	BP-ECU TO RESET ECU AND REPROGRAMME (NETT)				✓ 154.00
5	B	BP-LAB REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				✓ 616 1232.00
6	B	BP-RES RESPRAY ACC AFFECTED AREAS				✓ 506 1012.00
7	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION (REAR BUMPER)				✓ 91.59
8	1	SP2061-12028 17 1D4 SILVER METALLIC REVERSE SE	1.00	155.20		un X 155.20
9	2	S52159-0Z904 COVER, RR BUMPER	1.00	546.10		de- 546.10
10	3	S52161-OK040 PIECE, RR BUMPER	10.00	4.00		un 40.00
11	4	S52575-02140 RETAINER, RR BUMPER R	1.00	107.20		un X 107.20
12	5	S52576-02140 RETAINER, RR BUMPER L	1.00	107.20		un X 107.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
Please acknowledge receipt of vehicle		Parts	<p>16/8/18 @ 1350</p> <p>Resurvey before paint</p> <p>05 days</p> <p>sur@borneomotors.com</p>
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	Amount Due

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TO SECURITY GUARD

PLEASE ALLOW THE UNMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES

Acknowledged by Repairer

DATE 30/07/2018

TIME 14:32

3722912

3722912

VEHICLE NO SLZ0828A

CUSTOMER

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotaasingsapore.com.sgToyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188Co.Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail		Account No		Customer Detail				
THIRD PARTY CLAIM		S1000020 / TPCLAIM		Mdm Goh Sew Lan 642 Choa Chua Kang Street 64 #09-67 Singapore 680642 Mobile: 96059878				
		Document No						
		0						
		Document Date						
		30/07/2018						
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks	
18	GEXGPZ	S2	ZRE171R 26/06/2018	SLZ0828A	966	33777	72/DS/SLZ0828A	
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On		
MRO53REH604584044	1ZROB72491	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
13	6	S52023-02190 REINFORCEMENT, RR			1.00	391.60		h/m 391.60 ✓
14	7	S52181-02190 ARM, RR BUMPER RH			1.00	66.90		unq 66.90 X
15	8	S52182-02160 ARM, RR BUMPER LH			1.00	66.90		unq 66.90 X
<p>Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.</p>								
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total		
		Please acknowledge receipt of vehicle		Parts	1,481.10	GST 7.00%	4,329.41	
				Labour	2,756.72		303.06	
				Materials	91.59	Less	0.00	
				Lubrication/Fluid	0.00			
				Others	0.00			
						Amount Due	4,632.47	

PLEASE TEAR ALONG PERFORATED LINE

3722913

3722913

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 30/07/2018
TIME 14:32

VEHICLE NO SLZ0828A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462

Tel No.: 6631 1188

ESTIMATE

Account Detail		Account No	Customer Detail	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mdm Goh Sew Lan 642 Choa Chua Kang Street 64 #09-67 Singapore 680642 Mobile: 96059878	
		Document No		
		0		
		Document Date		
		18/08/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	GEXGPZ	S2	ZRE171R	26/06/2018	SLZ0828A	966	33777 72/DS/SLZ0828A
Chassis No		Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
MR053REH604584044		1ZROB72491	60	Thomas Pang W T	16/08/2018	8.00	18/08/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: CHINA TAIPING TP VEH: SJS 9782Z DATE OF ACC: 26.07.2018 BY:LKK-TAUFIKH @ 16.08.2018 03 WORKING DAYS				50.00
2	B	BP-LAB CHECK WIRING AND CONDUCT WATER TEST (NET 21 T)				104.72
3	B	BP-LAB DRILL HOLE AND INSTALL REVERSE SENSOR (N 21 ETT)				154.00
4	B	BP-ECU TO RESET ECU AND REPROGRAMME (NETT)	18			154.00
5	B	BP-LAB REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS	21			616.00
6	B	BP-RES RESPRAY ACC AFFECTED AREAS	*			506.00
7	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION (REAR BUMPER) PO:18049	164			91.59
8	1	S52159-0Z904 COVER, RR BUMPER	1.00	546.10		546.10
9	2	S52161-OK040 PIECE, RR BUMPER	10.00	4.00		40.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3748273

3748273

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 18/08/2018
TIME 10:21

VEHICLE NO
SLZ0828A

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631-1188

ESTIMATE

Account Detail		Account No	Customer Detail	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mdm Goh Sew Lan 642 Choa Chua Kang Street 64 #09-67 Singapore 680642 Mobile: 96059878	
Document No		0		
Document Date		18/08/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	GEXGPZ S2	ZRE171R	26/06/2018	SLZ0828A	966	33777	72/DS/SLZ0828A
Chassis No		Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
MR053REH604584044		1ZROB72491	60	Thomas Pang W T	16/08/2018 8.00	18/08/2018 18.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	3	S52023-02190 REINFORCEMENT, RR	1.00	391.60		391.60

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	
	Please acknowledge receipt of vehicle	Parts	2,654.01	
		Labour 977.70	GST 7.00%	185.78
		Materials 1,584.72	Less	0.00
		Lubrication/Fluid 91.59		
		Others 0.00		
		0.00	Amount Due	2,839.79

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO

SLZ0828A

CUSTOMER

DATE 18/08/2018
TIME 10:21

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

3748274

3748274

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 7 September 2018 11:53 AM
To: 'Thomas Pang PTCBC'; Taufikh (LKKAUTO)
Cc: SUR; Admin A
Subject: RE: finalize report for SLZ 828A

Dear Thomas,

WITHOUT PREJUDICE

Confirm amount \$2654.01 before GST @ 3 working days.

Kindly send Final invoice and all supporting documents to CHINA TAIPING INSURANCE

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Thomas Pang PTCBC <Thomas.Pang@borneomotors.com.sg>
Sent: Thursday, 6 September 2018 10:42 AM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: finalize report for SLZ 828A

Dear Taufikh,

Attach finalize report for your perusal. 03 WORKING DAYS

Thank you

Regards

Thomas
Borneo Motors
DID:6631 1860 FAX:6773 3094

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Aug 2018		01 Aug 2018 16:26 Edit Adj Rpt	S\$2,654.01 Edit Estimates	S\$2,654.01 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	- ID: -								
Main Claimant:	GOH SEW LAN , ID: S1379458H								
Vehicle Reg. No.:	SLZ828A	Date of Loss:	26/07/2018 11:00 - :59 [1 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03676C02	Policy/Cover Note No.:	DMHCSN1684751801						
Vehicle Reg. No. (Insured):	SJS9782Z	Policy No. (Claimant):	P2143808						
		Excess:	S\$0.00						
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Hwang Shiang Yi - 63896541]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/08/2018]								
Adj Asg. Remarks:	EST \$4632.47, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLZ828A (SNM18D03676C02)
[SJS9782Z]
TP
GOH SEW LAN
Jul 26 2018 11:00AM
[-]
Borneo Motors (S) Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Video								1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)							Thumbnail	Print	
1	28/07/18 11:48	Video - Accident [Linked Accident Report Documents]							Load MP4		
Assessment Reports								1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)							Thumbnail	Print	
1	28/07/18 11:52	Accident Statement							Load HTM		
Photos/Images								3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)							Thumbnail	Print	
1	28/07/18 10:16	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
2	28/07/18 10:16	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
3	28/07/18 10:16	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
4	28/07/18 10:16	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
5	28/07/18 10:16	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
6	28/07/18 10:16	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
7	28/07/18 10:16	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
8	28/07/18 10:16	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
9	28/07/18 10:16	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
10	28/07/18 10:16	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
11	28/07/18 10:16	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
12	28/07/18 10:16	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
13	28/07/18 10:19	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
14	28/07/18 10:19	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
15	28/07/18 10:19	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
16	28/07/18 10:19	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
17	28/07/18 10:19	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
18	28/07/18 10:19	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
19	28/07/18 10:19	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
20	28/07/18 10:19	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
21	28/07/18 10:19	Driving License/Nric [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
22	28/07/18 10:19	Identification Card//Nric [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/09/18 11:35	General View	Load PDF	
2	07/09/18 11:35	Reinspection Photo	Load PDF	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	28/07/18 10:52	Sketch Plan <small>[Linked Accident Report Documents]</small>	Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/08/18 16:25	EMAIL FM BORNEO	Load PDF	
2	01/08/18 16:25	REPAIR EST	Load PDF	
3	01/08/18 16:25	TP GIA	Load PDF	
4	01/08/18 16:26	OI GIA	Load PDF	

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	28/07/18 11:48	Video - Accident	Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	28/07/18 11:52	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	28/07/18 10:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	28/07/18 10:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	28/07/18 10:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	28/07/18 10:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	28/07/18 10:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	28/07/18 10:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	28/07/18 10:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	28/07/18 10:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	28/07/18 10:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	28/07/18 10:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	28/07/18 10:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	28/07/18 10:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	28/07/18 10:19	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	28/07/18 10:19	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	28/07/18 10:19	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
16	28/07/18 10:19	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
17	28/07/18 10:19	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
18	28/07/18 10:19	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
19	28/07/18 10:19	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
20	28/07/18 10:19	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
21	28/07/18 10:19	Driving License/Nric	Load JPG	<input checked="" type="checkbox"/>
22	28/07/18 10:19	Identification Card//Nric	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	28/07/18 10:52	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118014045/T1VD3Q2

Date: 10/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSN1684751801

Claimant Vehicle
No: SLZ828AInsured Vehicle
No: SJS9782Z

Date of Loss: 26/07/2018

Nature of Claim: TP

Claim
No: SNM18D03676C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLZ828A

Make & Model: TOYOTA COROLLA ALTIS, 1.6 Elegance (A)

Reg. Date: 26/06/2018 (Man. Year: 2018)

Colour: Silver

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 1ZR0B72491

Chassis No: MR053REH604584044

Odometer: 4085 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Front Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Tyre Size: 215/45 R17

Rear Left Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,581.10	1,027.70	553.40	35.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,748.31	1,626.31	1,122.00	40.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,329.41	2,654.01	1,675.40	38.70
+ GST 7.00/7.00% (S\$)	303.06	185.78	117.28	38.70
Nett Amount (S\$)	4,632.47	2,839.79	1,792.68	38.70

INSPECTION

Date of Assignment: 01/08/2018

Date Inspected: 16/08/2018 Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Sep 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 Elegance (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ828A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	100.00 FS	*50.00 FS
2	1		*1D4 SILVER METALLIC REVERSE SE	Not Necessary	155.20 FS	*- FS
3	1		*COVER ,RR BUMPER	Deformed	546.10 FS	*546.10 FS
4	10		*PIECE ,RR BUMPER	Deformed	40.00 FS	*40.00 FS
5	1		*RETAINER ,RR BUMPER R	Not Necessary	107.20 FS	*- FS
6	1		*RETAINER ,RR BUMPER L	Not Necessary	107.20 FS	*- FS
7	1		*REINFORCEMENT ,RR	Bent	391.60 FS	*391.60 FS
8	1		*ARM ,RR BUMPER RH	Not Necessary	66.90 FS	*- FS
9	1		*ARM ,RR BUMPER LH	Not Necessary	66.90 FS	*- FS
Total Parts (\$\$)					1,581.10	1,027.70

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND CONDUCT WATER TEST	New	104.72	104.72
2	DRILL HOLE AND INSTALL REVERSE SENSOR	New	154.00	154.00
3	TO RESET ECU AND REPROGRAMME	New	154.00	154.00
4	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN /REALIGN ACC AFFECTED AREAS	New	1,232.00	616.00
5	RESPRAY ACC AFFECTED AREAS	New	1,012.00	506.00
6	LABOUR FOR FLATINUM SHINEPRO & SHINE PER PANEL APPLICATION (REAR BUMPER)	New	91.59	91.59
Gross Labour Cost (S\$)			2,748.31	1,626.31

Report was unsubmitted during this print-out.

< END OF ESTIMATES >