

ASS. REC. BY:

REF CS3/CTI18014046/NZ40302

Special Instructions:

Surveyor:
Munier

Naz

ASSIGNMENT (Office)

From (Person):

Irene Iy

of

CTI

Date/Time:

1/8/18 @ 4:54pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8J 4041 J

Insured:

SLT 4746H

at Workshop take:

8 peragon

Tel:

9794 6477

of

7 woodlands Ave 10# 01-10

Policy No:

DMPCSN 3009131800

Claim No:

SNM18D03732C02

Sum Insured:

Excess:

Make of Velt:

(Client's Record)

D.O.A

30/07/2018

CA / REV / REP. / REV 24 HRS

hp)

Date/Time:

10:26am 02/8/18

Person Contacted:

Edward

H.O.D. Endorsement:

Vehicle:

IN/OUT

Date/Time

Action/Instruction

(X) Estimate

8J 4041 J - X

SLT 4746H - X

REF:

Surveys N92

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 15 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJT 4041J Yr Regn: SEP 2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA STREAM c.c. 1700Colour: RED A/C: Insured Std / NI / NASp. Reading: 300, 340 T/Radio: Insured Std / NI / NA

Eng/No: _____

C/No: DBA - RN6

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45 R17R: 11BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 21/8/18Survey held at 8 PARAGON

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FRONT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated repair range \$15,000 - \$19,000

29/8/2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report1) _____
Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: 160

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) \$ + RS. \$ _____☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

TOTAL

160

Report Format : _____

Lump Sum / I.B.I. (\$) _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Jul 2018		01 Aug 2018 16:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	THAM KEANG YEN, ID: 57211982G			
Main Claimant:	AZWIN ISKANDAR HAIROH			
Vehicle Reg. No.:	SJJ4041J	Date of Loss:	30/07/2018 17:00 - :59	
Claim Type:	TP / SNM18D03732C02	Policy/Cover Note No.:	DMPCSN3009131800 (Comprehensive)	
Vehicle Reg. No. (Insured):	SLT4746H	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	8 Paragon Pte Ltd (HQ) 71 WOODLANDS AVE 10 #01-10 WOODLANDS INDUSTRIAL XCHANGE, 737743 Woodlands - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/08/2018]			
Adj Asg. Remarks:	NO EST, CASE W/O SJE.			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN201330709H

ARULCHELVAN S • A. RAVIDASS

Our ref: SJJ 4041 J (lz)

Your ref: SLT 4746 H

31 July 2018

China Taiping Insurance (Singapore) Pte Ltd
Singapore

Dear Sirs,

**NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2
WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL
FOR NIMA CASE
ACCIDENT INVOLVING MOTOR VEHICLES SJJ 4041 J AND SLT 4746 H ON 30
JULY 2018**

We act for owner of motor vehicle SJJ 4041 J which has appointed us to act on his behalf to claim against your insured's vehicle no. SLT 4746 H in regards to the road traffic accident on 30 July 2018.

Please be informed that the said motor vehicle can be inspected at:-

**8 Paragon Pte Ltd
72 Woodlands Avenue 10
#01-10 Woodlands Industrial
Singapore 737743**

Kindly contact Mr Edward at 9794 6477 to make the necessary arrangements.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



MR ARULCHELVAN S



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI18014046/Nz4d3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 02-08-2018



Code : CTI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLT 4746H	Veh. Inspected	SJJ 4041J
Policy No.	DMPCSN3009131800	Coverage (\$)	0.00
Claim No.	SNM18D03732C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	02/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	30/07/2018	Inspection Date	02/08/2018
Survey held at	-		

5a. Remarks

<p>A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.</p>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 01/08/2018 16:05
 Date Of Accident 30/07/2018 17:00
 Exact Location Of Accident CTE 300M BEFORE YIO CHU KANG EXIT
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number **SLT4746H**
Insured/Policyholder
 Name Of Registered Owner THAM KEANG YEN
 NRIC No S7211982G
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-93832330
 Alternative Phone No Office-93832330

Vehicle Particulars

Manufacturer MERCEDES-BENZ
 Model E200

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number DMPCSN3009131800
 Cover Note Number

Driver

Name of Driver THAM KEANG YEN
 NRIC No S7211982G
 Date Of Birth 03/04/1972
 Occupation OUTDOOR
 Date Of Driving Pass 14/12/1994

Driving Experience	23 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93832330
Fax Number	
Contact Number	OFFICE-93832330
Email Address	NOEMAIL
Address	BLK 55 EDGEDALE PLAINS #08-12
Postcode	828679
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	Name: : THAM HOCK ZHONG Gender: : Female
Passenger 2	Name: : LIU QINGLEI Gender: : Female
Passenger 3	Name: : GU LAY MEE Gender: : Female

Details of Police Action

Was the accident reported to the police?	YES
If Yes,Please state which Police Station	
Police Station Name	HOUGANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 60 HOUGANG AVE 9 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4890999 - FAX NO: 63128989
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

PLEASE REFER TO DOCUMENTS ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB5928K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJJ4041J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

~ send 22-03-18; 12:41 ;

RECEIVED 04/04/2018 02:24
Kok Laong

2/ 3


SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/PPN No.:

GIA/RAAC Singapore Form V1


Sketch Plan #2

send22-03-18:12:41

RECEIVED 04/04/2018 02:24
Kok Leong

3/ 3

SKETCH PLAN



① SLT 4764 H
② SHB 5928 K
③ SJI 4041 J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 30/7/2018 at 17 hrs, I was travelling along TE
Toward Woodlands. I stopped my vehicle as cars are
stopped in front. After about 3 seconds of stationary a
land bang from behind my car. Next my vehicle was hit
and skidded to right lane and was hit by a car from
behind.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

WARMC SketchPlanForm_v3

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Officer Personnel's Signature

Name:

NRIC/FIN No.:


**SINGAPORE
POLICE FORCE**


T/20180731/2014

1 of 3

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20180731/2014

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 31/07/2018 02:24	Vide Report No.: F/20180730/0178	Station Diary No.: 23
--	-------------------------------------	--------------------------

Informant's Particulars			
Name of Informant: THAM KEANG YEN		Address: APT BLK 55 EDGEDALE PLAINS #08-12 SINGAPORE 828679	
ID Type / ID No.: NRIC NO / S7211982G		Contact No.: Home/Office: Mobile: 93832330	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 46	Date of Birth: 03/04/1972	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: SELF EMPLOYED		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 30/07/2018 16:35	Type of Location: Flyover
Location: Along Road 1 CENTRAL EXPRESSWAY				
CTE(SLE) 14.7KM				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHB5928K	Car				Seriously Damaged	1
SJJ4041J	Car				Slightly Damaged	3
SLT4746H	Car	MERCEDES BENZ	E 200	Blue	Seriously Damaged	3

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20180731/2014

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

2 of 3

Report No. T/20180731/2014

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
SLT4746H	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMPCSN3009131800	30/01/2018	29/01/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	THAM KEANG YEN		ID No. S7211982G
Related Vehicle	SLT4746H (Car)		Contact No. 93832330
Hospital/Clinic	RAFFLES HOSPITAL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	30/07/2018		Date Discharge 30/07/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 30/07/2018 at about 1630hrs, I was on my back home driving my vehicle bearing license plate number: SLT4746H along CTE(SLE). During that point in time, it was heavy traffic as such the traffic was moving very slowly that eventually came to a stop. Suddenly, I felt a huge impact from the rear of my vehicle and that's where I realized that one taxi bearing license plate, SHB5928K had collided with the rear of my vehicle. I made a check with the passengers on board and everyone seem to be okay. We all alighted from the vehicle and that was where I saw my vehicle was badly damaged. Someone else called ambulance for us and I insisted on calling the traffic police.

Moments later, traffic police arrived at scene to make a check. They interviewed all involved parties and provided me with a case card and advised me to lodge a traffic police report. My domestic helper who was in the vehicle informed paramedics at scene that she was feeling unusual pain and was conveyed via ambulance. Myself and the remaining passengers all followed the tow truck back to the workshop as my vehicle was unable to operate anymore. It was back at the work shop where they informed me that my vehicle was very badly damaged.

Subsequently, I start to feel pain on my upper back, right elbow and left leg and as such I decided to make a visit to the doctor where I was subsequently given 3 days worth of MC.

As such, I made my way to Hougang NPC to lodge this traffic accident report. I wish to inform that I do not have any in-vehicle camera on board of my vehicle.

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20180731/2014

3 of 3

Report No. T/20180731/2014

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 KOH YEW WEI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

31/07/2018 02:24

Officer In Charge Of Case:

TP / GIT /

SI YEO CHUN JIAN

Contact No.: 65476213

Classification Of Case:

Authentication Stamp

NP166

CERTIFICATE OF INSURANCE

CERTIFICATE OF INSURANCE

PAGE 1 OF 2



中国太平保險(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

HKIDE SH
AW0584A
Cov. Type: C
AUTODATA

CERTIFICATE OF INSURANCE
Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 188)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1980
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1982 (Malaysia)

CERTIFICATE No.	UMPCSN3009131800	Engine No : X718603373447 Chassis No: WUP2120482A129744
1. Index Mark and Registration Number of Vehicle	SLT4746H	
2. Name of Policy Holder	MIAM KHANG YUN	
3. Effective date of the Commencement of Insurance for the purpose of the Regulations, Ordinance or Enactment (12:00 HOURS)	30 JANUARY 2018	NAMED DRIVERS EX SECT. 1\$2750.00 ADDITIONAL EX OTHER THAN NAMED DRIVERS: EX SECT. 1 - AGE 4- 25.....\$31,000.00 EX SECT. 1 - AGE 26- 34.....\$4800.00 * AGE AS AT DATE OF ACCIDENT EX ON WINDUCCUPH\$8100.00
4. Date of Expiry of Insurance	29 JANUARY 2019	
5. Persons or Classes of Persons entitled to drive *	<p>(A) THE POLICYHOLDER.</p> <p>(B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS PERMISSION.</p> <p>PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.</p>	
6. Limitations as to use: *	<p>USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS.</p> <p>THE POLICY DOES NOT COVER USE FOR HIRE OR HIRE-TO-DRIVE TUITION DRIVING TEST RACING RACE-MAKING, RALLYING, TRIAL, SPRINT-TESTING, THE CARRIAGE OF GOODS OTHER THAN SAMPLES IN CONNECTION WITH ANY TRADE OR BUSINESS OR USE FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.</p> <p>EXCESS WHICHEVER IS APPLICABLE FOR LOSSES OCCURRING OUTSIDE SINGAPORE (CONSTRUCTIVE TOTAL LOSS/THEFT) WILL BE DOUBLED.</p> <p>ONE TIME WAIVER OF EXCESS FOR THE FIRST \$21,000 WILL APPLY TO THE INSURED AND NAMED DRIVERS IN THE EVENT OF OWN DAMAGE CLAIM AT ONE AUTHORIZED WORKSHOPS FOR EACH POLICY YEAR.</p>	
<p>HIRE PURCHASE CO. : TUNCO CENTURY LEASING (S) PTE LTD</p> <p>* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 188) and Section 56 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.</p>		

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 188) and Part IV of the Road Transport Act, 1987 (Malaysia).
Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Terry's Office
35 Finlayson Avenue #04-01 S-467014
Tel/Fax: 9127 8514

Countersigned By:

Authorized Officer

Authorized Signatory

3 Anson Road #18-00 Springleaf Tower Singapore 079699 Tel: 6388 8111 Fax: 6225 3582 Website: www.sg.cntaiping.com

http://sgportal.cntaiping.com/chinainsB2B/Spool/AN0584A-SLT4746H-DMPCSN300... 30/1/2018

PAGE 2

69098119

ATLANTIC AUTOMOBILE

31.07.2018 12:42

RECEIVED 13/08/2018 02:18

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/07/2018 13:53
Date Of Accident	30/07/2018 16:30
Exact Location Of Accident	ALONG CTE TWDS SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJJ4041J
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	AZWIN ISKANDAR BIN HAIRON
NRIC No	S8308199F
Email Address	SAUDADE_18@YAHOO.COM
Mobile Phone No	(LOCAL) +65-81820721
Alternative Phone No	OTHERS-81820721

Vehicle Particulars

Manufacturer	HONDA
Model	STREAM-1.8 RSZ (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPC17S013804
Cover Note Number	11/09/17 - 10/09/18

Driver

Name of Driver	AZWIN ISKANDAR BIN HAIRON
NRIC No	S8308199F
Date Of Birth	28/02/1983
Occupation	INDOOR
Date Of Driving Pass	03/06/2008
Driving Experience	10 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81820721
Fax Number	
Contact Number	
EEmail Address	SAUDADE_18@YAHOO.COM

Address	BLK 848 WOODLANDS ST.82 #07-173
Postcode	730848
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : WIFE GENDER: : FEMALE
Passenger 2	NAME: : SON GENDER: : MALE
Passenger 3	NAME: : DAUGHTER GENDER: : FEMALE
Passenger 4	NAME: : DAUGHTER GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS EAST N.P.C
Police Station Address	ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	SD CARD WITH TRAFFIC POLICE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT4746H
Vehicle Make/Model/Colour	BLUE MERC BENZ E200
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	THAM KEANG YEN
NRIC/Passport Number	S7211982G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHB5928K
Vehicle Make/Model/Colour	TOYOTA PRIUS SMRT TAXI
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	HILWA BINTE MOHAMED(WIFE)
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJJ4041J
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	SON
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJJ4041J
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Sketch Plan

SKETCH PLAN

VEHICLE NO.: SJ3 4041J

INSURER : ERGO

DATE & TIME: 30/7/18 @ 16-30

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: CPB
NRIC/Pass No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report No: T/2018 0731/2053

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature:
(If driver is not the policyholder)
Date & Time:

Reporting Centre / Personnel's Signature
Name: (S)
NRIC/FIN No:

() Claim Own Policy () Claim Third Party () Reporting Only
(✓) Claim OE/TP at other workshop (DU 8 Yarrow Plc Ltd)



**SINGAPORE
POLICE FORCE**



T/20180731/2053

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7579999

1 of 3

Report No. T/20180731/2053

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 31/07/2018 12:30	Vide Report No.:	Station Diary No: 133
--	------------------	--------------------------

Informant's Particulars

Name of Informant: AZWIN ISKANDAR BIN HAIRON			Address: APT BLK 848 WOODLANDS STREET 82 #07-173 SINGAPORE 730848		
ID Type / ID No. NRIC NO / S8308199F			Contact No. Home/Office:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 30/07/2018 16:30	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 CENTRAL EXPRESSWAY SELETAR EXPRESSWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHB5928K	Car	TOYOTA	PRIUS TAXI (SMRT)			0
SJJ4041J	Car	HONDA	STREAM 1.8 RSZ A	Red		4
SLT4746H		MERCEDES BENZ	E 200	Blue		0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
-------------	-------------------	---------------	-----------	-------------



**SINGAPORE
POLICE FORCE**



T/20180731/2053

Police Station Of Origin
Woodlands East N P C
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

2 of 3

Report No: T/20180731/2053

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
SJJ4041J	SHC INSURANCE PTE. LTD.	DMPC17S013804	11/09/2017	10/09/2018

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	AZWIN ISKANDAR BIN HAIRON		ID No.	S8308199F
Related Vehicle	SJJ4041J (Car)		Contact No.	81820721
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2.3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL
Driver				
Name	THAM KEANG YEN		ID No.	S7211982G
Related Vehicle	SLT4746H		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL

Brief Details.

On the above mentioned date and time, I was driving along CTE towards SLE on lane 1. I was driving SJJ4041J. While driving, I briefly saw a taxi (SHB5928K) hit onto the rear of a car (SLT4746H) on the second lane. Due to the impact, SLT4746H swerved to his right side and hit on the left side of my vehicle. I applied brakes during the impact. My car swerved slightly to the right and hit onto the divider. There was damages on the whole left portion of my vehicle and few scratches and dents on the front right side of my vehicle. 2 of my passengers mainly, my wife (Hilwa Binte Mohamed) and my son was conveyed by ambulance. My son received 2 days of mc.

PR



**SINGAPORE
POLICE FORCE**



T/20180731/2053

Police Station Of Origin:
Woodlands East N.P.C
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

3 of 3

Report No: T/20180731/2053

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / Sgt 2 MUHAMMAD SYAZRUL HAZEEQ BIN MOHD MASHARUDIN	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 31/07/2018 12:30
Officer In Charge Of Case: TP / GIT / SI YEO CHUN JIAN Contact No : 65476213	Classification Of Case: SN 130
Authentication Stamp NP158	Signature :  Singapore Police Force

IC & DL

REPUBLIC OF SINGAPORE
IDENTITY CARD NO S6308199F



Name
**AZWIN ISKANDAR BIN
HAIRON**

Sex
MALAY

Date of Birth
28 Feb 1983

Place of Birth
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number **S6308199F**



Name
**AZWIN ISKANDAR BIN
HAIRON**

Valid Until **28 Feb 1983**

Issue Date **11 May 2007**

IC No **S6308199F**



5386700



IC No **S6308199F**



Issue Group **07** Date of Issue
15-07-2002

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

CLASS	VEHICLE TYPE	PASS DATE
Class 2A	Motorcycles (11-200 cc)	21 Jan 2008
Class 2B	Motorcycles (motorcycles 201 cc and abv 400 cc)	21 Mar 2008
Class 2	Motorcycles (401 cc and abv 400 cc)	21 Apr 2007
Class 3	Motor cars (11-2000 cc) and light trucks (gross weight not exceeding 2500 kg) and motor vehicles (category 11-2500 kg)	21 Jan 2008

IC No **S6308199F**

S / No **9000078771**

License No **S6308199F**



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SJJ4041J		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	STREAM 1.8 RSZ A		
Chassis No. :	RN61077370		
Propellant :	Petrol		
Engine No. :	R18A1786055		
Engine Capacity :	1799 cc		
Maximum Power Output :	103.0 kW (138 bhp)		
Maximum Laden Weight :	1755 kg		
Unladen Weight :	1370 kg		
Year Of Manufacture :	2008		
Original Registration Date :	11 Sep 2008		
Lifespan Expiry Date :	-		
COE Category :	B - Car (1601cc & above)		
Quota Premium :	\$13,890.00		
COE Expiry Date :	10 Sep 2018		
Road Tax Expiry Date :	10 Sep 2018		
PARF Eligibility Expiry Date :	10 Sep 2018		
Inspection Due Date :	10 Sep 2019		
Intended Transfer Date :	29 Aug 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK Print

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Jul 2018		01 Aug 2018 16:54 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: THAM KEANG YEN , ID: S7211982G									
Main Claimant: AZWIN ISKANDAR HAIRON									
Vehicle Reg. No.: SJJ4041J		Date of Loss: 30/07/2018 17:00 - :59 [118 Months and 19 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D03732C02		Policy/Cover Note No.: DMPCSN3009131800 (Comprehensive)							
Vehicle Reg. No. (Insured): SLT4746H		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: 8 Paragon Pte Ltd (HQ) 71 WOODLANDS AVE 10 #01-10 WOODLANDS INDUSTRIAL XCHANGE, 737743 Woodlands - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 13/08/2018]									
Adj Asg. Remarks: NO EST, CASE W/O SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJJ4041J (SNM18D03732C02)**
[SLT4746H]

TP
















































AZWIN ISKANDAR HAIRON

Jul 30 2018 5:00PM

[THAM KEANG YEN]

8 Paragon Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)				Thumbnail		Print	
1	01/08/18 16:46	Accident Statement						Load HTML	
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)				Thumbnail		Print	
1	01/08/18 16:20	Accident Photo [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
2	01/08/18 16:20	Accident Photo [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
3	01/08/18 16:20	Accident Photo [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
4	01/08/18 16:20	Accident Photo [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
5	01/08/18 16:20	Accident Photo [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
6	01/08/18 16:20	Accident Photo [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
7	01/08/18 16:20	Accident Photo [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
8	01/08/18 16:20	Accident Photo [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
9	01/08/18 16:20	Accident Photo [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
10	01/08/18 16:20	Accident Photo [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
11	01/08/18 16:20	Accident Photo [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	04/08/18 01:13	General View						Load JPG <input checked="" type="checkbox"/>	
2	04/08/18 01:13	General View						Load JPG <input checked="" type="checkbox"/>	
3	04/08/18 01:13	General View						Load JPG <input checked="" type="checkbox"/>	
4	04/08/18 01:13	General View						Load JPG <input checked="" type="checkbox"/>	
5	04/08/18 01:13	General View						Load JPG <input checked="" type="checkbox"/>	
6	04/08/18 01:13	General View						Load JPG <input checked="" type="checkbox"/>	
7	04/08/18 01:13	General View						Load JPG <input checked="" type="checkbox"/>	
8	04/08/18 01:13	General View						Load JPG <input checked="" type="checkbox"/>	
9	04/08/18 01:13	General View						Load JPG <input checked="" type="checkbox"/>	
10	04/08/18 01:13	General View						Load JPG <input checked="" type="checkbox"/>	
11	04/08/18 01:13	General View						Load JPG <input checked="" type="checkbox"/>	
12	04/08/18 01:13	General View						Load JPG <input checked="" type="checkbox"/>	
13	04/08/18 01:13	General View						Load JPG <input checked="" type="checkbox"/>	
14	04/08/18 01:13	General View						Load JPG <input checked="" type="checkbox"/>	
15	04/08/18 01:13	General View						Load JPG <input checked="" type="checkbox"/>	
16	04/08/18 01:13	General View						Load JPG <input checked="" type="checkbox"/>	
17	04/08/18 01:13	General View						Load JPG <input checked="" type="checkbox"/>	
18	04/08/18 01:13	General View						Load JPG <input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
19	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
20	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
21	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
22	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
23	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
24	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
25	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
26	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
27	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
28	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
29	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
30	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
31	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
32	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
33	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
34	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
35	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
36	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
37	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
38	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
39	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
40	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
41	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
42	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
43	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
44	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
45	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
46	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
47	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
48	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
49	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
50	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
51	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
52	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
53	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
54	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
55	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
56	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
57	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
58	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
59	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
60	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
61	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
62	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
63	04/08/18 01:14	General View		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	01/08/18 16:24	Sketch Plan [Linked Accident Report Documents]		<input type="checkbox"/>
2	01/08/18 16:24	Sketch Plan #2 [Linked Accident Report Documents]		<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
3	01/08/18 16:27	POLICE REPORT [Linked Accident Report Documents]		Load TIF
4	01/08/18 16:27	POLICE REPORT [Linked Accident Report Documents]		Load TIF
5	01/08/18 16:27	POLICE REPORT [Linked Accident Report Documents]		Load TIF
6	01/08/18 16:29	NRIC AND RIVING LICENSE (FRONT) [Linked Accident Report Documents]		Load TIF
7	01/08/18 16:29	NRIC AND DRIVING LICENSE (BACK) [Linked Accident Report Documents]		Load TIF
8	01/08/18 16:29	CERTIFICATE OF INSURANCE [Linked Accident Report Documents]		Load TIF
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/08/18 16:53	PRS		Load PDF

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	01/08/18 16:46	Accident Statement		Load HTM
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	01/08/18 16:20	Accident Photo		Load JPG
2	01/08/18 16:20	Accident Photo		Load JPG
3	01/08/18 16:20	Accident Photo		Load JPG
4	01/08/18 16:20	Accident Photo		Load JPG
5	01/08/18 16:20	Accident Photo		Load JPG
6	01/08/18 16:20	Accident Photo		Load JPG
7	01/08/18 16:20	Accident Photo		Load JPG
8	01/08/18 16:20	Accident Photo		Load JPG
9	01/08/18 16:20	Accident Photo		Load JPG
10	01/08/18 16:20	Accident Photo		Load JPG
11	01/08/18 16:20	Accident Photo		Load JPG
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	01/08/18 16:24	Sketch Plan		Load TIF
2	01/08/18 16:24	Sketch Plan #2		Load TIF
3	01/08/18 16:27	POLICE REPORT		Load TIF
4	01/08/18 16:27	POLICE REPORT		Load TIF
5	01/08/18 16:27	POLICE REPORT		Load TIF
6	01/08/18 16:29	NRIC AND RIVING LICENSE (FRONT)		Load TIF
7	01/08/18 16:29	NRIC AND DRIVING LICENSE (BACK)		Load TIF
8	01/08/18 16:29	CERTIFICATE OF INSURANCE		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118014046/NZ4D3E2

Date: 30/08/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3009131800

Claimant Vehicle
No: SJJ4041JInsured Vehicle
No: SLT4746H

Date of Loss: 30/07/2018

Nature of Claim: TP

Claim
No: SNM18D03732C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJJ4041J

Make & Model: HONDA STREAM, 1.8 RSZ (A)

Reg. Date: 11/09/2008 (Man. Year: 2008)

Colour: Red

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: R18A1786055

Chassis No: RN61077370

Odometer: 306346 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Rear Tyre Size: 215/45 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 01/08/2018

Date Inspected: 02/08/2018 Inspected At:

8 Paragon Pte Ltd (HQ)
71 WOODLANDS AVE 10 #01-10
WOODLANDS INDUSTRIAL XCHANGE
Singapore 737743

Estimated Period of Repair: 15.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000.00 - \$19,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Aug 2018)
Parts:	M1-MPV	HONDA STREAM 1.8 RSZ (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJJ4041J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >