

ASS. REC. BY:

REF: CS/MSG18014047/Urd3n2

Special Instruction:

Surveyor

ASSIGNMENT (Office)

menimen

Person (Person):

Katherine Wang

of

MSG

Date/Time 02/8/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 8797T

Insured:

SGY 6693X

at Workshop m/s:

Chew Motor

Tel:

67479241

of

311 Kalei Bldg Ave 6 # 01-43

Policy No:

A2864718ARW

Claim No:

566027

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/07/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

10:30am 02/8/18

Person Contacted:

Suky

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLD 8797T - X

SGY 6693X - X

Revert thru menimen

(08/11/13) wef:

ASS. REQ. BY: *Morales*

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / INS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: *SLD8777*at Workshop m/s *Cher motor*

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *3* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: *SLD8777* Regn: *12 10*Type: *M.Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CAI*Make: *JAGUAR XJ5.0L 5000*Colour: *White* A/C: Insured / Std / NI / NASp. Reading: *101111* T/Radio: Insured / Std / NI / NAEng/No: *SAJAC26L6BMV11637*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *Good* / Jammed / Leaked / Burnt orBrake: *Good* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim orTyre Size: *F:**R: 275/35ZR20*

BS / DUN / EXNOVA / GY / FS / LIZA / MCO / HTSU / PIR / SUMI /

TOYO / YOKO or

Front: *6* mm Rear: *6* mmR/Bal. *6* mm R/Bal. *6* mmL/Bal. *6* mm L/Bal. *6* mmD.O.A. *29/7/18* D.O.I. *2/8/18*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rear
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/9/18 17A 76743
4/5 @ 3100 confirmed with Repaire
Red: \$18,839.20, 86%.

RECEIVED 13 SEP 2018

Date/Time, File Pass to?

1) *typist*

Date/Time, File Return to?

2) _____

☐ : Prel. Report☒ : Final ReportDays Of Repair: *3*Resurvey No. of Trip: *1*

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ - RS - SI

Photos

Others

TOTAL

*200**10**210*Report Format: *TP*Lump Sum / I.B.# (\$ *3100*)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 13 Sep 2018

Preliminary Advice

Insured Vehicle No	: SGY6693X	Accident Date	: 29/07/2018
TP Vehicle No	: SLD8797T	Assignment Date	: 02/08/2018
Make	: JAGUAR XJ	Est. Duration of Repair	: 3.00
Date of Inspection	: 02/08/2018		
Inspection At	: CHEW MOTOR PTE LTD (HQ) BLOCK 1 KAKI BUKIT AVE 6, #01-43 SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,650.00 (only labour)
Revised Amount	:S\$	980.00 (only labour)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	980.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2018		02 Aug 2018 10:16 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TONY SIM LENG WOON, ID: S7641716D, Tel: +6581612275, Email: tony.sim@gmail.com		
Main Claimant:	KIM CHAI KEAN, ID: S8364862G		
Vehicle Reg. No.:	SLD8797T	Date of Loss:	29/07/2018 22:00 - :59 [93 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 566027	Policy/Cover Note No.:	A28644718AVW (Comprehensive) Coverage: 13/11/2017 - 12/11/2018
Vehicle Reg. No. (Insured):	SGY6693X	Policy No. (Claimant):	
		Excess:	
Repairer:	Chew Motor Pte Ltd (HQ) BLOCK 1 KAKI BUKIT AVE 6, #01-43, 417883 Kaki Bukit - Tel: 67479241		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/08/2018]		
Driver/Custodian (Insured):	TONY SIM LENG WOON (41 / Male), NRIC: S7641716D, Tel: +6581612275		
Adj Asg. Remarks:	Third Party Pre-Repair Survey. TP selected LKK to be SJE. Liability- unclear Contact : Ms Sukyi/ Reena @ 6747 9241		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MSME1808235 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME 30/07/2018 15:30
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/07/2018 15:30
Date Of Accident	29/07/2018 22:05
Exact Location Of Accident	JB TUAS SECOND LINK CUSTOM TWDS SG CUSTOM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD8797T
Insured/Policyholder	
Name Of Registered Owner	KIM CHAI KEAN
NRIC No	S8364862G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90039098
Alternative Phone No	OFFICE-90039098

Vehicle Particulars

Manufacturer	JAGUAR
Model	XJ-5.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA367378
Cover Note Number	

Driver

Name of Driver	KIM CHAI KEAN
NRIC No	S8364862G
Date Of Birth	12/03/1983
Occupation	OUTDOOR
Date Of Driving Pass	24/11/2003
Driving Experience	14 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90039098
Fax Number	
Contact Number	OFFICE-90039098
EEmail Address	NOEMAIL

Address BLK 2 LORONG 7 TOA PAYOH #10-17
 Postcode 310002
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 6

Passenger 1
 NAME: : TAN KAI CHEE
 GENDER: : FEMALE
 Passenger 2
 NAME: : ISABELLE LIM ZI XIN
 GENDER: : FEMALE
 Passenger 3
 NAME: : TAN YEE LUEN
 GENDER: : MALE
 Passenger 4
 NAME: : LEE QIAN NI
 GENDER: : FEMALE
 Passenger 5
 NAME: : TAN YEE YAN
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS STATIONARY AT JB TUAS SECOND LINK CUSTOM TWD SINGAPORE CUSTOM TO QUEUE FOR PASSPORT CLEARANCE. SUDDENLY, I FELT AN IMPACT. VEHICLE B COLLIDED ONTO REAR RH PORTION OF MY VEHICLE AND CAUSED DAMAGES. I WISH TO LODGE THE REPORT TO CLAIM AGAINST VEHICLE B.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGY6693X

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE B

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/Fin No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

JB CUSTOM	A: SLDB794T B: SGY6693X
	JB Trav second link Custom Towards SG custom

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stationary at JB Trav second link custom towards SG custom for queue for passport clearance.

Suddenly, I felt an impact. Van "B" collided onto rear RH portion of my vehicle and caused damaged.

I wish lodge the report claim against van "B".

Passenger:

- ① Tan Kai Chee (F)
- ② Isabelle Lim Si Xin (F)
- ③ Tan Yee Luen (M)
- ④ Lee Qian Ni (F)
- ⑤ Tan Yee Yan (M)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #3 Pg. 1

LETTER OF UNDERTAKING

I/We, Lim Chai Kean, the owner of vehicle no. SLD87977 involving in an
accident with vehicle no. (TP) SG466934 on 29.07.2018 along JB Toas Second link
Custom towards SG Custom

My/Our insurance is under **M/S AXA Insurance Singapore Pte Ltd**, I/we shall decide whether to claim under my/our policy or against Third Party and if the former shall submit such a claim to M/s AXA Insurance Singapore Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handled by my/our preferred workshop, Chew motor pte ltd

Signed and Acknowledged by:

Lim Chai Kean
Name and signature of policyholder


Company Stamp

30/07/18
Date

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 4862G

Vehicle Details

Vehicle No.: SLD8797T
Vehicle to be Exported: No
Intended De-registration Date: 30 Jul 2018
Vehicle Make: JAGUAR
Vehicle Model: XJ 5.0L AT PORTFOLIO SC GAS/D 2WD SR
Primary Colour: Black
Manufacturing Year: 2010
Engine No.: 10090403480508PS
Chassis No.: SAJAC26L6BMV11637
Maximum Power Output: 346.0 kW (463 bhp)
Open Market Value: \$103,012.00
Original Registration Date: 24 Dec 2010
First Registration Date: 24 Dec 2010
Transfer Count: 1
Actual ARF Paid: \$103,012.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 23 Dec 2020
PARF Rebate Amount: \$61,807.00

Intended COE Rebate Details

COE Expiry Date: 23 Dec 2020
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$62,502.00
COE Rebate Amount: \$14,970.00
Total Rebate Amount: \$76,777.00

The information contained herein is correct as at 30 Jul 2018

OK

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4862G
Vehicle Details	
Vehicle No.:	SLD8797T
Vehicle to be Exported:	No
Intended De-registration Date:	02 Aug 2018
Vehicle Make:	JAGUAR
Vehicle Model:	XJ 5.0L AT PORTFOLIO SC GAS/D 2WD SR
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	10090403480508PS
Chassis No.:	SAJAC26L6BMV11637
Maximum Power Output:	346.0 kW (463 bhp)
Open Market Value:	\$103,012.00
Original Registration Date:	24 Dec 2010
First Registration Date:	24 Dec 2010
Transfer Count:	1
Actual ARF Paid:	\$103,012.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Dec 2020
PARF Rebate Amount:	\$61,807.00
Intended COE Rebate Details	
COE Expiry Date:	23 Dec 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$62,502.00
COE Rebate Amount:	\$14,936.00
Total Rebate Amount:	\$76,743.00

The information contained herein is correct as at 02 Aug 2018

OK

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD![Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)**New 5 Years Coe Renewal Toyota Altis 1.6A**

\$2500 Downpayment Monthly
From \$588 Onwards. Lowest
3.68%P.A@GV Cars Financing
GV Credit Pte Ltd StarAd

ABWIN

Browse by Category ▼

Sort by

1 vehicles

Jaguar XJ

Advanced

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Search Selection**Jaguar XJ**

Any

Any

2010

Any

**Jaguar XJ 5.0A****\$90,800****\$19,630 /yr****03-Dec-2010****5,000 cc****44**

502 Bhp XJ 5.0A Supersport Supercharged With High OMV. Guarantee Accident Free, Wearnes Unit. STA And VICOM Ev...
Monthly Installment. Highest Trade In Value For Used Car. Fast An...

Posted: 28-May-2018 Tags: 2010 Jaguar XJ, Jaguar XJ, Jaguar, XJ, Used Jaguar

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

For old advertisements, view **Expired ads**

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [For](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars buy used Jaguar XJ, Jaguar XJ Singapore, used Jaguar XJ Singapore, used Jaguar XJ, used vehicles Singapore or even buy used Jaguar XJ Singap importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle le

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or wa

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection](#)

©2004-2018 sgCarMart. All rights reserved.

[Compare](#)



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

not done
30/07/2018
Lhu
2/5
3 dy.

Accident date: 29/07/2018

Estimated repair cost for vehicle no: SLD8797T JAGUAR XJ 5.0 A '10

CHASSIS: SAJAC26L6BMV11637

S/n	Qty	Items / List	U/price	Amount
1	1	Rear Bumper <i>deep cut</i>		
2	10	Rear Bumper Clip <i>in</i>		
3	2	Rear Bumper Side Retainer <i>11 X</i>		
4	1	Rear Bumper Number Plate <i>in</i> <i>POS-N GLUE TYPE</i>		
5	1	Rear Bumper Centre Chrome Moulding <i>in</i>		
6	1	Rear R/H Rim <i>2X</i>		
7	1	Rear R/H Tyre <i>11 X</i>		
8	1	Rear R/H Lower Arm <i>11 X</i>		
9	1	Rear R/H Upper Arm <i>in</i>		
10	1	Rear R/H Knuckle Arm <i>11 X</i>		
11	1	Rear R/H Knuckle Arm Bearing <i>11 X</i>		
12	1	Rear R/H Trailing Arm <i>11 X</i>		
13	1	Rear R/H Shock Absorber <i>11 X</i>		
14	4	Rear Reverse Sensor Holder <i>11 X</i>		
15	4	Rear Reverse Sensor Seal Rubber <i>11 X</i>		

Subtotal :- \$0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Labour charges

To remove & refit reverse sensor	50	\$100.00
To remove & refit rear R/H undercarriage	11 X	\$450.00
To check wheel alignment	80	\$150.00
Tuff kote	11 X	\$150.00
Panel beating	300	\$1,400.00
Spray painting	550 300	\$1,400.00

Subtotal :- \$3,650.00

Total:- \$3,650.00



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 29/07/2018

Estimated repair cost for vehicle no: SLD8797T JAGUAR XJ 5.0 A '10

CHASSIS: SAJAC26L6BMV11637

not adjust 30/07/2018
LKR
2/5 ~~3100~~
327.

S/n	Qty	Items / List	U/price	Amount
1	1	Rear Bumper <i>repair</i>	<i>2563.60</i>	\$3,350.90
2	10	Rear Bumper Clip <i>in</i>	\$8.00	\$80.00
3	2	Rear Bumper Side Retainer <i>11 X</i>	\$155.80	\$311.60
4	1	Rear Bumper Number Plate <i>in</i>	<i>POS-N GLUE TYPE</i>	\$150.00
5	1	Rear Bumper Centre Chrome Moulding <i>in</i>	<i>358.70</i>	\$556.70
6	1	Rear R/H Rim <i>in</i>		\$2,800.00
7	1	Rear R/H Tyre <i>11 X</i>		\$580.00
8	1	Rear R/H Lower Arm <i>11 X</i>		\$1,682.00
9	1	Rear R/H Upper Arm <i>11 X</i>		\$1,189.00
10	1	Rear R/H Knuckle Arm <i>11 X</i>		\$2,352.00
11	1	Rear R/H Knuckle Arm Bearing <i>11 X</i>		\$1,067.00
12	1	Rear R/H Trailing Arm <i>11 X</i>		\$1,196.00
13	1	Rear R/H Shock Absorber <i>11 X</i>		\$1,886.00
14	4	Rear Reverse Sensor Holder <i>11 X</i>	\$155.00	\$620.00
15	4	Rear Reverse Sensor Seal Rubber <i>11 X</i>	\$117.00	\$468.00

520

Subtotal :- \$18,289.20

P-30021
52
2851.99
S.N-80
labour-980
3911.99
3129

Labour charges

To remove & refit reverse sensor	50	\$100.00
To remove & refit rear R/H undercarriage	11 X	\$450.00
To check wheel alignment	80	\$150.00
Tuff kote	11 X	\$150.00
Panel beating	300	\$1,400.00
Spray painting	550 300	\$1,400.00

Subtotal :- \$3,650.00

Total:- \$21,939.20

980

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18014047/URD3N2

Date: 25/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28644718AVW
Claimant Vehicle No :	SLD8797T	Insured Vehicle No :	SGY6693X
Date of Loss:	29/07/2018	Nature of Claim:	TP
		Claim No:	566027

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD8797T	Engine No:	10090403480508PS
Make & Model:	JAGUAR XJ, 5.0 (A)	Chassis No:	SAJAC26L6BMV11637
Reg. Date:	24/12/2010 (Man. Year: 2010)	Odometer:	101111 km
Colour:	White		
Engine Capacity:	5000 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/35ZR20	Rear Tyre Size:	275/35ZR20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,289.20	2,931.99	15,357.21	83.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	980.00	2,670.00	73.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,939.20	3,911.99	18,027.21	82.17
Approved Total (Overridden) (\$\$)		3,100.00		
Nett Amount (\$\$)	21,939.20	3,100.00	18,839.20	85.87

INSPECTION

Date of Assignment:	02/08/2018	
Date Inspected:	02/08/2018	Inspected At: Chew Motor Pte Ltd (HQ) BLOCK 1 KAKI BUKIT AVE 6, #01-43 Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Sep 2018)
Parts: 143	JAGUAR XJ 5.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLD8797T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deep Cut	3,350.90 F	*2,563.60 FL
2	10	*REAR BUMPER CLIP	Necessary	80.00 F	*80.00 FL
3	2	*REAR BUMPER SIDE RETAINER	Not Necessary	311.60 F	*- FL
4	1	*REAR BUMPER CENTRE CHROME MOULDING	Necessary	556.70 F	*358.50 FL
5	1	*REAR R/H RIM	Repair	2,800.00 F	*- FL
6	1	*REAR R/H TYRE	Not Necessary	580.00 F	*- FL
7	1	*REAR R/H LOWER ARM	Not Necessary	1,682.00 F	*- FL
8	1	*REAR R/H UPPER ARM	Not Necessary	1,189.00 F	*- FL
9	1	*REAR R/H KNUCKLE ARM	Not Necessary	2,352.00 F	*- FL
10	1	*REAR R/H KNUCKLE ARM BEARING	Not Necessary	1,067.00 F	*- FL
11	1	*REAR R/H TRAILING ARM	Not Necessary	1,196.00 F	*- FL
12	1	*REAR R/H SHOCK ABSORBER	Not Necessary	1,886.00 F	*- FL
13	4	*REAR REVERSE SENSOR HOLDER	Not Necessary	620.00 F	*- FL
14	4	*REAR REVERSE SENSOR SEAL RUBBER	Not Necessary	468.00 F	*- FL
15	1	*REAR BUMPER NUMBER PLATE (GLUE TYPE)	Necessary	150.00 FS	*80.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	18,289.20	3,082.10
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	150.11
Total Parts (\$\$)	18,289.20	2,931.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
2	TO REMOVE & REFIT REAR R/H UNDERCARRIAGE	New	450.00	-
3	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
4	TUFF KOTE	New	150.00	-
5	PANEL BEATING	New	1,400.00	300.00
6	SPRAY PAINTING	New	1,400.00	550.00
Gross Labour Cost (S\$)			3,650.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >