

INS. CASE OWNER:

CC 4/AIG1801

4061, GEB

LKK:

IDAC:

Surveyor:

YGA

DOI:

ASSIGNMENT

Date / Time:

2/8/18

Registered in Merimen:

2/8/18

Pre-assign / CCU / FTE:



Insured Vehicle No.:

SJY 66124

Name of Insured:

SAHABUDEEN SHEIKH ABU NURHAN

Insured Tel No.:

HP: 98407415

Excess See II :SS

D.O.A: 24/7/18

Is driver the owner?

YES / NO

Nature of Accident:

Claim No.:

112596728959

Policy No.:

20042214-02

Make / Model:

TOYOTA

Place of Accident:

FAMU LING KO

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO TP GIA REPORT: YES / NO

Insured Liability: Final ? Yes / No

JWW 1887



INSRS:

WSP:

Tel:

Liability:

RMKS:

SG 98



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

17/8/18
Wskh

SAWIBET -
SJY 66124 - 43/01/17/18/19/20/21/22/23/24/25/26/27/28/29/30/31/12/18

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	2.9.18
After call ltr to OI:	
Documentation Check List:	Handler Typist
Notification ltr (if non-pickup)	
After call ltr to OI:	<input checked="" type="checkbox"/>
Authorisation To Act:	<input checked="" type="checkbox"/>
Release Voucher:	<input checked="" type="checkbox"/>
Final Repair Bill:	<input checked="" type="checkbox"/>
Car Rental Invoice:	
Towing Invoice:	
LTA / GIA:	
Medical Bill:	
PIR:	
Mandate/Reject Instruction:	
LOD:	
Payment Breakdown Form:	
Post-Repair Photos:	
Others:	

20.8.18 23.48

CRASH OI CONFIRMED ACCIDENT. OI EXIT FROM THE MOTOR
FIND THE OI TO TP. INFORM TP LHM ACCIDENT TO SERVE
AND AMBER ABOUT NEW ISSUE.
Enter WSP LIABILITY CLAIM.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time: 20.8.18

Confirm with: ROSE

Confirm by: YGA

Repair Cost:

SS 1,295.00

(3 days) Reduction:

28 %

Email

Call

FINAL SETTLEMENT

Date/Time: 20.8.18

Confirm with: ROSE

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

01 EXISTING MAJOR ROAD

If NO or B 28, Ass. Lia:

Repair Cost:

SS 1,295.00

Loss of Rental (LOR):

SS -

(3 days)

Loss of Use (LOU):

SS 45.00

(5.15 x 3 days)

Loss of Income (LOI):

SS -

(5 x 3 days)

LOR only

☒ LOR + LOU

☐ LOR + LO

[Tick only one]

GIA/LTA Search

SS -

Medical:

SS -

Disbursement:

SS -

(e.g. Tow / Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

320

Total:

SS 1,295.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 20.8.18

Confirm with: ROSE

Email

Call

Payee 1:

SS 1,295.00

Name 1:

SG 98 MOTOR PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC4/AIG18014061/Geb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 02-08-2018	
			Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJY 6612U		Veh. Inspected	JNW 1887
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	02/08/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/07/2018		Inspection Date	06/08/2018
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Ms Gonalize. Tks / Rina

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 6 August 2018

To : LKK

By Fax: 6256-4315

Attn : Taufikh (Tel: 97495749)

VEHICLE NO : JNW 1887

Kawasaki Ninja 250R

ACCIDENT DATE: 24 July 2018

	Description	Qty	Quotation \$
1	Gear Shifter / BT	1	180.00
2	Gear Pedal / BT	1	150.00
3	LH Side Garnish Cover / CUT	1	350.00
4	Front LH Fairing / CUT	1	350.00
5	Front Footrest LH / BT	1	165.00
6	Footrest Bracket LH / DIS	1	190.00

Sub-Total 1,385.00
Less 10% 138.50
Sub-Total 1,246.50

Nett items

1	Spray paint work - touch up paint work	250.00	150
2	Labour to remove & replace parts etc	250.00	180
Sub-Total		500.00	
Nett Total		1,746.50	

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

Good Q. & P.

LKK

06/8/18

30 DAY

email
Taufikh
10/8

Your password will expire in 11 days. [Click here to change it.](#)

- Pre repair inspection request - JNW1887 VS SJY6612U (OI) DOA: 24/07/2018

From: Mithoosingh, Aashweenjeetkaur
To: admin-a@kkauto.com, assignments@kkauto.com
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi
Sent: 2/8/2018 11:22:35 AM
Attachments:  JNW1887-PRI.PDF

Hi,

Please refer to the enclosed request from SG 98 Motor Pte Ltd.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign Mohammed Rasul as Single Joint Expert as requested.

Thanks and regards,

Aashweenjeet Kaur (Aashween)
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Sg motor enterprise Giam [mailto:sg_motor_enterprise@yahoo.com.sg]

Sent: Thursday, August 02, 2018 11:15 AM

To: Mithoosingh, Aashweenjeetkaur

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi

Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJY6612U AND JNW1887 ON 24/07/2018

Hi all,

pls arrange - LKK Consultant - mr Rasul to survey bike no: JNW 1887.

thank you
rose

On Wednesday, 1 August 2018, 12:11:00 PM GMT+8, Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com> wrote:

Without Prejudice

Your Reference : JNW1887

Our Reference : SJY6612U

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd

11.26am @ 2/8/2018
person @ Rose
vehicle not in

Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Aashweenjeet Kaur (Aashween)

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

From: Sg motor enterprise Giam [mailto:sg_motor_enterprise@yahoo.com.sg]
Sent: Wednesday, August 01, 2018 11:39 AM
To: AIG SGP, Claims-Survey
Subject: RE: JNW 1887 and SJY 6612U accident on 24 July 2018

Hi claim dept,

pls arrange PRI on Bike No : JNW 1887 accident on 24 July 2018

as per attached.

We would like to do direct settlement for property damages.

thank you

rose

SG 98 Motor Pte Ltd

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date : 1 August 2018

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
AIG Building
SINGAPORE 079120

Attn: Motor Claims Dept
Fax No.: 6835-7416 / 6415-3727
Email: aigsgp_claimssurvey@aig.com

Dear Sir/Mdm,


PRE-REPAIR INSPECTION

Accident between JNW 1887 and SJY 6612U on 24 July 2018 at 2000hrs
Location: Yung Kuang Road

- 1) We hereby give you NOTICE that we are claiming against your insured motor Vehicle No : SJY 6612U damages to our client's Motor Vehicle No: JNW 1887
- 2) Plse provide a list of surveyors and their respective company name.
- 3) Kindly let us know if you wish to conduct a pre-repair inspection only after 11.30am at Blk 4001 Ang Mo Kio Industrial Park 1 #01-21 Singapore 569622.
(Tel : 6452 4898, HP : 9171 1655)
- 4) If we do not hear from you within the next two (2) working days, we shall advise our clients to proceed with their own inspection and repairs.

Hope you are able to assist us on the above matter soonest.

Yours faithfully


Rose
SG 98 Motor Pte Ltd
Tel : 6452 4898

See on di

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Wednesday, 12 September 2018 3:03 PM
To: SA@REITZINDIA.COM
Subject: ACCIDENT INVOLVING SJY 6612U AND JNW 1887 ON 24/07/2018

Our Ref: CC4/AIG18014061/Geb3

12 SEPT 2018

SAHABUDEEN SHEIK ABDULLAH

Dear Sir/Madam,

ACCIDENT INVOLVING SJY 6612U AND JNW 1887 ON 24/07/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: Ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT


I, Tee Wei Chen ("the third party claimant")
of No. 24 Sun Marak Taman Sentosa 85300 Labis Johor (address),
owner of JN1W1887 (vehicle no.) hereby authorize
SG98 Motor Pte Ltd


("the workshop") to act for me with respect to my claim for
repair costs and/or rental and/or loss of use ("claim") for my
vehicle no. JN1W1887 that was damaged pursuant to the
accident which occurred on 24/7/18 (date) along Perai 1
Yung Kuang Road (location)
involving vehicle no/s 83766124
("the accident").

I further authorize the workshop to settle my above mentioned
claim in a manner that they deem fit and the workshop is further
authorized to receive payment further to settlement of my claim
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach
on my behalf is on a without prejudice and without admission of
liability basis insofar as the driver/owner/insurers of the
other vehicle/s is concerned.

Dated this 31st day of July (month) 20 18 (year)


Signed by "the third party claimant"


Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **SG 98 MOTOR PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$1,250.00** (Repair Cost), **S\$45.00** (Loss of Use/Rental), **S\$ -** (Disbursement) for vehicle no. **JNW 1887** that was damaged pursuant to the accident which occurred on **24/07/2018** (date) along **ROAD 1 YUNG KUANG ROAD** (location) involving vehicle no/s **SJY 6612U**.

This is pursuant to the inspection conducted on **06/08/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **TEE WEI CHEN** ("the third party claimant") of vehicle no. **JNW 1887** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **JNW 1887** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 22nd (day) of Month (month) 2019 (year)



XGQ

Signed by appointed surveyor



Signed by "the workshop" (with chop)

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4888

Email: sg_motor_enterprise@yahoo.com.sg

DATE: 22 March 2019

Invoice No: SG98-PD-19-020

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
SINGAPORE 079120

PD - Direct Settlement

Your Insured: SJY 6612U

Date of Accident: 24-Jul-18

Location: Yung Kuang Road

FINAL REPAIR COSTS

VEHICLE NO. JNW 1887 (Kawasaki Ninja 250R)

Cost of Repair for Vehicle No.:	JNW 1887 (lump sum)	\$1,250.00
---------------------------------	---------------------	------------

Total:	\$1,250.00
--------	------------

SINGAPORE DOLLARS: ONE THOUSAND TWO HUNDRED FIFTY ONLY

Notes:

1. All cheque payment should be "Crossed" and made payable to SG 98 MOTOR PTE LTD
2. All cheque should have our "invoice No" written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us


SG 98 Motor Pte Ltd

LG

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Aug 2018 Edit Reg		02 Aug 2018 00:00 Edit Adj Rpt	S\$1,250.00 Edit Estimates	S\$1,250.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	SHEIK ABDULLAH SAHABUDEEN , ID: G6353699M								
Main Claimant:	TEE WEI CHEN , Co. Reg. No.: G2031763P								
Vehicle Reg. No.:	JNW1887	Date of Loss:	24/07/2018 00:00 - :59 [69 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1125963289SG	Policy/Cover Note No.:	2100432294 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJY6612U	Policy No. (Claimant):							
		Excess:							
Repairer:	Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/08/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (03/08/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*JNW1887 (1125963289SG)
[SJY6612U]
TP
TEE WEI CHEN
Jul 24 2018 12:00AM
[SHEIK ABDULLAH SAHABUDEEN]
Sg 98 Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser	
Letters/Correspondences													1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown										1	Edit			
Photos/Images													3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print		
1	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
2	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
3	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
4	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
5	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
6	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
7	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
8	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
9	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
10	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
11	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
12	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
13	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
14	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
15	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
16	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
17	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
18	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
19	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
20	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
21	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
22	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
23	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
24	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
25	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
26	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
27	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
28	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
29	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
30	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
31	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
32	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
33	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		
34	21/03/19 17:10	General View										1	Load JPG	<input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	21/03/19 17:10	General View	 Load JPG	<input checked="" type="checkbox"/>
36	21/03/19 17:10	General View	 Load JPG	<input checked="" type="checkbox"/>
37	21/03/19 17:10	General View	 Load JPG	<input checked="" type="checkbox"/>
38	21/03/19 17:10	General View	 Load JPG	<input checked="" type="checkbox"/>
39	21/03/19 17:10	General View	 Load JPG	<input checked="" type="checkbox"/>
40	21/03/19 17:10	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/08/18 14:29	EMAIL FROM AIG DD 02082018	 Load PDF	
2	02/08/18 14:29	WKSP NOTICE	 Load PDF	
3	13/08/18 18:49	INS CERT & LOG CARD	 Load PDF	
4	13/08/18 18:49	TP POLICE REPORT	 Load PDF	
5	12/09/18 15:16	LETTER TO OI	 Load PDF	
6	21/03/19 16:48	ESTIMATE	 Load PDF	
7	26/03/19 16:18	WORKSHOP INVOICE	 Load PDF	
8	26/03/19 16:18	AUTHORISATION TO ACT FORM	 Load PDF	
9	26/03/19 16:18	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	03/08/18 09:50	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJY6612U (Insd veh)	Model:	KAWASAKI EX250-L 249CC
	JNW1887 (TP veh)		
Date of Accident:	24/07/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	: \$	1,746.50		
Final Repair Cost	: \$	1,250.00		
Loss of Use	: \$	45.00		3.00 days at \$15.00 per day
Rental (if any)	: \$	0.00		days
LTA / GIA Search Fee	: \$	0.00		
Others:	: \$	0.00		
	: \$			
Final Settlement Sum	: \$	1,295.00		

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	SG 98 Motor Pte Ltd	: \$	1,295.00
2)		: \$	

JOANNE LEE KHANG MIN

26 Mar
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18014061/GEB3Q2

Date: 26/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100432294
Claimant Vehicle No : JNW1887 **Insured Vehicle No :** SJY6612U
Date of Loss: 24/07/2018 **Nature of Claim:** TP **Claim No:** 1125963289SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **JNW1887**
 Make & Model: KAWASAKI EX250-L, 249cc Engine No: EX250KEC43693
 Reg. Date: 27/09/2012 (Man. Year: 2012) Chassis No: PNKEX250KKMC43693
 Colour: Orange Odometer: 0 km
 Engine Capacity: 249 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100/80-17 Rear Tyre Size: 140/70-17
 Front Left Side: Metzeler 5 mm Rear Left Side: Metzeler 5 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,246.50	1,246.50	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	500.00	330.00	170.00	34.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,746.50	1,576.50	170.00	9.73
Approved Total (Overridden) (S\$)		1,250.00		
Nett Amount (S\$)	1,746.50	1,250.00	496.50	28.43
+ Loss of Use (3.0 x S\$15.00/day) (S\$)		45.00		
Nett Liability (S\$)		1,295.00		

INSPECTION

Date of Assignment: 02/08/2018
 Date Inspected: 06/08/2018 Inspected At: Sg 98 Motor Pte Ltd (HQ)
 BLK 4001 ANG MO KIO INDUSTRIAL
 PARK 1 #01-21
 Singapore 569622

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GEAR SHIFTER	Bent	180.00 FL	*180.00 FL
2	1		*GEAR PEDAL	Bent	150.00 FL	*150.00 FL
3	1		*LH SIDE GARNISH COVER	Cut	350.00 FL	*350.00 FL
4	1		*FRONT LH FAIRING	Cut	350.00 FL	*350.00 FL
5	1		*FRONT FOOTREST LH	Bent	165.00 FL	*165.00 FL
6	1		*FOOTREST BRACKET LH	Distorted	190.00 FL	*190.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,385.00	1,385.00
- List Item Discount on L Items 10.00/10.00% (S\$)	138.50	138.50
Total Parts (S\$)	1,246.50	1,246.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINT WORK-TOUCH UP PAINT WORK	New	250.00	150.00
2	LABOUR TO REMOVE & REPLACE PARTS ETC	New	250.00	180.00
Gross Labour Cost (\$\$)			500.00	330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >