

ASS. REC. BY

REF CS3/FWD18010391/Nvd3^{en}

(Construction)

Surveyor

From (Person)

Ndz

ASSIGNMENT (Office)

josy Loh

of

FWD

Date/Time

02/08/2018

Estimated Cost

Bill to

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SDN 89Z

Insured:

SIG 8855 S

at Workshop n/s

Target Auto

Tel:

9383 5100/82288881

of

160 Sin Ming Drive # 07-17

Policy No.

Claim No:

1201800006914

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A.

4/6/2018

CA / REV / REP. / REV 24 HRS

lup)

8/6/18 @ Morning

H.O.D. Endorsement

Date/Time

2:47pm @ 7/6/18

Person Contacted

Anna

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

SDN 89Z - x

SIG 8855S - x

11/6/18

Dismantled

10/6/18

After repair

3/8/18

Email to FWD when report ready

URGENT

5/9/18 LS \$ 5200 (Red 4300, 4590), 5 days

RECEIVED 05 SEP 2018


 5/9/2018

NAZ

FWD

ASSURANCE

File No

Date

8/6/18

Estimated Cost

OD (IP) WS / TP RES / OD RES / EVA / INV / MV

Transport Vehicle No

SDN 892

at Workshop no

target Auto

at 160 Siaming Drive #07-17

Insured

Excess

Sum Insured

Excess


(Client's Record)

Manning

Make of Veh

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection



Est. or Market Value

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repair: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP / 24 HRS / up

Date: Person Contacted

Vehicle: IN / OUT

Date: Time: Action: Instruction

Vehicle

SDN 892

Regn 25/JAN/2013

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

AUDI SPORTRAC

cc 1395

Colour

WHITE

A/C

Insured / Std / Nil / NA

Sp Reading

17,506

T/Radio

Insured / Std / Nil / NA

Eng/No

ChNo

W44Z228V7DA075440

Gen Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

225/40 R18

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A

D.O.I

08/06/2018

Survey held at

TARGET AUTO

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

O/S / FRONT / CENTRE

The UIC / Chassis frame / Body Structure affected due to collision

* Repair Estimate = \$\$\$ 13000 - 15000

* 4 days

13/6/18 Submit PRS Report.

RECEIVED 13 JUL 2018

Line Item: Rep/Excess



Prel. Report

To



Final Report

Line Item: File Return

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

1. 2. 3. 4. 5. 6. 7. 8. 9. 10.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10.

80

50

50

180

Report Format

Lump Sum / LB /

Add Fee:



Site Visit: 15



Interpret: 15



Photograph: 15



Other: 15

Nivitha (LKK Auto)

From: josey.loh@fwd.com
Sent: Thursday, 2 August 2018 2:19 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: motorclaims.sg@fwd.com; sur@lkkauto.com
Subject: [Paper Survey] Accident involving SJG8855S and SDN89Z on 04/06/2018 (Our Ref: 1201800006914)
Attachments: 20180802140209190.pdf

Hi LKK team,

Please conduct a paper resurvey on an urgent basis.

Kindly let us have the paper resurvey report soonest possible via email.


Thank you.

Kind Regards

Josey Loh
Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872
E josey.loh@fwd.com
W fwd.com.sg



ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

PRESTIGE APPRAISER SERVICES

VEHICLE INSPECTION REPORT

To: Mr Looi Cheng Sin Robert
c/o 160 Sin Ming Drive
#07-17 Sin Ming Auto City
Singapore 575722

Date : 19th June 2018
Our Ref : PS/004/06/18
Policy No :
Sum Insured :
Excess : T/P Claim

Assigned By : Mr Looi Cheng Sin Robert
Assignment Date : 07th June 2018
Accident Date : 04th June 2018
Inspection Date : 07th June 2018
Workshop Name : Target Auto Pte Ltd
Survey Conducted At : 160 Sin Ming Drive
#07-17 Sin Ming Auto City
Singapore 575722

PARTICULARS OF VEHICLE

Registration No	: SDN 0089 Z	Mileage	: 17506km
Make/Model	: Audi A3	Engine No	: CMB143257
Type Of Body	: Motorcar	Chassis No	: WAUZZZ8V7DA075440
Year Of Manu./Regn.	: 2013	Passenger Cap.	: 4 Passengers
Colour	: White	Others	: -

CONDITION OF TYRES

R/H SIDE

Front Tyre : 6mm 225/40R18 Bridgestone
Rear Tyre : 6mm 255/35R18 Goodyear

L/H SIDE

6mm 225/40R18 Bridgestone
6mm 255/35R18 Goodyear

The above represent the estimated remaining life of the tyre treads.

PRE-ACCIDENT CONDITION (Static tests only)

Handbrake	: Serviceable	Body Work	: Good
Footbrake	: Serviceable	Paint Work	: Good
Steering	: Serviceable	Others	: -

POINT OF IMPACT

The vehicle sustained an impact on the R/H front portion.

GENERAL DESCRIPTION OF DAMAGES

The front bumper, R/H fender, door, door pillar were dented/distorted.
The R/H front undercarriage were also affected.

For details of damages please refer to schedule attached.

REMARKS :

This survey was conducted strictly without prejudice.

PRESTIGE APPRAISER SERVICES

Vehicle No : SDN 0089 Z

Our Ref :

PS/004/06/18

Qty	Descriptions	Conditions	Repairer's Est.	Our Revised.
	<u>LIST ITEMS</u>			
1	front bumper	dented/cut	\$ 1,250.00	\$ 1,250.00 XR
1	R/H front bumper side retainer	dented	48.00	48.00 XSVC NN
8	front bumper clip	necessary	40.00	40.00 XSVC AN
1	R/H front fender	dented/distorted	955.00	800 955.00 DD
1	R/H front fender dust cover	serviceable	242.00	- XSVC
1set	R/H front fender dust cover clip	necessary	40.00	40.00
1	R/H front door	dented/distorted	1,980.00	1,980.00 DD
1	R/H front door weatherstrip	necessary	189.00	150 189.00
1	R/H front door glass moulding	necessary	215.00	130 215.00
1	R/H front door hinge	dented	240.00	150 240.00
2	R/H front door lock	dented	425.00	400 425.00
1	R/H front door regulator gear	dented	289.00	289.00
1	R/H front door regulator gear motor	damaged	455.00	455.00
1	R/H door wing mirror	damaged	1,185.00	1,185.00 DM
1	R/H front door inner trimboard	serviceable	798.00	- XSVC
1	R/H front lower arm	dented/distorted	568.00	450 568.00
1	R/H front knuckle arm	dented/distorted	625.00	625.00
1	R/H front knuckle arm bearing	necessary	298.00	298.00
1	R/H front shock absorber	warped	552.00	400 552.00
1	R/H front driveshaft	serviceable	1,250.00	- XSVC
			11,644.00	9,354.00
		Less 10%	-	935.40
			\$ 11,644.00	\$ 8,418.60
	<u>S/NETT ITEMS</u>			
1	R/H front tyre	wall cut	400.00	240.00 XSVC
1	R/H front wheel rim	sliced	1,000.00	700.00 XSVC R
	<u>Labour Charges & Misc</u>			
	To dismantle & replace damaged parts, panel beat where necessary.		1,250.00	900.00
	To putty, apply primer & spray-paint on the affected portion.		1,300.00	1,000.00
	To apply rust-proofing on repaired, replaced panel.		150.00	120.00
	To remove/renew R/H front undercarriage.		450.00	320.00
	To remove/transfer R/H front door mechanisms.		120.00	80.00
	To wheel alignment.		150.00	120.00
	To check wiring functions.		50.00	30.00
			\$ 16,514.00	\$ 11,928.60

? days

PRESTIGE APPRAISER SERVICES

Vehicle No : SDN 0089 Z

Our Ref : PS/004/06/18

Qty

Descriptions

Conditions

Repairer's Est.

Our Revised.

Note: The repairer has agreed to undertake the repairs at our adjusted amount of **\$9,500.00 lump sum** corresponding to supply of parts, labour and spray-painting charges.

Under normal circumstances, the estimated repair period would be **FIVE (5)** days.

Pursuant to your instruction we have **not** authorised repairs on your behalf.

PRESTIGE APPRAISER SERVICES



LOUIS S C NG CAE AMIMI (UK)

Licensed Appraiser

Dip. MTM. Automotive Engineer

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/06/2018 11:20
Date Of Accident	04/06/2018 14:45
Exact Location Of Accident	ORCHARD POINT/ CUPPAGE PLAZA CARPARK EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJG8855S
Insured/Policyholder	
Name Of Registered Owner	LIM FATT SENG
NRIC No	S0210253F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98185816
Alternative Phone No	HOME-98185816

Vehicle Particulars

Manufacturer	NISSAN
Model	X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00002858
Cover Note Number	

Driver

Name of Driver	LIM FATT SENG
NRIC No	S0210253F
Date Of Birth	14/07/1951
Occupation	INDOOR
Date Of Driving Pass	23/05/1977
Driving Experience	41 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98185816
Fax Number	
Contact Number	HOME-98185816
Email Address	NOEMAIL

Address	15 LORONG KISMIS #01-02 SINGAPORE 2159
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN:

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDN89Z
Vehicle Make/Model/Colour	AUDI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LOOI SWEE LIN LINDA
NRIC/Passport Number	S7401055E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2018-00002858 (Comprehensive - Prestige Plan)

Car plate number: SJG8855S

Your name (As the policyholder): Lim Fatt Seng

Coverage start date: 23/02/2018

Coverage end date: 22/02/2019

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company: Tan Chong Credit Pte Ltd

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 19/02/2018

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.

1844694

VNC No. S0210253F

15 LORONG KISMIS
#01-02
SINGAPORE 2159

Blood Group: O+ Date of Issue: 31-03-1994

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

<p>Class 2B Motorcycles <= 200 cc</p> <p>Class 2A Motorcycles between 201 cc and 400 cc</p> <p>Class 2 Motorcycles > 400 cc</p> <p>Class 3 Motor cars <= 3000 kg with <= 7 passengers, exclusive of the driver, and motor tractors</p> <p>Class 4 Vehicles <= 2500 kg</p>	<p>PASS DATE:</p> <p>18 Aug 1976</p> <p>18 Aug 1976</p> <p>18 Aug 1976</p> <p>23 May 1977</p>
--	---

Licence No: S0210253F

NP 428A

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S0210253F

Name: LIM FATT SENG

Race: CHINESE

Date of Birth: 14-07-1951

Sex: M

Country of Birth: SINGAPORE

REPUBLIC OF SINGAPORE

DRIVING LICENCE


Name: LIM FATT SENG

Licence Number: S0210253F

Birth Date: 14 Jul 1951

Issue Date: 12 Oct 2004

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS I EXIT CAR PARK (ORCHARD POINT/CUPPAGE PLAZA, I TURNED RIGHT. VEHICLE SDN 892 APPEARED BEHIND A PARKED LORRY AND MY VEHICLE COLLIDED ONTO SDN 892 FRONT DOOR.

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a **FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE** within the stipulated time frame from the day of the occurrence.

	- Reporting Only
	- Claim OD
	- Claim TP
✓	- Claim <u>OD</u> TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

Policyholder's signature
Date & Time

Driver's Signature
(if driver not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
Nric/Fin No.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Transfer Fee Enquiry

Page 1 of 1

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SJG8855S		
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1 :	With Sun Roof		
Vehicle Scheme :	Normal		
Vehicle Make :	NISSAN		
Vehicle Model :	X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR		
Chassis No. :	JN1JANT32Z0003041		
Propellant :	Petrol		
Engine No. :	MR20972478B		
Engine Capacity :	1997 cc		
Maximum Power Output :	106.0 kW (142 bhp)		
Maximum Laden Weight :	2190 kg		
Unladen Weight :	1626 kg		
Year Of Manufacture :	2016		
Original Registration Date :	23 Feb 2017		
Lifespan Expiry Date :	-		
COE Category :	E - Open Category		
Quota Premium :	\$48,556.00		
COE Expiry Date :	22 Feb 2027		
Road Tax Expiry Date :	22 Feb 2019		
PARF Eligibility Expiry Date :	22 Feb 2027		
Inspection Due Date :	22 Feb 2020		
Intended Transfer Date :	06 Jun 2018		
CO2 Emission :	178.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FWD SINGAPORE PTE LTD			Ref : CS3/FWD18010391/Nvd3e2-1	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4SINGAPORE 038986			Date : 05-09-2018	
			Code : FWD	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJG 8855S	Veh. Inspected	SDN 89Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	1201800006914	Excess (\$)	0.00	
Assign From	JOSEY LOH	Assign Date	02/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A3 SPORTBACK	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WAUZZZ8V7DA075440	Colour	WHITE	
Odometer	17506	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	225/40 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/40 R18	GOODYEAR	6 mm	
L/H Rear Tyre	225/40 R18	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/06/2018	Inspection Date	08/06/2018	
Survey held at	TARGET AUTO PTE LTD 160 SIN MING DRIVE #07-17 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDN 89Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,250.00	-
1	R/H FRONT BUMPER SIDE RETAINER	NOT NECESSARY	48.00	-
8	FRONT BUMPER CLIP	NOT NECESSARY	40.00	-
1	R/H FRONT FENDER	DENTED	955.00	800.00
1	R/H FRONT FENDER DUST COVER	SERVICEABLE	242.00	-
1	SET R/H FRONT FENDER DUST COVER CLIP	NECESSARY	40.00	40.00
1	R/H FRONT DOOR	DENTED	1,980.00	1,980.00
1	R/H FRONT DOOR WEATHERSTRIP	NECESSARY	189.00	150.00
1	R/H FRONT DOOR GLASS MOULDING	NOT NECESSARY	215.00	-
2	R/H FRONT DOOR HINGE	DENTED / BENT	240.00	150.00
1	R/H FRONT DOOR LOCK	DENTED / JAMMED	425.00	400.00
1	R/H FRONT DOOR REGULATOR GEAR	DENTED / DISTORTED	289.00	289.00
1	R/H FRONT DOOR REGULATOR GEAR MOTOR	NOT NECESSARY	455.00	-
1	R/H DOOR WING MIRROR	DAMAGED / CUT	1,185.00	1,185.00
1	R/H FRONT DOOR INNER TRIMBOARD	SERVICEABLE	798.00	-
1	R/H FRONT LOWER ARM	NOT NECESSARY	568.00	-
1	R/H FRONT KNUCKLE ARM	NOT NECESSARY	625.00	-
1	R/H FRONT KNUCKLE ARM BEARING	NECESSARY / BENT	298.00	298.00
1	R/H FRONT SHOCK ABSORBER	NOT NECESSARY	552.00	-
1	R/H FRONT DRIVESHAFT	SERVICEABLE	1,250.00	-
	LESS 10% DISCOUNT		-	-529.20
			11,644.00	4,762.80
<u>SPECIAL NETT ITEMS</u>				
1	R/H FRONT TYRE (SN)	SERVICEABLE	400.00	-
1	R/H FRONT WHEEL RIM (SN)	TO REPAIR SEE LABOUR	1,000.00	-
			1,400.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY. INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND R/H FRONT WHEEL RIM.		1,250.00	600.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.		1,300.00	800.00
	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL.		150.00	50.00
	TO REMOVE / RENEW R/H FRONT UNDERCARRIAGE.		450.00	150.00
	TO REMOVE / TRANSFER R/H FRONT DOOR MECHANISMS.		120.00	50.00
	TO WHEEL ALIGNMENT.		150.00	60.00
	TO CHECK WIRING FUNCTIONS.		50.00	30.00
			3,470.00	1,740.00
	GRAND TOTAL		16,514.00	6,502.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,200.00

Report Ref No. CS3/FWD18010391/Nvd3e2-1

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.