





### Workshops

59 Loyang Drive Singapore 508969  
383 Sin Ming Drive Singapore 575717  
45 Pandan Road Singapore 609286  
320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156  
7 Sungei Kadut Way Singapore 728791  
501 Yishun Industrial Park A Singapore 768732

member of COMFORTDELGRO

Date/Time: 02.08.2018 13:28 Page : 1

Team: ARC Repair TP(CLS0)1

### JOB CARD

Sales Order: 3844723

JC NO.: 305195274

TOMER

MS COMFORT TRANSPORTATION PTE LTD  
TOMER NO. 7010045  
RESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
(R) 65508755 (O)  
(P)

|                                          |                                         |
|------------------------------------------|-----------------------------------------|
| REGN NO.:<br><b>SHA7989B</b>             | MILEAGE                                 |
| MAKE :<br><b>HYUNDAI</b>                 | FUEL<br>E.....1/2.....F                 |
| MODEL<br><b>I-40</b>                     | DATE/TIME IN<br><b>02.08.2018 11:15</b> |
| YR OF MANU.<br><b>10.09.2015</b>         | TARGET DATE                             |
| CHASSIS CODE<br><b>KMHLB41UMGU077465</b> | COMPLETION DATE/TIME:                   |


COUNT CARD NO.

### JOB DESCRIPTION

Accident Date: 01.08.2018  
NATURE: 3P 01.08.18/B

S/NO LABOR CODE

### DESCRIPTION



CHECKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

B:  
IO.:  
le No.: **SHA7989B** **FZ AXA**

Vehicle No.: **SHA7989B**

e of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard