

ASS. REC. BY:

REF CS / AIG18014129/Gsd3ⁿ²

used instruction

Survivor's

From (Person):

Guo Qiong
Mithoo Singh

ASSIGNMENT (Office)

of AIG

Date/Time: 3/8/18 @ 11:22am.

Estimated Cost:

Bill to:

OD (IP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJX 5353D

Insured:

SLZ 5851Z

at Workshop m/s

Sin Wee Chuen

Tel:

6748 0573

of

Blk 3021A Ubi Rd 1 #01-40

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A.

31/07/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

11:47am @ 3/8/18

Person Contacted:

Mike

Vehicle IN

(OUT)

Date/Time	Action/Instruction (✓) Estimate
	SJX 5353D-X
	SLZ 5851Z-X
8/8/18	Dismantled.
	JAN: repair day.

ASSIGNMENT

From:

Date:

7/8/18

Estimated Cost:

OD: ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No:

SIX5353D

at Workshop m/s

Sin Wee chuan

of

Blk 3021A # 01-40 Ubi Rd 1

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SIX5353D Yr Regn: Sep / 2015

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Toyota Harrier c.c. 1986

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

9/4/10

T/Radio: Insured / Std / NI / NA

Eng/No:

854600054.777

C/No:

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/55 R18

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKG or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

07-08-18

Survey held at

w/s

1230 pm

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

07/8

Estimate given later.

\$4013.69

13/09/18

Confirmed P/P \$4,013.69 @ 5 days with XGR.
C\$4,431.58 Red - 52%

13/9/2018

RECEIVED 18 SEP 2018

Date/Time, File Pass to?

12/09/18

1) Typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 4,013.69 P/P)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS/AIG18014129/Gsd3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 03-08-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLZ 5851Z	Veh. Inspected	SJX 5353D
Policy No.	1800051197	Coverage (\$)	0.00
Claim No.	0569803283SG	Excess (\$)	0.00
Assign From	MITHOOSINGH	Assign Date	03/08/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	31/07/2018	Inspection Date	07/08/2018
Survey held at	SIN WEE CHUAN SPRAY PAINTING & SERVICE BLK 3021A #01-40 UBI RD 1 SINGAPORE 408715		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Your password will expire in 10 days. [Click here to change it.](#)

- Pre repair inspection request - SJX5353D VS SLZ5851Z (OI) DOA 31/07/2018

From: Mithoosingh, Aashweenjeetkaur

To: admin-a@lkkauto.com, assignments@lkkauto.com

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi

Sent: 3/8/2018 11:22:45 AM

Attachments:  SKMBT_C364e18080216460.pdf

Hi,

Please refer to the enclosed request from **CHEONGHOH LAW CORPORATION**.

Claim no : 0569803283SG003

Case Owner : WAN NUR SALIHA BINTE SYED YUSOFF

If you have any queries/concerns, please let us know.

Kindly assist to assign Xing Guo Qiang as Single Joint Expert as requested.

Thanks and regards,

Aashweenjeet Kaur (Aashween)

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]

Sent: Friday, August 03, 2018 11:09 AM

To: Mithoosingh, Aashweenjeetkaur

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi

Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLZ5851Z AND SJX5353D ON 31/07/2018 (Our ref: LCH.Ig/UB05-80691.18)

Dear Sirs,

We refer to the above matter and to your email of even date.

Kindly inform Xing Guo Qiang of LKK Auto Consultants Pte Ltd to contact Mr Mike Law at 6748 0573 from Sin Wee Chuan Spray Painting & Service Workshop, Blk 3021A Ubi Road 1 #01-40 Singapore 408715 for the necessary arrangement.

Thanks & regards

Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 3 Aug 2018, at 8:17 AM, Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com> wrote:

Without Prejudice

Your Reference : LCH.Ig/UB05-80691.18

Our Reference : 0569803283SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-

repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd

Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Aashweenjeet Kaur (Aashween)
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Cheonghoh Law [<mailto:mail@cheonghoh.sg>]
Sent: Thursday, August 02, 2018 4:53 PM
To: Supramaniam, Darshene; Abu Kassim, Noor Mariesa
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene; Chin, Lee-Ying
Subject: Re: PRS for SJX 5353 D involving vehicle SLZ 5851 Z on 31 July 2018 along Upper Serangoon Road (Our ref: LCH.lg/UB05-80691.18)

Dear Sirs,

We append below our letter of PRS and await your urgent reply.

Thanks & regards
Catherine
CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05
Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

Begin forwarded message:

From: c364@cheonghoh.sg
Subject: Message from KMBT_C364e
Date: 2 August 2018 at 4:46:18 PM SGT
To: mail@cheonghoh.sg
Reply-To: c364@cheonghoh.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.
<SKMBT_C364e18080216460.pdf>

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 18 September 2018 10:08 AM
To: 'Mike Law'
Cc: 'sur@lkkauto.com'
Subject: RE: SJX 5353 D Repair Quotation

Re-Send

Hi Mike,

Confirmed 5 days of repairs.

Final invoice and all supporting documents sent over to **AIG Asia Pacific Insurance Pte. Ltd.**

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Tuesday, 18 September 2018 10:03 AM
To: 'Mike Law' <mike_lawsw@yahoo.com.sg>
Cc: 'sur@lkkauto.com' <sur@lkkauto.com>
Subject: RE: SJX 5353 D Repair Quotation

Hi Mike,

Confirmed 4 days of repairs.

Final invoice and all supporting documents sent over to **AIG Asia Pacific Insurance Pte. Ltd.**

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mike Law [mailto:mike_lawsw@yahoo.com.sg]
Sent: Monday, 17 September 2018 12:09 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: Re: SJX 5353 D Repair Quotation

Hi , Shirley

We are please to accepted this offer. @

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 18 September 2018 10:03 AM
To: 'Mike Law'
Cc: 'sur@lkkauto.com'
Subject: RE: SJX 5353 D Repair Quotation

Hi Mike,

Confirmed 4 days of repairs.

Final invoice and all supporting documents sent over to **AIG Asia Pacific Insurance Pte. Ltd.**

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mike Law [mailto:mike_lawsw@yahoo.com.sg]
Sent: Monday, 17 September 2018 12:09 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: Re: SJX 5353 D Repair Quotation

Hi , Shirley

We are please to accepted this offer. @

\$ 4013.69. But the repair we need to increase to 5 working days .

Thank you

Sin Wee Chuan Spray Painting & SVS

Mike Law

Sent from my iPhone

On 14 Sep 2018, at 10:00 AM, Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Dear Mike,

Please confirm final fig \$4,013.69 @ 4 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

From: swc painting [mailto:mike_lawsw@yahoo.com.sg]

Sent: Thursday, 13 September 2018 3:48 PM

To: SUR <sur@lkkauto.com>

Subject: Re: SJX 5353 D Repair Quotation

On Thursday, 30 August 2018, 4:30:58 PM GMT+8, swc painting <mike_lawsw@yahoo.com.sg> wrote:

Hi Guo Qiang ,

For your action

Thank You

Mike Law

Sin Wee Chuan Spray Painting & Service

<ESTIMATE MARKED.pdf>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/08/2018 18:10
Date Of Accident	31/07/2018 18:30
Exact Location Of Accident	UPPER SERANGOON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJX5353D
Insured/Policyholder	
Name Of Registered Owner	CHIA GEK HUP
NRIC No	S1614577G
Email Address	MIKE_LAWSW@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-91897200
Alternative Phone No	OTHERS-91074888

Vehicle Particulars

Manufacturer	LEXUS
Model	HERRIER

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV010113232

Cover Note Number

Driver

Name of Driver	CHIA GEK HUP
NRIC No	S1614577G
Date Of Birth	01/11/1963
Occupation	INDOOR
Date Of Driving Pass	19/07/1993
Driving Experience	25 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91897200
Fax Number	
Contact Number	OTHERS-91074888
E Mail Address	MIKE_LAWSW@YAHOO.COM.SG

Address
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

SKETCH PLAN

Upper Serangoon Road Toward Hougang
(Near Porten Pasar)



A - STX 5353D


B - SL2 5851Z

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was driving along upper serangoon road toward
Hougang, suddenly a veh SL2 5851Z, HIT
onto my veh STX 5353D Rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

 2/8/18
Reporting Centre Personnel's Signature
Name:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

1-12-18

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Enquire Transfer Fee

Vehicle No. :	SJX5353D
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover
Vehicle Attachment 1 :	With Sun Roof
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model :	HARRIER PREMIUM 2.0 A
Chassis No.:	ZSU600054777
Propellant :	Petrol
Engine No.:	3ZRB623418
Engine Capacity :	1986 cc
Maximum Power Output :	111.0 kW (148 bhp)
Maximum Laden Weight :	1885 kg
Unladen Weight :	1610 kg
Year Of Manufacture :	2015
Original Registration Date :	25 Sep 2015
Lifespan Expiry Date :	-
COE Category :	B - Car above 1600cc or 97kW (130bhp)
Quota Premium :	\$62,101.00
COE Expiry Date :	24 Sep 2025
Road Tax Expiry Date :	24 Sep 2018
PARF Eligibility Expiry Date :	24 Sep 2025
Inspection Due Date :	24 Sep 2018
Intended Transfer Date :	15 Aug 2018
CO2 Emission :	133.00 (g/km)
CEV/VES Rebate Utilised Amount :	\$5,000.00
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

The current road tax expiry is 24 Sep 2018. You may renew the road tax from 25 Jun 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 24 Sep 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 25 Sep 2018 to 24 Mar 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	598.00	-	598.00
Total Amount Payable :			623.00
Amount Payable (From 25 Sep 2018 to 24 Sep 2019)			

	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	1,196.00	-	1,196.00
Total Amount Payable :			1,221.00

You may print this page for reference.

Print



SIN WEE CHUAN SPRAY PAINTING & SERVICE

BLK 3021-A, UBI ROAD 1, # 01-40, SINGAPORE 408715

TEL : 67480573 FAX : 67435192

GST M90357486J

Estimate No : 9227/18

20-08-2018

Accident Involving SJX 5353 D And SLZ 5851 Z on 31-07-2018

Re : Estimate Repair Bill For Veh No SJX 5353 D

Item	Description	Qty	U/Price	SSAmount
1.	Rear Bumper / <i>RE</i>	01		1,495.90 /
2.	Rear Bumper Spone / <i>CRA</i>	01		109.80 /
3.	Rear Bumper Carrier X <i>NN</i>	01		520.20 X
4.	Rear Bumper Lower Defuser / <i>SCR</i>	01		419.60 /
5.	Rear End Panel X <i>Repair</i>	01		781.30 X
6.	Rear Boot Lid / <i>buc</i>	01		1,559.62 /
7.	Rear Sensor / <i>DM</i>	1 02	280.00	560.00 <i>280</i>
8.	Boot lid Lamp L/H X <i>NN</i>	01		496.90 X
9.	Tail Lamp L/H X <i>NN</i>	01		631.95 X
10.	Clip / <i>NCL</i>	10	2.00	20.00 /
Parts Total				6,595.27 <i>3884.92</i>

Disc 25% : 2913.69

Labour Charge

Labour To Re-Spray	900.00	<i>600</i>
To Panel Beating /Remove & Install New Parts	650.00	<i>400</i>
To Remove & Install Rear Windscreen	300.00	<i>100</i>
Labour Charge	1,850.00	<i>1100</i>

Parts Total
Labour Charge
Parts & Labour
GST 7%
Grand Total

SS 6,595.27
SS 1,850.00
SS 8,445.27
SS 591.17
SS 9,036.44

4013.69

SIN WEE CHUAN SPRAY PAINTING & SERVICE

MIKE LAW 91074888

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

part by part .
4 Days .

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18014129/GSD3N2

Date: 25/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800051197
 Claimant Vehicle No : SJX5353D Insured Vehicle No : SLZ5851Z
 Date of Loss: 31/07/2018 Nature of Claim: TP Claim No: 0569803283SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJX5353D
 Make & Model: TOYOTA HARRIER, 2.0 Premium (A) Engine No: 3ZRB623418
 Reg. Date: 25/09/2015 (Man. Year: 2015) Chassis No: ZSU600054777
 Colour: Black Odometer: 91410 km
 Engine Capacity: 1986 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55R18 Rear Tyre Size: 235/55R18
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,595.27	2,913.69	3,681.58	55.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,100.00	750.00	40.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	8,445.27	4,013.69	4,431.58	52.47
+ GST 7.00/7.00% (\$\$)	591.17	280.96	310.21	52.47
Nett Amount (\$\$)	9,036.44	4,294.65	4,741.79	52.47

INSPECTION

Date of Assignment: 03/08/2018
 Date Inspected: 07/08/2018 Inspected At: Sin Wee Chuan Spray Painting & Service (HQ)
 Blk 3021A Ubi Road 1, #01-140
 Singapore 408715
 Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,495.90 F	*1,495.90 FL
2	1		*REAR BUMPER SPONE	Cracked	109.80 F	*109.80 FL
3	1		*REAR BUMPER CARRIER	Not Necessary	520.20 F	*- FL
4	1		*REAR BUMPER LOWER DEFUSER	Scratched	419.60 F	*419.60 FL
5	1		*REAR END PANEL	Repair	781.30 F	*- FL
6	1		*REAR BOOT LID	Buckled	1,559.62 F	*1,559.62 FL
7	1		*REAR SENSOR	Damaged (1 Pc only)	560.00 F	*280.00 FL
8	1		(2 Pcs) *BOOT LID LAMP L/H	Not Necessary	496.90 F	*- FL
9	1		*TAIL LAMP L/H	Not Necessary	631.95 F	*- FL
10	10		*CLIP	Necessary	20.00 F	*20.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,595.27	3,884.92
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	971.23
Total Parts (\$\$)	6,595.27	2,913.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO RE-SPRAY	New	900.00	600.00
2	TO PANEL BEATING/REMOVE & INSTALL NEW PARTS	New	650.00	400.00
3	TO REMOVE & INSTALL REAR WINDSCREEN	New	300.00	100.00
Gross Labour Cost (S\$)			1,850.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >