

22/03/2001

ASS. REC. BY:

REF: CS3/CT118014135/N24d312

Special Instruction:

Surveyor:

N92

ASSIGNMENT (Office)

From (Person):

Naimen
Janyan ty

of

CTI

Date/Time:

2/8/18 @ 2:04 pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

FZ64654

Insured:

GBD 2333G

at Workshop m/s

MCS Auto

Tel:

6296 4038 / 6296 9939

of

1100 Serangoon Rd

Policy No.:

DMCVSN 3049171700

Claim No.:

8NM18D03716C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 27/07/2018

CA / REV / REP. / REV 24 HRS

1up?

16/8/2018

H.O.D. Endorsement:

Date/Time:

2/8/18 @ 3:25 pm

Person Contacted:

Stephanie

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	FZ64654-X
	GBD 2333G - CS/CTI 18000728 / Nrd3n2 DOA: 8/01/2018
3/8/18	- vehicle still not in
7/8/18	- vehicle still not in
10/8/18	- vehicle still not in yet (5:30pm)
15/8/18	- vehicle in road camera on 16/8/18

ASSIGNMENT

From: _____ Date: 16/8/18

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FZ 64654

at Workshop m/s MCS Auto

of 1100 Surunguan Rd

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

/	
N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FZ 64654 Yr Regn: 13 SEP 2005

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KAWASAKI KR 150K c.c 148

Colour: RED A/C: Insured / Std / NI / NA

Sp. Reading: 62,600 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KR 150 EE A62443

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 80/90 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or METZELER

Front

Rear

R/Bal. 6 mm R/Bal. 5 mm

L/Bal. mm L/Bal. mm

D.O.A. 27/7/18 D.O.I. 16/8/18

Survey held at MCS AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT, N/S, O/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Estimated repair range \$3,800 - \$4,300
11/9/18	submit PRS report
	Range + No of days
	31/8/2018

Date/Time, File Pass to?

 : Preli. Report
 : Final Report

Days Of Repair: _____

1) Date/Time, File Return to?

Resurvey No. of Trip: -

Survey Fee: 150

2) _____

Add Fee:

 : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

150
150

Report Format: PRS

Lump Sum / I.B.I: (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS3/CTI18014135/Nz4d3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 03-08-2018	
		Code : CTI	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	GBD 2333G	Veh. Inspected	FZ 6465U
Policy No.	DMCVSN3049171700	Coverage (\$)	0.00
Claim No.	SNM18D03716C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	03/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	27/07/2018	Inspection Date	16/08/2018
Survey held at	MCS AUTO NO. 1100 SERANGOON ROAD SINGAPORE 328195		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Aug 2018		02 Aug 2018 14:04 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	IQUARTZ PTE LTD, Co. Reg. No.: 199901511H		
Main Claimant:	MOHAME HAIKAL ARSYAD BIN ALI AMRAN		
Vehicle Reg. No.:	FZ6465U	Date of Loss:	27/07/2018 12:00 - :59
Claim Type:	TP / SNM18D03716C02	Policy/Cover Note No.:	DMCVSN3049171700 (Comprehensive)
Vehicle Reg. No. (Insured):	GBD2333G	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Mcs Auto (HQ) 1100 Serangoon Rd, 328195 Serangoon - Tel: 62969939		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/08/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



CA 500557

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg No. 200412212G)
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
msig.com.sg

CERTIFICATE OF INSURANCE

Road Transport Act, 1987 (Malaysia)
The Motor Vehicles (Third Party Risks) Rules, 1959 (Federation of Malaysia)
The Motor Vehicles (Third Party Risks and Compensation) Act (CAP. 189 of the Revised Edition) (Republic of Singapore)
The Motor Vehicles (Third Party Risks and Compensation) Rules, 1996 Edition (Republic of Singapore)
Or any Amendment, Act or Acts passed in substitution thereof.

CERTIFICATE NO : MSD/VMT/17-367394-CA A0074-001/10209 6518268

SUM INSURED : TPL
EXCESS : NIL

1. Index mark and Registration Number of Vehicle **FZ6465U**
KAWASAKI 148 c.c.
2. Name of Policyholder **MOHAMED HAIKAL ARSYAD BIN ALI AMRAN**
3. Effective date of the Commencement of Insurance
for the purposes of the Act **1201AM 24/06/2018**
4. Date of Expiry of Insurance **03/08/2018**
5. Persons or Classes of Persons entitled to drive
 - a. The Policyholder.
 - b. **MOHAMED DANIEL ALFIAN BIN ALI AMRAN ONLY**



Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered and licensed under the Road Traffic Act and its registration and licensing under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitation as to Use

Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.


7. The Policy does not cover

1. Use for hire or reward.
2. Use for racing, pace-making, reliability trial or speed-testing.
3. Use for the carriage of goods (other than samples) in connection with any trade or business.
4. Use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia).

Repl CN: 72009130
25/01/2018 (SL)
CA/CI-03 (05/13)


COMMERCIAL AGENCY PTE. LTD.
Underwriting Agent
For MSIG Insurance (Singapore) Pte. Ltd.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9909577F



Name
**MOHAMED HAIKAL ARSYAD BIN
ALI AMRAN**



Race
MALAY

Date of birth
05-04-1999

Country/Place of birth
SINGAPORE

Sex
M



Licence Number: **S9909577F**
Name:
**MOHAMED HAIKAL ARSYAD BIN
ALI AMRAN**

Birth Date: **05 Apr 1999**
Issue Date: **19 Jun 2017**

002695345G



5339280

NRIC No. **S9909577F**



Date of issue
13-08-2014

Address
**APT BLK 348 UBI AVENUE 1
#02-1049
SINGAPORE 400348**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		EFFECTIVE DATE
Class 2B	Motorcycles <= 200 CC	19 Jun 2017
Class 2A	Motorcycles between 201 CC and 400 CC	19 Jul 2018
Class 3	Motor cars <= 3000 kg with <= 7 passengers, exclusive of the driver; and motor tractors/vehicles <= 2500 kg	30 Jan 2018

S / No. 9000317551

S9909577F

NP 428A



> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9577F
Vehicle Details	
Vehicle No.:	FZ6465U
Vehicle to be Exported:	No
Intended De-registration Date:	24 Aug 2018
Vehicle Make:	KAWASAKI
Vehicle Model:	KR150K
Primary Colour:	Red
Manufacturing Year:	2005
Engine No.:	KR150EEA62443
Chassis No.:	KR150KA62443
Maximum Power Output:	-
Open Market Value:	\$2,801.00
Original Registration Date:	13 Sep 2005
First Registration Date:	13 Sep 2005
Transfer Count:	15
Actual ARF Paid:	\$421.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jan 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,797.00
COE Rebate Amount:	\$1,017.00
Total Rebate Amount:	\$1,017.00

The information contained herein is correct as at 24 Aug 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/07/2018 13:47
Date Of Accident	27/07/2018 12:00
Exact Location Of Accident	OLD AIRPORT ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FZ6465U
-----------------------------	---------

Insured/Policyholder

Name Of Registered Owner	MOHAMED HAIKAL ARSYAD BIN ALI AMRAN
NRIC No	S9909577F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94241139
Alternative Phone No	OTHERS-94241139

Vehicle Particulars

Manufacturer	KAWASAKI
Model	KR150K-148CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	MSD/VMT/17-367394-CA
Cover Note Number	24/06/2018-03/08/2018

Driver

Name of Driver	MOHAMED HAIKAL ARSYAD BIN ALI AMRAN
NRIC No	S9909577F
Date Of Birth	05/04/1999
Occupation	INDOOR
Date Of Driving Pass	19/06/2017
Driving Experience	1 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-94241139
Fax Number	(LOCAL) +65-94241139
Contact Number	OTHERS-94241139
Email Address	NOEMAIL

Address	BLK 348 UBI AVENUE 1 #02-1049
Postcode	400348
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	KAMPONG UBI NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 9 EUNOS CRESCENT #01-2687 , POSTCODE: 400009 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7479999 - FAX NO: 67453410
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: T/20180727/2089.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	MELISSA
Phone Number	92972019
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD2333G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MOHAMED HAIKAL ARSYAD BIN ALI AMRAN
Approximate Age	19
Injuries Sustain	MULTIPLE ABRASIONS ON RT HAND & RT LEGS
Injured person in which vehicle?	FZ6465U
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time:




 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:



 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



Refer to Police Report
T/ 20180727/2089

veh A: F26465U
veh B: GBD2332G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A large rectangular area with horizontal lines for text entry. A diagonal line is drawn across the middle of the area. The text "Refer to Police Report" is written in cursive across the lower-left portion of the area.

DECLARATION


I/We declare the foregoing particulars are true in every respect.



 Policyholder's Signature
 Date & Time:



 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:



 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180727/2089

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

82-99 9939 1100 1800-7479999 ROAD 2 of 3

Report No. T/20180727/2089

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MOHAMED HAIKAL ARSYAD BIN ALI AMRAN	ID No.	S9909577F
Related Vehicle	FZ6465U (Motorcycle)	Contact No.	94241139
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details.

On the above mentioned date and time, I was travelling along Mountbatten Rd heading towards Kallang Leisure. After I passed by the junction of Old Airport Road and Mountbatten Road, I intended to change lane to the extreme left thus I signaled left before changing lane to the left. While I was in the midst of changing lane, I checked my blindspot on the left one more time to ensure that there was not incoming vehicle from the filter lane. However, as I turned to look to the front, I noticed a lorry (GBD2333G) suddenly came into my lane and jam brake thus I follow suit. However, it was too late for me so I swerved to my right to avoid colliding into the lorry. As such, my motorcycle had skidded and I fall off my bike. After which, the lorry did not stopped to assist me and continue driving off. There is no traffic police or ambulance at scene. I sustained abrasion and open wound on my right elbow and leg. My motorcycle had also sustained scratches, my cover set had loosen and my brake is not working. I wish to lodge this report for insurance claiming purposes.



Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 MANDRIC NGOH	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 27/07/2018 16:09
Officer In Charge Of Case: TP / AEIT / SI DZUL HAIRIE BIN RAMLI Contact No. 65476220	Classification Of Case:
Authentication Stamp NP168 	

Report No: T20190727/2000

400009
Tel No: 1800-7479999

CONTINUATION OF REPORT


Details of Person Involved		Use of Pedestrian Crossing: NA	
Any Pedestrian Involved: No		No of Pedestrians Injured: NIL	
Name	MOHAMED HAIKAL ARSYAD BIN ALI AMRAN	ID No.	S9909577F
Related Vehicle	FZ6465U (Motorcycle)	Contact No.	94241139
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details

On the above mentioned date and time, I was travelling along Mountbatten Rd heading towards Kallang Leisure. After I passed by the junction of Old Airport Road and Mountbatten Road, I intended to change lane to the extreme left thus I signaled left before changing lane to the left. While I was in the midst of changing lane, I checked my blindspot on the left one more time to ensure that there was not incoming vehicle from the filter lane. However, as I turned to look to the front, I noticed a lorry (GBD2333G) suddenly came into my lane and jam brake thus I follow suit. However, it was too late for me so I swerved to my right to avoid colliding into the lorry. As such, my motorcycle had skidded and I fall off my bike. After which, the lorry did not stopped to assist me and continue driving off. There is no traffic police or ambulance at scene. I sustained abrasion and open wound on my right elbow and leg. My motorcycle had also sustained scratches, my cover set had loosen and my brake is not working. I wish to lodge this report for insurance claiming purposes.

I wish to state that I have an eye witness by the name of Melissa (9397 2018).
Furthermore, I wish to state that I was already being followed when the lorry cut into my lane and did a hard brake.

Ju HAIKAL ARSYAD



Set 730045
Kampong Ubi NPP
Block 9 Eunus Crescent
101-2867 Singapore 400009
Tel: 1800-7479999

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Aug 2018		02 Aug 2018 14:04 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	IQUARTZ PTE LTD, Co. Reg. No.: 199901511H			
Main Claimant:	MOHAME HAIKAL ARSYAD BIN ALI AMRAN			
Vehicle Reg. No.:	FZ6465U	Date of Loss:	27/07/2018 12:00 - :59 [154 Months and 14 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM18D03716C02	Policy/Cover Note No.:	DMCVSN3049171700 (Comprehensive)	
Vehicle Reg. No. (Insured):	GBD2333G	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	Mcs Auto (HQ) 1100 Serangoon Rd, 328195 Serangoon - Tel: 62969939			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 14/08/2018]			
Adj Asg. Remarks:	NO EST, CASE W/O SJE.			

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*FZ6465U (SNM18D03716C02)
 [GBD2333G]
 TP
 MOHAME HAIKAL ARSYAD BIN ALI AMRAN
 Jul 27 2018 12:00PM
 [IQUARTZ PTE LTD]
 Mcs Auto

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	30/07/18 10:54	Accident Statement	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	30/07/18 10:16	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	30/07/18 10:16	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	30/07/18 10:16	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	30/07/18 10:16	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	30/07/18 10:16	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
2	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
3	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
4	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
5	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
6	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
7	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
8	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
9	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
10	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
11	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
12	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
13	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
14	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
15	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
16	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
17	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
18	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
19	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
20	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
21	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
22	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
23	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
24	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
25	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
26	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
27	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>
28	16/08/18 22:40	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/08/18 14:02	PRS WITH TP GIA	Load PDF	
2	02/08/18 14:03	OI GIA	Load PDF	

No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	30/07/18 10:15	Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	30/07/18 10:15	Sketch Plan #2 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	30/07/18 10:15	LIC [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	30/07/18 10:54	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	30/07/18 10:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	30/07/18 10:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	30/07/18 10:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	30/07/18 10:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	30/07/18 10:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	30/07/18 10:15	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	30/07/18 10:15	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>
3	30/07/18 10:15	LIC	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118014135/NZ4D3E2

Date: 04/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN3049171700	
Claimant Vehicle No: FZ6465U	Insured Vehicle No: GBD2333G	
Date of Loss: 27/07/2018	Nature of Claim: TP	Claim No: SNM18D03716C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FZ6465U		
Make & Model:	KAWASAKI KR150K, 148cc	Engine No:	KR150EEA62443
Reg. Date:	13/09/2005 (Man. Year: 2005)	Chassis No:	KR150KA62443
Colour:	Red	Odometer:	62600 km
Engine Capacity:	148 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80/90 R17	Rear Tyre Size:	80/90 R17
Front Left Side:	Metzeler 6 mm	Rear Left Side:	Metzeler 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	02/08/2018		
Date Inspected:	16/08/2018	Inspected At:	Mcs Auto (HQ) 1100 Serangoon Rd Singapore 328195
Estimated Period of Repair:	3.0 days		

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,800.00 -\$4,300.00

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 04 Sep 2018)
Parts:	N/A	KAWASAKI KR150K 148cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FZ6465U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >