

ASS. REC. BY:

REF: CS/GAI10014/46/4+d367

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Rachel Tan

of GAI

Date/Time: 3/8/18 @ 11:11 am

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLX 3571E

Insured: SGL 5880Y

at Workshop m/s Autolution

Tel: 6703 8691

of 19 Ubi Rd 4

Policy No:

Claim No: CLMOMVP000000811

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A. 16/07/2018

CA / REV / REP. / REV 24 HRS (up)

6/8/18 @ 10 am

Date/Time: 11:15 am @ 3/8/18

Person Contacted:

Elmer

H.O.D. Endorsement:

Vehicle: IN / ~~OUT~~

Date/Time	Action/Instruction (✓) Estimate
	SLX 3571E - X
	SGL 5880Y - X

ASSIGNMENT

From: Date: 06/08/18

Estimated Cost:

OT / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX3571E

at Workshop m/s: AutoLution

of: 19 Ubi Rd 4

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record) 10am @ owner waiting

Make of Veh: Elmer

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

PIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 1.8% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SLX3571E Yr Regn: 3, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer (CA)

Make: Nissan Note c.c. 1198

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 12912 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN1TAAE12X0980320

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 16/7/18 D.O.I. 6/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Rear o/s dented etc

9/1/19 Confirmed final by \$ 1031.96 with Elmer (led: 4513.20 (91%))

RECEIVED 09 JAN 2019

Date/Time, File Pass to?

9/1/19 Typist

Date/Time, File Return to?

2)

Preli. Report Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee: 250

Transportation:

S + RS, SI

Photos

Others

TOTAL

250
250

Add Fee: Site Insp (\$), Interview (\$), Tech. Invs (\$), Weekend (\$)

Report Format: TP

Lump Sum / I.B.I. (\$ 1031.96)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18014146/Utd3	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 03-08-2018	
		Code : GAI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGL 5880Y	Veh. Inspected	SLX 3571E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	RACHEL TAN	Assign Date	03/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	16/07/2018	Inspection Date	06/08/2018
Survey held at	AUTOLUTION INDUSTRIAL PTE LTD 19 UBI ROAD 4 SINGAPORE 408623		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## Nivitha (LKK Auto)

---

**From:** Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Sent:** Friday, 3 August 2018 11:11 AM  
**To:** elmer@tanchong.com  
**Cc:** hamzah\_saad@tanchong.com; LKK Assignments  
**Subject:** RE: Accident involving third party VEHICLE NO.: SLX3751E and our insured VEHICLE NO:SGL5880Y (GA) on 16.07.2018  
**Attachments:** SLX3571E-CI-EXPIRY 25.3.2019.tif; SLX3571E-ESTIMATE-16.7.2018.pdf; SLX3571E-ICDL.TIF; SLX3571E-SAS-16.7.2018.pdf

Without Prejudice

Dear Elmer

Thank you for taking my call. Our client has not reported the accident, we are unable to comment on liability and direct settlement.

As requested, we will arrange for LKK to conduct PRI on a without prejudice basis.

Dear LKK

Please accept assignment, attached documents for your reference.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

---

**From:** Ong, Joanna **On Behalf Of** General Claims

**Sent:** Friday, August 3, 2018 10:05 AM

**To:** Tan, Rachel <Rachel.Tan@sg.gaig.com>

**Subject:** FW: Accident involving third party VEHICLE NO.: SLX3751E and our insured VEHICLE NO:SGL5880Y (GA) on 16.07.2018

Hi Rachel,

FYNA.

Best regards,

**Joanna Ong**, Executive | P. +65 6804 6047 | F. +65 6235 3354 | [Joanna.Ong@sg.gaig.com](mailto:Joanna.Ong@sg.gaig.com)



**Claims** | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



**Moody's**  
**A1 (Good)**  
Affirmed December 2017

**Standard & Poor's**  
**A+ (Strong)**  
Affirmed February 23, 2018

**From:** Elmer Alfonso <[elmer@tanchong.com](mailto:elmer@tanchong.com)>

**Sent:** Thursday, August 02, 2018 4:06 PM

**To:** General Claims <[GeneralClaims@sg.gaig.com](mailto:GeneralClaims@sg.gaig.com)>

**Cc:** Hamzah <[hamzah\\_saad@tanchong.com](mailto:hamzah_saad@tanchong.com)>

**Subject:** [External] Accident involving third party VEHICLE NO.: SLX3751E and our insured VEHICLE NO:SGL5880Y on 16.07.2018

Dear Ma'am/Sir,

Good Morning,

Prior the above, my client wish to make third party claim against your insured, direct settlement with claiming for loss of use/vehicle rental . Can you Arrange survey on August 06 2018 Monday 10:00 am.

Kindly check your insured liability and revert.

Attachment are my client accident report and workshop estimate

Regards,

Elmer Alfonso

Autolution Industrial Pte Ltd

19 Ubi Road 4

S408623

Tel:[67038691](tel:67038691) EMAIL: [elmer@tanchong.com](mailto:elmer@tanchong.com)

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

## Denise Tay (LKKAuto)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Wednesday, 9 January 2019 4:51 PM  
**To:** Denise Tay (LKKAuto)  
**Subject:** FW: CLMOMVP000000811 - TP SLX3751E v SGL5880Y (GA) on 16.07.2018

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Elmer Alfonso [<mailto:elmer@tanchong.com>]  
**Sent:** Tuesday, 14 August 2018 4:15 PM  
**To:** Tan, Rachel <[Rachel.Tan@sg.gaig.com](mailto:Rachel.Tan@sg.gaig.com)>  
**Cc:** Hamzah <[hamzah\\_saad@tanchong.com](mailto:hamzah_saad@tanchong.com)>; LKK Assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Subject:** RE: CLMOMVP000000811 - TP SLX3751E v SGL5880Y (GA) on 16.07.2018

Hi Rachel,

Please be inform that the car number should be SLX3571E not SLX3751E.

Thank you for your kind and consideration.

Best Regards,

Elmer Alfonso

---

**From:** Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]  
**Sent:** Tuesday, 14 August 2018 2:13 PM  
**To:** Elmer Alfonso <[elmer@tanchong.com](mailto:elmer@tanchong.com)>  
**Cc:** Hamzah <[hamzah\\_saad@tanchong.com](mailto:hamzah_saad@tanchong.com)>; LKK Assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Subject:** RE: CLMOMVP000000811 - TP SLX3751E v SGL5880Y (GA) on 16.07.2018

Without Prejudice

Dear Elmer

Our client has reported accident. Based on the driver's sketch plan, liability is not in our favor.

Regards  
Rachel Tan  
Executive, Motor Claims, Great American Insurance Company  
Tel: 6804 7846

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	5213E
<b>Vehicle Details</b>	
Vehicle No.:	SLX3571E
Vehicle to be Exported:	No
Intended De-registration Date:	06 Aug 2018
Vehicle Make:	NISSAN
Vehicle Model:	NOTE 1.2 CVT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	HR12280350B
Chassis No.:	JN1TAAE12Z0980320
Maximum Power Output:	58.0 kW (77 bhp)
Open Market Value:	\$13,497.00
Original Registration Date:	26 Mar 2018
First Registration Date:	26 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Mar 2028
PARF Rebate Amount:	\$3,750.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	25 Mar 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,810.00
COE Rebate Amount:	\$35,464.00
<b>Total Rebate Amount:</b>	<b>\$39,214.00</b>

The information contained herein is correct as at 06 Aug 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/07/2018 14:53
Date Of Accident	16/07/2018 19:30
Exact Location Of Accident	YISHUN AVE 2 NEAR KHATIB MRT STATION
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX3571E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	METALLIC ENGINEERING (F.E) PTE LTD
Co Reg No	199705213E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-93976592

### Vehicle Particulars

Manufacturer	NISSAN
Model	NOTE-1.2 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA335786/1
Cover Note Number	

### Driver

Name of Driver	REDDY TILAK
NRIC No	S8660843Z
Date Of Birth	11/10/1986
Occupation	OUTDOOR
Date Of Driving Pass	02/09/2017
Driving Experience	0 YEAR AND 10 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-93976592
Fax Number	
Contact Number	
EMail Address	TILAK1986@HOTMAIL.COM

Address BLK 104A CANBERRA STREET #11-487  
 Postcode 751104  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1 NAME: : SATHYA  
 GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name WOODLANDS EAST N.P.C  
 Police Station Address ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

SEE ATTACHED SKETCH PLAN

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SGL5880Y  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

*[Signature]*  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]*  
Reporting Centre Personnel's Signature  
Name:  
NIC/FIN No.:  
SUZUKI MOTOR INDUSTRIAL PTE LTD  
19 UBI ROAD 4  
SINGAPORE 408623  
TEL: 6490 9666 FAX: 6848 7483



redefining / insurance

AXA Insurance Pte Ltd  
 1800 880 4888 (Within Singapore)  
 (65) 6880 4888 (International)  
 (65) 6880 4740  
 customer.care@axa.com.sg  
 www.axa.com.sg

# Certificate of Insurance

account number  
 03813

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 -Road Transport Act, 1987 (Malaysia)  
 -Motor Vehicles (Third-Party Risks ) Rules, 1959 (Malaysia)

## Policy details

Policyholder name	METALLIC ENGINEERING (F.E.) PTE LTD	Certificate number	GA335786 / 1
Cover	Comprehensive	Chassis number	JN1TAAE12Z0980320
Plan name	Flexi	Engine number	HR12280350B
NCD applicable	0%		
Vehicle registration number	SLX3571E		
Period of Insurance	from 26/03/2018 to 25/03/2019 (both dates inclusive)		
Finance loan company	HENLY ENTERPRISES CO (PTE) LTD		

## Persons or classes of persons entitled to drive\*

(a) Any Named Driver as stated in the Policy:

1. LOW SOO KWANG

(b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

## Limitation as to use\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	SGD 500.00
	Windscreen Excess	SGD 100.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

## Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

## Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the Insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period falling which there would be no liability under the policy, renewal certificate, endorsement etc.

Accident Reporting for Customer

Insured and Driver's particulars

Car Number : SLX 3571E  
Date of accident : 16-07-2018  
Time : 18:30  
Place : YISHUN AVENUE-2, Near KHATIB MRT STATION  
Email (Insured) \_\_\_\_\_  
Email (Driver) tilak 1986@hotmail.com  
Contact (Insured) +65  
Contact (Driver) +6593976592  
Alternative phone insured (home/office) \_\_\_\_\_  
Number of people inside car : 2 (including driver)  
1) REDDY DILAK (Male/Female)  
2) SATHYA (Male/Female)  
3) \_\_\_\_\_ (Male/Female)

Claiming under (Reporting, OD Claim, O/D Recovery, Third Party)

---

The Other Party particulars.

Car Number : SGL 5880Y  
Name : \_\_\_\_\_ (Optional)  
I/C No : \_\_\_\_\_  
Contact No : \_\_\_\_\_  
Weather (Fine/Raining)  
Any prosecution note or traffic summon from traffic police (Yes/No)

## SKETCH PLAN

### IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:  
INDUSTRIAL PTE LTD  
19 UBI ROAD 4  
SINGAPORE 408623  
TEL: 6490 9666 FAX: 6846 7483





Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 17/07/2018 01:29		Vide Report No.:		Station Diary No.: 26	
<b>Informant's Particulars</b>					
Name of Informant: REDDY TILAK			Address: APT BLK 104A CANBERRA STREET #11-487 SINGAPORE 751104		
ID Type / ID No.: NRIC NO / S8660843Z			Contact No.:		Mobile: 93976592
Nationality: INDIAN			Email:		
Sex: Male	Age: 31	Date of Birth: 11/10/1986	Type of Informant: Driver		
Race: Indian		Language: English		Institution / School Name:	
Occupation: QA/QC MANAGER		Driving Licence Information: Class: 2B,3		Date of Expiry:	

<b>General Information of the Accident</b>					
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 16/07/2018 18:30	Type of Location: Straight Road	
Location: Along Road 1 YISHUN AVENUE 2  NEAR TO KHATIB MRT STATION					
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGL5880Y	Car					0
SLX3571E	Car				Slightly Damaged	2

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

**CONTINUATION OF REPORT**

Driver			
Name	REDDY TILAK	ID No.	S8660843Z
Related Vehicle	SLX3571E (Car)	Contact No.	93976592
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 16/07/2018 at about 1830hrs, I was driving my car along Yishun Avenue 2. When I was near the speed camera, traffic was very slow and heavy. I then following the traffic, suddenly I felt an impact from my rear. The car then went beside me and signal to me sorry, after which he drove off. I then parked near the bus stop to checked for my damage, when I saw that my car rear have dent and scratches, I tried to follow him but unable to do so due to heavy traffic.

After the accident, I went home and told my father in law about this and he informed that to lodged Police within 24 hour therefore I came to the nearby Police station to make a Police report. I wish to informed that there was a in build camera in my car however it was not recording as there was a memory card in my camera however it was full when the accident happened.



**SINGAPORE  
POLICE FORCE**



T/20180717/2008

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

3 of 3


Report No. T/20180717/2008

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: J/ Sgt 1 GLENN KUAN YONG SHENG 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 17/07/2018 01:29
Officer In Charge Of Case: TP/HRTY SIKALESWARI PALANI Contact No: 65476902  Authentication Stamp NP168 Singapore Police Force	Classification Of Case:

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S8660843Z



Name: REDDY TILAK



Race  
INDIAN  
Date of birth  
11-10-1986  
Country/Place of birth  
INDIA

Sex  
M



REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S8660843Z

Name:

REDDY TILAK

Birth Date: 11 Oct 1986

Issue Date: 02 Sep 2017



9453825



NRIC No. S8660843Z



Nationality  
INDIAN  
Date of issue  
02-08-2017

APT BLK 104A CANBERRA STREET #11-487  
SINGAPORE 751104

NRIC No: S8660843Z Date: 16/03/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 2B Motorcycles =< 200 cc	07 Nov 2016
Class 3 Motor cars with unladen weight =< 3000kg with =< 7 passengers, exclusive of driver; and other motor vehicles with unladen weight =< 2500kg	02 Sep 2017



AUTOLUTION INDUSTRIAL PTE LTD  
19 UBI ROAD 4  
SINGAPORE 408623  
TEL: 65 6390 9666 FAX: 6843 7122

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0420/18  
DATE : 17-JUL-2018

GREAT AMERICAN INSURANCE COMPANY  
3 TEMASEK AVENUE  
#16-01 CENTENNIAL TOWER  
S(039190)  
TEL : 68046059  
FAX : 62353354  
ATTN: MOTOR CLAIM MANAGER

OWNER'S NAME : M/S METALLIC ENGRG (FE) P L  
ADDRESS : 002 LORONG B TOA PAYOH  
#04-1477 TOA PAYOH INDUSTRIAL PARK  
S(319074)  
TELEPHONE NO : 93469774/93976592

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO :  
VEHICLE NO : S1X3571E  
MODEL CODE : TDWARDZE12EDAY487Z  
MODEL/YEAR : NOTE 1.2 BASE (IV) MY2017  
ENGINE NO : W12280350B  
CHASSIS NO : JH1TAAE12Z0980320  
MILEAGE : 11004 KM  
DATE IN : 17/07/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : ELMER - 67038691  
ACCIDENT DATE : 05/07/2018

*Not Attached  
Loh  
marcus  
Tel: 67418434  
6/8/18  
2-3 days  
Take photo before parting.*

*email: elmer@tamchong.com*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLX3571E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR REAR END PANEL, RENEW REAR BUMPER, RENEW HATCH BACK DOOR	1950.00	390 .
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	800.00	250 .
3	ZZ/003	REMOVE AND TRANSFER HATCHBACK DOOR GLASS TO THE NEW HATCHBACK DOOR	150.00	X
4	ZZ/004	REMOVE AND TRANSFER HATCHBACK DOOR MECHANISM	80.00	X
5	ZZ/006	SUPPLY REAR LICENSE PLATE		
6	ZZ/007	REMOVE AND TRANSFER REVERSE CAMERA TO THE NEW HATCHBACK DOOR	240.00	X
7	ZZ/008	RENEW REVERSE SENSOR 2 EYE	55.00	✓
8	ZZ/009	APPLY SEALANT TO HATCHBACK DOOR GLASS	120.00	X
9	ZZ/10	APPLY SEALANT TO HATCHBACK DOOR	120.00	X
TOTAL LABOUR CHARGES			3515.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLX3571E

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	SUNDRIES	NPN		11	50.00	X
2	REAR LICENCE PLATE	RLP		11	80.00	X
3	REAR W/SCREEN SEALANT	SEALANT - 4		11	80.00	X
4	REAR W/SCREEN GLASS MOULDING	90352-3VA0A	11	65.70		X
5	REAR W/SCREEN CORENER MOULDING RH	90374-3VA0A	11	29.60		X
6	REAR W/SCREEN LOWER MOULDING LH	90375-3VA0A	11	29.60		X
7	ORNAMENT-BACK DOOR-NOTE	90892-3VA0A	11	73.60		X
8	EMBLEM-BACK DOOR-NISSAN	90890-3VA0A	11	59.70		X
9	REAR HATCH BACK DOOR	K010M-3VAMA	11	976.40		X
10	SENSOR-REVERSE	SENSOR		11	250.00	X
11	REAR REINFORCEMENT BUMPER	85064-1A92A	11	105.00		X
12	ENERGY ABSORBER REAR BUMPER	85090-3VA0A	11	111.90		X
13	LH REAR BUMPER SIDE BRACKET	85221-3VA0C	11	45.00		X
14	RH REAR BUMPER SIDE BRACKET	85220-3VA0C	11	45.00		X
15	CLIP REAR BUMPER @1.20 EACH	01553-10501	new	7.20		—
16	REAR BUMPER FASCIA	85022-3VA0H	ex/cus	414.00		—
SUB TOTAL:				1962.70	0.00	460.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)				392.54	0.00	0.00
GRAND TOTAL				1570.16	0.00	460.00
OVERALL TOTAL				2030.16		

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLX3571E

TOTAL LABOUR CHARGES	3515.00
TOTAL SPARE PARTS CHARGES	2030.16
GRAND TOTAL	5545.16 *

\* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

AUTOLUTION INDUSTRIAL PTE. LTD.

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : 195/1075A/0420/1B  
DATE : 17 JUL 2016

GREAT AMERICAN INSURANCE COMPANY  
3 TEMASEK AVENUE  
#16-01 CENTENNIAL TOWER  
S1039190)  
TEL : 68046059  
FAX : 62353354  
ATTN: MOTOR CLAIM MANAGER

*3 days*

OWNER'S NAME : M/S METALLIC ENGRG (FE) P L  
ADDRESS : 1002 LORONG 8 TOA PAYOH  
#04-1477 TOA PAYOH INDUSTRIAL PARK  
S1319074)  
TELEPHONE NO : 98469774/93996592

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO : -  
VEHICLE NO : S1335710  
MODEL CODE : TWARDZE12E0A4872  
MODEL/YEAR : NHTA 1.2 BASE (IV) MY2017  
ENGINE NO : H01228035/8  
CHASSIS NO : JH1TAAE1210980320  
MILEAGE : 11004 KM  
DATE IN : 17/07/2016  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : ELPER  
ACCIDENT DATE : 06/07/2016

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLX3571E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO RENEW REAR BUMPER	1950.00	390.00
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	800.00	250.00
3	ZZ/003	REMOVE AND TRANSFER HATCHBACK DOOR GLASS TO THE NEW HATCHBACK DOOR	150.00	.00
4	ZZ/004	REMOVE AND TRANSFER HATCHBACK DOOR MECHANISM	80.00	.00
5	ZZ/006	SUPPLY REAR LICENSE PLATE		
6	ZZ/007	REMOVE AND TRANSFER REVERSE CAMERA TO THE NEW HATCHBACK DOOR	240.00	.00
7	ZZ/008	RENEW REVERSE SENSOR 2 EYE	55.00	55.00
8	ZZ/009	APPLY SEALANT TO HATCHBACK DOOR GLASS	120.00	.00
9	ZZ/10	APPLY SEALANT TO HATCHBACK DOOR	120.00	.00
TOTAL LABOUR CHARGES			3515.00	695.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLX3571E

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
			NETT	LIST	S/NETT	REMARKS
1	REAR HATCH BATT DOOR	K010M-3VAMA	976.40			X
2	RH REAR BUMPER SIDE BRACKET	B5220-3VAOC	45.00			X
3	C.O.P REAR BUMPER BR.20 EACH	01553-10501	7.20			OK
4	REAR BUMPER FASCIA	B5022-3VAOH	414.00			OK
5	SUNRISES	NPN			50.00	X
6	REAR LICENSE PLATE	RLP			80.00	X
7	REAR W/SCREEN SEALANT	SEALANT - 4			80.00	X
8	REAR W/SCREEN GLASS MOLDING	90352-3VAOA	65.70			X
9	REAR W/SCREEN STRENER MOLDING RH	90374-3VAOA	29.60			X
10	REAR W/SCREEN LOWER MOLDING LH	90375-3VAOA	29.60			X
11	ORNAMENT-BACK DOOR-NOTE	90892-3VAOA	73.60			X
12	EMBLEM-BACK DOOR-NISSAN	90890-3VAOA	59.70			X
13	SENSOR REVERSE	SENSOR			250.00	X
14	REAR REINFORCEMENT BUMPER	B5064-1AS2A	105.00			X
15	ENERGY ABSORBER REAR BUMPER	B5090-3VAOA	111.90			X
16	LH REAR BUMPER SIDE BRACKET	B5221-3VAOC	45.00			X
SUB TOTAL			421.20	0.00	0.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			84.24	0.00	0.00	
GRAND TOTAL			336.96	0.00	0.00	
OVERALL TOTAL			336.96			

LEGEND: REMARKS: OK = APPROVED, REMARKS: X, J = NOT APPROVED

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLX3571E

NETT ITEM	421.20
LESS 20.00%	84.24
NETT AMOUNT	336.96
LIST ITEM	0.00
LESS 20.00%	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	0.00
LESS 20.00%	0.00
SPECIAL NETT AMOUNT	0.00
TOTAL LABOUR CHARGES	695.00
TOTAL SPARE PARTS CHARGES	336.96
TOTAL CHARGES	1031.96
ADD 7 % GST	72.24
GRAND TOTAL	1104.20



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18014146/Utd3e2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 11-01-2019	
Code : GAI			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGL 5880Y	Veh. Inspected	SLX 3571E
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVP000000811	Excess (\$)	0.00
Assign From	RACHEL TAN	Assign Date	03/08/2018
2. Vehicle Particulars & Condition			
Make & Model	NISSAN NOTE (A)	c.c	1198
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JN1TAAE12Z0980320	Colour	SILVER
Odometer	12912	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/65 R15	CONTINENTAL	6 mm
L/H Front Tyre	185/65 R15	CONTINENTAL	6 mm
R/H Rear Tyre	185/65 R15	CONTINENTAL	6 mm
L/H Rear Tyre	185/65 R15	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/07/2018	Inspection Date	06/08/2018
Survey held at	AUTOLUTION INDUSTRIAL PTE LTD 19 UBI ROAD 4 SINGAPORE 408623		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 3571E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR W/SCREEN GLASS MOULDING (N)	NOT NECESSARY	65.70	-
1	REAR W/SCREEN CORENER MOULDING RH (N)	NOT NECESSARY	29.60	-
1	REAR W/SCREEN LOWER MOULDING LH (N)	NOT NECESSARY	29.60	-
1	ORNAMENT-BACK DOOR-NOTE (N)	NOT NECESSARY	73.60	-
1	EMBLEM-BACK DOOR-NISSAN (N)	NOT NECESSARY	59.70	-
1	REAR HATCH BACK DOOR (N)	NOT NECESSARY	976.40	-
1	REAR REINFORCEMENT BUMPER (N)	NOT NECESSARY	105.00	-
1	ENERGY ABSORBER REAR BUMPER (N)	NOT NECESSARY	111.90	-
1	LH REAR BUMPER SIDE BRACKET (N)	NOT NECESSARY	45.00	-
1	RH REAR BUMPER SIDE BRACKET (N)	NOT NECESSARY	45.00	-
6	CLIP REAR BUMPER @\$1.20 (N)	NECESSARY	7.20	7.20
1	REAR BUMPER FASCIA (N)	DEFORMED / CUT	414.00	414.00
	LESS 20% DISCOUNT		-392.54	-84.24
			1,570.16	336.96
<b>SPECIAL NETT ITEMS</b>				
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
1	REAR LICENCE PLATE (SN)	NOT NECESSARY	80.00	-
1	REAR W/SCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	SENSOR-REVERSE (SN)	NOT NECESSARY	250.00	-
			460.00	-
<b>LABOUR</b>				
	LABOR CHARGES TO REPAIR REAR END PANEL, RENEW REAR BUMPER, RENEW HATCH BACK DOOR.		1,950.00	390.00
	CHARGES TO SPRAY PAINTING SAME.		800.00	250.00
	REMOVE AND TRANSFER HATCHBACK DOOR GLASS TO THE NEW HATCHBACK DOOR.	NOT NECESSARY	150.00	-
	REMOVE AND TRANSFER HATCHBACK DOOR MECHANISM.	NOT NECESSARY	80.00	-
	REMOVE AND TRANSFER REVERSE CAMERA TO THE NEW HATCHBACK DOOR.	NOT NECESSARY	240.00	-
	RENEW REVERSE SENSOR 2 EYE.		55.00	55.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	APPLY SEALANT TO HATCHBACK DOOR GLASS.	NOT NECESSARY	120.00	-
	APPLY SEALANT TO HATCHBACK DOOR.	NOT NECESSARY	120.00	-
			3,515.00	695.00
<b>GRAND TOTAL</b>			<b>5,545.16</b>	<b>1,031.96</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,031.96</b>

Report Ref No. CS/GAI18014146/Utd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.