

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Gerene Ler

of

FCI

Date/Time: 3/8/18 @ 2-40pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV/CS

To Inspect Vehicle No:

XE 3122B

Insured:

SH 66597

at Workshop in/s:

ASM Automotive

Tel:

92368218

of

No. 2 Kwong Min Road

Policy No:

Claim No:

D18005783MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 30/07/2018

CA / REV / REP. / REV 24 HRS

(DS)

Date/Time: 3:51pm @ 3/8/18

Person Contacted:

Jaclyn

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	XE 3122B-X
	SH 66597-CS3/FCI16014087/R1/bc2 DOA: 24/7/16
6/8/18 -	called wherp vehicle still not in yet (Jaclyn)
10/8/18 -	called wherp vehicle still not in yet (Jaclyn)
15/8/18 -	called Jaclyn vehicle still not in yet -
30/9/18	VNI yet

30/11/18- vehicle still not h.

7/12/18- VNI (due to unavailability of).
owner pending survey

P. J. M.


FCI

113972

Accident Report

Date: 22/2/19
Estimated Cost:
OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To Report Vehicle No: XE 3122 B
at Workshop no: ASM Automotive
at: 13 pioneer sector 1
Insured:
Policy No:
Claim No:
Sum Insured:
Excess:
(Client's Record)
Make of Veh:

(Policy Condition)
Remarks: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:
IDAG Accident Report: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 2 days Res: Yes or No
Turn Sum: % 3 Val: Yes or No
GA / REV / REP. / 24 HRS (DS)
Date: Person Contacted:
Vehicle: IN / OUT

Vehicle: XE 3122 B
Type: ☒ Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
☒ Truck / ☐ Trailer or
Make: Scania P400 LA
Colour: Blue
Sp. Boarding: 166124
Eng No:
Ch No: 452P4X2005463605
Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ Burnt
Steering: ☒ Harder / ☐ Jammed / ☐ Leaked / ☐ Burnt or
Brake: ☒ Harder / ☐ Jammed / ☐ Leaked / ☐ Burnt or
Mod: ☒ Nil / ☐ 5/Rim / ☐ STD A/Rim or
Tyre Size: F: 315/80 R22.5
R:
BS / DUN / EXNOVA / ☒ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /
TOYO / YOKO or
Front: Rear:
R/Bal: 8 mm R/Bal: 8/8 mm
L/Bal: 8 mm L/Bal: 8/8 mm
D.O.A: 30/07/18 D.O.I: 22/02/19
Survey held at: ASM Automotive
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S FR
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: 22/2/19 @ 11:00 AM Action/Instruction: Revised to severe loss by email.

Basal Analysed final fig @ 1662.37, 2 days.
(Red @ 571.90 + 24%)

RECEIVED 12 MAR 2019

Date/Time: File Pass to: ☐ : Preli. Report
12/3/19 *P. J. M.* ☐ : Final Report

Date/Time: File Return to:

By:

Report Format:

Lump Sum / L.B. @:

7P
1662.37

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp. @
☐ Interview @
☐ Tech. Fees @
☐ Weekend @

Survey Fee:

Transportation:

Food & Refreshment:

Hotel:

Other:

Total:

110
50
50
37
247



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005783MFSH

Date: 25 February 2019

Our Ref: CS/FCI18014155/R1qd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. XE 3122B .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/02/2019 at the premises of M/s ASM AUTOMOTIVE . and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,184.27</u> .
Revised Estimate Amount	: S\$ <u>1,662.37</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the n/s front portion.



Yours faithfully

Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	31-07-2018	Our Ref No. D18005783MFSH
Accident Date	30-07-2018	Claim Type. Third Party
Insured Vehicle	SH6659T	Third Party Vehicle. XE3122B
Survey Location	NO 2, KWONG MIN ROAD	
Contact Person.	JACLYN LAI	
Contact No.	62650980/ 92368218	Fax No. 62656068
Survey Type	DIRECT SETTLEMENT: EST. COR - \$2,184.27	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ASM AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: ASM Jaclyn <jaclynlai@asmauto.com.sg>
Sent: Friday, 1 March 2019 4:23 PM
To: Rasul (LKKAuto)
Cc: SUR
Subject: Finalization: XE3122B (TP claim - MS FCI)
Attachments: IMG_20190223_151822.jpg; IMG_20190223_151839.jpg; IMG_20190223_151850.jpg; IMG_20190223_151858.jpg; IMG_20190223_151903.jpg; IMG_20190223_151910.jpg; IMG_20190223_151914.jpg; IMG_20190223_151922.jpg; IMG_20190223_151928.jpg; IMG_20190223_151946.jpg

Dear Rasul,

Kindly refer attached before paint and damaged parts' photos.

COR pbp \$1,662.37 and 2 days. Please confirm.

Thank you

*Our office & workshop is now at **No. 13 Pioneer Sector 1, Singapore 628424.***

***All contact numbers and fax number are remain unchanged.*

Best Regards,

Jaclyn Lai


Motor Claims Executive

ASM Automotive Services Pte Ltd

No. 13, Pioneer Sector 1, Singapore 628424.

Hp: 9236 8218 | DID: 6265 0026 | Fax: 6265 6068

Web: www.asmauto.com.sg



Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 25 February 2019 2:11 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005783MFSH/1
Attachments: CSFCI18014155R1qd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of XE 3122B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 3 August 2018 3:53 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005783MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 3 August 2018 2:39 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005783MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014155/R1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 13-03-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6659T	Veh. Inspected	XE 3122B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005783MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	03/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	SCANIA P400LA	c.c	12742	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	YS2P4X20005463605	Colour	BLUE	
Odometer	166124	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	315/80 R22.5	GOODYEAR	8 mm	
L/H Front Tyre	315/80 R22.5	GOODYEAR	8 mm	
R/H Rear Tyre	315/80 R22.5 (D)	GOODYEAR	8/8 mm	
L/H Rear Tyre	315/80 R22.5 (D)	GOODYEAR	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/07/2018	Inspection Date	22/02/2019	
Survey held at	ASM AUTOMOTIVE SERVICES PTE LTD 2 KWONG MIN ROAD SINGAPORE 628705			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 3122B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER,LHS	BENT	1,050.00	1,050.00
1	END PIECE,LHS	SCRATCHED	95.30	95.30
1	STEP COVER,CENTER LHS	SERVICEABLE	191.00	-
1	STEP PLATE,LOWER LHS	SCRATCHED	424.00	424.00
	LESS 10% DISCOUNT		-176.03	-156.93
			1,584.27	1,412.37
LABOUR				
	TO REMOVE AND REPLACE DAMAGED PARTS,JACK AND STRAIGHTEN STEP BERACKET.		350.00	200.00
	SPRAY PAINTING.		250.00	50.00
			600.00	250.00
GRAND TOTAL			2,184.27	1,662.37
RECOMMENDED COST OF REPAIRS				1,662.37

Report Ref No. CS/FCI18014155/R1qd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.