Surveyor NAZ | REF: AIG | TAX/07/18/2141

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

	N/S	O/S
X		

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHB 5760B Yr Regn: 12 DEC 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA PRIUS c.c 1798

Colour BROWN A/C: Insured / Std / NI / NA

Sp.Reading 63401 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTDKB3FU903575842

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or YOKOHAMA (R), FALKEN (F)

Front		Rear	
R/Bal.	6 mm	R/Bal.	5 mm
L/Bal.	6 mm	L/Bal.	5 mm

D.O.A. 28/7/18 D.O.I. 2/8/18

Survey held at SMRT WOODLANDS

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	AIG P/P

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation: S + RS. SI

Photos

Others

TOTAL