

ASS. REC. BY:

REF CS3/AG18014241/B2403

Special Instruction:

Surveyor

TG. Lim

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of AG

Date/Time: 6/8/18 @ 11:22am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 536C

Insured:

SLK 9716J

at Workshop m/s:

Sin Sang Hong Spray

Tel:

9627 8521

of

31K 3022A # 01-53 Ubi Rd 1

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

1/8/2018

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time:

6/8/18 @ 12:06pm

Person Contacted:

Andy

Vehicle:

IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLK 9716J - NA/INC18014177/24

D.O.A: 1/8/2018

SLX 536C - NA/INC18014177/24

D.O.A: 4/8/2018

5/9/18

After Repair

Range: 6000z - 10000z

3DR? repair days?

Repair days 3

(08/11/13) wef
ASS. REC. BY: *

REF: ALG

ASSIGNMENT

From: Date: 13/08/2018

Estimated Cost:

On (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX 536C

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLX 536C Yr Regn: 2 Feb / 2009

Type: (M) Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Avante C.C 1591

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 303.7 trip B T/Radio: Insured / Std / NI / NA

Eng/No: G4C9U

C/No: KMHDU41BR9U690284

Gen. Cond: (Good) Fair / Poor / Burnt

Steering: (in order) Jammed / Leaked / Burnt or

Brake: (in order) Jammed / Leaked / Burnt or

Modi: Nil / (S/Rim) / STD A/Rim or

Tyre Size: F: 195/50R15

R: 195/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. D.O.I. 13/8/18 1125

Survey held at LKK Auto Consultants Pte Ltd

Des. of Damages: Frt / (Rear) O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/8/18 Submit DAR Report

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee:

Transportation:

___ S + RS, ___ SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

TG Lim

him 15/8/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18014241/Bz4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 06-08-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLK 9716J	Veh. Inspected	SLX 536C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	06/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	04/08/2018	Inspection Date
Survey held at	SIN SENG HONG SPRAY PAINTING & SERVICES BLK 3022A UBI ROAD 1 #01-53 . SINGAPORE 408716	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Your password will expire in 7 days. [Click here to change it.](#)

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying

To: assignments@lkkauto.com, Admin A

Cc: Fong, Andy-SY

Sent: 6/8/2018 11:22:03 AM

Attachments:  tmp8083.tif  LIST OF INDEPENDENT SURVEYORS.DOCX

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors **Commissioner For Oaths** **Notary Public**
UEN NO : 201523418E
(a law corporation with limited liability)

161 CHIN SWEE ROAD #14-15/16
 MANHATTAN HOUSE
 SINGAPORE 169876
 TEL : (65) 6532 2455
 FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: thling@tcmg.com.sg;mdmling@tcmg.com.sg

Our Ref: TCMG/SLX536C/0818/SSH

Your Ref: SLK 9716 J

6 August 2018

M/s AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way #07-16
 AIG Building
 Singapore 079120
 Singapore 068811

BY FAX NO. 6835-7416 ONLY

Attn: Motor Claims Department

Dear Sirs,

PRE-REPAIR INSPECTION NOTICE

We act for **M/s Torque Concept**, the owner and/or driver of motor vehicle no. **SLX 536 C**, which was involved in an accident along Elias Road junction Pasir Drive 1 on 4 August 2018 at 13:25 hrs.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. **SLK 9716 J** for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Sin Seng Hong Spray Painting & Service, (3022A #01-53, Ubi Road 1, Singapore 408716 - Andy Yeo @ 9627 8521).

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.

Yours faithfully,


MR LING LEONG HUI

cc. M/s Sin Seng Hong Spray Painting & Svc
 (Yref: SLX536C)

BY E-MAIL ONLY

DIRECTOR : LING LEONG HUI

CONSULTANTS : TOMMY CHOO TUCK SOON
 POOTS LAURENCE JAMES

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GAA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if requested.

ACCIDENT STATEMENT

Date Of Report 04/08/2018 14:52
Date Of Accident 04/08/2018 13:25
Exact Location Of Accident JUNG ELIAS RD & PASIR RIS DR 1
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLX538C
Insured/Policyholder
Name Of Registered Owner TORQUE CONCEPT
Co Reg No 53276051E
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-91729140
Alternative Phone No OFFICE-91729140

Vehicle Particulars

Manufacturer HYUNDAI
Model HD AVANTE 1.6 A
Exact Purpose for which vehicle was being used at time of accident COMMERCIAL USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Excess Policy NO
Policy Number 5099234344
Cover Note Number

Driver

Name of Driver JULIAN CHIA CHUN HAO
NRIC No S9340295B
Date Of Birth 27/10/1993
Occupation INDOOR
Date Of Driving Pass 25/03/2013
Driving Experience 5 YEARS AND 4 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-88236044
Fax Number
Contact Number OFFICE-88236044
Email Address NOEMAIL

BLK 7 TAMPINES AVENUE 8
#07-12
529597

Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle
Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance NO
Number of Passengers (including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

ON STATED DATE AND TIME, MY VEHICLE WAS STATIONARY STOPPED ALONG LANE 1 ELIAS RD AS THE TRAFFIC JUNCTION WAS RED. SUDDENLY I FELT AN IMPACT OF MY VEHICLE. I ALIGHT FROM MY VEHICLE AND REALIZE THAT VEHICLE B HIT ONTO MY VEHICLE REAR PORTION.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLK97153
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver JAMES LAU OON BENG (LIU EN MING)
NRC/Passport Number S17457158
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (including Driver) 1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **rescind policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the signing of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my interactions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information to be collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Person(s) Signature
Name:
NRIC/IN No.:

Accident Sketch Plan

SKETCH PLAN



A. SLX576C

BTLE9216J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

to Jan	Jan	to Feb
1	2	3
4	5	6
7	8	9
10	11	12
13	14	15
16	17	18
19	20	21
22	23	24
25	26	27
28	29	30
31	32	33
34	35	36
37	38	39
40	41	42
43	44	45
46	47	48
49	50	51
52	53	54
55	56	57
58	59	60
61	62	63
64	65	66
67	68	69
70	71	72
73	74	75
76	77	78
79	80	81
82	83	84
85	86	87
88	89	90
91	92	93
94	95	96
97	98	99
100	101	102
103	104	105
106	107	108
109	110	111
112	113	114
115	116	117
118	119	120
121	122	123
124	125	126
127	128	129
130	131	132
133	134	135
136	137	138
139	140	141
142	143	144
145	146	147
148	149	150
151	152	153
154	155	156
157	158	159
160	161	162
163	164	165
166	167	168
169	170	171
172	173	174
175	176	177
178	179	180
181	182	183
184	185	186
187	188	189
190	191	192
193	194	195
196	197	198
199	200	201
202	203	204
205	206	207
208	209	210
211	212	213
214	215	216
217	218	219
220	221	222
223	224	225
226	227	228
229	230	231
232	233	234
235	236	237
238	239	240
241	242	243
244	245	246
247	248	249
250	251	252
253	254	255
256	257	258
259	260	261
262	263	264
265	266	267
268	269	270
271	272	273
274	275	276
277	278	279
280	281	282
283	284	285
286	287	288
289	290	291
292	293	294
295	296	297
298	299	300
301	302	303
304	305	306
307	308	309
310	311	312
313	314	315
316	317	318
319	320	321
322	323	324
325	326	327
328	329	330
331	332	333
334	335	336
337	338	339
340	341	342
343	344	345
346	347	348
349	350	351
352	353	354
355	356	357
358	359	360
361	362	363
364	365	366
367		

DECLARATION OF TRUTH
I, the undersigned, declare that the foregoing particulars are true in every respect.



Anderson & Turner



Drawer's Signature
(if drawer is not the payeeholder)
Date & Time:

Reporting Centre: *Part 1* Hospital's Signature
Name: _____
Appointed By: _____

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	8051E
Vehicle Details	
Vehicle No.:	SLX536C
Vehicle to be Exported:	Yes
Intended De-registration Date:	13 Aug 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	G4FC9U599626
Chassis No.:	KMH DU41BR9U690284
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,740.00
Original Registration Date:	12 Feb 2009
First Registration Date:	12 Feb 2009
Transfer Count:	3
Actual ARF Paid:	\$11,740.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Feb 2019
PARF Rebate Amount:	\$5,870.00
Intended COE Rebate Details	
COE Expiry Date:	11 Feb 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$1,020.00
COE Rebate Amount:	\$50.00
Total Rebate Amount:	\$5,920.00

The information contained herein is correct as at 13 Aug 2018

OK

Labour

1. Remove rear bumper for painting
2. spray the rear bumper

400.00

200.00

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	SCR	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	6
1147	992976	Rear Bumper Bracket			2
1148	993068	Rear Bumper Side Retainer			2
1149	993045	Rear Bumper Reinforcement			2
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	CRA	✓	
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No:

SLX 536C

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
11365	990247	Sticker			

No of Items:

Assessor:

JG Liu

...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Aug 2018 Edit Reg		06 Aug 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	JAMES LAU OON BENG (LIU EN MING) , ID: S1745715B		
Main Claimant:	TORQUE CONCEPT , Co. Reg. No.: 53278061E		
Vehicle Reg. No.:	SLX536C	Date of Loss:	04/08/2018 12:00 - :59 [113 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8933707458SG	Policy/Cover Note No.:	2100500193 (Comprehensive)
Vehicle Reg. No. (Insured):	SLK9716J	Policy No. (Claimant):	
		Excess:	
Repairer:	Sin Seng Hong Spray Painting & Service (HQ) BLK 3022A UBI ROAD 1 #01-53, 408716 Ubi - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 16/08/2018]		
Claimant's Solicitor:	TOMMY CHOO, MARK GO LLC - Tel: 65322455		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (17/08/2018): Request To Upload TP GIA Report
- AIG_SG (07/08/2018): No Policy Found

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLX536C (8933707458SG)**

[SLK9716J]

TP

TORQUE CONCEPT

Aug 4 2018 12:00PM

[JAMES LAU OON BENG (LIU EN MING)]

Sin Seng Hong Spray Painting & Service

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

[View](#)
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/08/18 14:41	General View	 Load JPG	☒
2	13/08/18 14:41	General View	 Load JPG	☒
3	13/08/18 14:41	General View	 Load JPG	☒
4	13/08/18 14:41	General View	 Load JPG	☒
5	13/08/18 14:41	General View	 Load JPG	☒
6	13/08/18 14:41	General View	 Load JPG	☒
7	13/08/18 14:41	General View	 Load JPG	☒
8	13/08/18 14:41	General View	 Load JPG	☒
9	13/08/18 14:41	General View	 Load JPG	☒
10	13/08/18 14:41	General View	 Load JPG	☒
11	13/08/18 14:41	General View	 Load JPG	☒
12	13/08/18 14:41	General View	 Load JPG	☒
13	13/08/18 14:41	General View	 Load JPG	☒
14	13/08/18 14:41	General View	 Load JPG	☒
15	13/08/18 14:41	General View	 Load JPG	☒
16	13/08/18 14:41	General View	 Load JPG	☒
17	13/08/18 14:41	General View	 Load JPG	☒
18	20/08/18 11:39	Photo After Spray	 Load JPG	☒
19	20/08/18 11:39	Photo After Spray	 Load JPG	☒
20	20/08/18 11:39	Photo After Spray	 Load JPG	☒
21	20/08/18 11:39	Photo After Spray	 Load JPG	☒
22	20/08/18 11:39	Photo After Spray	 Load JPG	☒
23	20/08/18 11:39	Photo After Spray	 Load JPG	☒
24	20/08/18 11:39	Photo After Spray	 Load JPG	☒
25	20/08/18 11:39	Photo After Spray	 Load JPG	☒
26	20/08/18 11:39	Photo After Spray	 Load JPG	☒
Documentation			1 per page	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/08/18 11:50	OI GIA REPORT	 Load PDF	

Documents Checklist

[DOCUMENTS CHECKLIST](#)
[Reset](#)
[Save](#)
[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18014241/BZ4D3S2

Date: 28/08/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100500193
Claimant Vehicle No :	SLX536C	Insured Vehicle No :	SLK9716J
Date of Loss:	04/08/2018	Nature of Claim:	TP
		Claim No:	8933707458SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX536C	Engine No:	G4FC9U599626
Make & Model:	HYUNDAI AVANTE, 1.6 HD (A)	Chassis No:	KMH DU41BR9U690284
Reg. Date:	12/02/2009 (Man. Year: 2009)	Odometer:	3039 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60R15	Rear Tyre Size:	195/60R15
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	06/08/2018	
Date Inspected:	13/08/2018	Inspected At: Sin Seng Hong Spray Painting & Service (HQ) BLK 3022A UBI ROAD 1 #01-53 Singapore 408716
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	0.00 F	*-F
2	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
3	2		*REAR BUMPER BRACKET	*Check	0.00 F	*-F
4	2		*REAR BUMPER SIDE RETAINER	*Check	0.00 F	*-F
5	1		*REAR BUMPER REINFORCEMENT	*Check	0.00 F	*-F
6	1		*REAR BUMPER SPONGE	Cracked	0.00 F	*-F
				Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >