

Review

ASS. REC. BY:

REF:

05/MSG18014272/Gqd3er

Special Instruction:

Surveyor
Menmen
From (Person)

Guo Qun
Lionel Tan

ASSIGNMENT (Office)

MSIG

Date/Time: 6/8/18 @ 4:04 pm

Estimated Cost

Bill to

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8J4 2262T

Insured:

8JL 501P

at Workshop info:

Hock with Motor

Tel:

6785 3933

of

Blk 900B Tampines St 93, Ind. Park A # 01-204

Policy No:

A80451431QMY

Claim No:

566349

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/08/2018

CA / REV / REP. / REV 24 HRS

1 up

8/8/2018

H.O.D. Endorsement:

Date/Time:

4:21 pm @ 6/8/18

Person Contacted:

Mr. Tan

Vehicle IN

☒ OUT

Date/Time

Action/Instruction () Estimate

8J4 2262T - X

8JL 501P - X

13/8-

Revert preli advise via menmen

30/11/18 @ 3:36 pm

confirmed with her team LS \$1450, 4 days.
(Red \$ 2016.64, 58%)

11/11/13 waf

ASS. REC. BY: YHL

REF: MSIG

5643H /

ASSIGNMENT

(-2021)

From: Date: 8/8/18

Estimated Cost:

On ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJ4 2262 T
at Workshop m/s Hock wach Motor
of BLK 900 B Impines 8/93 #01-204
Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Vehl:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$26K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 4hrs

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJ42262T Yr Regn: 27J6/2006

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda adyssey c.c 2354

Colour: Silver A/C: Insured / Std / NI / NA

Sp.Reading: 432396 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMRB 18507C 200492

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I. 08-08-18

Survey held at W/S 12:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 03 DEC 2018

Date/Time, File Pass to?

03/12/18

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) 1450

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

150

10

160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Aug 2018		06 Aug 2018 16:04 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	MAGYLIC CHEW CHOON YONG, ID: S1288518J, Tel: +6592728181, Email: MAGYLIC@GMAIL.COM		
Main Claimant:	LIM GEOK HWA, ID: S7165643H		
Vehicle Reg. No.:	SJU2262T	Date of Loss:	02/08/2018 16:00 - :59 [144 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 566349	Policy/Cover Note No.:	A80451431QMY (Comprehensive) Coverage: 26/01/2018 - 25/01/2019
Vehicle Reg. No. (Insured):	SJL501P	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Hock Wah Motor Workshop Pte Ltd (Tampines) Blk 900B, Tampines Street 93,, Tampines Industrial Park A, #01-204, 528840 Tampines - Tel: 6785 3933 / 8339 6888		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/08/2018]		
Driver/Custodian (Insured):	MAGYLIC CHEW CHOON YONG (60 / Female), NRIC: S1288518J, Tel: +6592728181		
Adj Asg. Remarks:	on WP. Liability : NOT CLEAR Please appoint MARCUS CHUA from LKK AUTO to conduct the survey . Kindly survey the vehicle 8/8/2018 Wednesday and Please contact DEHAN @ 6785 3933 .		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18014272/Gqd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 06-08-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJL 501P	Veh. Inspected	SJU 2262T
Policy No.	A80451431QMY	Coverage (\$)	0.00
Claim No.	566349	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	06/08/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	02/08/2018	Inspection Date	08/08/2018
Survey held at	BLK 900B TAMPINES ST.93 #01-204		
Repairer	HOCK WAH MOTOR WORKSHOP PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 13 Aug 2018

Preliminary Advice

Insured Vehicle No	: SJL501P	Accident Date	: 02/08/2018
TP Vehicle No	: SJU2262T	Assignment Date	: 06/08/2018
Make	: HONDA ODYSSEY	Est. Duration of Repair	: 4.00
Date of Inspection	: 08/08/2018		
Inspection At	: HOCK WAH MOTOR WORKSHOP PTE LTD (TAMPINES) BLK 900B, TAMPINES STREET 93,, TAMPINES INDUSTRIAL PARK A, #01-204 SINGAPORE 528840		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,466.64
Revised Amount	:S\$	1,818.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,818.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/08/2018 14:01
Date Of Accident	02/08/2018 16:30
Exact Location Of Accident	BOON KENG RD AFTER BOON KENG MRT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU2262T
Insured/Policyholder	
Name Of Registered Owner	LIM GEOK HWA
NRIC No	S7165643H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96917819
Alternative Phone No	OTHERS-96917819

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY
Exact Purpose for which vehicle was being used at time of accident	PERSONAL PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5041463222-08
Cover Note Number	27/07/2018-26/07/2019

Driver

Name of Driver	LIM GEOK HWA
NRIC No	S7165643H
Date Of Birth	15/10/1971
Occupation	OUTDOOR
Date Of Driving Pass	18/03/2002
Driving Experience	16 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96917819
Fax Number	
Contact Number	OTHERS-96917819
EMail Address	NOEMAIL

Address BLK 642A PUNGGOL DRIVE #07-343
 Postcode 821642
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON THE STATED DATE & TIME, I WAS TRAVELING AROUND BOON KENG ROAD LANE 3. IT WAS AFTER THE BOON KENG MRT STATION ALONG THE ROAD, I FELT AN IMPACT FROM REAR LEFT AND REALISED THAT VEHICLE B HAD COLLIDED WITH MY VEHICLE REAR LEFT WHEN THE OWNER OF VEHICLE B OF MAKING A LANE CHANGE FROM LANE 4 TO LANE 3. THERE WERE NO INJURIES INVOLVED. 1 PAX ON VEHICLE A AND 1 PAX ON VEHICLE B.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJL501P
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer [collectively the "Personal Information"] and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

03-08-18
2:30 PM

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Representative/Insurer's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 03-08-18 2.30pm


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: _____
NIC/FIN No.: _____

SKETCH PLAN

BOON KENG
MRT

A: SJU2262T
B: SJL501P



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO AIA REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	5643H

Vehicle Details

Vehicle No.:	SJU2262T
Vehicle to be Exported:	No
Intended De-registration Date:	10 Aug 2018
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	K24A64000499
Chassis No.:	JHMRB18507C200492
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$29,632.00
Original Registration Date:	27 Jul 2006
First Registration Date:	27 Jul 2006
Transfer Count:	2
Actual ARF Paid:	\$32,596.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	30 Jun 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$24,240.00
COE Rebate Amount:	\$14,005.00
Total Rebate Amount:	\$14,005.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Aug 2018

OK

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204
SINGAPORE 528840
TEL : 67853933 FAX: 67883933
R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : S7165643H
LIM GEOK HWA
BLK 642A PUNGGOL DRIVE
07-343
SINGAPORE 821642
TEL : FAX :
PH : 96917819
ATTN :

ESTIMATE BILL

Number : EBK0000246
Date : 03/08/2018
Case No : ADK0000320
Vehicle No : SJU2262T
Chassis:
Year of Mfr
Policy No
Model : HONDA ODYSSEY
2.4A

Term: CASH

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	RR BUMPER <i>cut</i>	1.0	756.40	20	605.12
2	RR BUMPER SIDE RETAINER LH <i>acc</i>	1.0	19.80	20	15.84
3	RR DOOR LH <i>x repair</i>	1.0	934.80	20	747.84
4	RR DOOR MOULDING LH <i>scr</i>	1.0	102.40	20	81.92
5	RR FENDER MOULDING LH <i>scr</i>	1.0	19.90	20	15.92
List Price - Parts Sub Total					1,466.64
Parts Total					1,466.64
6	RR ROCKER PANEL GARNISH LH REPAIR	1.0	20% = 718.8		
7	RR FENDER LH REPAIR	1.0			
8	RR RIM LH REPAIR	1.0			
9	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	1.0		0	1,000.00
10	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,000.00	0	1,000.00
Labour 1 Sub Total					2,000.00
<i>4 Days -</i> <i>Unpam Repair.</i> <i>After repair photos.</i> <i>Guo Qianf - 82880282</i> <i>(Lkk)</i> <i>08/8/18.</i>					
SINGAPORE DOLLARS : THREE THOUSAND SEVEN HUNDRED NINE AND CENTS THIRTY-ONLY					
Less Excess					0.00
SUBTOTAL					3,466.64
GST 7.00%					242.66
TOTAL					3,709.30

Date of accident : 02/08/2018 04:30 PM Place : BOON KENG RD AFTER BOON KENG MRT

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

Acknowledged by Repairer
Signature:

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Aug 2018		06 Aug 2018 16:04 Edit Adj Rpt	S\$1,450.00 Edit Estimates	S\$1,450.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: MAGYLIC CHEW CHOON YONG , ID: S12885181, Tel: +6592728181, Email: MAGYLIC@GMAIL.COM									
Main Claimant: LIM GEOK HWA , ID: S7165643H									
Vehicle Reg. No.: SJU2262T		Date of Loss: 02/08/2018 16:00 - :59 [144 Months and 6 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 566349		Policy/Cover Note No.: A80451431QMY (Comprehensive) Coverage: 26/01/2018 - 25/01/2019							
Vehicle Reg. No. (Insured): SJLS01P		Policy No. (Claimant):							
		Excess: S\$500.00							
Repairer: Hock Wah Motor Workshop Pte Ltd (Tampines) Blk 900B, Tampines Street 93,, Tampines Industrial Park A, #01-204, 528840 Tampines - Tel: 6785 3933 / 8339 6888									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 05/09/2018]									
Driver/Custodian (Insured): MAGYLIC CHEW CHOON YONG (60 / Female), NRIC: S12885181, Tel: +6592728181									
Adj Asg. Remarks: on WP. Liability : NOT CLEAR Please appoint MARCUS CHUA from LKK AUTO to conduct the survey . Kindly survey the vehicle 8/8/2018 Wednesday and Please contact DEHAN @ 6785 3933 .									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJU2262T (566349)
 [SJL501P]
 TP
 LIM GEOK HWA
 Aug 2 2018 4:00PM
 [MAGYLIC CHEW CHOON YONG]
 Hock Wah Motor Workshop Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Video

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/08/18 11:43	Video - Accident	 Load MP4	

Assessment Reports

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/08/18 16:37	Accident Statement Addm. #1 From: SC - Reg. No: SJL501P, Claimant: MAGYLIC CHEW CHOON YONG	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/08/18 10:55	Adjuster Immediate Advice	 Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/12/18 14:28	General View	 Load JPG	☒
2	03/12/18 14:28	General View	 Load JPG	☒
3	03/12/18 14:28	General View	 Load JPG	☒
4	03/12/18 14:28	General View	 Load JPG	☒
5	03/12/18 14:28	General View	 Load JPG	☒
6	03/12/18 14:28	General View	 Load JPG	☒
7	03/12/18 14:28	General View	 Load JPG	☒
8	03/12/18 14:28	General View	 Load JPG	☒
9	03/12/18 14:28	General View	 Load JPG	☒
10	03/12/18 14:28	General View	 Load JPG	☒
11	03/12/18 14:28	General View	 Load JPG	☒
12	03/12/18 14:28	General View	 Load JPG	☒
13	03/12/18 14:28	General View	 Load JPG	☒
14	03/12/18 14:28	General View	 Load JPG	☒
15	03/12/18 14:28	General View	 Load JPG	☒
16	03/12/18 14:28	General View	 Load JPG	☒
17	03/12/18 14:28	General View	 Load JPG	☒
18	03/12/18 14:28	General View	 Load JPG	☒
19	03/12/18 14:28	General View	 Load JPG	☒
20	03/12/18 14:28	General View	 Load JPG	☒
21	03/12/18 14:28	General View	 Load JPG	☒
22	03/12/18 14:28	General View	 Load JPG	☒
23	03/12/18 14:28	General View	 Load JPG	☒
24	03/12/18 14:28	General View	 Load JPG	☒
25	03/12/18 14:28	General View	 Load JPG	☒
26	03/12/18 14:28	General View	 Load JPG	☒
27	03/12/18 14:28	General View	Load JPG	☒
28	03/12/18 14:28	Odometer Reading	Load JPG	☒

Video			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
29	03/12/18 14:29	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/08/18 16:37	TPD SJU2262T GIA REPORT From: SC - Reg. No: SJL501P, Claimant: HAGYUIC CHEW CHOON YONG	 Load PDF	
2	03/08/18 16:39	TPD SJU2262T - PRI	 Load PDF	
3	06/08/18 08:07	Reply email from TP Workshop & appoint MARCUS CHUA from LKK AUTO	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18014272/GQD3E2

Date: 04/12/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80451431QMY

Claimant Vehicle
No : SJU2262T

Insured Vehicle No : SJL501P

Date of Loss: 02/08/2018

Nature of Claim: TP

Claim No: 566349

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJU2262T

Make & Model: HONDA ODYSSEY, 2.4 (A)

Engine No: K24A64000499

Reg. Date: 27/07/2006 (Man. Year: 2006)

Chassis No: JHMRB18507C200492

Colour: Silver

Odometer: 432396 km

Engine Capacity: 2354 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,466.64	718.80	747.84	50.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,100.00	900.00	45.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,466.64	1,818.80	1,647.84	47.53
Approved Total (Overridden) (S\$)		1,450.00		
(S\$)	3,466.64	1,450.00	2,016.64	58.17
+ GST 7.00/7.00% (S\$)	242.66	101.50	141.16	58.17
Nett Amount (S\$)	3,709.30	1,551.50	2,157.80	58.17

INSPECTION

Date of Assignment: 06/08/2018

Date Inspected: 08/08/2018 Inspected At:

Hock Wah Motor Workshop Pte Ltd
(Tampines)
Blk 900B, Tampines Street 93, Tampines
Industrial Park A, #01-204
Singapore 528840

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Dec 2018)
Parts: M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJU2262T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER	Cut	756.40 FL	*756.40 FL
2	1		*RR BUMPER SIDE RETAINER LH	Necessary	19.80 FL	*19.80 FL
3	1		*RR DOOR LH	Repair	934.80 FL	*- FL
4	1		*RR DOOR MOULDING LH	Scratched	102.40 FL	*102.40 FL
5	1		*RR FENDER MOULDING LH	Scratched	19.90 FL	*19.90 FL
6	1		*RR ROCKER PANEL GARNISH LH (NPA)	Repair	0.00 FL	*- FL
7	1		*RR FENDER LH (NPA)	Repair	0.00 FL	*- FL
8	1		*RR RIM LH (NPA)	Repair	0.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,833.30	898.50
- List Item Discount on L Items 20.00/20.00% (S\$)	366.66	179.70
Total Parts (S\$)	1,466.64	718.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	New	1,000.00	500.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	1,000.00	600.00
Gross Labour Cost (\$\$)			2,000.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >