

ASS. REC. BY:

REF es/CT#18014276 / G30302

Initial Instruction:

Surveyor
Menmen

GQ

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CT#

Date/Time:

6/8/18 @ 3:41pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

FZ 22852

Insured:

GW 1985Y

at Workshop m/s:

New Union Company

Tel:

8754 2877

of

Blk 9004, Tampines St 93 #01-106

Policy No:

DMCVSN3028691800

Claim No:

SNM18D 03779002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 31/07/2018

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

4:39 pm @ 6/8/18

Person Contacted:

Mr. Boon

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

FZ 22852 - NA / CT#18013963 / h4

DOA: 31/07/18

GW 1985Y - NA / CT#18013963 / h4

DOA: 31/07/18

(08/11/13) wef

ASS. REC. BY:

REF: CFI

ASSIGNMENT

From: Date: 10/08/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FZ 2285Z

at Workshop m/s

of 9004 Tampines St 93 #01-06

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FZ 2285Z

Yr Regn:

13 May 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kawasaki KRR

c.c

149

Colour:

Green

A/C:

Insured / Std / NI / NA

Sp. Reading

44920

T/Radio:

Insured / Std / NI / NA

Eng/No:

KR150KA6150.8

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

90/80-17

R:

600/80-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

10-08-18

Survey held at

w/s

11:30AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

10/8

Estimate Given later.

Finalized \$2100 with BT by Gmws/

31/10/18

Confirmed HS \$2,100/- @ 4 days with XGR. (\$1,840.00 red - 47%)

31/10/2018

RECEIVED 31 OCT 2018

Date/Time, File Pass to?

31/10/18

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$ 2,100/- HS)

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

220

Transportation:

Photos

Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Aug 2018		06 Aug 2018 15:41 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	M/S HOME RENOVATION & CONSTRUCTION, Co. Reg. No.: -		
Main Claimant:	AHMAD HAZIQ BIN AHMAD RIDWAN		
Vehicle Reg. No.:	FZ2285Z	Date of Loss:	31/07/2018 23:00 - :59
Claim Type:	TP / SNM18D03779C02	Policy/Cover Note No.:	DMCVSN3028691800 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	GW1985Y	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	New Union Company (HQ) BLK 9004 TAMPINES STREET 93 #01-106, 528838 Tampines - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/08/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: GeneralNU <numotor@singnet.com>
Sent: Saturday, 4 August, 2018 8:58 AM
To: Claims Dept of CTI
Subject: Accident Involving Your Insured
Attachments: receipt_LTA Search.pdf; PoliceRpt_FZ2285Z.PDF; GIA_FZ2285Z.PDF

Dear Sir/Mdm,

We are instructed by our client to act upon an accident involving your insured. Attached are the police and GIA reports for your reference. Pls arrange Pre-repair assessment.

Thanks & Best Rgds
Boon Teck
New Union Company
HP:87542877

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18014276/Gsd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 06-08-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GW 1985Y	Veh. Inspected	FZ 2285Z
Policy No.	DMCVSN3028691800	Coverage (\$)	0.00
Claim No.	SNM18D03779C02	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE CHEONG)	Assign Date	06/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	31/07/2018	Inspection Date
Survey held at	NEW UNION COMPANY 9004 TAMPINES ST 93 #01-06 SINGAPORE 528838	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5589I
Vehicle Details	
Vehicle No.:	FZ2285Z
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Sep 2018
Vehicle Make:	KAWASAKI
Vehicle Model:	KRR ZX150 M
Primary Colour:	Blue
Manufacturing Year:	2005
Engine No.:	KR150EEA61508
Chassis No.:	KR150KA61508
Maximum Power Output:	-
Open Market Value:	\$2,886.00
Original Registration Date:	13 May 2005
First Registration Date:	13 May 2005
Transfer Count:	6
Actual ARF Paid:	\$433.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 May 2020
COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$2,961.00
COE Rebate Amount:	\$1,552.00
Total Rebate Amount:	\$1,552.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	01/08/2018 16:11
Date Of Accident	31/07/2018 23:15
Exact Location Of Accident	TAMPINES STREET 81, B/897A
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FZ2285Z
Insured/Policyholder	
Name Of Registered Owner	AHMAD HAZIQ BIN AHMAD RIDWAN
NRIC No	S9815589I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81383949
Alternative Phone No	OTHERS-81383949
Vehicle Particulars	
Manufacturer	KAWASAKI
Model	KRR ZX150 M
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5096819390 TP
Cover Note Number	
Driver	
Name of Driver	AHMAD HAZIQ BIN AHMAD RIDWAN
NRIC No	S9815589I
Date Of Birth	07/05/1998
Occupation	OUTDOOR
Date Of Driving Pass	07/12/2017
Driving Experience	0 YEAR AND 7 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81383949
Fax Number	
Contact Number	OTHERS-81383949
Email Address	NOEMAIL

Address	BLK 328 #06-364 TAMPINES STREET 32
Postcode	520328
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GW1985Y
Vehicle Make/Model/Colour	NISSAN CABSTAR
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under [d] above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: cas@idacsb.com.sg

Name:

NRIC/FIN No.:

Policyholder's Signature


Date & Time: 1/8/18

Driver's Signature

(If driver is not the policyholder)

Date & Time:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My motorcycle was parked by the side of the curb, not obstructing anything, and a lorry hit it on the right side and it fell on its left. The lorry stopped to check the damages of his lorry but did not agree on settling it ~~at~~ with insurance or privately. When I ask for particulars, he went in his lorry and left.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature
Date & Time: 1/8/18

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: yackb@singnet.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

GST Reg No. M90370043N

P: 67849488
F: 67847588

Email: numotor@singnet.com

Quotation No. #14 08 2018 1

Quote Date:

Email:

Quotation For: Bike Repair - FZ2285Z

~~60~~ -
X
/
~~X~~ - 120
/
20
~~X~~ ~~40~~
/
X
X
~~X~~ -
/
/
/
/
/
/
/
/
/
X
~~X~~ -
X
/
/
10 (SN)
~~150~~ 250
~~150~~ ~~180~~
270

Date:

2195
10%: 1975.5
SN, 10

labour: 390 + \$230
~~2375.5~~ 2635.5
 209: ~~1900~~ ²⁰⁵⁰ 2100 4 Days

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Aug 2018		06 Aug 2018 15:41 Edit Adj Rpt	S\$2,100.00 Edit Estimates	S\$2,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: M/S HOME RENOVATION & CONSTRUCTION , Co. Reg. No.: -									
Main Claimant: AHMAD HAZIQ BIN AHMAD RIDWAN									
Vehicle Reg. No.: FZ2285Z		Date of Loss: 31/07/2018 23:00 - :59 [158 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D03779C02		Policy/Cover Note No.: DMCVSN3028691800 (TP, Fire & Theft)							
Vehicle Reg. No. (Insured): GW1985Y		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: New Union Company (HQ) BLK 9004 TAMPINES STREET 93 #01-106, 528838 Tampines - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 16/08/2018]									
Adj Asg. Remarks: NO EST, ASSIGN ADRIAN LING AS SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FZ2285Z (SNM18D03779C02)
[GW1985Y]
TP
AHMAD HAZIQ BIN AHMAD RIDWAN
Jul 31 2018 11:00PM
[M/S HOME RENOVATION & CONSTRUCTION]
New Union Company


Upload Documents			Upload Photos			Compose New Letter			View <div>View in Browser</div>		
Video									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)							Thumbnail	Print	
1	01/08/18 14:07	Video - Accident [Linked Accident Report Documents]							Load MP4		
2	01/08/18 14:07	Video - Accident [Linked Accident Report Documents]							Load MP4		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)							Thumbnail	Print	
1	01/08/18 14:09	Accident Statement							Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)							Thumbnail	Print	
1	01/08/18 14:06	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
2	01/08/18 14:06	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
3	01/08/18 14:06	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
4	01/08/18 14:06	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
5	01/08/18 14:06	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
6	01/08/18 14:06	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
7	01/08/18 14:06	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
8	01/08/18 14:06	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
9	01/08/18 14:06	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
10	01/08/18 14:06	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
11	01/08/18 14:06	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
12	01/08/18 14:06	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
13	01/08/18 14:06	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	31/10/18 09:12	General View							Load JPG	<input checked="" type="checkbox"/>	
2	31/10/18 09:12	General View							Load JPG	<input checked="" type="checkbox"/>	
3	31/10/18 09:12	General View							Load JPG	<input checked="" type="checkbox"/>	
4	31/10/18 09:12	General View							Load JPG	<input checked="" type="checkbox"/>	
5	31/10/18 09:12	General View							Load JPG	<input checked="" type="checkbox"/>	
6	31/10/18 09:12	General View							Load JPG	<input checked="" type="checkbox"/>	
7	31/10/18 09:12	General View							Load JPG	<input checked="" type="checkbox"/>	
8	31/10/18 09:12	General View							Load JPG	<input checked="" type="checkbox"/>	
9	31/10/18 09:12	General View							Load JPG	<input checked="" type="checkbox"/>	
10	31/10/18 09:12	General View							Load JPG	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
11	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
12	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
13	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
14	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
15	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
16	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
17	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
18	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
19	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
20	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
21	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
22	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
23	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
24	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
25	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
26	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
27	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
28	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
29	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
30	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
31	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
32	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
33	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
34	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
35	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
36	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
37	31/10/18 09:12	General View	 Load JPG	<input checked="" type="checkbox"/>
38	31/10/18 09:13	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
39	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	31/10/18 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
61	31/10/18 09:14	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
62	31/10/18 09:14	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
63	31/10/18 09:14	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
64	31/10/18 09:14	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
65	31/10/18 09:14	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
66	31/10/18 09:14	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
67	31/10/18 09:14	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
68	31/10/18 09:14	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
69	31/10/18 09:14	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
70	31/10/18 09:14	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
71	31/10/18 09:14	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
72	31/10/18 09:14	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
73	31/10/18 09:14	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
74	31/10/18 09:14	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
75	31/10/18 09:14	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
76	31/10/18 09:14	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
77	31/10/18 09:14	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
78	31/10/18 09:14	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
79	31/10/18 09:14	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
80	31/10/18 09:14	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
81	31/10/18 09:14	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/08/18 15:40	PRS	Load PDF	
2	06/08/18 15:40	TP GIA	Load PDF	
3	06/08/18 15:41	OI GIA	Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	01/08/18 14:06	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	01/08/18 14:06	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	01/08/18 14:06	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	01/08/18 14:06	DRIVING DOC [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	01/08/18 14:07	Video - Accident	Load MP4	
2	01/08/18 14:07	Video - Accident	Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	01/08/18 14:09	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	01/08/18 14:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	01/08/18 14:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	01/08/18 14:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	01/08/18 14:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
5	01/08/18 14:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	01/08/18 14:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	01/08/18 14:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	01/08/18 14:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	01/08/18 14:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	01/08/18 14:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	01/08/18 14:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	01/08/18 14:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	01/08/18 14:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	01/08/18 14:06	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	01/08/18 14:06	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	01/08/18 14:06	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
4	01/08/18 14:06	DRIVING DOC	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18014276/GSD3E2

Date: 31/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3028691800
Claimant Vehicle No :	FZ2285Z	Insured Vehicle No :	GW1985Y
Date of Loss:	31/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03779C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FZ2285Z	Engine No:	KR150EEA61508
Make & Model:	KAWASAKI KRR ZX150 M, 149cc (M)	Chassis No:	KR150KA61508
Reg. Date:	13/05/2005 (Man. Year: 2005)	Odometer:	44920 km
Colour:	Green		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	90/80-17	Rear Tyre Size:	100/80-17
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,030.00	1,985.50	1,044.50	34.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	910.00	650.00	260.00	28.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,940.00	2,635.50	1,304.50	33.11
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	3,940.00	2,100.00	1,840.00	46.70
+ GST 7.00/7.00% (S\$)	275.80	147.00	128.80	46.70
Nett Amount (S\$)	4,215.80	2,247.00	1,968.80	46.70

INSPECTION

Date of Assignment:	06/08/2018	
Date Inspected:	10/08/2018 Inspected At:	New Union Company (HQ) BLK 9004 TAMPINES STREET 93 #01-106 Singapore 528838
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 Oct 2018)	
Parts:	N/A	KAWASAKI KRR ZX150 M 149cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FZ2285Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRAKE DISC, FRONT DISC	Not Necessary	185.00 F	*- FL
2	2		*WHEEL BEARING	Necessary	40.00 F	*40.00 FL
3	1		*FRONT WHEEL SHAFT	Not Necessary	35.00 F	*- FL
4	1		*STEERING CORN BEARING	Necessary	120.00 F	*120.00 FL
5	1		*SET FRONT SIGNAL LAMP	N/S Cracked / O/S NotNecessary	40.00 F	*20.00 FL
6	1		*FRONT COWLING BRACKET	Repair	260.00 F	*- FL
7	1		*HANDLE BAR ASSY	Bent	185.00 F	*185.00 FL
8	2		*BALANCER	Not Necessary	40.00 F	*- FL
9	1		*HANDLE GRIP 1 x PAIR	Not Necessary	20.00 F	*- FL
10	1		*CLUTCH LEVER	Cut	25.00 F	*25.00 FL
11	1		*FRONT FENDER	Cut	95.00 F	*95.00 FL
12	1		*FRONT COWLING	Cut	185.00 F	*185.00 FL
13	1		*LHS - SIDE COWLING	Cut	140.00 F	*140.00 FL
14	1		*RHS - SIDE COWLING	Cracked	140.00 F	*140.00 FL
15	1		*RADIATOR ASSY	Bent	220.00 F	*220.00 FL
16	1		*CLUTCH HOUSING ASSY	Cut	330.00 F	*330.00 FL
17	1		*CLUTCH LEVER	Cracked	220.00 F	*220.00 FL
18	1		*CLUTCH GASKET	Necessary	15.00 F	*15.00 FL
19	1		*ENGINE OIL	Necessary	25.00 F	*25.00 FL
20	1		*WATER PUMP ASSY	Not Necessary	160.00 F	*- FL
21	1		*FRONT FOOTREST ASSY	Bent	160.00 F	*160.00 FL
22	2		*SIDE COWLING ENCLOSURE	Not Necessary	90.00 F	*- FL
23	1		*COWLING VISOR	Cracked	45.00 F	*45.00 FL
24	1		*EXHAUST EN-CAM	Cut	230.00 F	*230.00 FL
25	1		*NO.PLATE, FRONT	Necessary	25.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,030.00	2,205.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	219.50
Total Parts (\$\$)	3,030.00	1,985.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	FRONT RIM PRESS	New	140.00	60.00
2	FORK PRESS	New	140.00	120.00
3	SPRAY PAINT	New	380.00	250.00
4	LABOUR CHARGES	New	250.00	220.00
Gross Labour Cost (\$\$)			910.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >