

RESTRICTED



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Kampong Glam NPP
17A Beach Road SINGAPORE 199596
Tel No: 1800-2989999



12018025250171

2/9/11
Report No: 12018025250171

CONTINUATION OF REPORT

Driver			
Name	QUAK SHOU KANG	ID No.	S9544568A
Related Vehicle	MID41583 (Car)	Contact No.	97866539
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class 3 Date of Expiry: Nil
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	CHEW KANG SUNG	ID No.	S00993231
Related Vehicle	XD9999D (Prime Mover)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class 4 Date of Expiry: Nil
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the abovementioned date, time and location, while entering the roundabout from Stadium Drive and negotiating the left bend into Nicoll Highway, there was a heavy vehicle in front of my vehicle (MID41583) and a heavy vehicle behind me (XD9999D). While negotiating the left bend, as the driver behind me was too close to me while negotiating the left bend, he swiped the front left side of his vehicle to rear right side of my vehicle. We stepped out and traded particulars.

There is a dent and some deep scratches on the rear right side of my vehicle, while the front left bumper of his vehicle was also scratched. I am lodging this report for record purposes.

K-1
RESTRICTED

RESTRICTED

ANNEX C

STATEMENT OF S9641823Z, REC CHUA YANG JIE DARREN

NRIC NO: S9641823Z	Rank: REC	Name: CHUA YANG JIE DARREN
Alias(es): NIL	UNIT: HQ 2 PDF G8 Br	Appointment: ADMIN SUPPORT ASST
Age: 21	Sex: M	Vocation: ADMIN SUPPORT ASST
Type Of Service: ARMY	DOE: 13/02/2018	ORD: 12/02/2020
Address: 10A #16-103 BENDENEER ROAD S(331010)		HP No: 88684590

STATEMENT OF WITNESS

I, S9641823Z, REC DARREN CHUA YANG JIE, together with my madam, Madam Rathy and Madam Sandya, were heading for our out-pro at Kallang Sea Training Centre on 25th May 2018 at about 1205HRS.

There is a roundabout at Stadium Drive heading towards Nicoll Highway. As the roundabout was narrow, the driver, LCP QUAK SHOU KANG was cautious and as he saw a lorry in front struggling with the turn, he slowed down, but to my surprise, the lorry, license plate, **XD 9999 D** behind us bumped onto our car.

All personnel are unhurt. That is all I have to say.

<< via email >>
REC CHUA YANG JIE DARREN
ASA, G8 BR

<< via email >>
MWO CHEW SEOW HONG
OPS WO, G8 BR

C-1
RESTRICTED



SMRT Automotive Services Pte Ltd
6 ANG MO KIO STREET #2
SINGAPORE 686140

Contract Ref No
8016100475

HQ Maintenance Engineering Support

151, Choa Chu Kang Way, Singapore 686248
Blk B22, #02-14, Kranji Camp 3

Dear Sir,

Quotation Ref No: AUG18/QY2/073 TPT HUB: Central Hub
Quotation Request Date: 15/08/2018 UNIT: Clementi Camp
Quotation Submission Date: 16/08/2018

Vehicle Number: MID 41583 Vehicle Grouping: A / B
Vehicle Type/Model: FORD FOCUS 1.5A
Type of Repair: Accident / Damaged / Modification

We hereby submit the quote for repair for the above-mentioned vehicle in accordance to the job description attached.

Job carried out by SMRT Automotive Services Pte Ltd

Total Repair Labour Cost: \$ 681.08 22.5 @ \$ 30.27 per hr
Spares Cost: \$ 429.00
Transportation Cost: \$ 123.86
Grand Total Cost: \$ 1,233.94 (Excluding GST)
GST @ 7%: \$ 86.38
Grand Total Cost: \$ 1,320.31 (including GST)

Delivery Period: 12 Days from date of Purchase Order (PO) Approval

Validity Period: 90 Days from the date of quotation

Spares purchased by Vendor's Name are subjected to mark up and overcost items based on CIF price.
The grand total repair cost of labour and spare(s) material(s) used are subjected to Good and Services Tax.

Yours Faithfully


SMRT Automotive Services Pte Ltd

Name: Tan Yong Wei
Appointment: Manager

For Authority Use Only

PO / PR NUMBER	DATE CREATED	DATE RELEASED	RELEASED BY	SIGNATURE
			GR on	

RESTRICTED



D-2
RESTRICTED


CLOSE-UP VIEW OF THE ACCIDENT VEHICLE(S)

FIGURE D-1 – OVERVIEW OF MID 41583



Front View of MID 41583

Rear View of MID 41583



Left Side View of MID 41583

Right Side View of MID 41583


Damage Assessment: Scratches and a dent on rear right body

RESTRICTED

FIGURE D-2 – CLOSE-UP VIEW OF MID 41583



FIGURE D-3 – CLOSE-UP VIEW OF XD 9999 D



D-2
RESTRICTED

RESTRICTED

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 22 Apr 2019 / 16:05:06

Receipt Date/Time : 22 Apr 2019 / 16:05:06

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190422-002511

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - XD9999D As at 25 May 2018/00:00:01 Insurance Co: GREAT AMERICAN INSURANCE COMPANY			
1	Insurance Enquiry - XD9999D Enquiry Fee 20190422160324048525	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	xxxxxxxxxxxx9189			
	Credit Card: Visa/MasterCard			7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.