

22/03/2002

S. REC. BY:

REF: CS/EG1/8014342/Vrd3

n2

Special Instruction:

follow

Veyor:

Marcus

ASSIGNMENT (Office)

(Person):

Yee Pei Li

of

EG1

Date/Time: 8/8/18 1-16pm

Estimated Cost:

Bill to:

OD TP WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 3839T

Insured:

GW 3756D

at Workshop m/s

Fastech Auto

Tel:

67465405

of

Ikulsi 8k Ave 6 # 01-46/48

Policy No:

Claim No:

GW3756D/SL/p1

Sum Insured:

Excess:

Make of Veh:

D.O.A.

06/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

1:20pm @ 8/8/18

Person Contacted:

Nancy

Vehicle IN/OUT

OUT

Date/Time	Action/Instruction (✓) Estimate
8/8/18	Informed Pei Li pending workshop est by email
14/8/18	Email preli revised to Pei Li

(08/11/13) wef

ASS REC. BY: Mercus

REF:

ER1/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP ☒ WS ☒ TP RES ☒ OD RES ☒ EVA ☒ INV ☒ MV ☒To Inspect Vehicle No: SLH 383PTat Workshop m/s R.

of _____

Insured: GW 3756D

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS L7A53478

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLH 383PT Yr Regn: 10/16Type: ☒ M/Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /Truck / Trailer or (A)Make: Volkswagen Golf c.c. 1395Colour: blue A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 31688 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: WVWZKZAUZHWO68710Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or okBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☐ Nil / ☐ S/Rim / ☐ STD A/Rim orTyre Size: F: 225/40ZHR
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 6/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

2/5 R 2The ☒ U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

heading 2023.1313/8/18 2/5 #7500 conf. int with Alan. (Red 13,500.70, 64%)

RECEIVED 14 AUG 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 14/8 - typistDays Of Repair: 4Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Photos

Others

TOTAL

350

Report Format: TPLump Sum / I.B.I: (\$ 7500/2)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18014342/Uvd3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 07-08-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GW 3756D	Veh. Inspected	SLH 3839T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	07/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	06/08/2018	Inspection Date	07/08/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GW3756D/SL/pl
Our Ref: CS/EG18014342/Uvd3

Date: 14/8/2018

The Motor Claims Department
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SLH 3839T


We thank you for your instruction on 8/8/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 7/8/2018 at the premises of M/s FASTECH AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$21,020.70
Revised Estimate Amount	: S\$7,500.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s front portion. The undercarriage affected due to collision.



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 14 August 2018 9:42 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: GW3756D / TP : SLH3839T/LKK / DOA : 06.08.2018
Attachments: SLH 3839T PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SLH 3839T
Date of survey: 7/8/2018
Number of days : 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 8 August 2018 3:27 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GW3756D / TP : SLH3839T/LKK / DOA : 06.08.2018

Dear Pei Li,

Please be informed that we have inspected the vehicle SLH 3839T on 7/8/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 8 August 2018 1:21 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GW3756D / TP : SLH3839T/LKK / DOA : 06.08.2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]

Sent: Wednesday, 8 August 2018 1:16 PM

To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>

Cc: 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>

Subject: OI : GW3756D / TP : SLH3839T/LKK / DOA : 06.08.2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : NANCY LAM @ 6746 5405

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,

Yee Pei Li

Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9194
Tel. : +65 6829 9199
Fax : +65 6829 9247

www.ergo.com.sg

ERGO

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 8 August 2018 3:27 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: GW3756D / TP : SLH3839T/LKK / DOA : 06.08.2018

Dear Pei Li,

Please be informed that we have inspected the vehicle SLH 3839T on 7/8/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 8 August 2018 1:21 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GW3756D / TP : SLH3839T/LKK / DOA : 06.08.2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Wednesday, 8 August 2018 1:16 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>
Subject: OI : GW3756D / TP : SLH3839T/LKK / DOA : 06.08.2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : NANCY LAM @ 6746 5405

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID: +65 6829 9194
Tel: +65 6829 9199
Fax: +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Wednesday, 8 August 2018 1:16 PM
To: 'admin-d@lkkauto.com'
Cc: 'ASSIGNMENTS@LKKAUTO.COM'
Subject: OI : GW3756D / TP : SLH3839T/LKK / DOA : 06.08.2018
Attachments: GW3756D - SAS.pdf; SLH3839T - SAS.pdf; SLH3839T - PRS FORM.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : NANCY LAM @ 6746 5405

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID: +65 6829 9194
Tel: +65 6829 9199
Fax: +65 6829 9247

www.ergo.com.sg

The ERGO logo consists of the word "ERGO" in a bold, sans-serif font. The letters are white and are set against a dark, rectangular background.

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

ERGO

Date: 08.08.2018
Our Reference: GW 3756D/SL/pl
Your Reference: SLH 3839T

To: FASTECH AUTO PTE LTD

Sent via Fax

or

Email

nancy.lam@fastechauto.com.sg

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLH 3839T
Insured's Vehicle: GW 3756D
Date Of Accident: 06.08.2018


We acknowledge receipt of your request for PRS on: 07.08.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐ Our Insured's driver has not reported the accident to us todate.
☒ Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5110D
Vehicle Details	
Vehicle No.:	SLH3839T
Vehicle to be Exported:	No
Intended De-registration Date:	07 Aug 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF 1.4 TSI AT 5G13HZ HID SR
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	CZC144022
Chassis No.:	WVWZZZAUAZHW068710
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$23,827.00
Original Registration Date:	31 Oct 2016
First Registration Date:	31 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$15,358.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Oct 2026
PARF Rebate Amount:	\$11,518.00
Intended COE Rebate Details	
COE Expiry Date:	30 Oct 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$56,340.00
COE Rebate Amount:	\$41,957.00
Total Rebate Amount:	\$53,475.00

The information contained herein is correct as at 07 Aug 2018

OK



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find o](#)

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Powerful Audi R8 2012 With Lowest Mileage!



Full Agent Maintained With Only
1 Owner! Excellent Condition
Not To Be Missed!
HTS Motor StarAd

[click](#)
[Browse by Category](#)
[« Back \(1 2 \) Next »](#)
[Sort b](#)

24 vehicles

Volkswagen Golf

[Advant](#)

Make Model Price Depreciation Reg Date Eng Cap Mil

Search Selection

Volkswagen Golf

Any

Any

2016

Any



Volkswagen Golf 1.4A TSI

-

N.A

22-Jun-2016

1,395 cc

20

1st Owner, Warranty Till 21/6/2019 Gearbox 6/2021 Auto Retractable Wing Mirrors, Knockdown Rare Seats, Very Low Mi Agent.

Posted: 07-Aug-2018 Tags: 2016 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf, Used Volkswagen



Volkswagen Golf 1.4A TSI EQP

\$86,800

\$9,420 /yr

29-Dec-2016

1,395 cc

15

Agent Warranty Till 2019. High Spec Sunroof, Gps, Keyless, Auto Park Model. \$4k Down Payment! STA Certified Accident Low Mileage Done For Peace Of Mind. 100% Loan Approval ...

Cosmo Automobiles

Posted: 07-Aug-2018 Tags: 2016 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf, Used Volkswagen



Volkswagen Golf 1.4A TSI

\$86,800

\$9,420 /yr

30-Dec-2016

1,395 cc

26

Almost New Excellent Condition. Powerful And Responsive Engine! Flawless Condition! Premium Model With Factory Fitted Beautiful Interior, Low Mileage Done! Under Agent Warrant...

Posted: 07-Aug-2018 Tags: 2016 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf, Used Volkswagen



Volkswagen Golf 1.4A TSI

\$73,800

\$9,260 /yr

25-Jan-2016

1,395 cc

45

7k Down! Monthly Only \$978. 1 Owner Only! Comes With 5 Years VW Agent Warranty. Safe Purchase. Powerful And Res And Exterior Looks Like New Car! Flexible Bank Or In House L...

Posted: 05-Aug-2018 Tags: 2016 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf, Used Volkswagen

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

► Buy
► Lat

Compare

swagen Golf 1.2A TSI

\$67,688

\$8,410 /yr

25-Feb-2016

1,197 cc

46

COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

Company: FASTECH AUTO PTE LTD
VIN: SLH 3839 T
Date: 7.8.18 13:25



SLH 3839 T

Volkswagen : Golf VII Variant 2014- (BA) : Front Wheel Drive : without Independent Rear Suspension : Standard Suspension (G01 G02 G05 G07 G16 G18 G22) + 2UA

Front : Left

Actual	Before	Specified Range
-0°57'	-0°57'	-1°00' 0°00'
7°18'	7°18'	7°07' 8°07'
0°12'	0°11'	0°00' 0°10'
8°12'	8°12'	
7°15'	7°15'	
		-1°39' -0°59'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-1°13'	-1°13'	-1°00' 0°00'
8°05'	8°05'	7°07' 8°07'
0°12'	0°13'	0°00' 0°10'
6°54'	6°53'	
5°40'	5°40'	
		-1°39' -0°59'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°17'	0°16'	-0°30' 0°30'
-0°47'	-0°47'	-0°30' 0°30'
1°18'	1°18'	
0°24'	0°24'	0°00' 0°20'

Rear : Left

Actual	Before	Specified Range
-1°08'	-1°08'	-1°10' -0°50'
0°15'	0°15'	-0°10' 0°30'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°02'	-1°02'	-1°10' -0°50'
0°12'	0°12'	-0°10' 0°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°06'	-0°06'	-0°30' 0°30'
0°27'	0°27'	0°08' 0°32'
0°01'	0°02'	-0°20' 0°20'

Not Allowed
 1/2 7500/-
 4 day
 7/8/18

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6

#01-46,48,50 Autobay

SINGAPORE 417883

VEHICLE NO:SLH 3839T

QTY	PARTICULAR	
1 PCS	FRONT BUMPER	Sub/Toin 1266.12 \$1,655.20
1 PCS	FRONT BUMPER SIDE HOLDER O/S	cm \$89.90
1 SET	FRONT BUMPER CLIPS	neu \$50.00
1 PCS	FRONT BUMPER REINFORCEMENT	11 \$365.30 X
1 PCS	FRONT FENDER O/S	3.1/3 20 686.40 \$866.10
1 PCS	FRONT FENDER INNER SHIELD O/S	Toin \$199.00
1 SET	FRONT FENDER INNER SHIELD CLIPS O/S	neu \$50.00
1 PCS	FRONT FENDER INNER SIDE GARNISH O/S	Toin \$65.00
1 PCS	FRONT FENDER INNER PANEL O/S	n \$899.20 X
1 PCS	HEADLAMP O/S	cm \$1,855.00
1 PCS	FRONT DOOR O/S	10/3 1345.12 \$1,650.00
1 PCS	FRONT DOOR CHECKER O/S	11 \$108.00 X
2 PCS	FRONT DOOR HINGES @\$105.00	11 \$210.00 X
1 PCS	FRONT DOOR RUBBER O/S	neu \$266.00
1 PCS	FRONT DOOR INNER TRIM BOARD O/S	11 \$895.00 X
1 SET	FRONT DOOR INNER TRIM BOARD CLIPS O/S	11 \$50.00 X
1 PCS	FRONT DOOR FRAME BLACK GARNISH O/S	neu \$110.00
1 PCS	FRONT DOOR INNER LOCK O/S	11 \$320.00 X
1 PCS	BONNET	n \$1,055.00 X
1 PCS	FRONT SHOCK ABSORBER O/S	11 \$640.00 X
1 PCS	FRONT KNUCKLE ARM O/S	Sub 650.32 \$822.00
1 PCS	FRONT LOWER ARM BEARING O/S	Daye 266.50 \$350.00
1 PCS	FRONT LOWER ARM O/S	11 \$399.00 X
1 PCS	FRONT STEERING ASSY	11 \$2,166.00 X
1 PCS	FRONT SPORT RIM O/S	20/3 1000 \$1,005.00
1 PCS	FRONT PILLAR O/S	n \$620.00 X
		\$16,760.70

LABOUR CHARGES:

TO CHECK WIRING	\$80.00 - 20
TO TRANSFER FRONT DOOR MECHANISM	\$120.00 - 80
TO CONDUCT WHEEL ALIGNMENT	\$180.00 - 80
TO DISMENTLE & REPLACING FRONT UNDERCARRIAGE	\$380.00 - 120
TO MOUNT VEHICLE ON CAR O-LINER	11 \$380.00 X
TO SPRAY RUST PROOFING	\$120.00 50
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,200.00 600

P-790436

52
 7509.44

1950

	TO PUTTY & SPRAY PAINTING		\$1,800.00 /000
		TOTAL	\$21,020.70

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18014342/Uvd3n2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 16-08-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GW 3756D	Veh. Inspected	SLH 3839T
Policy No.		Coverage (\$)	0.00
Claim No.	GW3756D/SL/pl	Excess (\$)	0.00
Assign From	PEI LI	Assign Date	08/08/2018
2. Vehicle Particulars & Condition			
Make & Model	VOLKSWAGEN GOLF (A)	c.c	1395
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WWWZZZAUZHW068710	Colour	BLUE
Odometer	31688	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40 ZR18	PIRELLI	6 mm
L/H Front Tyre	225/40 ZR18	PIRELLI	6 mm
R/H Rear Tyre	225/40 ZR18	PIRELLI	6 mm
L/H Rear Tyre	225/40 ZR18	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	06/08/2018	Inspection Date	07/08/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 3839T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BENT / TORN	1,655.20	1,266.12
1	FRONT BUMPER SIDE HOLDER O/S	CRACKED	89.90	89.90
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	365.30	-
1	FRONT FENDER O/S	BADLY DENTED	866.10	686.40
1	FRONT FENDER INNER SHIELD O/S	TORN	199.00	199.00
1	SET FRONT FENDER INNER SHIELD CLIPS O/S	NECESSARY	50.00	50.00
1	FRONT FENDER INNER SIDE GARNISH O/S	TORN	65.00	65.00
1	FRONT FENDER INNER PANEL O/S	TO REPAIR SEE LABOUR	899.20	-
1	HEADLAMP O/S	CRACKED	1,855.00	1,855.00
1	FRONT DOOR O/S	DENTED / BENT	1,650.00	1,345.12
1	FRONT DOOR CHECKER O/S	NOT NECESSARY	108.00	-
2	FRONT DOOR HINGES @\$105.00	NOT NECESSARY	210.00	-
1	FRONT DOOR RUBBER O/S	NECESSARY	266.00	266.00
1	FRONT DOOR INNER TRIM BOARD O/S	NOT NECESSARY	895.00	-
1	SET FRONT DOOR INNER TRIM BOARD CLIPS O/S	NOT NECESSARY	50.00	-
1	FRONT DOOR FRAME BLACK GARNISH O/S	NECESSARY	110.00	110.00
1	FRONT DOOR INNER LOCK O/S	NOT NECESSARY	320.00	-
1	BONNET	TO REPAIR SEE LABOUR	1,055.00	-
1	FRONT SHOCK ABSORBER O/S	NOT NECESSARY	640.00	-
1	FRONT KNUCKLE ARM O/S	BENT	822.00	650.32
1	FRONT LOWER ARM BEARING O/S	DAMAGED	350.00	266.50
1	FRONT LOWER ARM O/S	NOT NECESSARY	399.00	-
1	FRONT STEERING ASSY	NOT NECESSARY	2,166.00	-
1	FRONT SPORT RIM O/S	DENTED / BENT	1,005.00	1,005.00
1	FRONT PILLAR O/S	TO REPAIR SEE LABOUR	620.00	-
	LESS 5% DISCOUNT		-	-395.22
			16,760.70	7,509.14

Report Ref No. CS/EG18014342/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO CHECK WIRING.		80.00	20.00
	TO TRANSFER FRONT DOOR MECHANISM.		120.00	80.00
	TO CONDUCT WHEEL ALIGNMENT.		180.00	80.00
	TO DISMENTLE & REPLACING FRONT UNDERCARRIAGE.		380.00	120.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	TO SPRAY RUST PROOFING.		120.00	50.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER INNER PANEL O/S,BONNET AND FRONT PILLAR O/S.		1,200.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,800.00	1,000.00
			4,260.00	1,950.00
GRAND TOTAL			21,020.70	9,459.14
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,500.00

Report Ref No. CS/EGI18014342/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.