

ASS. REC. BY:

REF: CS3/AIG18014350/Gzad3<sup>52</sup> Special Instruction

Surveyor

Guo Qiang

ASSIGNMENT (Office)

From (Person):

Chin Lee Yung

of

AIG

Date/Time:

7/8/18 @ 12:01pm

Estimated Cost:

Bill to:

OD (TI) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKX 4915C

Insured:

SLL 535T

at Workshop n/s:

H.S. Automotive

Tel:

65381368

of

Blk 2 Kelki Blk Ave 2 #02-25

Policy No:

0999994765

Claim No:

814268644986

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A.

25/07/2018

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

12:39pm @ 7/8/18

Person Contacted:

Alex

Vehicle IN/OUT

Date/Time

Action/Instruction (x) Estimate

SKX 4915C - NA / MSG18014295 / 13

DOA: 25/07/2018

SLL 535T - NA / MSG18014295 / 13

DOA: 25/07/2018

8/8/18

24 months led.

DOA? Repair (days)

13/8/18

After repair.





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG18014350/Gz4d3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 07-08-2018	
		Code : AIG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SLL 535T	Veh. Inspected	SKX 4915C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	07/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/07/2018	Inspection Date	07/08/2018
Survey held at	H S AUTOMOTIVE SERVICES 2 KAKI BUKIT AVE 2 #01-15 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Your password will expire in 6 days. [Click here to change it.](#)

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...**

From: Chin, Lee-Ying

To: assignments@lkkauto.com, Admin A

Cc: Fong, Andy-SY

Sent: 7/8/2018 12:01:27 PM

Attachments:  tmp8C70.tif  tmp8C70.tif

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

---

**From:** Sim Teo Koon [mailto:tk\_sim@juseq.com.sg]

**Sent:** Tuesday, August 07, 2018 11:19 AM

**To:** Mithoosingh, Aashweenjeetkaur

**Subject:** FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLL535T AND SKX4915C ON 25/07/2018

Dear Sir,

We refer to your email.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

- 1) PAR Automotive Consultancy,
- 2) SK Auto Consultants,
- 3) Chartered Auto Assessors,
- 4) LCW APPRAISER PTE LTD
- 5) Sincere Appraisal Services,
- 6) Pal's Appraisal Pte Ltd,
- 7) Mc-Coy Appraiser Pte Ltd,
- 8) CM Automotive Consultancy,

Please be informed that if the above is not agreeable by you, our client's motor vehicle is available for pre-repair inspection at the under-stated workshop:-

**H S Automotive Services**

Blk 2 Kaki Bukit Avenue 2 #02-25

Kaki Bukit AutoHub,

Singapore 417921

Person In-Charge: Mr. Alex. Tel: 6538 1368. Fax: 6538 1367

\* Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11.

Regards,

Sim Teo Koon (On behalf of Mr Michael Yap)

JusEquity Law Corporation

171 Chin Swee Road #02-06, CES Centre

Singapore 169877

Tel: 6506 6488 / 6536 9339

Fax: 6536 5368

E-mail: tk\_sim@juseq.com.sg

This message (and all its attachments) is intended only for the use of the individual or entity to whom it is addressed and is privileged and confidential. If you are not the intended recipient, please notify us immediately by return electronic mail, delete this message and you should not disseminate, distribute or copy any information contained herein.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



# Jusequity Law Corporation

## ADVOCATES & SOLICITORS - COMMISSIONER FOR OATHS

171 Chin Swee Road #02-06, CES Centre, Singapore 169677  
Telephone (65) 6536 9339, (65) 6253 1812, (65) 6397 2008, (65) 6533 2327  
Fax : (65) 6253 0120 (Convooyanding) ; (65) 6536 5368 (Litigation)  
Email : [lvj@juseq.com.sg](mailto:lvj@juseq.com.sg) website: [www.juseq.com.sg](http://www.juseq.com.sg)

Our Ref: JEQ/180626/0818/ HS A

Your Ref: SLL535T

7 August 2018

**LCRF PTE LTD**  
60 ANSON ROAD # 11 - 01  
MAPLETREE ANSON  
SINGAPORE 079914

By Post Only

**AIG Asia Pacific Insurance Pte Ltd**  
Singapore

By Fax: 6835 7416 Only

Dear Sir

### ACCIDENT INVOLVING SKX4915C & SLL535T ON 25-7-2018

We act for the owner of vehicle no. SKX4915C.

We hereby notify you of a road traffic accident on **25 July 2018** at about **0930 hrs.**, at Woodlands Ave 2 involving our client's vehicle and vehicle registration no. **SLL535T** driven by you / your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

**CONFIDENTIALITY CAUTION**

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	06/08/2018 17:22
Date Of Accident	25/07/2018 09:30
Exact Location Of Accident	WOODLANDS AVE 2
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX4915C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG CHOON GUAN KENNETH
NRIC No	S8233835G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91775358
Alternative Phone No	OTHERS-91775358

#### Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 80449566 QMX
Cover Note Number	

#### Driver

Name of Driver	NG CHOON GUAN KENNETH
NRIC No	S8233835G
Date Of Birth	07/10/1982
Occupation	INDOOR
Date Of Driving Pass	30/08/2004
Driving Experience	13 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91775358
Fax Number	
Contact Number	OTHERS-91775358
E Mail Address	NOEMAIL

Address BLK 682A EDGEDALE PLAINS  
 #12-753  
 Postcode 821682  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General information of the Accident**

Type Of Accident COLLISION - CHANGE/CROSS LANE  
 Weather Conditions RAINING  
 Road Surface WET

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

PLS REFER TO THE ATTACHED STATEMENT.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLL535T  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE HIRE  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

## SKETCH PLAN

### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

MY INTENTION IS GOING STRAIGHT TOWARDS WOODLANDS RIVERSIDE ROAD AND MY VEH WAS STATIONERY AT LANE SO I CHECKED MY LEFT SIDE MIRROR AND CONFIRMED THAT TRAFFIC WAS CLEARED FROM LANE 3, WHILE I TURNING VEH B SUDDENLY CUT INTO LANE 3 AND HIT ONTO MY VEH LEFT HAND FRONT PORTION.

VEH B CHANGE LANE FROM LANE 4 TO LANE 3

(REASON OF LATE REPORTING IS BECAUSE VEH B DRIVER INTENTION TO SETTLE PRIVATELY, HIS CAR IS UNDER PRIVATE HIRER CONTRACT)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]* 06/08/18

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

[> Back to OneMotoring](#)**Enquire Transfer Fee****Vehicle Details**

Vehicle No. :	SKX4915C
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	HYUNDAI
Vehicle Model :	ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Chassis No. :	KMHDH41CMGU653608
Propellant :	Petrol
Engine No. :	G4FGFU059943
Engine Capacity :	1591 cc
Maximum Power Output :	97.0 kW ( 130 bhp)
Maximum Laden Weight :	1800 kg
Unladen Weight :	1292 kg
Year Of Manufacture :	2015
Original Registration Date :	16 Dec 2015
Lifespan Expiry Date :	-
COE Category :	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium :	\$56,989.00
COE Expiry Date :	15 Dec 2025
Road Tax Expiry Date :	15 Dec 2018
PARF Eligibility Expiry Date :	15 Dec 2025
Inspection Due Date :	15 Dec 2018
Intended Transfer Date :	13 Aug 2018
CO2 Emission :	163.00 (g/km)
CEV/VES Rebate Utilised Amount :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

**Amount Payable**

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
<b>Total Amount Payable :</b>			<b>25.00</b>

You may print this page for reference.

OK

Print

## &gt; Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	3835G
<b>Vehicle Details</b>	
Vehicle No.:	SKX4915C
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Sep 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	G4FGFU059943
Chassis No.:	KMHDH41CMGU653608
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$15,037.00
Original Registration Date:	16 Dec 2015
First Registration Date:	16 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$15,037.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Dec 2025
PARF Rebate Amount:	\$11,277.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	15 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,989.00
COE Rebate Amount:	\$41,439.00
<b>Total Rebate Amount:</b>	<b>\$52,716.00</b>

The information contained herein is correct as at 07 Sep 2018

OK



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Jul 2018 <a href="#">Edit Reg</a>		07 Aug 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LCRF PTE LTD , Co. Reg. No.: 201624597K		
Main Claimant:	NG CHOON GUAN KENNETH, ID: S8233835G		
Vehicle Reg. No.:	SKX4915C	Date of Loss:	25/07/2018 00:00 - :59 [31 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8142686449SG	Policy/Cover Note No.:	0999994765 (Comprehensive)
Vehicle Reg. No. (Insured):	SLL535T	Policy No. (Claimant):	
		Excess:	
Repairer:	Hs Automotive (HQ) autohub, 408070 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Wilson-KL]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 20/08/2018]		
Claimant's Solicitor:	JusEquity Law Corporation - Tel: 65369339		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG (10/08/2018): Request To Upload TP GIA Report

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.



# Claim Documents

**\*SKX4915C (8142686449SG)**  
**[SLL535T]**  
**TP**  
**NG CHOON GUAN KENNETH**  
**Jul 25 2018 12:00AM**  
**[LCRF PTE LTD ]**  
**Hs Automotive**

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <span style="float:right">View in Browser ▼</span>	
<b>Photos/Images</b>										3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	10/08/18 10:17	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>		
2	10/08/18 10:17	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>		
3	10/08/18 10:17	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>		
4	10/08/18 10:17	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>		
5	10/08/18 10:17	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>		
6	10/08/18 10:17	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>		
7	10/08/18 10:17	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>		
8	10/08/18 10:17	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>		
9	10/08/18 10:17	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>		
10	10/08/18 10:17	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>		
11	10/08/18 10:17	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>		
12	10/08/18 10:17	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>		
13	10/08/18 10:17	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>		
14	10/08/18 10:17	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>		
15	10/08/18 10:17	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>		
16	10/08/18 10:17	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>		
17	10/08/18 10:17	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>		
18	10/08/18 10:17	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>		
19	10/08/18 10:18	<b>Dismantled Parts</b>						 Load JPG	<input checked="" type="checkbox"/>		
20	10/08/18 10:18	<b>Dismantled Parts</b>						 Load JPG	<input checked="" type="checkbox"/>		
21	10/08/18 10:18	<b>Dismantled Parts</b>						 Load JPG	<input checked="" type="checkbox"/>		
22	10/08/18 10:18	<b>Dismantled Parts</b>						 Load JPG	<input checked="" type="checkbox"/>		
23	10/08/18 10:18	<b>Dismantled Parts</b>						 Load JPG	<input checked="" type="checkbox"/>		
24	10/08/18 10:18	<b>Dismantled Parts</b>						 Load JPG	<input checked="" type="checkbox"/>		
25	10/08/18 10:18	<b>Dismantled Parts</b>						 Load JPG	<input checked="" type="checkbox"/>		
26	10/08/18 10:18	<b>Dismantled Parts</b>						 Load JPG	<input checked="" type="checkbox"/>		
27	10/08/18 10:18	<b>Dismantled Parts</b>						 Load JPG	<input checked="" type="checkbox"/>		
28	10/08/18 10:18	<b>Dismantled Parts</b>						 Load JPG	<input checked="" type="checkbox"/>		
29	10/08/18 10:18	<b>Dismantled Parts</b>						 Load JPG	<input checked="" type="checkbox"/>		
30	10/08/18 10:18	<b>Dismantled Parts</b>						 Load JPG	<input checked="" type="checkbox"/>		
31	10/08/18 10:18	<b>Dismantled Parts</b>						 Load JPG	<input checked="" type="checkbox"/>		
32	10/08/18 10:18	<b>Dismantled Parts</b>						 Load JPG	<input checked="" type="checkbox"/>		
33	10/08/18 10:18	<b>Dismantled Parts</b>						 Load JPG	<input checked="" type="checkbox"/>		
34	10/08/18 10:18	<b>Dismantled Parts</b>						 Load JPG	<input checked="" type="checkbox"/>		
35	10/08/18 10:18	<b>Dismantled Parts</b>						 Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
38	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	10/08/18 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	15/08/18 12:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	15/08/18 12:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	15/08/18 12:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	15/08/18 12:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	15/08/18 12:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	15/08/18 12:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	15/08/18 12:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	15/08/18 12:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	15/08/18 12:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	15/08/18 12:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	15/08/18 12:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	15/08/18 12:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	15/08/18 12:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	15/08/18 12:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	10/08/18 09:32	OI GIA REPORT	 Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG18014350/GZ4D3S2  
**Date:** 25/09/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994765  
**Claimant Vehicle No :** SKX4915C **Insured Vehicle No :** SLL535T  
 Date of Loss: 25/07/2018 Nature of Claim: TP Claim No: 8142686449SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX4915C**  
 Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGFU059943  
 Reg. Date: 16/12/2015 (Man. Year: 2015) Chassis No: KMHDH41CMGU653608  
 Colour: White Odometer: 56299 km  
 Engine Capacity: 1591 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16  
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm  
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 07/08/2018  
 Date Inspected: 07/08/2018 Inspected At: HS AUTOMOTIVE (HQ)  
 BLK 2 KAKI BUKIT AVE 2 #02-25  
 Singapore 413002  
 Estimated Period of Repair: 5.0 days

**Adjuster:** XING GUO QIANG

**Manager:** Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cut	0.00 F	*- F
2	1		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
3	1		*FRT BUMPER SPONGE	Cut	0.00 F	*- F
4	1		*FRT LH HEADLAMP ASSY	Broken	0.00 F	*- F
5	1		*FRT LH FENDER INNER SHIELD	Cut	0.00 F	*- F
6	1		*FRT GRILLE	Cut	0.00 F	*- F
7	1		*FRT GRILLE LOGO	Necessary	0.00 F	*- F
				<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >