

ASS. REC. BY:

REF: CS3/ICS/8014372/B240307

Special Instruction:

Mr. Lim

Mr. Lim

ASSIGNMENT (Office)

From (Person):

Janice

of

ECICS

Date/Time:

7/8/18 @ 11:52am

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

81Y 2152G

Insured:

SLD 1339D

at Workshop m/s

Wee Hoe Auto

Tel:

6855 0019

of

19 Kim Chuan Terrace

Policy No:

Claim No:

DMPC 1800316H/02/CT

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/08/2018

CA / REV / REP. / REV 24 HRS

Cup

H.O.D. Endorsement:

Date/Time

12:28pm @ 7/8/18

Person Contacted:

Mr. Kiat

Vehicle - IN / OUT

Date/Time	Action/Instruction (X) Estimate
	81Y 2152G - X
	SLD 1339D - X
8/5/18	Dismantled.
13/8/18	AHIC Repair


PRS

ASSIGNMENT

From: _____ Date: 8/8/2018
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJY 2152 G
 at Workshop m/s: WEE HEE AUTO
 of: 19 Kim Chuan Terrace
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SJY 2152 G Yr Regn: 12 Aug 2010
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mazda 2 c.c 1498
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 195136 T/Radio: Insured / Std / NI / NA
 Eng/No: ZY 633238
 C/No: MM6DE10Y1A0117142
 Gen. Cond: Good Fair / Poor / Burnt
 Steering: Normal / Jammed / Leaked / Burnt or _____
 Brake: Normal / Jammed / Leaked / Burnt or _____
 Modi: Nil S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/50R15
 R: 195/50R15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or CST
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 8/8/18
 Survey held at LKK Auto Cons. 1115
 Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 10 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS (up)
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Date / Time	Action / Instruction
<u>15/8/18</u>	<u>submit PRS Report</u>
	<u>Range \$6800/2 - 7,800/2</u>
	<u>[Signature]</u>
	<u>15/8/2018</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____

Report Format : _____
 Lump Sum / I.B.I: (\$) _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 S + RS: _____
 Photos: _____
 Others: _____
 TOTAL: 310

Nivitha (LKK Auto)

From: Janice Goh Siew Geok (ECICS, Claims) <Janice_Goh@ecics.com.sg>
Sent: Tuesday, 7 August 2018 11:52 AM
To: 'assignments'
Cc: lalita@mcclegalfirm.com; Crystabelle Tan Gek Peng (ECICS, Claims); ECICS Claims; LS4
Subject: RE: ACCIDENT INVOLVING SJY2152G AND SLD1339D ALONG PIE/CHANGI (BEFORE CTE), SINGAPORE ON 1 AUGUST 2018 AT 1520 HOURS ; ECICS's ref DMPC1800316H/02/CT
Attachments: pri ecics.pdf; gia.pdf; lta d.pdf

Hi LKK

Please refer to the email below.
Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: ECICS Claims
Sent: Tuesday, 7 August, 2018 11:50 AM
To: 'LS4'
Cc: lalita@mcclegalfirm.com; ECICS Claims; Crystabelle Tan Gek Peng (ECICS, Claims)
Subject: RE: ACCIDENT INVOLVING SJY2152G AND SLD1339D ALONG PIE/CHANGI (BEFORE CTE), SINGAPORE ON 1 AUGUST 2018 AT 1520 HOURS ; ECICS's ref DMPC1800316H/02/CT

Without Prejudice

Hi Jayme

Thank you for your email.
We are not agreeable with your surveyor and we will appoint LKK for the PRS.

Aside to LKK

Please assist to arrange TP PRS.

Our claim no DMPC1800316H/02/CT and case handler is Ms Crystabelle Tan.

Thank you.

Regards,

Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: LS4 [mailto:ls4@mcclegalfirm.com]
Sent: Monday, 6 August, 2018 4:47 PM
To: ECICS Claims
Cc: lalita@mcclegalfirm.com
Subject: RE: ACCIDENT INVOLVING SJY2152G AND SLD1339D ALONG PIE/CHANGI (BEFORE CTE), SINGAPORE ON 1 AUGUST 2018 AT 1520 HOURS

Our Ref LC/5144/18/PKB1(V1)B
Your Ref SLD1339D

6 August 2018

ECICS LIMITED
(INSURER OF SLD1339D)
Attn : Ms Janice Goh

BY EMAIL ONLY

Dear Sirs

NOTICE FOR PRE-REPAIR INSPECTION
CLAIMANT: PONNANAMPATTI KRISHNAN BABU
ACCIDENT INVOLVING SJY2152G AND SLD1339D ALONG PIE/CHANGI (BEFORE CTE), SINGAPORE ON 1 AUGUST 2018 AT 1520 HOURS

We refer your email of 6/8/18.

We regret to inform that our client rejects the list of proposed surveyors as given by you.

Our client proposes Prominent Appraiser for your due consideration.

Kindly let us know if you agree or disagree to our above surveyor within the timeline stipulated under the NIMA protocol.

Yours Faithfully

Jayne Lim (Ms)
Legal Secretary
MATHEW CHEW & CHELLIAH (UEN No: 53131184L)
133 New Bridge Road
#13-10 Chinatown Point
Singapore 059413
Tel: 6533 1123 Fax: 6533 1121 Email: lawyers@mcclegalfirm.com

CONFIDENTIALITY: The information contained in this message is confidential information and is also subject to legal professional privilege. If you are not the intended recipient, you should not disseminate,

distribute or copy this communication. If you have received this document in error, please notify us immediately by fax or phone.

From: ECICS Claims [mailto:claims@ecics.com.sg]

Sent: Monday, 6 August, 2018 15:29

To: LS4

Cc: lalita@mcclegalfirm.com; ECICS Claims

Subject: RE: ACCIDENT INVOLVING SJY2152G AND SLD1339D ALONG PIE/CHANGI (BEFORE CTE), SINGAPORE ON 1 AUGUST 2018 AT 1520 HOURS

Without prejudice

Dear Jayme

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Regards,

Janice Goh

Claims Division

DID: +65 6303 0182

FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

From: LS4 [mailto:ls4@mcclegalfirm.com]

Sent: Monday, 6 August, 2018 2:39 PM

To: ECICS Claims

Cc: lalita@mcclegalfirm.com

Subject: ACCIDENT INVOLVING SJY2152G AND SLD1339D ALONG PIE/CHANGI (BEFORE CTE), SINGAPORE ON 1 AUGUST 2018 AT 1520 HOURS

Our Ref LC/SJY2152G

Your Ref SLD1339D

6 August 2018

ECICS LIMITED

BY EMAIL ONLY

(INSURER OF SLD1339D)

Dear Sirs

NOTICE FOR PRE-REPAIR INSPECTION

CLAIMANT: PONNANAMPATTI KRISHNAN BABU

ACCIDENT INVOLVING SJY2152G AND SLD1339D ALONG PIE/CHANGI (BEFORE CTE), SINGAPORE ON 1 AUGUST 2018 AT 1520 HOURS

We act for Ponnampatti Krishnan Babu.

We are instructed by our client to notify you of a road traffic accident on the above date and time and place involving our client's motor-vehicle **SJY2152G** and your insured motor-vehicle SLD1339D. A copy of our client's Singapore Accident Statement is enclosed.

As a result of the accident, our client's motor-vehicle has been damaged. Before our client proceeds to repair the damaged motor-vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey to our client's vehicle. Inspection may be carried out at the following address:-

Venue: **WEE HOE AUTO SERVICE**
19 Kim Chuan Terrace
Singapore 537041

Kindly confirm the date and time as well as the name of the surveyor who will be carrying out the inspection. You may contact the workshop at:

Contact Person: KIAT
Telephone no: 6858-0019

Acknowledgment by surveyor	
_____ Signature Name	_____ Date

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor-vehicle without further reference to you.

Yours faithfully

Cc **WEE HOE AUTO SERVICE - by fax**

Yours Faithfully

Jayme Lim (Ms)

Legal Secretary

MATHEW CHEW & CHELLIAH (UEN No: 53131184L)

133 New Bridge Road


#13-10 Chinatown Point

Singapore 059413

Tel: 6533 1123 Fax: 6533 1121 Email: lawyers@mcclegalfirm.com

CONFIDENTIALITY: The information contained in this message is confidential information and is also subject to legal professional privilege. If you are not the intended recipient, you should not disseminate,

distribute or copy this communication. If you have received this document in error, please notify us immediately by fax or phone.



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

MATHEW CHEW & CHELLIAH

advocates & solicitors ❖ commissioner for oaths ❖ notary public

133 New Bridge Road #13-10 Chinatown Point Singapore 059413
Tel: (65) 6533-1123 Fax: (65) 6533-1121 (not for service of Court documents) Email: lawyers@mcclegalfirm.com
UEN No: 53131184L

Our Ref LC/SJY2152G
Your Ref SLD1339D

6 August 2018

ECICS LIMITED
(INSURER OF SLD1339D)

BY EMAIL ONLY

Dear Sirs

NOTICE FOR PRE-REPAIR INSPECTION
CLAIMANT: PONNANAMPATTI KRISHNAN BABU
ACCIDENT INVOLVING SJY2152G AND SLD1339D ALONG PIE/CHANGI (BEFORE CTE), SINGAPORE ON 1 AUGUST 2018 AT 1520 HOURS

We act for Ponnampatti Krishnan Babu.

We are instructed by our client to notify you of a road traffic accident on the above date and time and place involving our client's motor-vehicle **SJY2152G** and your insured motor-vehicle SLD1339D. A copy of our client's Singapore Accident Statement is enclosed.

As a result of the accident, our client's motor-vehicle has been damaged. Before our client proceeds to repair the damaged motor-vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey to our client's vehicle. Inspection may be carried out at the following address:-

Venue: **WEE HOE AUTO SERVICE**
19 Kim Chuan Terrace
Singapore 537041

Kindly confirm the date and time as well as the name of the surveyor who will be carrying out the inspection. You may contact the workshop at:

Contact Person: KIAT
Telephone no: 6858-0019

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor-vehicle without further reference to you.

Yours faithfully

Cc **WEE HOE AUTO SERVICE - by fax**

Acknowledgment by surveyor

Signature
Name

Date



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ECICS LTD		Ref : CS3/ICS18014372/Bz4d3	
10 EUNOS ROAD 8 SINGAPORE POST CENTRE #09-04A SINGAPORE 408600		Date : 07-08-2018	
Code : ICS			
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SLD 1339D	Veh. Inspected	SJY 2152G
Policy No.		Coverage (\$)	0.00
Claim No.	DMPC1800316H/02/CT	Excess (\$)	0.00
Assign From	JANICE GOH	Assign Date	07/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/08/2018	Inspection Date	07/08/2018
Survey held at	WEE HOE AUTO SERVICE 19 KIM CHUAN TERRACE SINGAPORE 537041		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

689

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy at/will.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	02/08/2018 17:14
Date Of Accident	01/08/2018 15:20
Exact Location Of Accident	ALONG PIE/CHANGI (BEFORE CTE)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJY2152G /
Insured/Policyholder	
Name Of Registered Owner	PONNANAMPATTI KRISHNAN BABU
NRIC No	S79602771
Email Address	KRISHNANBABU.BABU@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91083508
Alternative Phone No	OFFICE-91083508
Vehicle Particulars	
Manufacturer	MAZDA
Model	2
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10705808
Cover Note Number	
Driver	
Name of Driver	PONNANAMPATTI KRISHNAN BABU
NRIC No	S79602771
Date Of Birth	10/09/1979
Occupation	INDOOR
Date Of Driving Pass	22/03/2004
Driving Experience	14 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91083508
Fax Number	
Contact Number	OFFICE-91083508
E-Mail Address	KRISHNANBABU.BABU@GMAIL.COM

DETAILS OF OTHER VEHICLE PROPERTY ?

Vehicle Registration Number	SLZ236H
Vehicle Make/Model/Colour	KIA/FORTE K3 1.6A
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN DRIVER
NRIC/Passport Number	
Contact Number	97102663
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

ACCIDENT STATEMENT (2000 characters)

I was travelling along PIE/CHANGI when vehicle in front of me stop. I managed to stop in time, about 2-3 seconds i felt an impact onto rear of my car SJY2152G. Due to the impact, my car SJY2152G move forward & had contact onto rear of car SLZ236H that was in front of me. No injuries involved.

Total 07 vehicles involved in chain collision. I only took 02 cars that was in front of me & rear.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHD FAZLY BIN ISMAIL



MARS Officer

Registered Owner or Driver's Signature

Job Complete Date/Time

2 August 2018 3:24 pm

Date/Time:

2 August 2018 3:24 pm

Address NA
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I was travelling along PIE/CHANGI when vehicle in front of me stop. I managed to stop in time, about 2-3 seconds I felt an impact onto rear of my car SJY2152G. Due to the impact, my car SJY2152G move forward & had contact onto rear of car SLZ236H that was in front of me. No injuries involved. Total 07 vehicles involved in chain collision. I only took 02 cars that was in front of me & rear.


Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WILL UPLOAD TO FILEZILA ONCE INSURED SEND
 Was there any audio recorded? NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLD1339D /
 Vehicle Make/Model/Colour TOYOTA/CAMRY 2.0
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver JAMES TAN
 NRIC/Passport Number
 Contact Number 98452431
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 1


Sketch Plan



Identification Card



Identification Card



> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0277I
Vehicle Details	
Vehicle No.:	SJY2152G
Vehicle to be Exported:	No
Intended De-registration Date:	08 Aug 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 SDN AT V GRADE
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	ZY633238
Chassis No.:	MM6DE10Y1A0117142
Maximum Power Output:	76.0 kW (101 bhp)
Open Market Value:	\$16,395.00
Original Registration Date:	12 Aug 2010
First Registration Date:	12 Aug 2010
Transfer Count:	1
Actual ARF Paid:	\$16,395.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Aug 2020
PARF Rebate Amount:	\$9,837.00
Intended COE Rebate Details	
COE Expiry Date:	11 Aug 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$32,104.00
COE Rebate Amount:	\$6,446.00
Total Rebate Amount:	\$16,283.00

The information contained herein is correct as at 08 Aug 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Aug 2018 16:26 Edit Reg		07 Aug 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -, Email: KRISHNANBABU.BABU@GMAIL.COM									
Main Claimant: PONNANAMPATTI KRISHNAN BABU , ID: S79602771									
Vehicle Reg. No.:	SJY2152G	Date of Loss:	01/08/2018 15:00 - :59 [95 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SLD1339D	Policy No. (Claimant):							
		Excess:							
Repairer: Wee Hoe Auto Service (HQ) 19 Kim Chuan Terrace, Singapore 537041, 537041 Kaki Bukit - Tel: 68580019									
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 30/08/2018]									
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJY2152G
[SLD1339D]
TP
PONNANAMPATTI KRISHNAN BABU
Aug 1 2018 3:00PM
[-]
Wee Hoe Auto Service

Upload Documents Upload Photos Compose New Letter			View <input type="button" value="View in Browser"/>
Photos/Images			3 per page <input type="button" value="v"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="checkbox"/>
1	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
2	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
3	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
4	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
5	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
6	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
7	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
8	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
9	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
10	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
11	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
12	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
13	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
14	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
15	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
16	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
17	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
18	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
19	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
20	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
21	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
22	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
23	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
24	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
25	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
26	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
27	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
28	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
29	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
30	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
31	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
32	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
33	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
34	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
35	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
36	20/08/18 15:02	General View	<input checked="" type="checkbox"/>
37	20/08/18 15:02	General View	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
39	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
40	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
41	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
42	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
43	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
44	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
45	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
46	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
47	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
48	20/08/18 15:03	Front View Right	Load JPG	<input checked="" type="checkbox"/>
49	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
50	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
51	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
52	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
53	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
54	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
55	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
56	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
57	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
58	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
59	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
60	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
61	20/08/18 15:03	General View	Load JPG	<input checked="" type="checkbox"/>
62	20/08/18 15:03	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
63	20/08/18 15:03	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
64	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
65	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
66	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
67	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
68	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
69	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
70	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
71	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
72	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
73	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
74	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
75	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
76	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
77	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
78	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
79	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
80	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
81	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
82	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
83	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
84	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
85	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
86	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
87	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
89	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
90	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
91	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
92	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
93	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
94	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
95	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
96	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
97	20/08/18 15:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
98	20/08/18 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
99	20/08/18 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
100	20/08/18 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
101	20/08/18 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
102	20/08/18 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
103	20/08/18 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
104	20/08/18 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
105	20/08/18 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
106	20/08/18 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
107	20/08/18 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
108	20/08/18 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
109	20/08/18 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
110	20/08/18 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
111	20/08/18 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
112	20/08/18 15:07	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
113	20/08/18 15:07	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/ICS18014372/BZ4D3E2
Date: 20/08/2018

REFERENCE

Handling Insurer: ECICS Limited	Policy No:			
Claimant Vehicle No : SJY2152G	Insured Vehicle No :	SLD1339D		
Date of Loss: 01/08/2018	Nature of Claim:	TP	Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY2152G	Engine No:	ZY633238
Make & Model:	MAZDA 2, 1.5 (A)	Chassis No:	MM6DE10Y1A0117142
Reg. Date:	12/08/2010 (Man. Year: 2010)	Odometer:	195136 km
Colour:	Grey		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	CST 6 mm	Rear Left Side:	CST 6 mm
Front Right Side:	CST 6 mm	Rear Right Side:	CST 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	07/08/2018	
Date Inspected:	08/08/2018 Inspected At:	Wee Hoe Auto Service (HQ) 19 Kim Chuan Terrace, Singapore 537041 Singapore 537041
Estimated Period of Repair:	10.0 days	

Adjuster: Lim Teow Guan

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,800.00 - \$7,800.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Aug 2018)
Parts: 143	MAZDA 2 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJY2152G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >