

INS CASE OWNER:

CC 4 / III180

14399

R1 j3 4

LKK:

IDAC:

Surveyor:

RASM

DOI:

6/8/18

Date / Time:

6/8/18

Registration / Version:

6/8/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SHB 4221 Y

Name of Insured : LPL

Insured Tel No. : HP:

Excess Sec II : S\$ D.O.A : 19/11/18

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : KHOO SWEE CONG

Driver Tel No. : 96283327 (V/L: YES / NO)

Claim No. : M LAM 001

Policy No. : H-140

Make / Model : BPE 7 WOODLANES

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

JMU 1954

INSRS:
WSP: G.N.G.
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

1/1/18
801

JMU 1954 - X;

SHB 4221 Y - 6/1/18 12:00 / 11/11/18 12:00

50% REQUEST IVF FOR REVIEW

WP - WSP PASS TO LAWYER.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 100 15

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

-

(\$

x

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:


COPIES SENT
12/11/18

Surveyor: *Rasul*

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OO / TP / WS / TP RES / QD RES / EVA / INV / MV
 To Inspect Vehicle No: *JMU 1954*
 at Workshop n/s *GNG MOTOR TRADING*
 of *BLK L, DEEN LANE W 10 # 0156*
 Insured: *III*
 Policy No. _____
 Claims No. _____
 Sum Insured _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: *4* days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: *Jmu 1954* Yr Regn: _____
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: *YAMAHA* C.C. _____
 Colour: *MULTI* A/C Insured / Std / NI / NA
 Sp Reading: *06957* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: _____
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / SRim / STD A/Rim or
 Tyre Size: F: *70/90-17*
 R: *80/90-17*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or *Duro*

Front *3* mm Rear *3* mm
 R/Bal. mm L/Bal. mm
 D.O.A. D.O.I. *06/08/18*

Survey held at *GNG MOTOR*
 Des. of Damages: Fr / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/5 \$900/-

R (\$521 / 379)

Date/Time: File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

_____ \$ = RS. _____ \$

} Photos

} Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)



南藝摩哆公司

G. N. G. MOTOR TRADING CO.

Block 6, Defu Industrial Estate Park C, Avenue 1

Defu Lane 10, #01-564, Singapore 1953.

TEL: 2836560, 2805065

REG. NO. 247124-00-A

代理各種摩哆西卡及保險
AGENT FOR ALL TYPES OF MOTOR-CYCLE & INSURANCE

Your Ref: JMU1954

Our Ref: YAMAHA 115ZR

Date: 02/08/18

1pc. Front MUDGUARD - 45 - sc	948
1SG. Front NO. PLATE - 20 - nu / (S/N)	10%
1pc Front WHEEL - 160 - repair Bt	853.20
1pc. Front BRAKE DISC - 85 - 7 X sc	S/N - 20
1pc. FOOTREST BRACKET - 55 - 7A	
1pc. LEFT FOOTREST RUBBER - 10 - at	
1SG. Front Fork ASSY - 250 - 7A	853.20
1SG. Front STEERING CONE - 85 - nu	20.00
2PCS L & R SIDE COVER - 90 - CRA	230.00
1SG. Front HEADLIGHT - 55 - sc	1103.20
1pc. Front HEADLIGHT COWLING - 38 - sc	20%
1pc. Front COWLING - 95 - sc	882.56
1pc. HANDLE BAR - 58 - 7 X sc	45-900
1SG. HANDLE BALANCER - 20 - sc	4 day
1SG. MIRROR - 30 - sc	Rasul
1pc. Brake Lever - 15 - sc	#p 9001026
230 { TOWING - 30 /	4 days
LABOUR CHARGE - 280	Lump sum
200	06/08/18 @ 1520
	Resony after repair
	email: rasul@1kkauto.com

BSA LAW CHAMBERS LLC

Advocates & Solicitors

Your Ref :

Our Ref : BSA.9484.jy

Date : 2nd August 2018133 New Bridge Road
#10-04 Chinatown Point
Singapore 059413

Tel : 6236 2001

Fax : 6532 0412

Email : bala@bsalaw.com.sg

UEN / GST Regn No: 201502330R

Secretary's DID: 6435 0019 (Jayanthi)
6435 0020 (Alice)

BY FAX No. 6224 4174 Only

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street #05-00 IOB Building

Singapore 049711


Motor Claims Department**NOTICE OF ACCIDENT****YOUR INSURED VEHICLE REGISTRATION NO: JMU 1954****ACCIDENT ON 19.7.2018 AT ABOUT 23.50 HRS INVOLVING JMU 1954 & SHB 4221Y
ALONG BKE**

We are informed by the repairers of vehicle registration no. JMU 1954 to notify you of the captioned road traffic accident.

Please note that State Court Practice Directions Amendment 1 of 2016 applies to this case. A copy of the accident statement / police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully


BALASUBRAMANIAM
Enccc GNG Motor Trading
By Fax No. 6383 3763
Vehicle No. JMU 1954



**SINGAPORE
POLICE FORCE**



T/20180720/2072

2 of 3

Police Station Of Origin:

Tiong Bahru NPP

128 Kim Tian Road #01-123 SINGAPORE

160128

Tel No: 1800-2739999

Report No. T/20180720/2072

CONTINUATION OF REPORT

Rider			
Name	CHOONG HOI KONG	ID No.	G0047143M
Related Vehicle	NIL	Contact No.	81932717
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the above mentioned date time and place, while I was riding on my motorbike, I was knocked from the rear by a blue colour taxi. I was injured and conveyed to the hospital. Traffic Police came and attended to the accident.

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 6 August 2018 1:58 PM
To: Jayanthi; Suraidah B Saidi PTCBC; Catherine Chong (LKK Auto)
Cc: 'Bala'; Zuhaidah Samsuri
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. JMU1954 (Accident involving JMU1954 and SHB4221Y on 19.07.2018)
Attachments: shb4221y_20180806093925.pdf

2.45pm @ 6/8/2018
person @ Mr-Ong
vehicle in
SUR @ Rahul

Dear Sir / Mdm,

Please conduct a survey on TP vehicle JMU1954 and let us have your report urgently.

This claim will be handled by Ms Aida.

*Kindly upload this survey request email to merimen.

Thank You,

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Jayanthi [mailto:jaya@bsalaw.com.sg]
Sent: 06 August, 2018 11:30 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: 'Bala' <bala@bsalaw.com.sg>
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. JMU1954 (Accident involving JMU1954 and SHB4221Y on 19.07.2018)

Dear Mr Wee,

We refer to your email dated 6th August 2018.

Kindly take note that we have received instructions from our client to appoint **LKK Auto Consultants Pte Ltd** to conduct the PRI.

Please note that our client's vehicle is available for inspection at the following address:-

G.N.G. Motor Trading

Blk 6 Defu Lane 10

#01-564

Singapore 539187

(Tel : 6283 6560/9664 8992)

Attention: Mr. Ong

Thank you

Regards
Ms Jayanthi
For and on behalf of
M/s BSA Law Chambers LLC
DID: 6435 0019

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, August 06, 2018 9:44 AM
To: bala@bsalaw.com.sg
Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. JMU1954 (Accident involving JMU1954 and SHB4221Y on 19.07.2018)

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee
Motor Claims Dept.
India International Insurance Pte Ltd
64 Cecil Street | #05 IOB Building | Singapore 049711
Tel: 6347 6100, Ext - 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



Virus-free. www.avast.com

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

BSA LAW CHAMBERS LLC

Advocates & Solicitors

Your Ref :
Our Ref : BSA.9484.jy
Date : 2nd August 2018

133 New Bridge Road
#10-04 Chinatown Point
Singapore 059413
Tel : 6236 2001
Fax : 6532 0412
Email : bala@bsalaw.com.sg
UEN / GST Regn No: 201502330R

Secretary's DID: 6435 0019 (Jeyanthi)
6435 0020 (Alice)

BY FAX No. 6224 4174 Only

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street #05-00 IOB Building
Singapore 049711
Motor Claims Department


NOTICE OF ACCIDENT**YOUR INSURED VEHICLE REGISTRATION NO: JMU 1954****ACCIDENT ON 19.7.2018 AT ABOUT 23.50 HRS INVOLVING JMU 1954 & SHB 4221Y
ALONG BKE**

We are informed by the repairers of vehicle registration no. JMU 1954 to notify you of the captioned road traffic accident.

Please note that State Court Practice Directions Amendment 1 of 2016 applies to this case. A copy of the accident statement / police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully


BALASUBRAMANIAM
Enc

cc GNG Motor Trading
By Fax No. 6383 3763
Vehicle No. JMU 1954



Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Wednesday, 17 April 2019 2:27 PM
To: Zuhaidah Samsuri; Mei Kwan (LKKAuto)
Cc: Hsiao Tong (LKKAuto)
Subject: RE: MCt18070583 *** LKK REF: CC4/III18014399/R1ja3

Hi Aida,

We will expedite submission of report.

Meanwhile, our adjusted COR is at lump sum \$900/- ; 4 days.

Thank you.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Zuhaidah Samsuri [<mailto:aida@iii.com.sg>]
Sent: Wednesday, 17 April 2019 11:55 AM
To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: RE: MCt18070583 *** LKK REF: CC4/III18014399/R1ja3

Hi Joy,

Please upload survey report asap as we have received TPD claim from lawyer.

Best Regards
Aida Samsuri
Motor Claims Dept
India International Insurance Pte Ltd
64 Cecil Street #04/#05 IOB Building
Singapore 049711
Tel: 6347 6100 Ext 257 Fax: 6224 4174
Email: aida@iii.com.sg
Co. Reg Number: 198703792K

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]
Sent: Wednesday, 6 March, 2019 2:25 PM
To: Mekavathanan Sarangapani <mekavathanan@iii.com.sg>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Zuhaidah Samsuri

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING






































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Aug 2018 Edit Reg		06 Aug 2018 00:00 Edit Adj Rpt	\$900.00 Edit Estimates	\$900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	CHOONG HOI KONG, ID: G0047143M								
Vehicle Reg. No.:	JMU1954	Date of Loss:	19/07/2018 23:00 - :59						
Claim Type:	TP / MCT18070583	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHB4221Y	Policy No. (Claimant):							
		Excess:							
Repairer:	G.N.G MOTOR TRADING CO. (HQ) BLK 6, DEFU INDUSTRIAL ESTATE PARK C, AVE 1 DEFU LANE 10 #01-564, 539187 Defu Lane - Tel: 6283 6560								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 20/08/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_5G (20/08/2018): Alert - Adj Mandate Approved (\$90.00) - JMU1954 - Claim Handler: Zuhaidah Bte Sa... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*JMU1954 (MCT18070583)
[SHB4221Y]
TP
CHOONG HOI KONG
Jul 19 2018 11:00PM
[COMFORT TRANSPORTATION PTE LTD]
G.N.G MOTOR TRADING CO.

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Video									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)							Thumbnail	Print	
1	20/08/18 14:27	Video - Accident (OID)								Load MP4	
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
2	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
3	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
4	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
5	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
6	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
7	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
8	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
9	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
10	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
11	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
12	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
13	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
14	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
15	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
16	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
17	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
18	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
19	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
20	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
21	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
22	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
23	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
24	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
25	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
26	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
27	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
28	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
29	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
30	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
31	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
32	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
33	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>
34	17/04/19 16:15	General View								Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
36	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
37	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
38	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
44	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
45	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
46	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
47	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
48	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
49	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
50	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
51	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
52	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
53	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
54	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
55	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
56	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
57	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
58	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
59	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
60	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
61	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
62	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
63	17/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
64	17/04/19 16:15	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
65	17/04/19 16:15	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
66	17/04/19 16:15	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
67	17/04/19 16:15	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
68	17/04/19 16:15	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
69	17/04/19 16:15	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
70	17/04/19 16:15	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
71	17/04/19 16:15	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
72	17/04/19 16:15	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/08/18 09:06	ACKNOWLEDGEMENT EMAIL TO III DD 06.08.2018	 Load PDF	
2	08/08/18 09:06	NOTIFICATION FROM WORKSHOP + TP POLICE REPORT	 Load PDF	
3	10/08/18 00:52	TP ESTIMATE - MARKED	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	10/08/18 09:11	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18014399/R1JA3Q2

Date: 18/04/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: MCOM0015

Claimant Vehicle No: JMU1954

Insured Vehicle No: SHB4221Y

Date of Loss: 19/07/2018

Nature of Claim: TP

Claim No: MCT18070583

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JMU1954

Make & Model: YAMAHA FZ150, 150cc

Engine No: HIDDEN

Reg. Date: (Man. Year: 1900)

Chassis No: 0

Colour: Multi-colour

Odometer: 6957 km

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90-17

Rear Tyre Size: 80/90-17

Front Left Side: Duro 3 mm

Rear Left Side: Duro 3 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,111.00	873.20	237.80	21.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	310.00	230.00	80.00	25.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,421.00	1,103.20	317.80	22.36
Approved Total (Overridden) (S\$)		900.00		
Nett Amount (S\$)	1,421.00	900.00	521.00	36.66
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 06/08/2018

Date Inspected: 06/08/2018 Inspected At:

G.N.G MOTOR TRADING CO. (HQ)
BLK 6, DEFU INDUSTRIAL ESTATE
PARK C, AVE 1 DEFU LANE 10 #01-564
Singapore 539187

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Apr 2019)	
Parts:	N/A	YAMAHA FZ150 150cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JMU1954)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MUDGUARD	Scratched	45.00 F	*45.00 FL
2	1		*FRONT NO PLATE	Necessary	20.00 FS	*20.00 FS
3	1		*FRONT WHEEL	Bent	160.00 F	*160.00 FL
4	1		*FRONT BRAKE DISC	Serviceable	85.00 F	*- FL
5	1		*FOOTREST BRACKET	Bent	55.00 F	*55.00 FL
6	1		*LEFT FOOTREST RUBBER	Cut	10.00 F	*10.00 FL
7	1		*FRONT FORK ASSY	Bent	250.00 F	*250.00 FL
8	1		*FRONT STEERING CONE	Necessary	85.00 F	*85.00 FL
9	2		*L&R SIDE COVER	Cracked	90.00 F	*90.00 FL
10	1		*FRONT HEADLIGHT	Scratched	55.00 F	*55.00 FL
11	1		*FRONT HEAD LIGHT COWLING	Scratched	38.00 F	*38.00 FL
12	1		*FRONT COWLING	Scratched	95.00 F	*95.00 FL
13	1		*HANDLE BAR	Serviceable	58.00 F	*- FL
14	1		*HANDLE BALANCER	Scratched	20.00 F	*20.00 FL
15	1		*MIRROR	Scratched	30.00 F	*30.00 FL
16	1		*BRAKE LEVER	Scratched	15.00 F	*15.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,111.00	968.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	94.80
Total Parts (\$\$)	1,111.00	873.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	30.00	30.00
2	LABOUR CHARGE	New	280.00	200.00
Gross Labour Cost (S\$)			310.00	230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >