

INS. CASE OWNER:

CC 3, TP 180 14423, Kea3

LKK: IDAC:

Surveyor: Kenneth

DOI: ASSIGNMENT 9/18/18

Date / Time: 7/9/18

Registered in Merimen: \_\_\_\_\_

Pre-assign / CCU / FTE



Insured Vehicle No. : \_\_\_\_\_

Claim No. : \_\_\_\_\_

Name of Insured : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Insured Tel No. : \_\_\_\_\_ HP: \_\_\_\_\_

Make / Model : \_\_\_\_\_

Excess Sec II :SS \_\_\_\_\_ D.O.A: 30/1/8

Place of Accident : \_\_\_\_\_

Is driver the owner? ( YES / NO ) Nature of Accident : \_\_\_\_\_

If NO, Driver Name / Age : \_\_\_\_\_

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : \_\_\_\_\_ (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SHC 5035 G →



INSRS: WSP: Trans-lab Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/ Time

SHC 5035 G - CC 3 / 11/160 20480 / Kea392; non 21/10/16

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	
<b>Documentation Check List: Handler Typist</b>	
Notification ltr (if non-pickup)	<input type="checkbox"/>
After call ltr to OI:	<input type="checkbox"/>
Authorisation To Act:	<input type="checkbox"/>
Release Voucher:	<input type="checkbox"/>
Final Repair Bill:	<input type="checkbox"/>
Car Rental Invoice:	<input type="checkbox"/>
Towing Invoice	<input type="checkbox"/>
LTA / GIA :	<input type="checkbox"/>
Medical Bill:	<input type="checkbox"/>
PIR:	<input type="checkbox"/>
Mandate/Reject Instruction:	<input type="checkbox"/>
LOD	<input type="checkbox"/>
Payment Breakdown Form:	<input type="checkbox"/>
Post-Repair Photos:	<input type="checkbox"/>
Others:	<input type="checkbox"/>

<b>PRELIMINARY ADVICE</b>	Date/Time: _____	Sent By: _____	Post-Repair Photos: <input type="checkbox"/>	Others: <input type="checkbox"/>
<b>FINALIZATION</b>	Date/Time: _____	Confirm with: _____	Confirm by: _____	
Repair Cost:	S\$ _____	( _____ days) Reduction: _____ %	Email <input type="checkbox"/>	Call <input type="checkbox"/>
<b>FINAL SETTLEMENT</b>	Date/Time: _____	Confirm with _____	Email <input type="checkbox"/>	Call <input type="checkbox"/>
Final Liability:	% _____	(Agreed / Assessed) BOLA S/N No. ;	If NO or B 28, Ass. Lia :	
Repair Cost:	S\$ _____			
Loss of Rental (LOR):	S\$ _____	( _____ days)		
Loss of Use (LOU):	S\$ _____	(\$ x _____ days)		
Loss of Income (LOI):	S\$ _____	(\$ x _____ days)		
LOR only <input type="checkbox"/>	LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/>	LOR + LOI <input type="checkbox"/>	[Tick only one]
GIA/LTA Search	S\$ _____			
Medical:	S\$ _____		1) Claim status: Normal/Reject/Private Settle	
Disbursement:	S\$ _____	(e.g. Tow/ Independent)	2) Report Format: _____	
Legal Cost	S\$ _____		3) Survey fee: _____	
<b>Total:</b>	S\$ _____	<b>Global Sum S\$:</b>		
<b>FINAL PAYMENT</b>	Date/Time: _____	Confirm with: _____	Email <input type="checkbox"/>	Call <input type="checkbox"/>
Payee 1:	S\$ _____	Name 1: _____		
Payee 2: (Strike if N.A.)	S\$ _____	Name 2: _____		
Payee 3: (Strike if N.A.)	S\$ _____	Name 3: _____		

ASS. REC. BY:

REF: TP/


Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Trans Cab  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: S14C 50356 Yr Regn: 12, 13  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or A)  
 Make: Renault Latitude c.c. 1995  
 Colour: M. White/Red A/C: Insured / Std / NI / NA  
 Sp. Reading: 653932 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_

C/No: VFI ABL 15AUC 276025  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rlm / STD A/Rlm or  
 Tyre Size: F: Giti 215/60R16  
 R: ling R: lay



(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or  
 Front R/Bal. 9 mm Rear R/Bal. 7 mm  
 L/Bal. 9 mm L/Bal. 7 mm  
 D.O.A. 30/7/18 D.O.I. 7/8/18

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 01 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
8/8	File pass to Cathorne / Rep @ 9501

Date/Time, File Pass to?  : Prell. Report  
 : Final Report

1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + RS. \$ \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_  
 TOTAL \_\_\_\_\_

Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I: (\$ \_\_\_\_\_)