

ASS. REC. BY:

REF: CS3/CIT/8014446/G2430 Special Instruction:

**Special Instruction:**

Survivor: Gwen Diones  
 Men: 1

ASSIGNMENT (Office)

From (Person): Huang Shiang Yi of CTI Date/Time: 7/8/18 09:37am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

$$\text{OD}(\text{TP})\text{WS} + \text{TP RES} / \text{OD RES} / \text{EVA} / \text{INV} / \text{MV} / \text{CS}$$

To Inspect Vehicle No: GBF 1803M Insured: GBF 54291

at Workshop m/s A-Tee Automotive Tel: 97103383

of 8 curli St Ave 4 # 05-27

Policy No: DMCRSN 30929 51700 Claim No: 8NM18P 03816C02

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 6/8/2018  
(Client's Record)

CA / REV / REP. / REV 24 HRS <sup>(up)</sup>

H.O.D. Endorsement:


Date/Time: 3:15pm @ 4:22pm Person Contacted: peggy Vehicle: IN/OUT

Vehicle IN/OUT

[illegible]

6/5/2018

Buy Used SUBARU IMPREZA 4AT Car in Sir



**Caarly**

Get Caarly on your mobile now!



Download Caarly to chat live with a sales represent  
have in store for drivers!



(<https://itunes.apple.com/sg/>)



<http://caarly.com/used-cars/ud/3782/Subaru-Impreza>

(08/11/13) wef

ASS. REC. BY:

REF:

CII

B6954B

## ASSIGNMENT

From: Date: 8/8/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBF 1803M

at Workshop m/s A-tec Automotive

of 8 Kalki Bkt Ave 4 # 05-27

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

GBF 1803M

Yr Regn:

22 Jul 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan cabstar c.c 2953

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading:

91740

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN15C2F 2480 8588 21

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195 R15 (Green-MAX)

R: 155 R13 (bearway)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A.

D.O.I.

08-08-18

Survey held at

w/s

11Am

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$ 3000 - \$ 4000

13/8/18

submit the report.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

150

150

Report Format :

Lump Sum / I.B.I: (\$ )

Add Fee:

☐

Site Insp (\$ )

☐

Interview (\$ )

☐

Tech. Invs (\$ )

☐

Weekend (\$ )

Accident Photo



## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Aug 2018		07 Aug 2018 09:37 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	EDDIE SIM GENERAL CONTRACTOR		
Vehicle Reg. No.:	GBF1803M	Date of Loss:	06/08/2018 00:00 - :59
Claim Type:	TP / SNM18D03816C02	Policy/Cover Note No.:	DMCVSN3092951700
Vehicle Reg. No. (Insured):	GBF5429J	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	A-Tec Automotive Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4 # 05-27 Premier, 415875 Kaki Bukit - Tel: (1) 90626929 , (2) 97103383		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Hwang Shiang Yi - 63896541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/08/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



**CHIA S ARUL LLC**  
ADVOCATES & SOLICITORS  
UEN 201330709H

ARULCHELVAN S

Our Ref : GBF 1803M (wk)

Your Ref : To be advised

6 August 2018

China Taiping Insurance (S) Pte. Ltd.

BY EMAIL

Dear Sirs,

**RE: PROPERTY DAMAGE CLAIM**  
**CLAIMANT : EDDIE SIM GENERAL CONTRACTOR**  
**ACCIDENT INVOLVING GBF 1803M & GBF 5429J ALONG BEDOK NORTH**  
**ROAD ON 6 AUGUST 2018**  
**PRE-REPAIR SURVEY NOTICE**

1. We act for Eddie Sim General Contractor, the owner of motor vehicle no. GBF 1803M which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. GBF 5429J for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor vehicle at:

Workshop	A-TEC Automotive Pte Ltd
Address	8 Kaki Bukit Avenue 4 #05 - 27 Premier Singapore 415875
Contact Person	Ms. Peggie (6384 5206)

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next two (2) working days (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

**MR ARULCHELVAN S**  
cc: Client (By Email)

151 CHIN SWEE ROAD • #03-09  
MANHATTAN HOUSE • SINGAPORE 169876  
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)  
EMAIL : info@chiaarul.com







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CS3/CTI18014446/Gz4d3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 08-08-2018 Code : CTI	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GBF 5429J	Veh. Inspected	GBF 1803M	
Policy No.	DMCVSN3092951700	Coverage (\$)	0.00	
Claim No.	SNM18D03816C02	Excess (\$)	0.00	
Assign From	MERIMEN (HWANG SHIANG YI)	Assign Date	08/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	06/08/2018	Inspection Date	08/08/2018	
Survey held at	A-TEC AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVE 4 #05-27 PREMIER SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/08/2018 16:03
Date Of Accident	06/08/2018 13:20
Exact Location Of Accident	BEDOK NORTH ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF1803M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	EDDIE SIM GENERAL CONTRACTOR
Co Reg No	53176954B
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90000000

### Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR-3.0 (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5086516873-01
Cover Note Number	

### Driver

Name of Driver	KHOO CHIN LYE(QIU JINLAI)
NRIC No	S7817091C
Date Of Birth	14/06/1978
Occupation	OUTDOOR
Date Of Driving Pass	29/05/2004
Driving Experience	14 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96892968
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 221 PENDING ROAD #07-131
Postcode	670221
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : IBRAHIM BIN MOHD SAAD GENDER: : MALE
Passenger 2	NAME: : - GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF5429J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	JUMALEE BIN AMAT
NRIC/Passport Number	S1655324G
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

GBF6365C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

TER POH HOCK

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name

KHOO CHIN LYE(QIU JINLAI)

Approximate Age

Injuries Sustain

Injured person in which vehicle?

GBF1803M

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

Address

Postcode

#### DETAILS OF INJURED PERSON 2

Name

•IBRAHIM BIN MOHD SAAD

Approximate Age

Injuries Sustain

Injured person in which vehicle?

GBF1803M

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


IDAC KAKI BUKIT (VAC)  
23 KAKI BUKIT AVE 4  
Singapore 415933

Tel: 67416697  
Reporting Centre Personnel's Signature  
Name: Fax: 67492505  
Email: vackb@singnet.com.sg  
NRIC/FIN No.:

- 7 AUG 2018

# Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling straight Bedok North Rd. when vehicle in front suddenly stop. I also stopped in time stationary. Suddenly vehicle B came from behind and hit onto the rear portion of my vehicle.

when I came out to check my vehicle, I realised it was a three vehicles chain collision

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

- 7 AUG 2018

IDAC KAKI BUKIT (VAC)  
23 KAKI BUKIT AVE 4  
Singapore 415933

Reporting Centre Tel: 67416697  
Name: Fax: 67492305  
NRIC/FID Email: vackb@singnet.com.sg





> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	6954B
Vehicle Details	
Vehicle No.:	GBF1803M
Vehicle to be Exported:	No
Intended De-registration Date:	10 Aug 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	ZD30012769N
Chassis No.:	JN1SC2F24Z0858821
Maximum Power Output:	-
Open Market Value:	\$24,942.00
Original Registration Date:	22 Jul 2016
First Registration Date:	22 Jul 2016
Transfer Count:	1
Actual ARF Paid:	\$1,248.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jul 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$22,608.00
COE Rebate Amount:	\$17,964.00
<b>Total Rebate Amount:</b>	<b>\$17,964.00</b>

The information contained herein is correct as at 10 Aug 2018

OK



### ...CLAIM SUBFOLDER...(Pending for Survey Report)
























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Aug 2018		07 Aug 2018 09:37 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: -, Co. Reg. No.: -									
Main Claimant: <b>EDDIE SIM GENERAL CONTRACTOR</b>									
Vehicle Reg. No.: <b>GBF1803M</b>		Date of Loss: 06/08/2018 00:00 - :59 [24 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / SNM18D03816C02</b>		Policy/Cover Note No.: DMCVSN3092951700							
Vehicle Reg. No. (Insured): <b>GBF5429J</b>		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: <b>A-Tec Automotive Pte Ltd (Kaki Bukit)</b> 8 Kaki Bukit Avenue 4 # 05-27 Premier, 415875 Kaki Bukit - Tel: (1) 90626929 , (2) 97103383									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Hwang Shiang Yi</b> - 63896541]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 17/08/2018]									
Adj Asg. Remarks: NO EST, CASE W/O SJE.									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*GBF1803M (SNM18D03816C02)  
[GBF5429J]  
TP  
EDDIE SIM GENERAL CONTRACTOR  
Aug 6 2018 12:00AM  
[-]  
A-Tec Automotive Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
2	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
3	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
4	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
5	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
6	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
7	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
8	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
9	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
10	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
11	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
12	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
13	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
14	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
15	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
16	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
17	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
18	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
19	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
20	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
21	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
22	10/08/18 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/08/18 09:37	PRS	 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>		<a href="#">Reset</a>   <a href="#">Save</a>   <a href="#">Print</a>
There are no document checklists configured.		
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>		
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>		









## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118014446/GZ4D3E2

Date: 15/08/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN3092951700

Claimant Vehicle  
No : GBF1803MInsured Vehicle  
No : GBF5429J

Date of Loss: 06/08/2018

Nature of Claim: TP

Claim  
No: SNM18D03816C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **GBF1803M**Make & Model: NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO  
5 (A)

Engine No: ZD30012769N

Reg. Date: 22/07/2016 (Man. Year: 2016)

Chassis No: JN1SC2F24Z0858821

Colour: Silver

Odometer: 91740 km

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 155 R13

Front Left Side: GREEN-MAX 5 mm

Rear Left Side: Bearway 5 mm

Front Right Side: GREEN-MAX 5 mm

Rear Right Side: Bearway 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 07/08/2018

Date Inspected: 08/08/2018 Inspected At:

A-Tec Automotive Pte Ltd (Kaki Bukit)  
8 Kaki Bukit Avenue 4 # 05-27 Premier  
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian



*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 14 Aug 2018)	
<b>Parts:</b>	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBF1803M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.





## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >

