

ASS. REC. BY:

REF:

CS/MSG/8014447/G24d302

Special Instruction:

Surveyor
menmen

GQ

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSG

Date/Time:

7/8/18 3:58pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 7929 K

Insured:

SKV 973X

at Workshop m/s

E.M. Solution

Tel:

8 456 0226

of

160 Sin Ming Drive # 03-18

Policy No:

A28607381 Arw

Claim No:

566514

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

4/8/18

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

11:06am 08/8/18

Person Contacted:

Bernard

Vehicle IN

OUT

Date/Time	Action/Instruction	(+) Estimate
	GBC 7929K-X	
	SKV 973X-CS/MSG/16018309/Tlgbn2	D.O.A: 16/9/2016

(S011/13) wef
ASS. REC: BY:

PRS

YHL

REF: MS19

B1502C

ASSIGNMENT

From: Date: 13/8/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBC 7929K

at Workshop m/s EM SOLUTION

of 160 Sin Ming Drive #03-18 119

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

GBC 7929K

Yr Regn: 11 Nov 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan NV350 c.c. 2488

Colour:

silver

A/C: Insured / Std / NI / NA

Sp. Reading

140605

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN1MC2E2680001377

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

D.O.I.

13-08-18

Survey held at

w/s

4:30 pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$ 3000 - \$ 4000

18/8/18 Submit PRS Report

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

120

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth ed	Status
Main	06 Aug 2018		07 Aug 2018 15:58 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Ee Huei Wuan, ID: S2511788C		
Main Claimant:	NPN ENGINEERING, Co. Reg. No.: 52971502C		
Vehicle Reg. No.:	GBC7929K	Date of Loss:	04/08/2018 17:00 - :59 [56 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 566514	Policy/Cover Note No.:	A28607381AVW (Comprehensive) Coverage: 28/08/2017 - 27/08/2018
Vehicle Reg. No. (Insured):	SKV973X	Policy No. (Claimant):	
		Excess:	
Repairer:	E M Solution Pte Ltd (HQ) 160 Sin Ming Drive,, #03-18, Sin Ming Autocity, 575722 Sin Ming - Tel: 64560226		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - F594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/08/2018]		
Driver/Custodian (Insured):	Ee Huei Wuan (30 / Female), NRIC: S2511788C		
Adj Asg. Remarks:	on WP. SJE Disagree Please appoint LKK and contact Mr. Bernard (Tel.: 6456-0226 / 9101-8302). Liability is not clear.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18014447/Gz4d3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 08-08-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKV 973X	Veh. Inspected	GBC 7929K
Policy No.	A28607381AVW	Coverage (\$)	0.00
Claim No.	566514	Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	08/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	04/08/2018	Inspection Date	13/08/2018
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/08/2018 16:09
Date Of Accident	04/08/2018 17:05
Exact Location Of Accident	BUKIT BATOK EAST AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC7929K
Insured/Policyholder	
Name Of Registered Owner	NPN ENGINEERING
Co Reg No	52971502C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65669138
Vehicle Particulars	
Manufacturer	NISSAN
Model	NV350-2.5 D PANEL VAN (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ17-005957
Cover Note Number	
Driver	
Name of Driver	BEE JOO PENG
NRIC No	S6882848A
Date Of Birth	14/05/1968
Occupation	INDOOR
Date Of Driving Pass	08/04/1991
Driving Experience	27 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92292682
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	56 BUKIT BATOK ST 31 #24-17
Postcode	659445
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKV973X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	96355293
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time


Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No:



Shuman
618/2018 @
339p

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 4/7/18 at about 5.02 pm I was driving my vehicle - GBC 7929 K along Bukit BATOK East AVE 3. I was stationary at the Traffic light junction while waiting for Traffic to turn green to move on. Out of a sudden, a vehicle - SKV 973 X from behind collided onto the rear portion of my vehicle.

I am reporting this incident for T/Party claim against SKV 973 X for my damages.

Repair at other workshop.

DECLARATION


I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

6/8/18 @
3.30pm



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	1502C
Vehicle Details	
Vehicle No.:	GBC7929K
Vehicle to be Exported:	No
Intended De-registration Date:	17 Aug 2018
Vehicle Make:	NISSAN
Vehicle Model:	NV350 URVAN 2.5 5MT ABS AB 5DR PANEL
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	YD25337031A
Chassis No.:	JN1MC2E26Z0001377
Maximum Power Output:	-
Open Market Value:	\$25,959.00
Original Registration Date:	11 Nov 2013
First Registration Date:	11 Nov 2013
Transfer Count:	0
Actual ARF Paid:	\$1,298.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 Nov 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$55,503.00
COE Rebate Amount:	\$29,039.00
Total Rebate Amount:	\$29,039.00

The information contained herein is correct as at 17 Aug 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Aug 2018		07 Aug 2018 15:58 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: Ee Huel Wuan , ID: S2511788C									
Main Claimant: NPN ENGINEERING , Co. Reg. No.: 52971502C									
Vehicle Reg. No.: GBC7929K		Date of Loss: 04/08/2018 17:00 - :59 [56 Months and 24 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 566514		Policy/Cover Note No.: A28607381AVW (Comprehensive) Coverage: 28/08/2017 - 27/08/2018							
Vehicle Reg. No. (Insured): SKV973X		Policy No. (Claimant):							
		Excess:							
Repairer: E M Solution Pte Ltd (HQ) 160 Sin Ming Drive,, #03-18, Sin Ming Autocity, 575722 Sin Ming - Tel: 64560226									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 08/08/2018]									
Driver/Custodian (Insured): Ee Huel Wuan (30 / Female), NRIC: S2511788C									
Adj Asg. Remarks: on WP. SJE Disagree Please appoint LKK and contact Mr. Bernard (Tel.: 6456-0226 / 9101-8302). Liability is not clear.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBC7929K (566514)
[SKV973X]
TP
NPN ENGINEERING
Aug 4 2018 5:00PM
[Ee Huei Wuan]
E M Solution Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page <input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/08/18 09:05	Accident Statement <small>From: SC - Reg. No: SKV973X, Claimant: EE HUEI WUAN</small>	Load HTM	<input type="checkbox"/>

Photos/Images				3 per page <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
2	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
3	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
4	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
5	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
6	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
7	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
8	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
9	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
10	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
11	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
12	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
13	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
14	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
15	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
16	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
17	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
18	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
19	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
20	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
21	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
22	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
23	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
24	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
25	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>
26	18/08/18 11:08	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page <input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/08/18 09:09	Third Party Accident Report	Load PDF	<input type="checkbox"/>
2	07/08/18 10:02	SJE DISAGREE LKK	Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18014447/GZ4D3E2
Date: 20/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A28607381AVW
Claimant Vehicle No: GBC7929K Insured Vehicle No: SKV973X
Date of Loss: 04/08/2018 Nature of Claim: TP Claim No: 566514

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBC7929K Engine No: YD25337031A
Make & Model: NISSAN NV350, 2.5 D Panel Van (M) Chassis No: JN1MC2E26Z0001377
Reg. Date: 11/11/2013 (Man. Year: 2013) Odometer: 140605 km
Colour: Silver
Engine Capacity: 2488 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/08/2018
Date Inspected: 13/08/2018 Inspected At: E M Solution Pte Ltd (HQ)
160 Sin Ming Drive., #03-18, Sin Ming
Autocity
Singapore 575722

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 20 Aug 2018)
Parts:	N/A NISSAN NV350 2.5 D Panel Van (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC7929K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >