

ASS. REC. BY:

REF: CS/MSG18014458/Usd3 n2

Special Instruction:

Surveyor:

Insurer:

ASSIGNMENT (Office)

F. om (Person):

Muhd Ashik

of

MS/G

Date/Time:

8/8/2018 @ 9:51am

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGS 125R

Insured:

EV 6699U

at Workshop m/s:

SM Automotive

Tel:

67479241

of

1 Kaki Bkt Avc 6 # 01-43

Policy No:

B28995743QMY

Claim No:

564930

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/06/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

11:17am 8/8/18

Person Contacted:

Reena

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SGS 125R - X

EV 6699U - CS/INCO9002627/Uvh

DoA: 30/4/2018

14/08/18

@ 18:09 p.m. revised IA to Muhd Ashik via reiner

(08/11/13) wel

ASS REC. BY: Marcus

REF:

MS16/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGS 125Rat Workshop mis SM Automobile

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 60k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGS 125R Yr Regn: 6.15Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or (A)Make: Volkswagen Jetta o.o. 1390Colour: Grey A/C: Insured / Std / Nil / NASp. Reading: 82244 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WVWZZZ16ZFM002419Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

7

Rear

7

R/Bal. _____ mm

R/Bal. _____ mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. 30/6/18D.O.I. 13/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s Body

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

LTA 52544 rep. byMarcus16/8/18 confirmed LTA \$2500 with value.(B \$5,784.20 Red - 70%)Part s prices checked by Marcus.

Date/Time, File Pass to?

17/08/181) Typst

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

15010160

Report Format : _____

Lump Sum / I.B.I. (\$ 2,500/- 4/5)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Disbursed	Status
Main	20 Jul 2018		08 Aug 2018 09:51 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TAY HANG CHO, ID: S1310994Z, Tel: +6590225670, Email: NOEMAIL		
Main Claimant:	LEE LEE CHAY, ID: S7102040A		
Vehicle Reg. No.:	SGS125R	Date of Loss:	30/06/2018 19:00 - :59 [36 Months and 25 Days From LTA Reg Date (Mon Yr)]
Claim Type:	TP / 564930	Policy/Cover Note No.:	B28995743QMY (Comprehensive) Coverage: 01/08/2017 - 14/11/2018
Vehicle Reg. No. (Insured):	EV6699U	Policy No. (Claimant):	
		Excess:	
Repairer:	Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 25 181]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/08/2018]		
Driver/Custodian (Insured):	TAY HANG CHO (59 / Male), NRIC: S1310994Z, Tel: +6590225670		
Adj Asg. Remarks:	on WP. Liability 100%, SJE agree - LKK, Contact : Sukyl at 6747 9241		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.
[View All](#) | [Continue Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Created By	Created Date	Complete
No results.									

[View All](#) | [Search Tasks](#) | [Create New Task](#) | [Complete](#)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18014458/Usd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 08-08-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EV 6699U	Veh. Inspected	SGS 125R
Policy No.	B28995743QMY	Coverage (\$)	0.00
Claim No.	564930	Excess (\$)	0.00
Assign From	MERIMEN (MUHD ASHIK)	Assign Date	08/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	30/06/2018	Inspection Date	13/08/2018
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 14 Aug 2018

Preliminary Advice

Insured Vehicle No	: EV6699U	Accident Date	: 30/06/2018
TP Vehicle No	: SGS125R	Assignment Date	: 08/08/2018
Make	: VOLKSWAGEN JETTA GP	Est. Duration of Repair	: 3 days
Date of Inspection	: 13/08/2018		
Inspection At	: Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43 Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,284.20
Revised Amount	:S\$	3,290.11
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,290.11

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

21/8/2018

Denise Tay (LKKAUTO)

From: Oh, Aik Seong (VWG Singapore) <Aikseong.Oh@vw.com.sg>
Sent: Wednesday, 15 August 2018 6:59 PM
To: Denise Tay (LKKAUTO)
Subject: RE: HELP ME CHEKC PART PRICE

Best Regards

Oh Aik Seong
(Body & Paint Dept)
Aftersale

Volkswagen Group Singapore Pte Ltd
No: 17 Tuas Ave 9

Mobile No: +65-85187912

aikseong.oh@vw.com.sg
<http://www.vw.com.sg>



From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Wednesday, August 15, 2018 4:07 PM
To: Oh, Aik Seong (VWG Singapore)
Subject: HELP ME CHEKC PART PRICE

Hi,

SGS 125R

WVWZZZ16ZFM002419

Volkswagen Jetta

Front door LH 1865.07
Front door outer handle LH 173.56
Rear door front rubber LH 164.08

Thanks a million.



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Vios 1.5A



\$2000 Downpayment Monthly
From \$488 Onwards. Lowest
3.68%P.A@GV Cars Financing
GV Credit Pte Ltd StarAd


Browse by Category







« Back (1 2 3) Next »

Sort by Date Posted 20 results/page

48 vehicles

Volkswagen Jetta

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Volkswagen Jetta		Any	Any	2015	Any	Any	Any	Available
	Volkswagen Jetta	GP 1.4A TSI Highline	\$67,800	\$7,960 /yr	30-Nov-2015	1,390 cc	-	Sedan	Available
Graded B by STA Up To 90% Loan! Flexible Repayment With In House Financing. Our Vehicle Inspected By Professional Team For Highest Quality. Owning A Car Is So Much Easier With Us. View To Believe. Call Us Now.									
Universe Motoring Posted: 13-Aug-2018 Tags: 2015 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
	Volkswagen Jetta	GP 1.4A TSI	\$63,800	\$8,790 /yr	11-Jun-2015	1,390 cc	37,800 km	Sedan	Available
New Arrival! Beautiful White Paintwork. Low Mileage Done. Single Owner Only. Please Call For Test Drive/Viewing Now. SKL Automobile Pte Ltd Posted: 13-Aug-2018 Tags: 2015 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
	Volkswagen Jetta	GP 1.4A TSI	\$67,800	\$8,480 /yr	28-Jul-2015	1,390 cc	51,000 km	Sedan	Available
Up To 100% Loan! Flexible Repayment With In House Financing. Our Vehicle Inspected By Professional Team For Highest Quality. Owning A Car Is So Much Easier With Us. View To Believe. Call Us Now. Hua Yang Credit Pte Ltd Posted: 13-Aug-2018 Tags: 2015 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
	Volkswagen Jetta	GP 1.4A TSI Highline	\$69,800	\$9,490 /yr	24-Jun-2015	1,390 cc	44,000 km	Sedan	Available
Pristine Condition Black Beauty, 1 Owner Only! Highline Model, Tyre Just Changed And Come With Volkswagen Tyre Insurance Package. Don't Wait Till Is Gone, Call Now To Book An Appointment With Us! Posted: 12-Aug-2018 Tags: 2015 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
Car Buying Car Selling Car Ownership Buying a pre-owned car, but Unsure of its Condition? Get, STA Car Evaluation Car Aftermarket On The Move Lifestyle									
	Volkswagen Jetta	GP 1.4A TSI	\$68,800	\$9,440 /yr	28-May-2015	1,390 cc	36,738 km	Sedan	Available
One Year Inchcape Pre-Owned Warranty Provided. Fully Agent Maintain. Low Mileage Of 36K Only. Conti Yet Japan Make Depreciation. One Owner. No Repair Needed. Low Fuel Consumption. Super Well Kept Inte... Inchcape Pre-Owned Posted: 12-Aug-2018 Tags: 2015 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
	Volkswagen Jetta	GP 1.4A TSI	\$64,800	\$8,920 /yr	10-Jun-2015	1,390 cc	69,325 km	Sedan	Available
One Year Inchcape Pre-Owned Warranty Provided. Fully Agent Maintain. Conti Yet Japan Make Depreciation. One Owner. No Repair Needed. Low Fuel Consumption. Super Well Kept Interior Condition With Smoot... Inchcape Pre-Owned Posted: 12-Aug-2018 Tags: 2015 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 2040A

Vehicle Details

Vehicle No.: SG5125R
Vehicle to be Exported: No
Intended De-registration Date: 02 Jul 2018
Vehicle Make: VOLKSWAGEN
Vehicle Model: JETTA GP 1.4 TSI 90 A/T HL 1634G5
Primary Colour: Grey
Manufacturing Year: 2014
Engine No.: CAXF18952
Chassis No.: WVVZZZ16ZFM002419
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$19,614.00
Original Registration Date: 05 Jun 2015
First Registration Date: 05 Jun 2015
Transfer Count: 0
Actual ARF Paid: \$9,614.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 04 Jun 2025
PARF Rebate Amount: \$7,210.00

Intended COE Rebate Details

COE Expiry Date: 04 Jun 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$66,590.00
COE Rebate Amount: \$46,095.00
Total Rebate Amount: \$53,305.00

The information contained herein is correct as at 02 Jul 2018

OK

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2040A

Vehicle Details

Vehicle No.: SGS125R
Vehicle to be Exported: No
Intended De-registration Date: 13 Aug 2018
Vehicle Make: VOLKSWAGEN
Vehicle Model: JETTA GP 1.4 TSI 90 A/T HL 1634G5
Primary Colour: Grey
Manufacturing Year: 2014
Engine No.: CAXF18952
Chassis No.: WVVZZZ16ZFM002419
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$19,614.00
Original Registration Date: 05 Jun 2015
First Registration Date: 05 Jun 2015
Transfer Count: 0
Actual ARF Paid: \$9,614.00 4807

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 04 Jun 2025
PARF Rebate Amount: \$7,210.00

Intended COE Rebate Details

COE Expiry Date: 04 Jun 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$66,590.00
COE Rebate Amount: \$45,344.00
Total Rebate Amount: \$52,554.00

The information contained herein is correct as at 13 Aug 2018

OK

MSME18084808 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 02/07/2018 12:37
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/07/2018 12:37
Date Of Accident	30/06/2018 07:45
Exact Location Of Accident	CHUI HUAY LIM CLUB CARPARK 190 KENG LEE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGS125R
Insured/Policyholder	
Name Of Registered Owner	LEE LEE CHAY
NRIC No	S7102040A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97837415
Alternative Phone No	OFFICE-97837415

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01009384
Cover Note Number	

Driver

Name of Driver	LEE LEE CHAY
NRIC No	S7102040A
Date Of Birth	10/01/1971
Occupation	OUTDOOR
Date Of Driving Pass	07/05/1993
Driving Experience	25 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-97837415
Fax Number	
Contact Number	OFFICE-97837415
Email Address	NOEMAIL

Address BLK 458 YISHUN AVE 11 #13-736
 Postcode 760458
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 30/06/2018, I PARKED MY VEHICLE AT THE CARPARK OF CHUI HUAY LIM CLUB AT ABOUT 1915HRS AND WENT FOR DINNER AT THE SAID CLUB. AT ABOUT 2230HRS, I WENT BACK TO MY CAR AND REALISED THAT THERE WERE DAMAGES ON THE LEFT SIDE OF MY VEHICLE. I THEREFORE CHECKED ON MY IN CAR CAMERA AND SAW THAT A M/CAR (EV6699U) HAD REVERSED HIS VEHICLE AND COLLIDED ONTO MY STATIONARY PARKED VEHICLE. AFTER THE ACCIDENT, THE CAR (EV6699U) DROVE OFF AND THE DRIVER OF THE SAID M/CAR ALSO DID NOT COME DOWN AND CHECK BEFORE HE LEFT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WITH TP WORKSHOP
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number EV6699U
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON THE 30-06-2018, I PARKED MY VEHICLE AT THE CARPARK OF CHUI HUAY LIM CLUB AT ABOUT 1915HRS AND WENT FOR DINNER AT THE SAID CLUB. AT ABOUT 2230HRS, I WENT BACK TO MY CAR AND REALISED THAT THERE WAS DAMAGE ON THE LEFT SIDE OF MY VEHICLE. I THEREFORE CHECK ON MY IN-CAR CAMERA AND SAW THAT A M/CAR EV 6699U HAD REVERSED HIS VEHICLE AND COLLIDED ONTO MY STATIONARY PARKED VEHICLE. AFTER THE ACCIDENT THE CAR EV 6699U DROVE OFF AND THE DRIVER OF THE SAID M/CAR ALSO DID NOT COME DOWN AND CHECK BEFORE HE LEFT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

2/7/18 12.15pm
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #3 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180702/7007

1 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180702/7007

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/07/2018 11:56	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: LEE LEE CHAY	Address: APT BLK 458 YISHUN AVENUE 11 #13-736 SINGAPORE 760458		
ID Type / ID No.: NRIC NO / S7102040A	Contact No.:	Mobile: 97837415	
Nationality: SINGAPORE CITIZEN	Home/Office:	Email: leelc@aia.com.sg	
Sex: Female	Age: 47	Date of Birth: 10/01/1971	Type of Informant: Driver
Race: Chinese	Language: English	Institution / School Name:	
Occupation: FINANCIAL SERVICE CONSULTANT	Driving Licence Information: Class: 3	Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 30/06/2018 19:42	Type of Location: CARPARK
Location: KENG LEE ROAD INSIDE CHUI HUAY LIM CLUB CARPARK				
Weather: Clear	Road Surface: Dry		Road Speed Limit: 50 Km/h	
Traffic Flow: Two Way	Traffic Control: Not Controlled		Traffic Volume: Light	
Type of Collision: Moving Vehicle Against - Parked Vehicle	Anyone conveyed by ambulance: No			

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
EV6699U	Car	MERCEDES BENZ		Grey		0
SGS125R	Car	VOLKSWAGO N	JETTA GP 1.4 TSI 90 A/T HL 1634G5	Grey	Slightly Damaged	0

Sketch Plan #4 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180702/7007

2 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No: T/20180702/7007

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SGS125R	TENET SOMPO INSURANCE PTE. LTD.	D18MTPV01009384	05/06/2018	04/06/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LEE LEE CHAY	ID No.	S7102040A
Related Vehicle	SGS125R (Car)	Contact No.	97837415
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTION DATE, I HAD PARKED MY VEHICLE AT THE CARPARK OF CHUI HUAY LIM CLUB AT ABOUT 1915 HRS AND WENT TO THE CLUB FOR DINNER. AFTER THE DINNER AT ABOUT 2230 HRS I WENT BACK TO MY VEHICLE AND REALISED THAT THERE WERE DAMAGE ON THE LEFT SIDE OF MY VEHICLE. I THAT CHECK MY IN CAR CAMERA AND REALISED THAT A MOTOR CAR EV6699U HAD REVERED HIS VEHICLE AND COLLIDED ONTO MY STATIONERY PARKED CAR. HE THAT DROVE OFF WITHOUT CHECKING AND LEFT THE SCENE. I HAD IN CAR CAMERA AND HAD CAPTURE THE FOOTAGE OF THE ACCIDENT.

Sketch Plan #5 Pg. 1

**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000



T/20180702/7007

3 of 3

Report No. T/20180702/7007

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPB /
ESTHER CHONG
Contact No: 65476368

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
02/07/2018 11:56

Classification Of Case:

13/8/18 3 day. Theoph. Allenby. 3167.93

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18014458/USD3N2

Date: 17/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B28995743QMY
Claimant Vehicle No :	SGS125R	Insured Vehicle No :	EV6699U
Date of Loss:	30/06/2018	Nature of Claim:	TP
		Claim No:	564930

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGS125R	Engine No:	CAXF18952
Make & Model:	VOLKSWAGEN JETTA GP, 1.4 TSI 90 A/T (A)	Chassis No:	WWWZZZ16ZFM002419
Reg. Date:	05/06/2015 (Man. Year: 2014)	Odometer:	82244 km
Colour:	Grey		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,954.20	2,057.94	3,896.26	65.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,330.00	1,110.00	1,220.00	52.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,284.20	3,167.94	5,116.26	61.76
Approved Total (Overridden) (\$\$)		2,500.00		
Nett Amount (\$\$)	8,284.20	2,500.00	5,784.20	69.82

INSPECTION

Date of Assignment:	08/08/2018	
Date Inspected:	13/08/2018 Inspected At:	Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43 Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 17 Aug 2018)

Parts: 143 **VOLKSWAGEN JETTA GP 1.4 TSI 90 A/T (A)** (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGS125R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT L/H DOOR	Badly Dented	1,963.45 F	*1,865.07 FL
2	1		*FRONT L/H DOOR SIDE MIRROR ASSY	Repair	854.45 F	*- FL
3	1		*FRONT L/H DOOR OUTER HANDLE	Cut	137.10 F	*137.10 FL
4	1		*FRONT L/H DOOR OUTER HANDLE COVER	Not Necessary	102.35 F	*- FL
5	1		*FRONT L/H DOOR INNER LOCK	Not Necessary	369.55 F	*- FL
6	1		*REAR L/H DOOR	Repair	1,963.45 F	*- FL
7	1		*REAR L/H DOOR CENTRE RUBBER	Cut	194.30 F	*164.08 FL
8	1		*REAR L/H DOOR INNER LOCK	Not Necessary	369.55 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	5,954.20	2,166.25
- List Item Discount on L Items 0.00/5.00% (S\$)	0.00	108.31
Total Parts (S\$)	5,954.20	2,057.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT FRONT & REAR L/H DOOR, GLASS, GEAR MOTOR, LOCK & TRIM BOARD	New	380.00	60.00
2	TO CHECK WIRING	New	100.00	-
3	TUFF KOTE	New	150.00	50.00
4	PANEL BEATING	New	850.00	400.00
5	SPRAY PAINTING	New	850.00	600.00
Gross Labour Cost (S\$)			2,330.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >