

REF: CS/MSG18014462/K18d362 Special Instruction:

ASS. REC. BY:

Surveyor
Meinen

Kalin

ASSIGNMENT (Office)

MSIG

Date/Time 8/8/18 @ 4:53pm

From (Person): Catherine Thia

Bill to:

Estimated Cost:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

Insured: SJL 5436L

To Inspect Vehicle No:

SHD 1055U

Tel: 654 46676

at Workshop m/s

Premier Taxis

of

23 Chongji South Ave 2 # 03-02

Policy No:

28958730 TMC

Claim No: 566545

Sum Insured:

Excess:

D.O.A. 4/8/2018

Make of Veh:
(Client's Record)

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 6:15pm 8/8/18

Person Contacted:

Virent

Vehicle - 3' OUT

| Date/Time | Action/Instruction (✓) Estimate | D.O.A. |
|-----------------------|---|----------|
| | SHD 1055U - CC3/III/7017253/K18d362 | 5/9/2017 |
| | SJL 5436L - x | |
| 12/08/18 @ 08:52 a.m. | revised IA to Catherine Thia sh. r. via meinen. | |
| | | |
| | | |
| | | |

(06/11/13) wef

ASS. REC. BY:

Kala

REF:

MSIG

ASSIGNMENT

From:

Date:

10/8/2018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHD 10554

at Workshop m/s

Premier

of

23 chengj South Ave 2#02-03

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

(sup)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 10554

Yr Regn:

24

Type: M.Car / M.Cycle / Bus / Van / Lorry / T/ri / Prime Mover /

Truck / Trailer or

Make:

Kia Optima

C.C.

1685

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp.Reading

317362

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KNAGM44ME.5464081

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Achilles

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

4/8/18

D.O.I.

14/8/18

Survey held at

Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/8/18

Change 45 \$550 / 24.

42

(\$295.42 Red. 35%)

RECEIVED 20 AUG 2018

Date/Time, File Pass to?

20/8/18

1)

Typist

Date/Time, File Return to?

2)

☐

: Preli. Report

☒

: Final Report

Days Of Repair:

2

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

150

Transportation:

S + RS, SI

Photos

10

Others

TOTAL

160

Report Format :

Lump Sum / I.B.I: (\$ 550/- 2/5)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--|---------|---------------|------------|--|
| Main | 06 Aug 2018 | | 08 Aug 2018 16:53 Assign | | | | New Assignment Cancel Case |

| | | | | |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

CLAIM SUBFOLDER DETAILS [Created by insurer]

| | | | |
|-----------------------------|--|------------------------|--|
| Insured: | JCM RENTAL PTE LTD, Co. Reg. No.: 201711659M | | |
| Main Claimant: | PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H | | |
| Vehicle Reg. No.: | SHD1055U | Date of Loss: | 04/08/2018 00:00 - :59 [48 Months and 25 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / 566545 | Policy/Cover Note No.: | 28958730TMC Coverage: 17/05/2018 - 16/05/2019 |
| Vehicle Reg. No. (Insured): | SJL5436L | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | Premier Taxis Pte Ltd - Changi (HQ) 23 Changi South Ave 2 #03-02, 486443 Changi - Tel: | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/08/2018] | | |
| Adj Asg. Remarks: | on WP, OI non reporting. Liability cannot be established. TP agree with SJE - assign Calvin Ng of LKK Auto Consultants Pte Ltd. contact: 6544 6676 / 6544 6689 | | |

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

opened pri



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18014462/K1sd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 08-08-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|--------------------------|----------------|------------|
| Insured Veh. | SJL 5436L | Veh. Inspected | SHD 1055U |
| Policy No. | 28958730TMC | Coverage (\$) | 0.00 |
| Claim No. | 566545 | Excess (\$) | 0.00 |
| Assign From | MERIMEN (CATHERINE THIA) | Assign Date | 08/08/2018 |

2. Vehicle Particulars & Condition

| | | |
|--------------|--------|--------------|
| Make & Model | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. |
| Chassis No. | | Colour |
| Odometer | - | Steering |
| Brakes | | Modification |
| General | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

| |
|--|
| |
|--|

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 04/08/2018 | Inspection Date | 14/08/2018 |
| Survey held at | PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443 | | |

5a. Remarks

| |
|---|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. |
| B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |

Text size + -

Enquire Transaction History**Transaction History Details**

| | | | |
|-------------------------------------|---------------------------------|---------------------|---|
| Log Date/Time: | 10 Jul 2014 / 08:51:04 | Receipt No.: | AACCK001-AX239-140710-000001 |
| Asset Type: | Vehicle | Transaction Amount: | \$65,817.00 |
| Asset ID: | SHD1055U | Channel: | AA Counterless - CYCLE & CARRIAGE KIA PTE LTD |
| Transaction Type: | 01.02 Register New Vehicle (AA) | | |
| Business Transaction Reference No.: | 20140710085104505099 | | |

| | |
|---------------|---|
| Vehicle No.: | SHD1055U |
| Vehicle Type: | H10 - Public Transport Taxi (Motor Car) |

| | |
|-----------------------------|----------------------|
| Vehicle Attachment 1: | Air-Con (Taxi) |
| Vehicle Attachment 2: | - |
| Vehicle Attachment 3: | - |
| Vehicle Scheme: | Taxi (Company) |
| First Registration Date: | 10 Jul 2014 |
| Original Registration Date: | 10 Jul 2014 |
| Vehicle Make: | KIA |
| Vehicle Model: | OPTIMA 1.7(A) DIESEL |
| Chassis No.: | KNAGM414ME5464081 |
| Engine No.: | D4FDDH307938 |
| Motor No.: | - |
| Trailer Chassis No.: | - |
| Propellant: | Diesel |
| Passenger Capacity: | 4 |
| Engine Capacity: | 1685 |
| Power Rating: | - |

| | |
|--------------------------------|----------------------|
| Unladen Weight: | 1584 |
| Maximum Laden Weight: | 2050 |
| Primary Color: | Silver |
| Secondary Color: | - |
| Manufacturing Year: | 2013 |
| Open Market Value: | \$19,908.00 |
| Minimum PARF Benefit: | \$7,444.00 |
| PARF Eligibility: | Y |
| No. of Transfer: | 0 |
| Effective Ownership Date/Time: | 10 Jul 2014 08:51:04 |
| COE No.: | 2014071001001185M |
| COE Expiry Date: | 09 Jul 2022 |
| COE Bid Category: | - |
| Actual QP/PQP Paid Amount: | \$53,269.00 |
| Lifespan Expiry Date: | 09 Jul 2022 |
| Owner ID Type: | Company |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 16 Aug 2018

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|--------------|
| Insured Vehicle No | : SJL5436L | Accident Date | : 04/08/2018 |
| TP Vehicle No | : SHD1055U | Assignment Date | : 08/08/2018 |
| Make | : KIA OPTIMA | Est. Duration of Repair | : 2 days |
| Date of Inspection | : 14/08/2018 | | |
| Inspection At | : Premier Taxis Pte Ltd - Changi (HQ) 23 Changi South Ave 2 #03-02 Singapore 486443 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|--------|
| Repairer's Estimate (Gross) | :S\$ | 845.42 |
| Revised Amount | :S\$ | 710.78 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 710.78 |

Lump Sum Repair :S\$

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|---|
| Date Of Report | 06/08/2018 12:48 |
| Date Of Accident | 04/08/2018 18:10 |
| Exact Location Of Accident | CARPARK DRIVEWAY @ PUNGGOL PLAINS BLK 209 |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|-----------------------|
| Vehicle Registration Number | SHD1055U |
| Insured/Policyholder | |
| Name Of Registered Owner | PREMIER TAXIS PTE LTD |
| Co Reg No | 200304975H |
| Email Address | NOEMAIL |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-62148880 |

Vehicle Particulars

| | |
|--|------------------|
| Manufacturer | KIA |
| Model | OPTIMA-1.7 D (A) |
| Exact Purpose for which vehicle was being used at time of accident | HIRED & REWARDS |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | TAXI |

Insurance Company

| | |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | THIRD PARTY |
| Fleet Policy | YES |
| Policy Number | 5095103893 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | ANG ING YONG |
| NRIC No | S0182754E |
| Date Of Birth | 25/05/1949 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 27/10/1972 |
| Driving Experience | 45 YEARS AND 9 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-93399058 |
| Fax Number | |
| Contact Number | |
| Email Address | NOEMAIL |

| | |
|---|--------------------------------|
| Address | 8 TAI THONG CRESCENT #13-08 |
| Postcode | 347842 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OTHER - HIRER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|-------------------------------|
| Type Of Accident | COLLISION - HEAD ON COLLISION |
| Weather Conditions | RAINING |
| Road Surface | WET |

Other Information

| | |
|---|--|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 3 |
| Passenger 1 | NAME: : PAX IN THE FRONT SEAT - MALAY GENDER: : MALE |
| Passenger 2 | NAME: : PAX IN THE REAR SEAT - MALAY GENDER: : FEMALE |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

VEH. A - 2 PAX VEH. B - SOME PAX

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|---------------|
| Vehicle Registration Number | SJL5436L |
| Vehicle Make/Model/Colour | HONDA |
| Details Of Properties | VEH. B |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | FEMALE DRIVER |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Submittal to Reporting Centre

X 0182754 E
X SHD 1035U

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

(SHD 1055U)

ON 04-08-2018 @ 1810HRS, I WAS DRIVING MY TAXI INTO THE C/P DRIVEWAY @ PUNGGOL PLAINS (NEARBY BLK 209), WITH 2 PASSENGERS ON BOARD. IT WAS RAINING AND I NEED TO ALIGHT MY PASSENGERS AT A SHELTERED DROP OFF POINT.

I STOPPED MY TAXI AS VEHICLE B (SJL 5436L - HONDA) WHICH WAS INFRONT OF ME STOPPED, BUT SUDDENLY VEHICLE B BEGAN TO REVERSE. AS SUCH THE RIGHT REAR OF VEHICLE A TO COLLIDE ON THE FRONT RIGHT OF MY TAXI.

DUE TO THE IMPACT MY TAXI HAD DAMAGES ON THE FRONT RIGHT PORTION AND VEHICLE A HAD DAMAGES ON THE REAR RIGHT PORTION.

NO INJURY INVOLVED

VEHICLE B HAD SOME PASSENGERS ONBOARD

* VIDEO FOOTAGE CAPTURED

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GAATMC SketchPlanForm_V38

PREMIER AUTOMOTIVE SERVICES PTE LTD**23 Changi South Ave 2****#01-02, Singapore 486443****Assessment Number: MSIG0029****Assessor Report****Version: PREMIERA/1****Printed: 10/08/2018****Summary Information****Claim**

| | | | |
|---------------------------------------|------------|----------------------------|-----|
| Claim Reference: | SHD1055U | Insured: | |
| Policy Number: | | Third Party: | |
| Date of Decision: | 10/08/2018 | Able to Authorise Repairs: | TBA |
| Repairer: | | Repairs Authorised? | TBA |
| Estimated Repair Time (Working Days): | 0.0 | | |

Insured's Liability

| | |
|------------------------|-------------------|
| Excess: | TBA |
| Customer Contribution: | \$0.00 (excl GST) |

Vehicle Details**Vehicle**

| | | | |
|---------------------|---|---------------------|--------|
| Registration: | SHD1055U | VIN/Chassis Number: | |
| Manufacturer: | KIA | Model: | Optima |
| Registration Month: | July | Registration Year: | 2014 |
| Odometer: | Not Known | Colour: | |
| Build Date: | | | |
| Model Specs | FROM 05/2015 PREPARE OFF VEHICLE BASECOAT CLEAR | | |

Vehicle Condition**Vehicle Status**

| | | | |
|-------------------------|------------|----------------------|------------|
| Date of Incident: | 04/08/2018 | Market Value: | Unknown |
| Pre-Accident Condition: | | Salvage Value: | Unknown |
| Pre-Accident Damage: | | Date of Inspection: | 10/08/2018 |
| Steering Rim Ply: | | Place of Inspection: | |
| Brake Pedal Travel: | | | |
| Vehicle Status: | | | |
| Damage Severity: | | | |

Tyres Condition:

Tread Depth LHF:
Tread Depth LHR:

Tread Depth RHF:
Tread Depth RHR:

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
Price/Dent = \$50.00/HR

Repair /**Guide Number Repair Details**

| | | WU | Cost Price (\$) |
|-----------|--|--------------|------------------------|
| 86512R00) | RENEW FRONT BUMPER (BUMPER REMOVED) | 7.0 | 35.00 |
| | INCLUDES: R + R NECESSARY ATTACHED PARTS | | |
| 86521R00) | R + R FRONT BUMPER IMPACT DAMPER (BUMPER REMOVED) | 2.0 X | 10.00 |

LABOUR COST

| | | |
|---|---------------|-------------|
| Total Work Units | 9.0 | |
| Corrosion Protection External Labour | 0.0HRS | 0.00 |
| Corrosion Protection Internal Labour | 0.0HRS | 0.00 |

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 Changi South Ave 2

#01-02, Singapore 486443

Assessment Number: MSIG0029

Version: PREMIERA/1

Assessor Report

Printed: 10/08/2018

| | | |
|--------------|--------|--------------|
| Sub Total | 0.9HRS | \$45.00 |
| Paint Labour | 3.1HRS | \$155.00 |
| Total Labour | 4.0HRS | \$200.00 190 |

| PAINT WORK | | Time Basis 10 WU = 1 HR. Price = \$50.00/HR | |
|------------------------------------|--|---|-------------------|
| Guide Number | Description | WU | Cost Price (\$) |
| | - PREPARE OFF VEHICLE | | |
| | - BASECOAT CLEAR | | |
| 283 | FRONT BUMPER NEW PART PAINT K1R | 13.0 | |
| 293 | FRT BUMPER TRIM CAP NEW PART PAINT K1R | 3.0 | |
| LABOUR COST - PAINT | | | |
| TIME(PAINT) | | 16.0 | |
| Preparation Main Work Plastic | | 15.0 | |
| Preparation Work Multi Layer Paint | | 0.0 | |
| Total Work Units (10WU/HR) | | 31.0 | |
| Total Paintwork Labour | | 3.1HRS | \$155.00 |
| MATERIAL COST - PAINT | | | Cost Price |
| New Part Painting - Plastic K1R | | | \$66.91 66.42 |
| Material-Const Main Work Plastic | | | \$28.60 |
| Total Excluding Pearlescent Uplift | | | \$95.51 95.02 |
| Pearlescent Uplift @ 0.0% | | | \$0.00 |
| Total Paint Material Cost | | | \$95.51 95.02 |

PARTS

| Guide No. Qty | | Description | Part Number | Supplier | Bet. | Price (\$) |
|---------------|---|---------------------------|-------------|--------------|------|-----------------|
| 283 | 1 | FRONT BUMPER | 865112T500 | ✓ <i>Red</i> | 0% | 531.00* |
| 293 | 1 | FRT BUMPER TRIM CAP | 865882T500 | X <i>hh</i> | 0% | 14.00* |
| 315 | 1 | FRT LWR IMPACT DAMP | 865202T500 | X <i>su</i> | 0% | 110.00* |
| 431 | 1 | GRILLE BADGE | 863183R500 | ✓ <i>su</i> | 0% | 50.17U |
| 296 | 1 | R/F BUMPER MOULDING | 865642T500 | X <i>su</i> | 0% | 51.00* |
| 320 | 1 | R/F CTR BUMPER BRKT | 865142T500 | X <i>su</i> | 0% | 16.00* |
| f: OEM Parts | | Sub Total | | | | \$772.17 |
| g: Original | | Deduction from RRP (35 %) | | | | -\$270.26 |
| h: Secondhand | | Total Parts | | | | \$501.91 |
| p: Parallel | | | | | | |
| x: Exchange | | | | | | |

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

| Description | Betterment | Price |
|---------------------|--------------|----------------|
| FRONT BUMPER CLIPS | 0% <i>su</i> | \$48.00 |
| Total Extras | | \$48.00 |

Final Calculation

| | |
|------------------------|-----------------|
| Total Parts | \$501.91 |
| Labour | |
| Total Panel/Mechanical | \$45.00 ✓ 35 |
| Total Paintwork | \$155.00 ✓ |
| Total Labour | \$200.00 |

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 Changi South Ave 2

#01-02, Singapore 486443

Assessment Number: MSIG0029

Version: PREMIERA/1

Assessor Report

Printed: 10/08/2018

Additional Costs

| | |
|------------------------------|---------|
| Corr Prot Materials External | \$0.00 |
| Corr Prot Materials Internal | \$0.00 |
| Cost of Specialist | \$48.00 |

Total of Additional Costs **\$48.00**

Total Paint/Material Costs **\$95.51** / 95.02

Grand Total Excludes GST **\$845.42**

GST @ 7 % **\$59.18**

Grand Total Includes GST **\$904.60**

Assessment Notes

Kahin (1/10/18)

14/8/18 09:40hr

2 hrs

4/5

After Repair p. 10/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to "market value"
- Third party survey is on "no win, no fee" basis
- No illegal modification
- Supplier price must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference: SHD1055U
Assessment Number: MSIG0029
Version: LKKAUTOC/2
Date Calculated: 15/08/2018 09:49

Full Report - V1
Registration: SHD1055U
Printed: 15/08/2018 16:50

Summary Information

Claim

| | | | |
|-----------------------|-----------------------------------|----------------------------|------------|
| Location: | Singapore (SG) | Currency: | SGD |
| Printed by: | LKK AUTO | Date of Incident: | 04/08/2018 |
| Authorisation Status: | Interim | Able to Authorise Repairs: | TBA |
| Work Provider: | MSIG Insurance (Singapore) Pte | Repairs Authorised: | TBA |
| Claim Reference: | SHD1055U | Estimated Repair Time: | |
| Policy Number: | | Quote Due Date: | |
| Other Reference: | LKK | Actual Repair Days: | |
| Third Party: | | Parts Ordered Date: | |
| Insured Amount: | | Hire Car Start: | |
| Under Warranty: | | Hire Car End: | |
| Warranty Expired: | | Vehicle Collected: | |

Vehicle Details

Vehicle

| | |
|---------------------|------------|
| Manufacturer: | KIA |
| Model: | Optima |
| Sub Model: | BASE MODEL |
| Model Sheet Number: | 2836 01 |
| Registration: | SHD1055U |
| Registration Month: | July |
| Registration Year: | 2014 |
| VIN Number: | |
| Odometer: | Not Known |
| Colour: | |
| Engine Number: | |
| Fuel Level: | % |

Model Specs

| | |
|----------------|---------------------|
| FROM 05/2015 | PREPARE OFF VEHICLE |
| BASECOAT CLEAR | |

Vehicle Condition

Vehicle Status

| | | |
|-------------------------|----------------------------------|------------|
| Pre-Accident Condition: | Severity of Impact: | |
| Steering: | Vehicle Status on Inspection: | |
| Brakes Pedal Travel: | Date of Inspection: | 10/08/2018 |
| Place of Inspection: | | |
| Pre-Accident Damage: | | |
| Tyres Condition: | Tread Depth RHF: | |
| Tread Depth LHF: | Tread Depth RHR: | |
| Tread Depth LHR: | Direction of Impact: | |
| Damage Areas: | | |

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: SHD1055U

Assessment Number: MSIG0029



Version: LKKAUTOC/2

Date Calculated: 15/08/2018 09:49

Full Report - V1

Registration: SHD1055U

Printed: 15/08/2018 16:50



Addresses

Cost Summary

| | |
|---------------------------|----------|
| Total Labour | \$190.00 |
| Total Paint/Material | \$95.02 |
| Total Parts | \$377.76 |
| Total of Additional Costs | \$48.00 |
| Excess: | TBA |
| Grand Total Exc GST: | \$710.78 |
| 7 % GST: | \$49.75 |
| Grand Total Inc GST: | \$760.53 |

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR

Price/Dent = \$50.00/HR

Repair /

Guide Number Repair Details

| Guide Number | Repair Details | WU | Cost Price (\$) |
|--------------|--|-----|-----------------|
| 86512R00) | RENEW FRONT BUMPER (BUMPER REMOVED) | 7.0 | 35.00 |
| | INCLUDES: R + R NECESSARY ATTACHED PARTS | | |

LABOUR COST

| | | |
|--------------------------------------|--------|----------|
| Total Work Units | 7.0 | |
| Corrosion Protection External Labour | 0.0HRS | 0.00 |
| Corrosion Protection Internal Labour | 0.0HRS | 0.00 |
| Sub Total | 0.7HRS | \$35.00 |
| Paint Labour | 3.1HRS | \$155.00 |
| Total Labour | 3.8HRS | \$190.00 |

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Guide Number Description

| Guide Number | Description | WU | Cost Price (\$) |
|--------------|-------------------------------------|------|-----------------|
| | - PREPARE OFF VEHICLE | | |
| | - BASECOAT CLEAR | | |
| 283 | FRONT BUMPER NEW PART PAINT K1R | 13.0 | |
| 1000 | CAP NEW P/PAINT K1R FRT BUMPER TRIM | 3.0* | |

LABOUR COST - PAINT

| | | |
|------------------------------------|--------|----------|
| TIME(PAINT) | 16.0 | |
| Preparation Main Work Plastic | 15.0 | |
| Preparation Work Multi Layer Paint | 0.0 | |
| Total Work Units (10WU/HR) | 31.0 | |
| Total Paintwork Labour | 3.1HRS | \$155.00 |

MATERIAL COST - PAINT

| | |
|------------------------------------|---------|
| New Part Painting - Plastic K1R | \$66.42 |
| Material-Const Main Work Plastic | \$28.60 |
| Total Excluding Pearlescent Uplift | \$95.02 |

Pearlescent Uplift @ 0.0% \$0.00
Total Paint Material Cost \$95.02

PARTS

| Guide No. Qty | | Description | Part Number | Supplier | Bet. | Price (\$) |
|---------------|---|--------------|--------------------|----------|------|-----------------|
| 283 | 1 | FRONT BUMPER | 865112T500 | | 0% | 531.00* |
| 431 | 1 | GRILLE BADGE | 863183R500 | | 0% | 50.17U |
| f: OEM Parts | | | Sub Total | | | \$581.17 |
| g: Original | | | Deduction from RRP | (35 %) | | -\$203.41 |
| h: Secondhand | | | Total Parts | | | \$377.76 |
| p: Parallel | | | | | | |
| x: Exchange | | | | | | |

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

| Description | Betterment | Price |
|-------------------------|------------|----------------|
| FRONT BUMPER SPECIALIST | 0% | \$48.00 |
| CLIPS | | |
| Total Extras | | \$48.00 |

Final Calculation

| | | |
|-----------------------------------|----------|-----------------|
| Total Parts | | \$377.76 |
| Labour | | |
| Total Panel/Mechanical | \$35.00 | |
| Total Paintwork | \$155.00 | |
| Total Labour | | \$190.00 |
| Additional Costs | | |
| Corr Prot Materials External | \$0.00 | |
| Corr Prot Materials Internal | \$0.00 | |
| Cost of Specialist | \$48.00 | |
| Total of Additional Costs | | \$48.00 |
| Total Paint/Material Costs | | \$95.02 |
| Grand Total Excludes GST | | \$710.78 |
| GST @ 7 % | | \$49.75 |
| Grand Total Includes GST | | \$760.53 |

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 06 Aug 2018 | | 08 Aug 2018 16:53 Edit Adj Rpt | S\$550.00 Edit Estimates | S\$550.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|--|-----------|--|------------|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: JCM RENTAL PTE LTD , Co. Reg. No.: 201711659M | | | | | | | | | |
| Main Claimant: PREMIER TAXIS PTE LTD , Co. Reg. No.: 200304975H | | | | | | | | | |
| Vehicle Reg. No.: SHD1055U | | Date of Loss: 04/08/2018 00:00 - :59 [48 Months and 25 Days From LTA Reg Date (Man Yr)] | | | | | | | |
| Claim Type: TP / 566545 | | Policy/Cover Note No.: 28958730TMC Coverage: 17/05/2018 - 16/05/2019 | | | | | | | |
| Vehicle Reg. No. (Insured): SJL5436L | | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: Premier Taxis Pte Ltd - Changi (HQ) 23 Changi South Ave 2 #03-02, 486443 Changi - Tel: | | | | | | | | | |
| Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545] | | | | | | | | | |
| Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 07/09/2018] | | | | | | | | | |
| Adj Asg. Remarks: on WP. OI non reporting. Liability cannot be established. TP agree with SJE - assign Calvin Ng of LKK Auto Consultants Pte Ltd. contact: 6544 6676 / 6544 6689 | | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

***SHD1055U (566545)**
[SJL5436L]
TP
PREMIER TAXIS PTE LTD
Aug 4 2018 12:00AM
[JCM RENTAL PTE LTD]
Premier Taxis Pte Ltd - Changi

| | | | | | | | | | | | | |
|--------------------|-----------------|---|---------------|--|--|--------------------|--|--|------------|-------------------------------------|-------------------------------------|--|
| Upload Documents | | | Upload Photos | | | Compose New Letter | | | View | | View in Browser | |
| Assessment Reports | | | | | | | | | 1 per page | | <input checked="" type="checkbox"/> | |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | Thumbnail | Print | | |
| 1 | 16/08/18 08:52 | Adjuster Immediate Advice | | | | | | | 1 Load HTM | | | |
| | | | | | | | | | 3 per page | | <input checked="" type="checkbox"/> | |
| Photos/Images | | | | | | | | | | | | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | Thumbnail | Print | | |
| 1 | 14/08/18 17:36 | General View | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| 2 | 14/08/18 17:36 | General View | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| 3 | 14/08/18 17:36 | General View | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| 4 | 14/08/18 17:36 | General View | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| 5 | 14/08/18 17:36 | General View | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| 6 | 14/08/18 17:36 | General View | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| 7 | 14/08/18 17:36 | General View | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| 8 | 14/08/18 17:36 | General View | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| 9 | 14/08/18 17:36 | General View | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| 10 | 14/08/18 17:36 | General View | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| 11 | 14/08/18 17:36 | General View | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| 12 | 14/08/18 17:36 | General View | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| 13 | 14/08/18 17:36 | General View | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| 14 | 14/08/18 17:36 | General View | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| 15 | 14/08/18 17:36 | General View | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| 16 | 14/08/18 17:36 | General View | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| 17 | 14/08/18 17:36 | General View | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| 18 | 14/08/18 17:36 | General View | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| 19 | 20/08/18 09:07 | Reinspection Photo | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| 20 | 20/08/18 09:07 | Reinspection Photo | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| 21 | 20/08/18 09:07 | Reinspection Photo | | | | | | | 1 Load JPG | <input checked="" type="checkbox"/> | | |
| | | | | | | | | | 1 per page | | <input checked="" type="checkbox"/> | |
| Documentation | | | | | | | | | | | | |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | | | | | | | Thumbnail | Print | | |
| 1 | 07/08/18 10:42 | SEND LISTING | | | | | | | 1 Load PDF | | | |
| 2 | 07/08/18 10:42 | TP PRI NOTICE AND GIA REPORT | | | | | | | 1 Load PDF | | | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | Thumbnail | Print | | |
| 1 | 16/08/18 08:48 | AUTODAX | | | | | | | 1 Load PDF | | | |
| 2 | 16/08/18 08:55 | ESTIMATE | | | | | | | 1 Load PDF | | | |

Documents Checklist

| | | | |
|--|-------|------|-------|
| DOCUMENTS CHECKLIST | Reset | Save | Print |
| There are no document checklists configured. | | | |

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18014462/K1SD3E2

Date: 20/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28958730TMC

Claimant Vehicle No : SHD1055U

Insured Vehicle No : SJL5436L

Date of Loss: 04/08/2018

Nature of Claim: TP

Claim No: 566545

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD1055U

Make & Model: KIA OPTIMA, 1.7 D (A)

Engine No: D4FDDH307938

Reg. Date: 10/07/2014 (Man. Year: 2013)

Chassis No: KNAGM414ME5464081

Colour: Silver

Odometer: 317362 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16

Rear Tyre Size: 205/65 R16

Front Left Side: Achilles 7 mm

Rear Left Side: Achilles 7 mm

Front Right Side: Achilles 7 mm

Rear Right Side: Achilles 7 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|---------------|---------------|---------------|--------------|
| Parts | 549.91 | 425.76 | 124.15 | 22.58 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 295.51 | 285.02 | 10.49 | 3.55 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 845.42 | 710.78 | 134.64 | 15.93 |
| Approved Total (Overridden) (S\$) | | 550.00 | | |
| (S\$) | 845.42 | 550.00 | 295.42 | 34.94 |
| + GST 7.00/7.00% (S\$) | 59.18 | 38.50 | 20.68 | 34.94 |
| Nett Amount (S\$) | 904.60 | 588.50 | 316.10 | 34.94 |

INSPECTION

Date of Assignment: 08/08/2018

Date Inspected: 14/08/2018 Inspected At:

Premier Taxis Pte Ltd - Changi (HQ)
23 Changi South Ave 2 #03-02
Singapore 486443

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | |
|--|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 20 Aug 2018) |
| Parts: 143 | KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SHD1055U) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk * |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|----------------------|---------------|------------|------------|
| 1 | 1 | | *FRONT BUMPER | Deformed | 531.00 FL | *531.00 FL |
| 2 | 1 | | *FRT BUMPER TRIM CAP | Not Necessary | 14.00 FL | *- FL |
| 3 | 1 | | *FRT LWR IMPACT DAMP | Serviceable | 110.00 FL | *- FL |
| 4 | 1 | | *GRILLE BADGE | Necessary | 50.17 FL | *50.17 FL |
| 5 | 1 | | *R/F BUMPER MOULDING | Serviceable | 51.00 FL | *- FL |
| 6 | 1 | | *R/F CTR BUMPER BRKT | Serviceable | 16.00 FL | *- FL |
| 7 | 1 | | *FRONT BUMPER CLIPS | Necessary | 48.00 FS | *48.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|---------------|---------------|
| Sub Total (\$\$) | 820.17 | 629.17 |
| - List Item Discount on L Items 35.00/35.00% (\$\$) | 270.26 | 203.41 |
| Total Parts (\$\$) | 549.91 | 425.76 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|------------------------------|----------|------------|--------|
| <u>Labour Items</u> | | | | |
| 1 | TOTAL PANEL / MECHANICAL | New | 45.00 | 35.00 |
| 2 | TOTAL PAINTWORK | New | 155.00 | 155.00 |
| 3 | TOTAL PAINT / MATERIAL COSTS | New | 95.51 | 95.02 |
| Gross Labour Cost (S\$) | | | 295.51 | 285.02 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >