



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CHEONG KWEE YING
BLK 767 WOODLANDS CIRCLE #08-338
SINGAPORE 730767

Attention : THE OWNER
Contact : 96918329

Supplementary Estimate : ES006422

Date : 16/08/2018
Vehicle Num. : SKC5137K
Make/Model : VOLKSWAGEN JETTA-2011
Chassis/Eng# : WVWZZZ16ZBM102255/CAV293689
Accident Date : 16/08/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS : REAR KNUCKLE ARM BUSH R/H		
----	---	---	--	--

List Total S\$:
20.00% Discount S\$:

107.40

78.00 ✓

78.00

7.8 15.00

70.20 62.40

LABOUR :
TO PRESS OUT AND IN REAR KNUCKLE BUSH R/H

55.00 30h

Labour Total S\$:

55.00

SingDollars : One Hundred Seventeen & Cents Forty Only

Total S\$: 117.40

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun