

(06/11/13)

Surveyor: KalvinREF: NS/INC18014478/K18d3n2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/ITP/RES/OD/RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: XD79114Policy No. 5673322670-02 C1/9/17-Claims No. MT/1006565-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / .REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 3005 B Yr Regn: 9 Jan 2016

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 200 c.c. 168Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 293014 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLCBXRUMG4091333Gen. Cond: Good / F / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rrim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Cooper

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 7/8/8 D.O.I. 8/8/8Survey held at CHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SHD 3005 B - CCG / 18005169 / khb342 DOA: 17/3/18 IncXD79114 - X 4513/8/18 Estimated 45 x 3000 / 3000(\$1,491.00 Red - 33%)

RECEIVED 14 AUG 2018

Date/Time, File Pass to?

14/08/181) Typist

Date/Time, File Return to?

2) _____

☐ : Prell. Report☒ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ 3,000.00 4/5)

160



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18014478/K1sd3

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 10-08-2018

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 7911U	Veh. Inspected	SHD 3005B
Policy No.	5073322670-02	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	10/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/08/2018	Inspection Date	08/08/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.

Date of Accident

Vehicle No.(For Motor)

Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5073322670-02		800 SUPER WASTE MANAGEMENT PTE LTD	198601155H	GFT	Comprehensive	XD7911U	XD7911U	01/09/2017	

TP Claims against NTUC Income: Follow-Through Survey

Date : 14/8/2018

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	MT/1006553-002	COMFORT TRANSPORTATION PTE LTD	SHA 7441P	SHD 1498A	9/8/2018	19:30	\$ 2,648.76
2	MT/1005720-002	COMFORT TRANSPORTATION PTE LTD	SHC 2783A	SKM 9296E	1/8/2018	22:00	\$ 3,986.00
3	MT/1005445-002	COMFORT TRANSPORTATION PTE LTD	SHD 3195K	GX 955K	30/7/2018	12:00	\$ 1,702.61
4	MT/1007065-001	COMFORT TRANSPORTATION PTE LTD	SHC 8895X	SJL 3120K	4/8/2018	10:45	\$ 7,775.32
5	MT/1006032-002	COMFORT TRANSPORTATION PTE LTD	SHC 2935D	SLQ 721X	4/8/2018	2:00	TOTAL LOSS
6	MT/1006368-002	COMFORT TRANSPORTATION PTE LTD	SHC 8643G	SJP 6149M	3/8/2018	21:20	\$ 2,481.58
7	MT/1006268-002	COMFORT TRANSPORTATION PTE LTD	SHB 4225L	SJT 7679Y	5/8/2018	3:00	\$ 5,577.26
8	MT/1006565-002	COMFORT TRANSPORTATION PTE LTD	SHD 3005B	XD 7911U	7/8/2018	11:15	\$ 4,490.76

Claim received from LKK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 07/08/2018 15:37
 Date Of Accident 07/08/2018 11:15
 Exact Location Of Accident SERANGOON NTH AVE 1 - SERVICE RD
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD3005B
Insured/Policyholder
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
 Co Reg No 199303821R
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768
Vehicle Particulars
 Manufacturer HYUNDAI
 Model I40
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
Insurance Company
 Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number MCOM0015
 Cover Note Number
Driver
 Name of Driver PANG ENG HIN
 NRIC No S1487419D
 Date Of Birth 11/05/1961
 Occupation OUTDOOR
 Date Of Driving Pass 12/11/1984
 Driving Experience 33 YEARS AND 8 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-92973700
 Fax Number
 Contact Number
 Email Address YUNQIHAN@SINGNET.COM.SG

Address 63 #12-213 TELOK BLANGAH HEIGHTS
 Postcode 100063
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

SEE ATTACH.


Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XD7911U
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver RONG BAOGUO
 NRIC/Passport Number S8379320A
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage NO DAMAGE
 No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

In Serangoon North Ave 1 car park. Near Block 103 Rubbish dump. Rubbish truck stop at right lane (2 way carriage) He just drove out of rubbish dump. I waited on left lane for him to move forward. After few second, no movement from truck driver. I slowly move left to overtake truck. Almost parallel with truck. He suddenly swerve towards my taxi and cause damage to right side of taxi.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Reporting Centre Personnel's Signature
Name:

[Signature]
7/8/18

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE. LTD.
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3005B

DATE 8/8/2018

MAKE :

MODEL : HYUNDAI i40

NTUC-LIS

TS

LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender (RH) — <i>del</i>			\$ 619.00
	Front Fender Shield (RH) <i>X</i>			\$ 169.80
	Front Fender Retainer <i>X</i>			\$ 9.20
	Front Door (RH) — <i>del</i>			\$ 1,403.00
	Front Door Mirror (RH) — <i>del</i>			\$ 980.50
	Front Wheel Hub Cap (RH) — <i>hatched</i>			\$ 150.70
	SUB TOTAL			\$ 3,332.20
	LESS 20%			\$ 666.44
	DISCOUNTED TOTAL			\$ 2,665.76
	Front Fender Advertisement Logo (RH) — <i>new</i>			\$ 100.00 Nett
	Front Door Comfort Logo (RH) — <i>new</i>			\$ 75.00 Nett
	Front Door Advertisement Logo (RH) — <i>new</i>			\$ 100.00 Nett
				\$ 275.00
	Labour Charge			
	Panel Beating			\$ 560.00 <i>450</i>
	Spray Painting Charge			\$ 650.00 <i>450</i>
	Wiring Charge			\$ 50.00 <i>20</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	Transfer of Door			\$ 120.00 <i>50</i>
	FRT Wheel Alignment			\$ 120.00 <i>20</i>
	TOTAL LABOUR			\$ 1,550.00
	ESTIMATE TOTAL			\$ 4,490.76
<p><i>Kalvin (LKK)</i> <i>8/8/18 1025h</i> <i>3 Rs</i> <i>4/5</i> <i>After Repair photo</i></p>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature
 Date:

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305197318
Date : 13/08/18

FINALIZATION FORM

To : LKK
Attn : KALVIN ANG
Vehicle Reg No. : SHD3005B

Fax :

Date of Accident : 07-Aug-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: NTUC --- XD7911U
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$3,000.00
Final Lumpsum Repair cost \$3,000.00


3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : KALVIN
Date : 13/8/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Marketing - 65 6385 6380 Faxline - 65 6250 9755

Workshops

38 Loyang Drive Singapore 508909
383 Sin Ming Drive Singapore 575117
45 Pandan Road Singapore 609766
403 Ulu Pandan Singapore 670000

34 Serangoon Road Singapore 738108
7 Sungei Road Way Singapore 725791
501 Yew San Industrial Park A Singapore 758732

Date/Time: 07.08.2018 17:03

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:

JC NO.: 305197318

STOMER

COMFORT TRANSPORTATION PTE LTD
7010045

VMS

STOMER NO.

383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)

DRESS

(R)

(P)

SCOUNT CARD NO.


REGN NO.	SHD3005B	MILEAGE
MAKE	HYUNDAI	FUEL E 1/2 F
MODEL	I-40	DATE/TIME IN 07.08.2018 13:30
YR OF MANU	09.06.2016	TARGET DATE
CHASSIS CODE	KMHLB41UMGU091333	COMPLETION DATE/TIME

JOB DESCRIPTION

Accident Date: 07.08.2018
NATURE: 3P 07.08.18/C

S/NO LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

31

Q:
Re No.:

SHD3005B

LIMITS

Vehicle No.:

SHD3005B

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: NS/INC18014478/K1sd3n2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 23-08-2018	
		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XD 7911U	Veh. Inspected	SHD 3005B
Policy No.	5073322670-02	Coverage (\$)	0.00
Claim No.	MT/1006565-002	Excess (\$)	0.00
Assign From		Assign Date	08/08/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU091333	Colour	BLUE
Odometer	293014	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	CAMPEON	7 mm
L/H Front Tyre	205/60 R16	CAMPEON	7 mm
R/H Rear Tyre	205/60 R16	CAMPEON	7 mm
L/H Rear Tyre	205/60 R16	CAMPEON	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	07/08/2018	Inspection Date	08/08/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3005B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER (RH)	DENTED	619.00	619.00
1	FRONT FENDER SHIELD (RH)	SERVICEABLE	169.80	-
1	FRONT FENDER RETAINER	SERVICEABLE	9.20	-
1	FRONT DOOR (RH)	DENTED	1,403.00	1,403.00
1	FRONT DOOR MIRROR (RH)	BROKEN	980.50	980.50
1	FRONT WHEEL HUB CAP (RH)	GRAZED	150.70	150.70
	LESS 20% DISCOUNT		-666.44	-630.64
			2,665.76	2,522.56
SPECIAL NETT ITEMS				
1	FRONT FENDER ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00
1	FRONT DOOR COMFORT LOGO (RH)(SN)	NECESSARY	75.00	75.00
1	FRONT DOOR ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00
			275.00	275.00
LABOUR				
	PANEL BEATING.		560.00	400.00
	SPRAY PAINTING CHARGE.		650.00	450.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.		50.00	20.00
	TRANSFER OF DOOR.		120.00	50.00
	FRT WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			1,550.00	940.00
GRAND TOTAL			4,490.76	3,737.56
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,000.00

Report Ref No. NS/INC18014478/K1sd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.