

(08/11/3)

Surveyor: KalvinREF: NS/INC18014488/K/vd3 n2

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD ☒ IWS / TP RES / OD RES / EVA / INV / MV

To Insp'd Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: 98G 86174Policy No. 5092793582-01 (20/07/18-Claims No. MT/100667-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHA 1798A Yr Regn: 2<sup>3</sup> Aug 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1700Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 150602 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTOKB3F41035 63524Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 5/8/8 D.O.I. 7/8/9Survey held at CHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
8/8/18	Continued P/P \$1580 / 2 hrs. (Red 1801.53, 5310) Inc
	SHA 1798A - NS/INC15013439 / H/vb n2 Dia: 13/8/15 PIP
	98G 86174-X

RECEIVED 04 SEP 2018

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 4/9-typistDays Of Repair: 2Resurvey No. of Trip: -

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I: (\$) 1580/2Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

160



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18014488/K1vd3

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 10-08-2018

189556



Code: INC4

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 8617H	Veh. Inspected	SHA 1798A
Policy No.	5092793582-01	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	10/08/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	05/08/2018	Inspection Date	08/08/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Denise Tay (LKKAUTO)

**From:** mtreg <mtreg@income.com.sg>  
**Sent:** Tuesday, 4 September 2018 10:18 AM  
**To:** Denise Tay (LKKAUTO)  
**Subject:** FW: REQUEST CLAIM NUMBER

Hi,

Claim created.

With Regards

Samsia  
Senior Admin Assistant,  
Motor Insurance  
[www.income.com.sg](http://www.income.com.sg)

 income  
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
Find out more at [Income.com.sg/careers](http://Income.com.sg/careers)

**in** with you

*'With effect from 1 Oct 2018, we will be discontinuing our fax number 6338 1504.  
Please forward all motor claims related correspondences to [mtcl@income.com.sg](mailto:mtcl@income.com.sg) so that we can attend to it accordingly.'*

**From:** Denise Tay (LKKAUTO) [mailto:[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)]  
**Sent:** Tuesday, September 04, 2018 9:34 AM  
**To:** mtreg <mtreg@income.com.sg>  
**Subject:** REQUEST CLAIM NUMBER

2	MT/1006804-002	COMFORT TRANSPORTATION PTE LTD	SHC
2	MT/1006167-002	COMFORT TRANSPORTATION PTE LTD SHA 1798A	SHA

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

eBaoTech

[Change Language](#) [Change Password](#) [Log Out](#)

Hello, NAC\_PAYA\_UBI\_800601

[My Desktop](#)  
[Notice of Loss](#)

## Policy Query

Policy No.

Vehicle No.(For Motor)

GBG8617H

Date of Accident

05/08/2018 11:39

Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5092793582-01		UNAG LOGISTICS PTE. LTD.	201601737W	GFT	Comprehensive	GBG8617H	GBG8617H	20/07/2018	

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/08/2018 14:02
Date Of Accident	05/08/2018 15:20
Exact Location Of Accident	HOUGANG AVE 2 CAR PARK STADIUM.
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA1798A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	TAY KIAN HOE
NRIC No	S1185589Z
Date Of Birth	03/09/1956
Occupation	OUTDOOR
Date Of Driving Pass	19/09/1980
Driving Experience	37 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97893587
Fax Number	
Contact Number	
Email Address	TAYMINGHONG@GMAIL.COM

Address	965 13-638 HOUGANG AVENUE 9
Postcode	530965
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	PASIR RIS NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

SEE POLICE REPORT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG8617H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	NOT SURE
No. Of Passenger (Including Driver)	

## Sketch Plan Pg. 1

### SKETCH PLAN

STRETCH PLAN

A

SHA 1798A

B

GBG 867H

B

R

Hougang ave 2

Carpark Station.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer: Report Police no T/20180806/2038

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE. LTD.  
CO REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)

Reporting Centre Personnel's Signature  
Name:

6/8/18  
Jackson Hong  
CSO *Shirone*



## Sketch Plan Pg. 2



**SINGAPORE  
POLICE FORCE**



T/20180806/2038

1 of 3

Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852999

Report No. T/20180806/2038

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 06/08/2018 12:04	Vide Report No.:	Station Diary No.: 39
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: TAY KIAN HOE	Address: APT BLK 965 HOUGANG AVENUE 9 #13-638 SINGAPORE 530965		
ID Type / ID No.: NRIC NO / S1185589Z	Contact No.: Home/Office: Mobile: 97893587		
Nationality: SINGAPORE CITIZEN	Email:		
Sex: Male	Age: 61	Date of Birth: 03/09/1956	Type of Informant: Driver
Race: Chinese	Language:		Institution / School Name:
Occupation: Taxi driver	Driving Licence Information: Class: 3,4 Date of Expiry:		

**General Information of the Accident**

Type of Accident: Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 05/08/2018 15:20	Type of Location: Car Park
Location: Along Road 1 HOUGANG AVENUE 2  CARPARK OF HOUGANG STADIUM			
Weather: Clear	Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way	Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
GBG8617H	Van	NISSAN		White	Slightly Damaged	0
SHA1798A	Car	TOYOTA	PRIUS HYBRID 1.8 CVT	Blue	Slightly Damaged	0



Sketch Plan Pg. 3



SINGAPORE  
POLICE FORCE



T/20180806/2038

Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852999

2 of 3  
Report No. T/20180806/2038

CONTINUATION OF REPORT

**Brief Details.**

On 05/08/2018 at about 1400hrs, I parked my taxi with plate bearing SHA1798A at HOUGANG Stadium. My vehicle was parked at lot number 95. Before I left my vehicle, I made a check on the surroundings at everything was intact. At about 1744hrs, I received a text message from ComfortDelgro who informed me that a person by the name of MS KOH (Hp:90267083) had witnessed an accident involving my taxi and a commercial vehicle at the said carpark. I then proceeded back to the carpark and when I arrived at the parking lot, I saw that my vehicle's right side mirror was damaged and there were also some scratches on the right body frame.

On the same day itself, I contacted the said person and she send me a video from her vehicle CCTV camera which shows how the accident took place. The commercial vehicle was reversing into an empty parking lot which was on the right side of my vehicle and it the midst of reversing, the said vehicle hit onto the right side of my vehicle. I wish to state that when I arrived back at my vehicle, the said commercial vehicle was nowhere at scene. The plate number of the said vehicle is GBG8617H from UNAG Logistics Company.



**SINGAPORE  
POLICE FORCE**



T/20180806/2038

Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852999

3 of 3

Report No. T/20180806/2038

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 MUHAMMAD FIRDAUS BIN ABDULLAH SHAFI-IE	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 06/08/2018 12:04
Officer In Charge Of Case: TP / HRT / Sr Staff Sgt ESTHER CHONG Contact No.: 65476368	Classification Of Case:
Authentication Stamp NP168	



## REPAIR ESTIMATE

VEHICLE NO : SHA 1798A

MAKE :

MODEL : TOYOTA PRIUS

NFTUC - CP/P

7/8/2018

TS

LKK - Kalvin

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
PANEL SUB-ASSY, FRONT DOOR, RH <i>X repair</i>			\$ 1,264.00
MIRROR ASSY, OUTER REAR VIEW, RH <i>- in</i>			\$ 1,390.00
COVER, OUTER MIRROR, RH <i>X repair</i>			\$ 141.90
OUTER MIRROR, RH <i>X repair</i>			\$ 212.80
<i>Front RH Door X repair</i>			
SUB TOTAL			\$ 3,008.70
LESS 25%			\$ 752.18
DISCOUNTED TOTAL			\$ 2,256.53
FRONT DOOR COMFORT LOGO <i>- in</i>		<i>- 16%</i>	\$ 75.00
LABOUR CHARGE			
Panel Beating			\$ 350.00 <i>200</i>
Spray Painting Charge			\$ 500.00 <i>250</i>
Wiring Charge			\$ 50.00 <i>20</i>
Tuff Kote			\$ 50.00 <i>X 24</i>
Transfer of Door			\$ 120.00 <i>X 47</i>
TOTAL LABOUR			\$ 1,070.00
ESTIMATE TOTAL			\$ 3,401.53

Kalvin LKK

7/8/18 1020h

2 Days

P/P

Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305196780  
REGN NO : SHA1798A  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(G4)  
DATE OF REGN : 23.08.2017  
DATE/TIME IN : 06.08.2018 12:45  
ACCIDENT DATE : 05.08.2018

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0302-0594-G WING MIRROR RH 1 1,390.00 25.00 1,042.50  
0002 28-01-0103-0003-A Frt Door ComfortDelGro RH 1 75.00 10.00 67.50

SUB-TOTAL : 1,110.00

## JOB NATURE

0000 L PANEL BEATING 200.00  
0001 23-502 SPRAYPAINT ON AFFECTED AREA 250.00  
0002 17-01 WIRING CHECK 20.00

SUB-TOTAL : 470.00

TOTAL : 1,580.00

  
MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive, Singapore 508969  
Fax: 6546 8156

Our Job Ref No : 305196780  
Date : 08/08/18

## FINALIZATION FORM

To : LKK  
Attn : KALVIN ANG  
Vehicle Reg No. : SHA1798A

Fax : \_\_\_\_\_  
Date of Accident : 05-Aug-18


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: NTUC --- GBG8617H
2. The finalized amount shall be:
 

(a) Spare Parts after List discount	\$1,110.00
(b) Labour Charges	\$470.00
<b>Total for Part-By-Part Repair Cost</b>	<b>\$1,580.00</b>
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	_____
<b>Final Lumpsum Repair cost</b>	_____

3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : LIM T S  
Tel : 62148398  
Fax : 65468156

Signature :   
Name : KALVIN  
Date : 8/8/18

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_  
\_\_\_\_\_



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18014488/K1vd3n2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 10-09-2018  
189556



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 8617H	Veh. Inspected	SHA 1798A
Policy No.	5092793582-01	Coverage (\$)	0.00
Claim No.	MT/1006167-002	Excess (\$)	0.00
Assign From		Assign Date	07/08/2018

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU103563524	Colour	BLUE
Odometer	150602	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	7 mm
L/H Front Tyre	195/65 R15	WEST LAKE	7 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	7 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	05/08/2018	Inspection Date	07/08/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------





# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1798A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	PANEL SUB-ASSY, FRONT DOOR, RH	TO REPAIR SEE LABOUR	1,264.00	-
1	MIRROR ASSY, OUTER REAR VIEW, RH	CRACKED	1,390.00	1,390.00
1	COVER, OUTER MIRROR, RH	TO REPAIR SEE LABOUR	141.90	-
1	OUTER MIRROR, RH	TO REPAIR SEE LABOUR	212.80	-
1	FRONT RH DOOR (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-752.17	-347.50
			2,256.53	1,042.50
<b><u>NETT ITEMS</u></b>				
1	FRONT DOOR COMFORT LOGO (N)	NECESSARY	75.00	75.00
	LESS 10% DISCOUNT		-	-7.50
			75.00	67.50
<b><u>LABOUR</u></b>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY, FRONT DOOR, RH, COVER, OUTER MIRROR, RH, OUTER MIRROR, RH AND FRONT RH DOOR.		350.00	200.00
	SPRAY PAINTING CHARGE.		500.00	250.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.	NOT NECESSARY	50.00	-
	TRANSFER OF DOOR.	NOT NECESSARY	120.00	-
			1,070.00	470.00
<b>GRAND TOTAL</b>			<b>3,401.53</b>	<b>1,580.00</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>1,580.00</b>

Report Ref No. NS/INC18014488/K1vd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.