



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Attn : Tel : Fax No. :

Quotation No. : QO18/06-1383	Quotation Date : 14/06/2018	Terms : 30 DAYS
Vehicle No. : SLW8154Z	Chassis No. : JM6BN22A8H0162656	Third Party Insurer : AIG
Model : MAZDA 3	Date of Accident : 11/06/2018	
Remarks : INSURED'S VEHICLE NO: SLP7579A		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER	1	1,075.0000	1,075.00
2	REAR BUMPER REINFORCEMENT	1	538.0000	538.00
3	REAR BUMPER REFLECTOR	2	51.0000	102.00
4	REAR BUMPER SIDE RETAINER	2	37.0000	74.00
5	REAR BUMPER SIDE GUIDE	2	55.1000	110.20
6	REAR BUMPER SIDE GUIDE RIVETS	4	9.1000	36.40
7	REAR BUMPER CLIPS	10	5.0000	50.00
8	REAR BUMPER SCREW SPACER	2	10.0000	20.00
9	REAR BUMPER SPACE SCREW	2	15.0000	30.00
10	REAR END PANEL	1	506.0000	506.00
11	REAR END PANEL INNER TRIM	1	86.0000	86.00
12	REAR END PANEL INNER TRIM CLIPS	4	5.0000	20.00
13	LESS 20% ITEM (1-12)	1	-529.5200	-529.52
14	REAR BUMPER PARKING SENSOR	1	450.0000	450.00
15	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	1	120.0000	120.00
16	TO RUST-PROOFING OF THE AFFECTED AREAS.	1	100.0000	100.00
17	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1	120.0000	120.00
18	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	700.0000	700.00
19	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	650.0000	650.00

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
--	--

Quotation No. : QO18/06-1383	Quotation Date : 14/06/2018	Terms : 30 DAYS
Vehicle No. : SLW8154Z	Chassis No. : JM6BN22A8H0162656	Third Party Insurer : AIG
Model : MAZDA 3	Date of Accident : 11/06/2018	
Remarks : INSURED'S VEHICLE NO: SLP7579A		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00

RASUL
 Hp 90010068
 2 days
 P/P
 07/06/18 @ 1540
 Resury bf paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Sub Total	4,258.08
GST(7.00%)	298.07
Total (SGD)	4,556.15

Please conduct the survey at
 Pegasus Engineering @ 74 Kian Teck Road Singapore 628800