

22/03/2002

ASS. REC. BY:

REF:

08/MSG/18014521/Grd321

Special Instruction:

Surveyor:
Menheren

GO

ASSIGNMENT (Office)

From (Person): Chhica Nyuk Rui

of

MSG

Date/Time:

10/8/18 @ 2-02pm

Estimated Cost:

Bill to:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKC9104D

Insured:

XB 8775A

at Workshop m/s

Keng Car Repair

Tel:

6 747 7636

of

No. 1 kaki Blk Ave 6 # 02-06

Policy No:

8289 793207MV

Claim No:

566810

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

7/8/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

2:58pm 10/8/18

Person Contacted:

Jeffrey

Vehicle:

☒ IN ☐ OUT

Date/Time	Action/Instruction	Estimate
	SKC9104D - NA/INC/3020512/r3	DOA: 31/10/18
	XB 8775A - X.	
	Revert 1A thru Menheren	
	Adrian confirm L/S \$3750.00 @ 5 days (Red: \$4725.55, 567.)	

REF:

ASS. REC. BY: Adrian King**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its
repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: SKC9104D Yr Regn: 2011 / octType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vios C.C. 1497Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 139750 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053HY930S268252Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil S/Rim / STD A/Rim orTyre Size: F: 185/65R15R: 185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 10/08/18Survey held at Kangy.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP MSLG.

RECEIVED 12 OCT 2018.

MV: 37K

PV: 24.9K

Nett: 12.1K.

Date/Time, File Pass to?

☐

Preli. Report

1) typist☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format: TPLump Sum / ~~FE~~ (\$) 3750.0015010160




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18014521/Grd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 10-08-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XB 8775A	Veh. Inspected	SKC 9104D
Policy No.	S28979320TMV	Coverage (\$)	0.00
Claim No.	566810	Excess (\$)	0.00
Assign From	MERIMEN (CHHIA NYUK PUI)	Assign Date	10/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	07/08/2018	Inspection Date	10/08/2018
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	
Main	08 Aug 2018		10 Aug 2018 14:02 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

[Created by insurer]

CLAIM SUBFOLDER DETAILS

Insured:	LH CONSTRUCTION AND MACHINERY LEASING PTE LTD, Co. Reg. No.: 200809157H		
Main Claimant:	COMFORTDELGRO DRIVING CENTRE PTE LTD, Co. Reg. No.: 199601882C		
Vehicle Reg. No.:	SKC9104D	Date of Loss:	07/08/2018 14:00 - :59 [81 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 566810	Policy/Cover Note No.:	S28979320TMV (Third Party Only) Coverage: 03/07/2018 - 02/07/2019
Vehicle Reg. No. (Insured):	XB8775A	Policy No. (Claimant):	
		Excess:	
Repairer:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67477636		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/08/2018]		
Driver/Custodian (Insured):	LEE LYE CHWENG (), NRIC: S1276401D, Tel: +6597187886		
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQUEST TO ASSIGN LKK (ADRIAN LING) LIABILITY: 100% CONTACT: JEFFREY 6747 7636		

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 12 Oct 2018

Preliminary Advice

Insured Vehicle No	: XB8775A	Accident Date	: 07/08/2018
TP Vehicle No	: SKC9104D	Assignment Date	: 10/08/2018
Make	: TOYOTA VIOS	Est. Duration of Repair	: 5.00
Date of Inspection	: 10/08/2018		
Inspection At	: KANG CAR REPAIRERS PTE LTD (HQ) NO 1 KAKI BUKIT AVE 6, #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,475.55
Revised Amount	:S\$	4,722.10
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,722.10
Lump Sum Repair	:S\$	3,750.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/08/2018 12:33
Date Of Accident	07/08/2018 13:15
Exact Location Of Accident	X JUNCTION OF KAKI BUKIT AVE 2 TWDS EUNOS LINK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC9104D
Insured/Policyholder	
Name Of Registered Owner	COMFORTDELGRO DRIVING CENTRE PTE LTD
Co Reg No	199601882C
Email Address	DARYLTAN@CDC.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-67401636

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 E (A)
Exact Purpose for which vehicle was being used at time of accident	TRAINING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	M489523
Cover Note Number	

Driver

Name of Driver	PERRY SIM KIAN SIONG
NRIC No	S9229781J
Date Of Birth	18/08/1992
Occupation	INDOOR
Date Of Driving Pass	07/08/2018
Driving Experience	0 YEAR AND 0 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97229399
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 137 JALAN BUKIT MERAH #04-1386
Postcode 160137
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - LEARNER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: : KENNY LEONG
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

ON 7TH AUGUST 2018 AT 1315HRS, I WAS STOPPING AT THE RIGHT TURN POCKET(2ND LANE) FROM KAKI BUKIT AVE 2, TWDS EUNOS LINK. WHEN A THIRD PARTY VEHICLE XB8775A, SUDDENLY COLLIDED INTO THE REAR RIGHT SIDE DOOR OF MY VEHICLE SKC9104D. NO ONE WAS INJURED , THAT IS ALL.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

Details of Witness 1

Name KENNY LEONG
Phone Number 96506455
Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XB8775A
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver LEE LYE CHWENG
NRIC/Passport Number S1276401D
Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7th August 2018 at 1315 hrs, I was stopping at the right-turn pocket (2nd lane) from Kaki Bukit Ave 2, towards Eunos Link, when a third party vehicle XB 8775A suddenly collided into the rear right-side door of my vehicle SKC9104D. No one was injured, that is all.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Signature of Policyholder

Signature of Driver

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 7/8/2018

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

TRAFIC POLICE


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1882C
Vehicle Details	
Vehicle No.:	SKC9104D
Vehicle to be Exported:	Yes
Intended De-registration Date:	10 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	1NZY401209
Chassis No.:	MR053HY9305268252
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$11,008.00
Original Registration Date:	14 Oct 2011
First Registration Date:	14 Oct 2011
Transfer Count:	0
Actual ARF Paid:	\$11,008.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Oct 2021
PARF Rebate Amount:	\$7,155.00
Intended COE Rebate Details	
COE Expiry Date:	13 Oct 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$55,989.00
COE Rebate Amount:	\$17,775.00
Total Rebate Amount:	\$24,930.00

The information contained herein is correct as at 10 Aug 2018

OK



FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Toyota Vios 1.5A

\$2000 Downpayment Monthly
 From \$488 Onwards. Lowest
 3.68% P.A. @ GV Cars Financing
 GV Credit Pte Ltd. StarAd

• Free VICOM evaluation
 • Free grooming and 6 months maintenance
 • In-house workshop ensures quality service
 • Member of SVTA and hire purchase association
 • 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category Save Search Print

4 vehicles | **Search** Advanced Search Search View All

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

☐ **Toyota Vios 1.5A E** **\$31,000** **\$10,170 /yr** **19-Jan-2011** **1,497 cc** **-** **Sedan** **Available**

Road Tax Renewed During July. Excellent Condition. 100% Accident Free.

☆ Posted: 28-Jul-2018 Tags: 2011 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota

☐ **Toyota Vios 1.5A E** **\$29,800** **\$9,590 /yr** **27-Jan-2011** **1,497 cc** **87,000 km** **Sedan** **Available**

\$0 Downpayment Available. Cheapest In Town And Guarantee Best Condition In Town. Excellent Condition, Call Now For An Appointment.

☆ Posted: 03-Aug-2018 Tags: 2011 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota

☐ **Toyota Vios 1.5A E** **\$35,800** **\$11,210 /yr** **15-Apr-2011** **1,497 cc** **88,618 km** **Sedan** **Available**

Don't Miss It! 1 Owner With Very Low Mileage Done. Only \$3,580 Down Payment. Up To 90% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrival...

☆ Posted: 16-Jul-2018 Tags: 2011 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota

☐ **Toyota Vios 1.5A E** **\$35,800** **\$10,280 /yr** **12-Jul-2011** **1,497 cc** **111,386 km** **Sedan** **Available**

Must View. New Facelift Model. 1 Owner Only. Superb Condition. Beautiful Colour With Bidded Number Plate. Only \$3,580 Down Payment. Up To 90% Flexible Loan. We Provide Lowest Interest Rate. Flexible Lo...

☆ Posted: 28-Jul-2018 Tags: 2011 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view [Expired ads](#)

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used vios, vios Singapore, used vios Singapore, used vios Singapore or even buy used vios Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)



Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : MSIG INSURANCE (SINGAPORE) PTE LTD

4 SHENTON WAY
#21-01 SGX CENTRE 2
SINGAPORE 068807

TEL: 68277888

FAX: 62257402

ATTN: Motor Claim Department

Estimate No: EST1800244

Date: 08 Aug 2018

Veh Reg No: SKC9104D

Make/Model: TOYOTA VIOS

Chasis No: MR053HY9305268252

Reg. Date: 14/10/2011

Your Ref No: XB8775A

Claim Type: Third Party

Accident Date: 07/08/2018

TP Veh Reg No: XB8775A

Estimate Repair Cost to Vehicle No :SKC9104D

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC REAR DOOR RH <i>Distorted</i>	863.60 ✓	
2	2 PCS REAR DOOR HINGE RH <i>3 new Best</i>	164.20 ✓✓	
3	1 PC REAR DOOR CHECK RH	146.70 ✓	
4	1 PC REAR DOOR PROTECTOR RH <i>Relnd</i>	78.10 -	
5	1 PC REAR DOOR PROTECTOR MOULDING RH <i>Relnd</i>	44.10 -	
6	1 PC REAR DOOR OUTER HANDLE RH <i>2 pc cruchd</i>	66.80 ✓	
7	1 PC REAR DOOR LOCK RH <i>Pangd</i>	424.80 -	
8	1 PC REAR DOOR RUBBER RH <i>ct</i>	152.80 -	
9	1 PC REAR DOOR OUTER MOULDING RH <i>Relnd</i>	62.90 ✓	
10	1 PC REAR DOOR GLASS RH <i>Shattred</i>	332.40 ✓	
11	1 PC REAR DOOR GLASS REGULATOR AND MOTOR ASSY RH <i>2nd</i>	716.80 ✓ <i>288.50</i>	
12	1 PC REAR DOOR GLASS CHANNEL <i>new</i>	150.70 ✗	
13	1 PC REAR DOOR QUARTER GLASS PILLAR RH <i>3 new</i>	128.80 ✗	
14	1 PC REAR DOOR QUARTER GLASS RUBBER RH	110.70 ✗	
15	1 PC REAR DOOR TRIM RH <i>cruchd</i>	468.70 ✓ <i>3282.80</i>	
16	1 PC REAR DOOR CENTRE PILLAR <i>2 pc</i>	128.80 ✗ <i>2462.10</i>	
17	1 PC DRIVER RH SEAT BELT <i>2 pc new</i>	744.60 ✗	
18	1 PC REAR DOOR FRAME FRAME BLACK STICKER RH <i>new</i>	48.30 -	
19	1 PC FRT DOOR RH <i>2 new 2 pc</i>	819.30 ✗✗	
20	1 PC FRT DOOR PROTECTOR RH <i>2 pc cut</i>	100.70 ✗	
21	1 PC FRT DOOR PROTECTOR & MOULDING <i>cut</i>	40.20 ✓	
		5,794.00	
	Less 25%	1,448.50	4,345.55
	Special Net		
22	1 SET REAR DOOR STICKER <i>new</i>	190.00 ✓	
23	1 SET FRT DOOR RH STICKER <i>new new</i>	195.00 ✓	
24	1 PC REAR FENDER STICKER <i>new</i>	195.00 ✓ <i>580</i>	
		580.00	580.00

Labour

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : MSIG INSURANCE (SINGAPORE) PTE LTD
4 SHENTON WAY
#21-01 SGX CENTRE 2
SINGAPORE 068807

TEL: 68277888 FAX: 62257402
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 07/08/2018
TP Veh Reg No: XB8775A

Estimate No: EST1800244
Date: 08 Aug 2018

Veh Reg No: SKC9104D
Make/Model: TOYOTA VIOS
Chasis No: MR053HY9305268252
Reg. Date: 14/10/2011
Your Ref No: XB8775A

Estimate Repair Cost to Vehicle No :SKC9104D

Quantity	Description	List Price	Amount
		SS	SS
25	1 TO REMOVE AND REFIT FRT DOOR GLASS <i>fitting</i>	100.00 *	
26	1 TO REMOVE AND REFIT REAR DOOR GLASS <i>fitting</i>	100.00 80	
27	1 TO REMOVE AND REFIT SEAT CUSHION	200.00 60	
28	1 TO REMOVE AND REFIT SEAT BELT	150.00 *	
29	1 TO SPRAY UNDERSEAL	100.00 40	
30	1 TO SPRAY PAINTING	1,300.00 800	
31	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,500.00 700	
32	1 TO REMOVE AND REFIT QUARTER GLASS	100.00 X	
		3,550.00	3,550.00
		Total	S\$ 8,475.55
		Add GST @ 7%	593.29
		Total Amount Payable	S\$ 9,068.84

TOTAL: SINGAPORE DOLLAR NINE THOUSAND SIXTY EIGHT AND CENTS EIGHTY FOUR ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

total: 4722.10

L/S 3750

3750

Adrian Lim.
L/S 10/08/18.
os days.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Aug 2018		10 Aug 2018 14:02 Edit Adj Rpt	S\$3,750.00 Edit Estimates	S\$3,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LH CONSTRUCTION AND MACHINERY LEASING PTE LTD , Co. Reg. No.: 200809157H								
Main Claimant:	COMFORTDELGRO DRIVING CENTRE PTE LTD , Co. Reg. No.: 199601882C								
Vehicle Reg. No.:	SKC9104D	Date of Loss:	07/08/2018 14:00 - :59 [81 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 566810	Policy/Cover Note No.:	S28979320TMV (Third Party Only) Coverage: 03/07/2018 - 02/07/2019						
Vehicle Reg. No. (Insured):	X88775A	Policy No. (Claimant):							
		Excess:							
Repairer:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67477636								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 09/09/2018]								
Driver/Custodian (Insured):	LEE LYE CHWENG (), NRIC: S1276401D, Tel: +6597187886								
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQUEST TO ASSIGN LKK (ADRIAN LING) LIABILITY: 100% CONTACT: JEFFREY 6747 7636								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKC9104D (566810)

[XB8775A]



































TP

COMFORTDELGRO DRIVING CENTRE PTE LTD

Aug 7 2018 2:00PM

[LH CONSTRUCTION AND MACHINERY LEASING PTE LTD]

Kang Car Repairers Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/08/18 09:25	Accident Statement From: SC - Reg. No: XB8775A, Claimant: LH CONSTRUCTION AND MACHINERY LEASING PTE LTD	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/10/18 11:58	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
2	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
3	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
4	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
5	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
6	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
7	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
8	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
9	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
10	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
11	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
12	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
13	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
14	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
15	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
16	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
17	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
18	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
19	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
20	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
21	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
22	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
23	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
24	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
25	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
26	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
27	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
28	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
29	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
30	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
31	26/09/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
32	26/09/18 17:03	Reinspection Photo	 Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	26/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/08/18 09:25	SKC9104D TP E-FILE REPORT	Load PDF	
2	10/08/18 09:25	ESTIMATE	Load PDF	
3	10/08/18 09:25	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK (ADRAIN LING).	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18014521/GRD3E2

Date: 16/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: S28979320TMV

Claimant Vehicle No : SKC9104D

Insured Vehicle No : XB8775A

Date of Loss: 07/08/2018

Nature of Claim: TP

Claim No: 566810

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKC9104D

Make & Model: TOYOTA VIOS, 1.5 (A)

Engine No: 1NZY401209

Reg. Date: 14/10/2011 (Man. Year: 2011)

Chassis No: MR053HY9305268252

Colour: Silver

Odometer: 139750 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,925.50	3,042.10	1,883.40	38.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,550.00	1,680.00	1,870.00	52.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,475.50	4,722.10	3,753.40	44.29
Approved Total (Overridden) (S\$)		3,750.00		
(S\$)	8,475.50	3,750.00	4,725.50	55.75
+ GST 7.00/7.00% (S\$)	593.29	262.50	330.79	55.76
Nett Amount (S\$)	9,068.79	4,012.50	5,056.29	55.75

INSPECTION

Date of Assignment: 10/08/2018

Date Inspected: 10/08/2018 Inspected At:

Kang Car Repairers Pte Ltd (HQ)

No 1 Kaki Bukit Ave 6, #02-06

AutoBay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Oct 2018)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC9104D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR DOOR RH	Distorted	863.60 FL	*863.60 FL
2	2	*REAR DOOR HINGE RH	Bent	164.20 FL	*164.20 FL
3	1	*REAR DOOR CHECK RH	Bent	146.70 FL	*146.70 FL
4	1	*REAR DOOR PROTECTOR RH	Deformed	78.10 FL	*78.10 FL
5	1	*REAR DOOR PROTECTOR MOULDING RH	Deformed	44.10 FL	*44.10 FL
6	1	*REAR DOOR OUTER HANDLE RH	Cracked	66.80 FL	*66.80 FL
7	1	*REAR DOOR LOCK RH	Damaged	424.80 FL	*424.80 FL
8	1	*REAR DOOR RUBBER RH	Cut	152.80 FL	*152.80 FL
9	1	*REAR DOOR OUTER MOULDING RH	Deformed	62.90 FL	*62.90 FL
10	1	*REAR DOOR GLASS RH	Shattered	332.40 FL	*332.40 FL
11	1	*REAR DOOR GLASS REGULATOR AND MOTOR ASSY RH	Damaged	716.80 FL	*288.50 FL
12	1	*REAR DOOR GLASS CHANNEL	Not Necessary	150.70 FL	*- FL
13	1	*REAR DOOR QUARTER GLASS PILLAR RH	Not Necessary	128.80 FL	*- FL
14	1	*REAR DOOR QUARTER GLASS RUBBER RH	Not Necessary	110.70 FL	*- FL
15	1	*REAR DOOR TRIM RH	Cracked	468.70 FL	*468.70 FL
16	1	*REAR DOOR CENTRE PILLAR	Repair	128.80 FL	*- FL
17	1	*DRIVER RH SEAT BELT	Not Necessary	744.60 FL	*- FL
18	1	*REAR DOOR FRAME BLACK STICKER RH	Necessary	48.30 FL	*48.30 FL
19	1	*FRT DOOR RH	Repair	819.30 FL	*- FL
20	1	*FRT DOOR PROTECTOR RH	Cut	100.70 FL	*100.70 FL
21	1	*FRT DOOR PROTECTOR & MOULDING	Cut	40.20 FL	*40.20 FL
22	1	*SET REAR DOOR STICKER	Necessary	190.00 FS	*190.00 FS
23	1	*SET FRT DOOR RH STICKER	Necessary	195.00 FS	*195.00 FS
24	1	*REAR FENDER STICKER	Necessary	195.00 FS	*195.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **6,374.00** **3,862.80**
 - List Item Discount on L Items 25.00/25.00% (\$\$) **1,448.50** **820.70**

Total Parts (\$\$) **4,925.50** **3,042.10**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT FRT DOOR FITTING	New	100.00	0.00
2	TO REMOVE AND REFIT REAR DOOR FITTING	New	100.00	80.00
3	TO REMOVE AND REFIT SEAT CUSHION	New	200.00	60.00
4	TO REMOVE AND REFIT SEAT BELT	New	150.00	0.00
5	TO SPRAY UNDERSEAL	New	100.00	40.00
6	TO SPRAY PAINTING	New	1,300.00	800.00
7	TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING / WELDING WORKS	New	1,500.00	700.00
8	TO REMOVE AND REFIT QUARTER GLASS	New	100.00	0.00
Gross Labour Cost (S\$)			3,550.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >