

ASS. REC. BY:

REF:

CS/SMD18014522/R/d3

n2

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

Gree Leo

of

SMO

Date/Time:

10/8/18 @ 11:29am

Estimated Cost:

Bill to:

☒ OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XE 497P

Insured:

at Workshop m/s:

ASM Automotive

Tel:

9236 8218

of

No. 2 Kwong Min Road

Policy No:

Claim No:

CMTD 1803338/NSW

Sum Insured:

Excess:

\$1,500.00

Make of Veh:

D.O.A 30/07/2018

(Client's Record)

☒ if consistent
CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:05pm @ 10/8/18

Person Contacted:

Yvonne

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

XE 497 P-X

Confirm L/s \$6,900, 10 days

Red: \$2707, 28%.

Summary CASUL

REF:

26750

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **XE 497P**
 at Workshop m/s: **ASM AUTOMOTIVE**
 of **No. 2 Kwong Mun RO**
 Insured: **Sompo**
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: **1500**
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: **90k**
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

☒ CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **XE 497P** Yr Regn: **2015 / APR**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
☒ Truck / Trailer or
 Make: **NO TRUCKS GKBSE** c.c **10837**
 Colour: **MULTI** A/C: Insured / Std / NI / NA
 Sp. Reading: **187688** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **GKBSE00491**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: ☒ Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **295/80R22.5**
 R: **210**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **XCEED**

Front		Rear	
R/Bal.	8 mm	R/Bal.	8/8 mm
L/Bal.	8 mm	L/Bal.	8/8 mm
D.O.A.	30/01/18	D.O.I.	10/08/18

Survey held at **ASM AUTOMOTIVE**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR 8 o/s FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 18 SEP 2018

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: **10**

Resurvey No. of Trip: **1**

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation

S + RS \$

Photos

Others

TOTAL

Report Format :

OD

Lump Sum / 1st: (\$ **6900**)

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18014522/R1rd3

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 10-08-2018



Code : SMO

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	XE 497P
Policy No.	Coverage (\$)	0.00
Claim No. CMTD1803338/NSW	Excess (\$)	1,500.00
Assign From GRACE TEO	Assign Date	10/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 30/07/2018	Inspection Date 10/08/2018
Survey held at ASM AUTOMOTIVE- NO.2 KWONG MIN ROAD	
Repairer CITY AUTO PTE LTD	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Friday, 10 August 2018 11:29 AM
To: CITY AUTO; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Ngo, Sau Wei Shawn; Ye, Yong Kang Melvin
Subject: CMTD1803338/NSW - OD(LKK)/ XE497P ACC ON 30.07.18
Attachments: XE497P - SAS (180730).pdf

Our Claim Reference : CMTD1803338/NSW

Hi Yvonne,

We acknowledged receipt of your claim documents.

Please be informed that Shawn Ngo the handler of this case.

Please be informed that we have appointed **LKK AUTO** to conduct the survey.

Authorisation will be further advised upon survey.

Excess - \$ 1,500.00

Aside to **LKK AUTO**,

Please assist to conduct motor survey on Own Damage basis.

Please submit with your preliminary report upon completion of survey to my colleague, Shawn Ngo.

Kindly proceed to authorise if consistent.

Excess applicable – \$ 1,500.00

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: CITY AUTO [mailto:cityauto@singnet.com.sg]
Sent: Wednesday, August 08, 2018 12:05 PM
To: Claims - Motor Survey
Subject: Arrange survey for XE497P

Dear Motor Claim Department,

Kindly arrange survey on **Friday 10/08/2018** for following vehicle,

Survey Before Repair

Claim No. : Sompo OD

Vehicle No. : XE497P

Location : No. 2 Kwong Min Road, Singapore 628705

Thanks & Regards,

Yvonne

City Auto Pte Ltd
Blk 8 Sin Ming Industrial Estate
#01-58/60/62 Singapore 575643
Tel: +65-6453 1235 (6 Line)
Fax: +65-6453 7944
Email: cityauto@singnet.com.sg

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Monday, September 17, 2018 12:46 PM
To: 'Ngo, Sau Wei Shawn'
Cc: 'Ye, Yong Kang Melvin'; SUR; 'Teo, Grace'
Subject: RE: CMTD1803338/NSW - OD(LKK)/ XE497P ACC ON 30.07.18
Attachments: XE 497P SUPPLEMENTARY ESTIMATE.pdf

Dear Shawn,

We refer to the above mentioned vehicle.

We have received supplementary from repairer.

Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Friday, August 10, 2018 12:06 PM

To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Ngo, Sau Wei Shawn' <Shawn.Ngo@sompo.com.sg>; 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: CMTD1803338/NSW - OD(LKK)/ XE497P ACC ON 30.07.18

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]

Sent: Friday, 10 August 2018 11:29 AM

To: CITY AUTO <cityauto@singnet.com.sg>; admin-d@lkkauto.com; assignments@lkkauto.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2675D
Vehicle Details	
Vehicle No.:	XE497P
Vehicle to be Exported:	No
Intended De-registration Date:	13 Aug 2018
Vehicle Make:	UD TRUCKS
Vehicle Model:	GKB5ELDHNT ESCOT V
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	GH11726019
Chassis No.:	GKB5E00491
Maximum Power Output:	-
Open Market Value:	\$71,031.00
Original Registration Date:	01 Apr 2015
First Registration Date:	01 Apr 2015
Transfer Count:	0
Actual ARF Paid:	\$3,552.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$53,202.00
COE Rebate Amount:	\$35,282.00
Total Rebate Amount:	\$35,282.00

The information contained herein is correct as at 13 Aug 2018

OK



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

SOMPO INSURANCE SINGAPORE PTE. LTD.

50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER
RAFFLES PLACE
SINGAPORE LAND TOWER
SINGAPORE 048623

Contact : 6265 0980/6265 0980

Fax No. : 62213302

Estimate : QUOT201808-000056(00)

Date : 03/08/2018

Vehicle No. : XE497P

Make/Model : UD TRUCKS GKB5ELDHNT ESCOT
V

Mileage (km) : 0

Chassis No. : GKB5E00491

Accident Date : 30/07/2018 00:00:00

Claim No. :

Reference : Sompoo OD

Policy No. : D18MTHCVE000531

S/No	Particular	Quantity	Unit Price	Amount S\$
NET ITEMS				
1	Front panel	1.0	1,030.00	1,030.00 <i>34</i>
2	RH corner panel	1.0	165.00	165.00 <i>CR</i>
3	Front bumper RH	1.0	365.00	365.00 <i>74</i>
4	Side bumper RH	1.0	72.00	72.00 <i>cut</i>
5	Bumper step protector RH	1.0	50.00	50.00 <i>sch</i>
6	Headlamp - RH	1.0	395.00	395.00 <i>84</i>
7	Fog lamp - RH	1.0	85.00	85.00 <i>84</i>
8	Bumper signal RH	1.0	36.00	36.00 <i>84</i>
9	Door panel - RH	1.0	1,724.00	1,724.00 <i>84</i>
10	Side sill - RH	1.0	99.00	99.00 <i>74</i>
11	Quarter panel RH	1.0	408.00	408.00 <i>84</i>
12	Exhaust silencer cover	1.0	329.00	329.00 <i>repair</i>
				4,758.00
				0.00
				4,758.00
SPECIAL NET				
1	Platform step	1.0	180.00	180.00 <i>74</i>
SPECIAL NET Total S\$:				180.00
LABOUR				
	Dismantle damaged door, transfer usable parts into new door. Cut and replace RHS quarter panel. Jack and realign RHS pillar and floorboard. Remove and replace other damaged parts.	1.0	2,500.00	2,500.00 <i>2000</i>
	Spray painting	1.0	650.00	650.00 <i>500</i>
				3,150.00

Rasul
Hq 900/10068
10 days
4/8
10/08/18 @ 1625
EXCESS: 1500
Repair
Resurvey after repair

I KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

for CITY AUTO PTE LTD

Signature:
Date:

E. & O.E.

Total S\$: 8,088.00 *9607*
GST 7% S\$: 566.16
Amount Due S\$: 8,654.16



CITY AUTO PTE LTD

One-Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Supplementary Estimate : QUOT201808-000056(00)

SOMPO INSURANCE SINGAPORE PTE. LTD.
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER
RAFFLES PLACE
SINGAPORE LAND TOWER
SINGAPORE 048623

Contact : 6265 0980/6265 0980 Fax No. : 62213302

Date : 03/08/2018
Vehicle No. : XE497P
Make/Model : UD TRUCKS GKB5ELD HNT ESCOT
V
Mileage (km) : 0
Chassis No. : GKB5E00491
Accident Date : 30/07/2018 00:00:00
Claim No. :
Reference : Sompoo OD
Policy No. : D18MTHCVE000531

S/No	Particular	Quantity	Unit Price	Amount S\$
NET ITEMS				
1	Front door hinge RH	2.0	124.00	248.00 PA
2	Front door inner lock - RH	1.0	206.00	206.00 PA
3	Radiator condenser tank	1.0	1,065.00	1,065.00 cat
				1,519.00
				0.00
				1,519.00

4429

1519

180

2500

8628

20%

6902.40

41-61900

10 days

1519

E. & O.E.

Total S\$: 1,519.00
GST 7% S\$: 106.33
Amount Due S\$: 1,625.33

for CITY AUTO PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18014522/R1rd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 24-09-2018



Code : SMO

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	XE 497P
Policy No.	D18MTHCVE000531	Coverage (\$)	0.00
Claim No.	CMTD1803338/NSW	Excess (\$)	1,500.00
Assign From	GRACE TEO	Assign Date	10/08/2018

2. Vehicle Particulars & Condition

Make & Model	UD TRUCKS GKB5E	c.c	10837
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	GKB5E00491	Colour	MULTI
Odometer	187688	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	XCEED	8 mm
L/H Front Tyre	295/80 R22.5	XCEED	8 mm
R/H Rear Tyre	295/80 R22.5 (D)	XCEED	8/8 mm
L/H Rear Tyre	295/80 R22.5 (D)	XCEED	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/07/2018	Inspection Date	10/08/2018
Survey held at	ASM AUTOMOTIVE- NO.2 KWONG MIN ROAD		
Repairer	CITY AUTO PTE LTD		

5a. Remarks

A)THE MARKET VALUE IS S\$90,000.00 (EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 497P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT PANEL (SN)	BENT	1,030.00	1,030.00
1	RH CORNER PANEL (SN)	CRACKED	165.00	165.00
1	FRONT BUMPER RH (SN)	BENT	365.00	365.00
1	SIDE BUMPER RH (SN)	CUT	72.00	72.00
1	BUMPER STEP PROTECTOR RH (SN)	SCRATCHED	50.00	50.00
1	HEADLAMP-RH (SN)	BROKEN	395.00	395.00
1	FOG LAMP-RH (SN)	BROKEN	85.00	85.00
1	BUMPER SIGNAL RH (SN)	CRACKED	36.00	36.00
1	DOOR PANEL-RH (SN)	BUCKLED	1,724.00	1,724.00
1	SIDE SILL-RH (SN)	BENT	99.00	99.00
1	QUARTER PANEL RH (SN)	BUCKLED	408.00	408.00
1	EXHAUST SILENCER COVER (SN)	TO REPAIR SEE LABOUR	329.00	-
1	PLATFORM STEP (SN)	BENT	180.00	180.00
2	FRONT DOOR HINGE RH @\$124.00 (SN)(ADDITIONAL)	BENT	248.00	248.00
1	FRONT DOOR INNER LOCK-RH (SN)(ADDITIONAL)	BENT	206.00	206.00
1	RADIATOR CONDENSER TANK (SN)(ADDITIONAL)	CUT	1,065.00	1,065.00
			6,457.00	6,128.00
	<u>LABOUR</u>			
	DISMANTLE DAMAGED DOOR, TRANSFER USABLE PARTS INTO NEW DOOR, CUT AND REPLACE RHS QUARTER PANEL, JACK AND REALIGN RHS PILLAR AND FLOORBOARD. REMOVE AND REPLACE OTHER DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF EXHAUST SILENCER COVER.		2,500.00	2,000.00
	SPRAY PAINTING.		650.00	500.00
	-		-	-
	-		-	-
	-		-	-
			3,150.00	2,500.00
	GRAND TOTAL		9,607.00	8,628.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,900.00
	LESS EXCESS			-1,500.00

Report Ref No. CS/SMO18014522/R1rd3n2



NETT LIABILITY			5,400.00
----------------	--	--	----------

Report Ref No. CS/SMO18014522/R1rd3n2

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.