

ASS. REC. BY:

REP:

es/FWD18014524/Usd302

Special Instruction:

Surveyor:
mermen

Narus

ASSIGNMENT (Office)

From (Person):

Belliana

of

FWD

Date/Time:

10/8/18 @ 1:29pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No.:

818 2063 L

Insured:

at Workshop n/s:

Ethoz

Tel:

9040 4688

of

30 Bkt Batok Crescent

Policy No.:

PNPV2018-00009090

Claim No.:

1201800010010

Sum Insured:

Excess:

\$500-00

Make of Veh:

(Client's Record)

D.O.A.

7/8/2018

CA / REV /

REV 24 HRS

Insp: tempines

13/08/2018 @ after 10am

R.O.D. Endorsement:

Date/Time:

4:03pm @ 10/8/18

Person Contacted:

Jimmy

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

22 tempines \$190 #

9520631-X

13/08/18

@ 15:45 p.m. revised IA to Belliana via merimer.

13/08/18

@ 15:47 p.m. mandate requested authorize repair to Belliana
via merimer.

14/08/18

@ 09:40 a.m. mandate approved by Josh Koh via merimer.

14/08/18

@ 11:05 a.m. revert authorize repair to Jimmy Guevarra via email.

08/11/13) Wef

ASS. REC. BY:

REF:

FWD

CS/FWD 18014524/USD3

ASSIGNMENT

From: Date: 13/8/18

Estimated Cost:

OR TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 3JS 2063T

at Workshop m/s E-thoz

of 22 jumpires st 92

Insured:

Policy No:

Claims No:

Sum Insured: Excess: \$500.00

(Client's Record)

After 10am

Make of Veh: Jimmy @ 9040 4688

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 17k.

IDAC Accident Rpt: Consistent? : Yes or No

Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 13.1 % 3 Val.: Yes or No

CA (REV) / REP. / 24 HRS

LIA 9338

Vehicle IN / OUT

Date: Person Contacted:

Veh No: 5JS2063L Yr Regn: 8 109

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Volkswagen Jetta c.c 1595

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 136378 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: W V W X X X 1 K 2 9 4 0 2 0 4 7 9

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rip / STD A/Rim or

Tyre Size: F: 225 / 45 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 4 mm

R/Bal. 5 mm

L/Bal. 4 mm

L/Bal. 5 mm

D.O.A. 7/8/18

D.O.I. 13/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/8/18 No second hand parts esky P/P.

confirmed - final by \$5676.00 with Jimmy

2. Brackets had been bent out but support panel cracked have to replace

RECEIVED 15 AUG 2018

Date/Time, File Pass to?

23/08/18

1) Typist

Date/Time, File Return to?

2)

☐ : Prell. Report

☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

200

50

50+50

10

Report Format :

Lump Sum / I.B.I: (\$ 5,676.00 P/P)

(06/11/13) wef

REF:

FWD

ASS. REC. BY:

ASSIGNMENT

From:

Date:

13/8/18

Estimated Cost:

On TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJS 2063T

at Workshop m/s

ETHOZ

of

22 tumpines st-92

Insured:

Policy No.

Claims No.

Sum Insured:

Excess: \$500.00

(Client's Record)


After 10am

Make of Veh:

Jimmy @ 9040 4688

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

17k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res: Yes or No

Lum Sum:

13%

3 Val: Yes or No

CA (REV) / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJS 2063L

Yr Regn:

109

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Volkswagen

C.C.

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

136378

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVWZZZ1K294020479

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

4

mm

R/Bal.

5

mm

L/Bal.

4

mm

L/Bal.

5

mm

D.O.A.

7/8/18

D.O.I.

13/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

n/s second hand parts esky p/p.

Fax 62864315

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Aug 2018 Sendback Est	10 Aug 2018 11:32 S\$6,745.00	10 Aug 2018 13:29 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	CHEE SIEW TUCK, ID: S6807523H, Tel: +6596904186, Email: SIEWTUCK@YAHOO.COM.SG		
Vehicle Reg. No.:	SJS2063L	Date of Loss:	07/08/2018 19:00 ~ :59 [108 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201800010010	Policy/Cover Note No.:	PNPV2018-00009090 (Comprehensive)
		Excess:	S\$500.00
Repairer:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel: 66547750/51		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Belliana - 67275741]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/08/2018]		
Driver/Custodian:	CHEE SIEW TUCK (50 / Male), NRIC: S6807523H, Tel: +6596904186		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS/FWD18014524/Usd3

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 10-08-2018



Code : FWD

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SJS 2063T
Policy No.	PNPV2018-00009090	Coverage (\$)	0.00
Claim No.	1201800010010	Excess (\$)	500.00
Assign From	MERIMEN (BELLIANA)	Assign Date	10/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	07/08/2018	Inspection Date	
Survey held at	ETHOZ- 22 TAMPINES ST 92		
Repairer	ETHOZ GROUP LTD		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

 [> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 7523H

Vehicle Details

Vehicle No.: SJS2063L

Vehicle to be Exported: No

Intended De-registration Date: 13 Aug 2018

Vehicle Make: VOLKSWAGEN

Vehicle Model: JETTA 1.6 A ZA 2WD

Primary Colour: Blue

Manufacturing Year: 2009

Engine No.: LTA1201097

Chassis No.: WVWZZZ1KZ9U020479

Maximum Power Output: 75.0 kW (100 bhp)

Open Market Value: \$17,205.00

Original Registration Date: 03 Aug 2009

First Registration Date: 03 Aug 2009

Transfer Count: 1

Actual ARF Paid: \$17,205.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 02 Aug 2019

PARF Rebate Amount: \$8,602.00

Intended COE Rebate Details

COE Expiry Date: 02 Aug 2019

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$7,589.00

COE Rebate Amount: \$736.00

Total Rebate Amount: \$9,338.00

The information contained herein is correct as at 13 Aug 2018

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement

Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Perfect C200 Sporty Black On Classic Cream Interior.



Down Payment Only \$13,800

With Monthly \$1813, C&C Maintain.

Speedo Motoring StarAd

Lake View Credit Pte Ltd

view our cars

> Low prices guaranteed

> Specialist in Japanese cars

> Easy loan approval

> All terms are negotiable

Browse by Category

Sort by Date Posted

20 results/page

7 vehicles

Volkswagen Jetta

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Volkswagen Jetta		Any	Any	2009	Any	Any	Any	Available
	Volkswagen Jetta	1.4A TSI	\$15,900	\$6,330 /yr	31-Jul-2009	1,390 cc	-	Sedan	Available
New Arrival! Beautiful Paintwork And Interior! Original Condition And Lowest Depreciation! Car Is In Good Working Condition. Wait No More And Call Us To Make An Appointment Now!									
Posted: 06-Aug-2018 Tags: 2009 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
	Volkswagen Jetta	1.4A TSI	\$19,600	\$10,360 /yr	16-Jul-2009	1,390 cc	109,000 km	Sedan	Available
New Tyres. Head Lamps Converted To Sport Model With Smoked Reflector. No Repairs Needed.									
Posted: 07-Jul-2018 Tags: 2009 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
	Volkswagen Jetta Sport	1.4A TSI	\$20,000	\$8,000 /yr	16-Oct-2009	1,390 cc	-	Sedan	Available
One Of The Powerful Volkswagen Unit On The Market. Spacious And Fuel Efficient. Well Maintained Condition For Interior And Exterior, Call Now. Viewing By Appointment Only!									
Posted: 29-Jun-2018 Tags: 2009 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
	Volkswagen Jetta	1.4A TSI	\$19,800	\$8,330 /yr	13-Oct-2009	1,390 cc	148,820 km	Sedan	Available
Extended Warranty Available! 1 Owner Only, Low Mileage! Professional Evaluation Services Provided! Purchase From Us, A Company Accredited With Outstanding Awards, With A Peace Of Mind. Professional Af...									
Dickson Automobile									
Posted: 28-Jun-2018 Tags: 2009 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
Car Buying	Car Selling	Car Ownership	Buying a pre-owned car, but Unsure of its Condition? Get, STA Car Evaluation						
Car Aftermarket	On The Move	Lifestyle							
	Volkswagen Jetta	1.4A TSI	\$17,800	\$9,940 /yr	18-Mar-2009	1,390 cc	104,000 km	Sedan	Available
Excellent And Original Condition, Well Maintained Interior And Exterior, Call Now For Viewing.									
Posted: 27-Jun-2018 Tags: 2009 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
	Volkswagen Jetta	1.6A	\$21,000	\$10,150 /yr	02-Nov-2009	1,595 cc	119,000 km	Sedan	Available
Direct Selling By 1st Owner. Good Condition. Selling Due To Family Expansion. View At Your Convenience.									
Posted: 24-Jun-2018 Tags: 2009 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
	Volkswagen Jetta	1.4A TSI	\$18,500	\$7,160 /yr	09-Sep-2009	1,390 cc	122,830 km	Sedan	Available
Facelifted Model. Your Ideal Continental Sedan, Great Balance Between Comfort, Sportiness And Safety. Low Depreciation Unit. Exterior Condition 9.5/10. Pictures Included. Interior Condition, Perfect. ...									

Compare

http://www.sgcarmart.com/used_cars/listing.php?RGD=2009&MOD=Volkswagen Jetta&RPG=20&VE...

13-Aug-18

Shirley Hiew (LKK Auto)

From: Jimmy Goh <jimmy.gohkl@ethozgroup.com>
Sent: Tuesday, 14 August 2018 11:11 AM
To: Shirley Hiew (LKK Auto)
Cc: sur@lkkauto.com; Jonathan Lim; Ng Boon Kai
Subject: RE: SJS 2063L OD (FWD)

Dear Shirley,

Noted.

Thanks

Best Regards,
Jimmy Goh
Motor Claims Operations



ETHOZ GROUP LTD

22 Tampines Street 92 Singapore 528876

DID:6654 7618 | Fax:6654 7648

Website: www.ethozgroup.com



From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: 14 August 2018 11:09
To: Jimmy Goh <jimmy.gohkl@ethozgroup.com>
Cc: sur@lkkauto.com
Subject: SJS 2063L OD (FWD)

Dear Jimmy,

As instructed by our client, please proceed to repair the insured vehicle **SJS 2063L (Excess \$ 500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 14 August 2018 11:09 AM
To: jimmy.gohkl@ethozgroup.com
Cc: sur@lkkauto.com
Subject: SJS 2063L OD (FWD)

Dear Jimmy,

As instructed by our client, please proceed to repair the insured vehicle **SJS 2063L (Excess \$ 500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5(408933)

View Received Message

This mail is associated with :

SJS2063L (1201800010010)

OD

Aug 7 2018 7:00PM

[CHEE SIEW TUCK]

ETHOZ Protect Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on **21/08/2018 15:21 PM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$5676.00) - SJS2063L - Claim Handler: Belliana

Approved:5676.00:

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Belliana

Date: 21 Aug 2018

Preliminary Advice

Vehicle No	: SJS2063L	Accident Date	: 07/08/2018
Make	: VOLKSWAGEN JETTA	Policy No.	: PNPV2018-00009090
Assignment Date	: 10/08/2018	Excess	: S\$500.00
Date of Inspection	: 13/08/2018	Est. Duration of Repair	: 5 days
Inspection At	: ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent Singapore 658075		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,603.00
Revised Amount	:S\$	5,676.00 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,676.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired; you are advised to invite tender for the wreck.
- (X) Other comments : Kindly approve supplementary amount \$ 858.00

View Received Message

This mail is associated with :

SJS2063L (1201800010010)

OD

Aug 7 2018 7:00PM

[CHEE SIEW TUCK]

ETHOZ Protect Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 14/08/2018 09:40 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3994.00) - SJS2063L - Claim Handler: Belliana

Approved:3994.00:Hi! Please re-seek mandate on check items after being verified

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Belliana

Date: 13 Aug 2018

Preliminary Advice

Vehicle No	: SJS2063L	Accident Date	: 07/08/2018
Make	: VOLKSWAGEN JETTA	Policy No.	: PNPV2018-00009090
Assignment Date	: 10/08/2018	Excess	: S\$500.00
Date of Inspection	: 13/08/2018	Est. Duration of Repair	: 4 days
Inspection At	: ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent Singapore 658075		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,745.00
Revised Amount	:S\$	3,758.00
Check Items (Estimated)	:S\$	236.00
Total	:S\$	3,994.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	17,000.00
COE / PARF Rebate	:S\$	9,338.00
Salvage Value	:S\$	
Margin for Repair	:S\$	7,662.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : NO SECOND HAND PARTS, REPAIRER ASKING PART BY PART. PENDING SOME PARTS PRICES.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/08/2018 08:36
Date Of Accident	07/08/2018 19:00
Exact Location Of Accident	X-JUNCTION (TAMPINES AVE 1 & 4)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS2063L
Insured/Policyholder	
Name Of Registered Owner	CHEE SIEW TUCK
NRIC No	S6807523H
Email Address	SIEWTUCK@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96904186
Alternative Phone No	OFFICE-96904186

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA 1.6 A ZA 2WD

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00009090
Cover Note Number	03/08/2018-02/08/2019

Driver

Name of Driver	CHEE SIEW TUCK
NRIC No	S6807523H
Date Of Birth	25/03/1968
Occupation	INDOOR
Date Of Driving Pass	12/12/1987
Driving Experience	30 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96904186
Fax Number	
Contact Number	OFFICE-96904186
Email Address	SIEWTUCK@YAHOO.COM.SG

Address	93 TAMPINES AVENUE 1
	#13-44
Postcode	528691
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO MOTORCYCLIST
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : TAN WOEI LING
	GENDER: : FEMALE
Passenger 2	NAME: : CHEE XIN JIE
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBD354J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	TAN WANG QUAN

NRIC/Passport Number:

Contact Number

96782605

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

TAN WANG QUAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBD354J

Were seat belts worn?

NO

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

10/8/2018 8:25am

Driver's Signature
(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

— See Traffic Accident Report —


T/20180809/7004

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a **Fourteen (14) days clause** whereby the claim must be made within the stipulated timeframe from the day of occurrence.

	Reporting Only
<input checked="" type="checkbox"/>	Claim OD
<input type="checkbox"/>	Claim TP
<input type="checkbox"/>	Claim OD / TP at other workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature

Date & Time:
10/8/2018 8:25am


Driver's Signature
(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20180809/7004

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 4

Report No. T/20180809/7004

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/08/2018 15:00	Video Report No.:	Station Diary No.:
--	-------------------	--------------------

Informant's Particulars

Name of Informant: CHEE SIEW TUCK			Address: 93 TAMPINES AVENUE 1 #13-44 SINGAPORE 528691		
ID Type / ID No.: NRIC NO / S6807523H			Contact No.: Home/Office: Mobile: 96904186		
Nationality: SINGAPORE CITIZEN			Email: siewtuck@yahoo.com.sg		
Sex: Male	Age: 50	Date of Birth: 23/03/1968	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: CORPORATE SUPPLIER DEVELOPMENT MANAGER			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident 07/08/2018 19:00	Type of Location: X-Junction
Location: TAMPINES AVENUE 1				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 60 Km/h
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Moving Vehicle Against - Others				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBD354J	Motorcycle				Slightly Damaged	0
SJS2063L	Car	VOLKSWAGO N	JETTA 1.6 A ZA 2WD	Blue		0

Details of Vehicle Insurance

Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
SJS2063L	FWD Singapore Pte. Ltd	PNPV2018- 00009090	03/08/2018	02/08/2019



Police Station Of Origin
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	Tan Wang Quan	ID No.	S8715840G
Related Vehicle	FBD354J (Motorcycle)	Contact No.	96782605
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	CHEE SIEW TUCK	ID No.	S6807523H
Related Vehicle	SJS2063L (Car)	Contact No.	96904186
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details:

My car was stopped at the X-Junction of Tampines Ave 1 and Tampines Ave 4. There was a motorcycle was stopped in front of me. I noticed the traffic light has changed and I noticed the motorcyclist starting to move off. I also started to move my car and knocked into the motorcycle in front of me. The motorcyclist wavered for a while before he and his motorcycle fell on his right side. Upon inspection, the motorcyclist checked that he suffered some abrasion on his right lower arm and no other visible injuries. I asked the motorcyclist if he is okay and he was conscious and acknowledged okay. His motorcycle was still in working conditions. The visible damages are slight dent in metal bracket of headlight, right hand top meter's plastic bracket showed some scratched marks. We drove to nearby workshop to inspect the motorcycle's damages and conditions. The mechanic at workshop further tested drive and confirmed the above defects plus slight mis-alignment in right handle bar. No other defects were reported. For my car, the damages are 1) right hand front bumper dented, scratched, detached; 2) driver's door rubbing sound against the dislodged front bumper body; 3) need to check and access if headlights, side lights and other electrical affected; 4) need to check if under chassis parts or areas also damaged. There is mutual agreement with the affected motorcyclist (confirmation via Whatsapp message) to claim his costs of damages through my car insurance. That is all that I have to report.



**SINGAPORE
POLICE FORCE**



T/20180809/7004

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 4

Report No. T/20180809/7004

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20180809/7004

4 of 4

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180809/7004

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Signature Of Interpreter:
Not applicable

Date/Time
09/08/2018 15:00

Officer In Charge Of Case:
TP / TPIB /
ANG YI TING, STEPHANIE
Contact No.: 65476414

Classification Of Case:

Please call 465-6322, 2072 for FWD Emergency Assistance

Authentication Stamp
NP168

CERTIFICATE OF INSURANCE

FWD

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S6807523H



CHEE SIEW TUCK

朱兆德

Race
CHINESE

Date of Birth
23-03-1966 M

Country of Birth
SINGAPORE



7193870

S6807523H

93 TAMPINES AVENUE 1 #13-44
SINGAPORE 528881

NRIC No: S6807523H

Date: 23/05/2014

REPUBLIC OF SINGAPORE

S6807523H



CHEE SIEW TUCK

Birth Date: 25 Mar 1968
Valid Date: 02 Jun 2008

000535021C

YOU ARE ELIGIBLE TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

PASSENGER

Class 3 Motor Cars and Motor Tractors the weight of which does not exceed 3500 kilograms

NP 428A

Licence No. S6807523H

CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2018-00009090 (Comprehensive - Classic Plan)

Car plate number: SJS2063L

Your name (As the policyholder): Chee Siew Tuck

Coverage start date: 03/08/2018

Coverage end date: 02/08/2019

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company: Tai Thong Lee Trading Pte Ltd

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 09/07/2018



Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.



INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2018-00009090	Date of Loss:	07/08/2018
Vehicle Reg. No.:	SJS2063L	Driveable?	
Driver Age/Info:	50 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	CHEE SIEW TUCK	Contact No:	+6596904186
Driver:	CHEE SIEW TUCK		
Make/Model:	VOLKSWAGEN JETTA, 1.6 (A)	Vehicle Reg. Date:	03/08/2009
Vehicle Colour:	BLUE		
Engine No:	LTA1201097	Chassis No:	WWZZZ1KZ9U020479
Odometer:	136262 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	REFER TO ATTACHMENT		
Remarks:	VEHICLE WITH OWNER!		
Present Location:	ETHOZ PROTECT PTE LTD (TAMPINES)		

*Not Authorized
take photo & video
Excess \$500
5 Aug.*

COST OF CLAIMS

	Amount
Parts	4,395.00
Miscellaneous Items	0.00
Labour	2,350.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	6,745.00
- Excess (S\$)	500.00
(S\$)	6,245.00
+ GST 7.00% (S\$)	437.15
Nett Amount (S\$)	6,682.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Calculated Gross Total (S\$)

- Excess (S\$)

(S\$)

+ GST 7.00% (S\$)

Nett Amount (S\$)

This claim is handled by: JIMMY GOH - 9040 4688

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Aug 2018)
Parts: 143 VOLKSWAGEN JETTA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJS2063L)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER <i>dis</i>	0.00	0.00	*850.00 F	/
2	1		*FRONT BUMPER BRACKET RH <i>11</i>	0.00	0.00	*48.00 F	X
3	1		*FRONT BUMPER SIDE RETAINER RH <i>can</i>	0.00	0.00	*45.00 F	/
4	1		*FRONT BUMPER SPONGE <i>11</i>	0.00	0.00	*98.00 F	X
5	1		*FRONT BUMPER REINFORCEMENT <i>11</i>	0.00	0.00	*420.00 F	X
6	1		*FRONT BUMPER CHROME MOULDING RH <i>all</i>	0.00	0.00	*295.00 F	/
7	1		*FRONT BUMPER CHROME MOULDING LH <i>all 11</i>	0.00	0.00	*295.00 F	X
8	10		*FRONT BUMPER RIVET <i>all</i>	0.00	0.00	*60.00 F	/
9	1		*FOG LAMP COVER RH <i>ground</i>	0.00	0.00	*118.00 F	/
10	1		*HEADLAMP RH <i>can</i>	0.00	0.00	*550.00 F	/
11	1		*HEADLAMP BRACKET RH <i>11</i>	0.00	0.00	*48.00 F	X
12	1		*BONNET <i>11</i>	0.00	0.00	-	X
			REPAIR				
13	1		*FRONT SUPPORT PANEL <i>11</i>	0.00	0.00	*800.00 F	/
14	1		*FRONT FENDER RH <i>no/buc</i>	0.00	0.00	*520.00 F	/
15	1		*FRONT FENDER INNER SHIELD RH <i>11</i>	0.00	0.00	*188.00 F	X
16	10		*FRONT FENDER INNER SHIELD CLIPS <i>11</i>	0.00	0.00	*60.00 F	X
17	1		*WING MIRROR ASSY RH <i>11</i>	0.00	0.00	-	X
			REPAIR				
18	1		*FRONT DOOR RH <i>11</i>	0.00	0.00	-	X
			REPAIR				

F=Franchise part

del grille can

Total Parts (S\$)

4,395.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR TO FACILITATE REPAIR	New	660 900.00
2	TO REMOVE & INSTALL AIRCON CONDENSOR INCLUDING CHARGE UP GAS	New	100 140.00
3	TO RESET & RE-PROGRAM HEADLAMP	New	20 < 180.00
4	TO CHECK & RECONNECT ALL NECESSARY WIRINGS	New	30.00
5	TO SPRAY PAINT ON AFFECTED AREAS	New	800 1,100.00
Gross Labour Cost (S\$)			2,350.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD

Company Registration No. 199005791M

30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.arix.com.sg>

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Aug 2018)

Parts: 143 VOLKSWAGEN JETTA 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ETHOZ Protect Pte Ltd/SJS2063L/17/08/2018 18:00

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT GRILLE <i>CR</i>	0.00	0.00	*430.00 F✓
2	1		*FRONT BUMPER LOWER GARNISH <i>De</i>	0.00	0.00	*270.00 F✓
3	1		*FRONT BUMPER WASHER COVER <i>Torn</i> RH	0.00	0.00	*78.00 F✓
4	1		*FRONT BUMPER CHROME BASE <i>1m</i> RH	0.00	0.00	*80.00 F✓

F=Franchise part.

Total Parts (S\$)

858.00

ETHOZ Protect Pte Ltd/SJS2063L/17/08/2018 18:00. Not valid without Reference section.

Generated using **Merimen e-Claims IEAS**



INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2018-00009090	Date of Loss:	07/08/2018
Vehicle Reg. No.:	SJS2063L	Driveable?	
Driver Age/Info:	50 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	CHEE SIEW TUCK	Contact No:	+6596904186
Driver:	CHEE SIEW TUCK		
Make/Model:	VOLKSWAGEN JETTA, 1.6 (A)	Vehicle Reg. Date:	03/08/2009
Vehicle Colour:	BLUE		
Engine No:	LTA1201097	Chassis No:	WWWZZZ1KZ9U020479
Odometer:	136262 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	REFER TO ATTACHMENT		
Remarks:	VEHICLE WITH OWNER!		
Present Location:	ETHOZ PROTECT PTE LTD (TAMPINES)		

*Not Authorized
to take photos & video
\$500
4 day.*

COST OF CLAIMS

	Amount
Parts	4,395.00
Miscellaneous Items	0.00
Labour	2,350.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	6,745.00
- Excess (S\$)	500.00
(S\$)	6,245.00
+ GST 7.00% (S\$)	437.15
Nett Amount (S\$)	6,682.15

This claim is handled by: JIMMY GOH - 9040 4688

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Estimate Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Aug 2018)
 Parts: 143 VOLKSWAGEN JETTA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SJS2063L)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER <i>dis</i>	0.00	0.00	*850.00 F
2	1		*FRONT BUMPER BRACKET RH <i>11</i>	0.00	0.00	*48.00 F
3	1		*FRONT BUMPER SIDE RETAINER RH <i>cm</i>	0.00	0.00	*45.00 F
4	1		*FRONT BUMPER SPONGE <i>11</i>	0.00	0.00	*98.00 F
5	1		*FRONT BUMPER REINFORCEMENT <i>11</i>	0.00	0.00	*420.00 F
6	1		*FRONT BUMPER CHROME MOULDING RH <i>all</i>	0.00	0.00	*295.00 F
7	1		*FRONT BUMPER CHROME MOULDING LH <i>all 11</i>	0.00	0.00	*295.00 F
8	10		*FRONT BUMPER RIVET <i>all</i>	0.00	0.00	*60.00 F
9	1		*FOG LAMP COVER RH <i>Scrub</i>	0.00	0.00	*118.00 F
10	1		*HEADLAMP RH <i>Scrub</i>	0.00	0.00	*550.00 F
11	1		*HEADLAMP BRACKET RH	0.00	0.00	*48.00 F
12	1		*BONNET <i>11</i>	0.00	0.00	-
			REPAIR			-
13	1		*FRONT SUPPORT PANEL <i>11</i>	0.00	0.00	*800.00 F
14	1		*FRONT FENDER RH <i>70/bul</i>	0.00	0.00	*520.00 F
15	1		*FRONT FENDER INNER SHIELD RH	0.00	0.00	*188.00 F
16	10		*FRONT FENDER INNER SHIELD CLIPS <i>11</i>	0.00	0.00	*60.00 F
17	1		*WING MIRROR ASSY RH <i>11</i>	0.00	0.00	-
			REPAIR			-
18	1		*FRONT DOOR RH <i>11</i>	0.00	0.00	-
			REPAIR			-

F=Franchise part.

del grille cm Total Parts (S\$) 4,395.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimate Report

Page 3 of 3

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR TO FACILITATE REPAIR	New	500 900.00
2	TO REMOVE & INSTALL AIRCON CONDENSOR INCLUDING CHARGE UP GAS	New	11 x 140.00
3	TO RESET & RE-PROGRAM HEADLAMP	New	20 < 180.00
4	TO CHECK & RECONNECT ALL NECESSARY WIRINGS	New	30.00
5	TO SPRAY PAINT ON AFFECTED AREAS	New	800 1,100.00
Gross Labour Cost (S\$)			2,350.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD

30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orix.com.sg>

Company Registration No. 199005791M

LIK Auto Consultants hence notify**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

EURO AUTOPART

TRADE

YOUR ONE STOP AUTOPARTS SOLUTION

TAX INVOICE

To COMPANY: ETHOZ PROTECT PTE LTD

INV NO: PF201808-09949

ATTENTION TO SALES PERSON: JIMMY

DATE: 14-Aug-18

P/O 160925

VEHICLE NO: SJS2063L VW JETTA

30 DAYS

SEND TO: 30 BUKIT BATOK CRES

S/NO.	PART NO.	PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1		FRT BUMPER	1	\$ 850.00	\$ 850.00
2		FRT BUMPER RETAINER RH	1	\$ 45.00	\$ 45.00
3		FRT BUMPER CHROME MLD RH	1	\$ 295.00	\$ 295.00
4		FRT BUMPER RIVET	10	\$ 6.00	\$ 60.00
5		FOGLAMP COVER RH	1	\$ 118.00	\$ 118.00
6		HEADLAMP RH	1	\$ 550.00	\$ 550.00
7		FRT FENDER RH	1	\$ 520.00	\$ 520.00
8		FRT GRILLE NO4	1	\$ 430.00	\$ 430.00
9		FRT BUMPER LOWER GARNISH	1	\$ 270.00	\$ 270.00
10		SUPPORT PANEL	1	\$ 800.00	\$ 800.00
11					\$ -
12					\$ -
13					\$ -
14		Dept Head			\$ -
15		Agreement No			\$ -
16		Job Card No			\$ -
17					\$ -
18		Finance			\$ -
19		Control No			\$ -
20		Invoice No			\$ -
21					\$ -
22		Remarks			\$ -
23					\$ -
24		Est. finalized Amt			\$ -
25					\$ -
SUB-TOTAL					\$ 3,938.00
GST @ 7%					\$ 275.66
GRAND TOTAL					\$ 4,213.66

NOTE: GOODS SOLD ARE NON RETURNABLE

RECEIVED BY:

AUTHORISED BY:



Jimmy Goh

NO. 50 PLAYFAIR ROAD #03-02F

NOEL BUILDING S(367995)

BRN:53225532A / GST REG NO: M90370620L

TEL: 6635 8238 FAX: 6280 5805 HP: 9451 5113 / 9457 4513



EURO AUTOPART TRADE

YOUR ONE STOP AUTOPARTS SOLUTION

TAX INVOICE

To COMPANY: ETHOZ PROTECT PTE LTD

INV NO: PF201808-09963

ATTENTION TO SALES PERSON: JIMMY

DATE: 15-Aug-18

P/O 160925

VEHICLE NO: SJS2063L VW JETTA

30 DAYS

SEND TO: 30 BUKIT BATOK CRES

S/NO.	PART NO.	PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1		FRT BUMPER WASHER COVER RH	1	\$ 78.00	\$ 78.00
2		FRT BUMPER CHROME BASE RH	1	\$ 80.00	\$ 80.00
3					\$ -
4					\$ -
5					\$ -
6					\$ -
7					\$ -
8					\$ -
9					\$ -
10					\$ -
11					\$ -
12					\$ -
13					\$ -
14		Dept Head			\$ -
15		Agreement No			\$ -
16		Job Card No			\$ -
17					\$ -
18		Finance			\$ -
19		Control No			\$ -
20		Invoice No			\$ -
21					\$ -
22		Remarks			\$ -
23		Est. finalized Amt			\$ -
24					\$ -
25					\$ -
SUB-TOTAL					\$ 158.00
GST @ 7%					\$ 11.06
GRAND TOTAL					\$ 169.06

NOTE: GOODS SOLD ARE NON RETURNABLE

RECEIVED BY:

AUTHORISED BY:



Jimmy Goh

NO. 50 PLAYFAIR ROAD #03-02F

NOEL BUILDING S(367995)

BRN:53225532A / GST REG NO: M90370620L

TEL: 6635 8238 FAX: 6280 5805 HP: 9451 5113 / 9457 4513

P-4096

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Aug 2018 Sendback Est	10 Aug 2018 11:32 \$56,745.00	10 Aug 2018 13:29 Edit Adj Rpt	\$55,676.00 Edit Estimates	\$55,676.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	17 Aug 2018 17:59	17 Aug 2018 18:00 \$5858.00	17 Aug 2018 18:00			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	CHEE SIEW TUCK , ID: S6807523H, Tel: +6596904186, Email: SIEWTUCK@YAHOO.COM.SG		
Vehicle Reg. No.:	SJS2063L	Date of Loss:	07/08/2018 19:00 - :59 [108 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201800010010	Policy/Cover Note No.:	PNPV2018-00009090 (Comprehensive)
		Excess:	\$5500.00
Repairer:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel: 66547750/51		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Belliana - 67275741]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 21/08/2018]		
Driver/Custodian:	CHEE SIEW TUCK (50 / Male), NRIC: S6807523H, Tel: +6596904186		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- FWD_SG (21/08/2018): Alert - Adj Mandate Approved (\$55676.00) - SJS2063L - Claim Handler: Belliana
- FWD_SG (14/08/2018): Alert - Adj Mandate Approved (\$3994.00) - SJS2063L - Claim Handler: Belliana
- FWD_SG (13/08/2018): Alert - Adj Mandate Maintained - SJS2063L - Claim Handler: Belliana

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJS2063L (1201800010010)
















































OD

Aug 7 2018 7:00PM



[CHEE SIEW TUCK]

ETHOZ Protect Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	10/08/18 11:32	Repairer Estimates	Load HTML	
2	17/08/18 18:00	Repairer Estimates Suppl. #1	Load HTML	
LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	13/08/18 15:45	Adjuster Immediate Advice	Load HTML	
2	21/08/18 11:22	Adjuster Immediate Advice	Load HTML	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
2	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
3	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
4	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
5	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
6	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
7	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
8	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
9	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
10	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
11	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
12	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
13	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
14	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
15	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
16	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
17	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
18	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
19	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
20	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
21	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
22	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
23	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
24	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
25	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
26	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
27	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
28	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
29	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
30	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
31	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>
32	21/08/18 11:14	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
33	21/08/18 11:14	General View		<input checked="" type="checkbox"/>
34	21/08/18 11:14	General View		<input checked="" type="checkbox"/>
35	21/08/18 11:14	General View		<input checked="" type="checkbox"/>
36	21/08/18 11:14	General View		<input checked="" type="checkbox"/>
37	21/08/18 11:14	General View		<input checked="" type="checkbox"/>
38	21/08/18 11:14	General View		<input checked="" type="checkbox"/>
39	21/08/18 11:14	General View		<input checked="" type="checkbox"/>
40	21/08/18 11:14	General View		<input checked="" type="checkbox"/>
41	21/08/18 11:14	General View		<input checked="" type="checkbox"/>
42	21/08/18 11:14	General View		<input checked="" type="checkbox"/>
43	21/08/18 11:14	General View		<input checked="" type="checkbox"/>
44	21/08/18 11:14	General View		<input checked="" type="checkbox"/>
45	21/08/18 11:14	General View		<input checked="" type="checkbox"/>
46	21/08/18 11:14	General View		<input checked="" type="checkbox"/>
47	21/08/18 11:14	General View		<input checked="" type="checkbox"/>
48	21/08/18 11:14	General View		<input checked="" type="checkbox"/>
49	21/08/18 11:14	General View		<input checked="" type="checkbox"/>
50	21/08/18 11:14	General View		<input checked="" type="checkbox"/>
51	21/08/18 11:14	General View		<input checked="" type="checkbox"/>
52	21/08/18 11:14	Odometer Reading		<input checked="" type="checkbox"/>
53	21/08/18 11:14	Chassis Number		<input checked="" type="checkbox"/>
54	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
55	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
56	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
57	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
58	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
59	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
60	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
61	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
62	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
63	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
64	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
65	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
66	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
67	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
68	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
69	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
70	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
71	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
72	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
73	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
74	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
75	21/08/18 11:16	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	20/08/18 09:38	Supplier's Bill		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/08/18 17:17	ESTIMATE		<input checked="" type="checkbox"/>
2	21/08/18 11:17	ESTIMATE MARKED & SUPPLEMENTARY		<input checked="" type="checkbox"/>
3	24/08/18 14:43	Parts Invoice		<input checked="" type="checkbox"/>

Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	10/08/18 09:08	Accident Statement	 Load HTML	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	10/08/18 08:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	10/08/18 08:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	10/08/18 08:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	10/08/18 08:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	10/08/18 08:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	10/08/18 08:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	10/08/18 08:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	10/08/18 08:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	10/08/18 08:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	10/08/18 08:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	10/08/18 08:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	10/08/18 08:52	Driving License	 Load JPG	<input checked="" type="checkbox"/>
13	10/08/18 08:52	Driving License	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	10/08/18 08:49	Sketch Plan	 Load TIF	
2	10/08/18 08:53	IC	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD18014524/USD3E2

Date: 24/08/2018

REFERENCE

Insured/Claimant: CHEE SIEW TUCK Policy No: PNPV2018-00009090
Date of Loss: 07/08/2018 Nature of Claim: OD Claim No: 1201800010010

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJS2063L**
Make & Model: VOLKSWAGEN JETTA, 1.6 (A) Engine No: LTA1201097
Reg. Date: 03/08/2009 (Man. Year: 2009) Chassis No: VWWZZZ1KZ9U020479
Colour: Blue Odometer: 136378 km
Engine Capacity: 1595 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Continental 4 mm Rear Left Side: Continental 5 mm
Front Right Side: Continental 4 mm Rear Right Side: Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,253.00	4,096.00	1,157.00	22.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	1,580.00	770.00	32.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,603.00	5,676.00	1,927.00	25.35
- Excess (\$\$)	500.00	500.00	0.00	0.00
(\$\$)	7,103.00	5,176.00	1,927.00	27.13
+ GST 7.00/7.00% (\$\$)	497.21	362.32	134.89	27.13
Nett Amount (\$\$)	7,600.21	5,538.32	2,061.89	27.13

INSPECTION

Date of Assignment: 10/08/2018 Present Location: ETHOZ Protect Pte Ltd (Bukit Batok)
Date Inspected: 13/08/2018 Inspected At: 22 TAMPINES ST 92
Repairer : ETHOZ Protect Pte Ltd (Bukit Batok)
Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Aug 2018)
Parts:	143	VOLKSWAGEN JETTA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS2063L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	850.00 F	*850.00 F
2	1		*FRONT BUMPER BRACKET RH	Not Necessary	48.00 F	*- F
3	1		*FRONT BUMPER SIDE RETAINER RH	Cracked	45.00 F	*45.00 F
4	1		*FRONT BUMPER SPONGE	Not Necessary	98.00 F	*- F
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	420.00 F	*- F
6	1		*FRONT BUMPER CHROME MOULDING RH	Necessary	295.00 F	*295.00 F
7	1		*FRONT BUMPER CHROME MOULDING LH	Not Necessary	295.00 F	*- F
8	10		*FRONT BUMPER RIVET	Necessary	60.00 F	*60.00 F
9	1		*FOG LAMP COVER RH	Grazed	118.00 F	*118.00 F
10	1		*HEADLAMP RH	Scratched	550.00 F	*550.00 F
11	1		*HEADLAMP BRACKET RH	Not Necessary	48.00 F	*- F
12	1		*BONNET (NPA)	Repair	-	*- F
13	1		*FRONT SUPPORT PANEL	Cracked	800.00 F	*800.00 F
14	1		*FRONT FENDER RH	Dented / Buckled	520.00 F	*520.00 F
15	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	188.00 F	*- F
16	10		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	60.00 F	*- F
17	1		*WING MIRROR ASSY RH (NPA)	Not Necessary	-	*- F
18	1		*FRONT DOOR RH (NPA)	Repair	-	*- F
Supplementary #1						
19	1		*FRONT GRILLE	Cracked	430.00 F	*430.00 F
20	1		*FRONT BUMPER LOWER GARNISH	Deformed	270.00 F	*270.00 F
21	1		*FRONT BUMPER WASHER COVER RH	Torn	78.00 F	*78.00 F
22	1		*FRONT BUMPER CHROME BASE RH	Twisted	80.00 F	*80.00 F

F=Franchise part.

Total Parts (S\$)	5,253.00	4,096.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO FACILITATE REPAIR	New	900.00	660.00
2	TO REMOVE & INSTALL AIRCON CONDENSOR INCLUDING CHARGE UP GAS	New	140.00	100.00
3	TO RESET & RE-PROGRAM HEADLAMP	New	180.00	20.00
4	TO CHECK & RECONNECT ALL NECESSARY WIRINGS	New	30.00	0.00
5	TO SPRAY PAINT ON AFFECTED AREAS	New	1,100.00	800.00
Gross Labour Cost (S\$)			2,350.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >