

ASS. REC. BY:

REF: 033/AIG18014548/G24036

Special Instruction:

Surveyor: GA
meimen

ASSIGNMENT (Office)

From (Person): Chin Lee Ying

of AIG

Date/Time: 8/8/18 @ 2.17pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLG 2135C

Insured: SLJ 9958H

at Workshop m/s 3 Motorwerkz

Tel: 9797 2800

of 25 Kelki Bkt Rd 4 Synergy # 01-42

Policy No: 0999994790

Claim No: 27650776886

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 08/08/2018

CA / REV / REP. / REV 24 HRS up

H.O.D. Endorsement:

Date/Time: 3:10pm @ 8/8/18

Person Contacted:

Jay

Vehicle IN OUT

Date/Time	Action/Instruction (X)	Estimate
10/8/18-	9.16am (call back)	
	SLG 2135C - CCG/AIG18007059/Kua 3s2	D.O.A: 10/1/18
	SLJ 9958H ->	
	After repair: 13/8/2018	
		DAR? Repair days?

113
Kne.

REF: ALG

C 2322G

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s 3 Motorwerks
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rport.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

<input checked="" type="radio"/>	<input type="radio"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Veh No: SLG2135C Yr Regn: 23 sep 2016
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Prius c.c. 1797
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 178829 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: ZVW 50600 8397
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195 / 65 R15
 R: 11
 BSI / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 10-08-18
 Survey held at w/s 4:40pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Int
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair days 4
	TQM
	18/10/18

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: 4
 Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Report Format : DAR
 Lump Sum / I.B.I: (\$)

Survey Fee: 180
 Transportation: _____
 S + RS, SI _____
 Photos _____
 Others: 20
 TOTAL: 200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18014548/Gz4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 10-08-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLJ 9958H	Veh. Inspected	SLG 2135C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	10/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	08/08/2018	Inspection Date	10/08/2018
Survey held at	3 MOTORWERKZ 25 KAKI BUKIT ROAD 4 SYNERGY @ KB #01-42 SINGAPORE 417800		

5a. Remarks

<p>A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.</p>
--

Your password will expire in 5 days. [Click here to change it.](#)

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying

To: assignments@lkkauto.com, Admin A

Cc: Fong, Andy-SY

Sent: 8/8/2018 2:17:21 PM

Attachments:  08082018132820.pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



RIAZ

L.L.C

ADVOCATES AND SOLICITORS
COMMISSIONER FOR OATHS

ACRA NUMBER : 200911678H

GST REGISTRATION NUMBER : 200911678H

08/08/2018

Our Ref: SLG 2135C (V) 3 MOTOR

Your Ref: SLJ 9958H

RIAZ QAYYUM (LLB HONS) NUS
(DIRECTOR)

ABDUL HALIM BIN ROSALAN (LLB HONS) UTAS
(ASSOCIATE)

MUHD RIDHWAN ABDUL RAHIM (LLB HONS) LEEDS
(ASSOCIATE)

TO: **AIG Asia Pacific Insurance Pte. Ltd.**
78 Shenton Way
Tower 2 #07-16
Singapore 079120
Attn: Motor Claims Department

BY FAX (6415-3727) ONLY

NOTICE OF ACCIDENT

Dear Sir

We are instructed by our client to *notify* you of a road traffic accident on 08 August 2018 at about 0930 hours along Junc of Marina Boulevard involving our client's vehicle registration number SLG 2135C and vehicle registration number SLJ 9958H driven by you or your authorized driver at the material time. A copy of Singapore accident statement / traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of workshop	:	3 MOTORWERKZ CONCEPT PTE LTD
Address	:	25 Kaki Bukit Road 4 Synergy @ KB #01-42 Singapore 417800
Telephone no.	:	9797 2800 (Jay)
Fax No.	:	6702 1909

Please let us hear from you by the stipulated time.

Yours faithfully

encs

cc Client

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor
(Name & signature)

Date & time of inspection



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2322G
Vehicle Details	
Vehicle No.:	SLG2135C
Vehicle to be Exported:	No
Intended De-registration Date:	13 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8S A
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	2ZR6668572
Chassis No.:	ZVW506008397
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$24,926.00
Original Registration Date:	23 Sep 2016
First Registration Date:	23 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Sep 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	22 Sep 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,501.00
COE Rebate Amount:	\$45,002.00
Total Rebate Amount:	\$48,752.00

The information contained herein is correct as at 13 Aug 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/08/2018 11:46
Date Of Accident	08/08/2018 09:30
Exact Location Of Accident	JUNCTION OF MARINA BOULEVARD & BAYFRONT AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG2135C
Insured/Policyholder	
Name Of Registered Owner	STAR DEALS LEASING PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91822218

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MH001278-R01
Cover Note Number	

Driver

Name of Driver	ER KEE POH
NRIC No	S7142447B
Date Of Birth	03/12/1971
Occupation	OUTDOOR
Date Of Driving Pass	25/06/1990
Driving Experience	28 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91822218
Fax Number	
Contact Number	
EEmail Address	ERKEE28@YAHOO.COM.SG

Address	BLK 751 YISHUN ST 72 #05-178
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ9958H
Vehicle Make/Model/Colour	NA
Details Of Properties	NA
Vehicle Category	PRIVATE HIRE
Name of Driver	WATT
NRIC/Passport Number	
Contact Number	91017638
Address	NA
	NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	NA
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. The Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this report by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will also be made available upon application by interested parties.
7. By the lodging of this report to the insurer(s) you hereby consent to the archiving of this report at the centre and to copies of the report being made available as stated above.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my work employer and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or processed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, medical reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages) and/or;
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purpose(s)").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purpose(s); and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purpose(s);
- (d) my Personal Information will also be collected and used to resolve claims/issues, for the purpose of fraud detection, investigation and management in present and/or future claims;
- (e) the information as collected under (a) above may be shared/disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel Signature
Name:
NIC/FIN No.:

Not to be filled in.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At 9:30 am, 8/8/2018, I was travelling along Manna Boulevard (Veh A: SLG 2135C), turning left to Bayford Ave on 2nd left lane. As I was turning left, Veh B - SLJ 9958H on the extreme left lane that can only turn left, move straight and hit my vehicle (Veh. A) on the left front bumper door parties.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[Signature] 8/8/2018

11:50 am



Condition (CON)

- (0) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
- (07) Deformed (08) Shaded (09) Punctured (10) Broken (11) Necessary (12) Missing
- (13) Torn (14) Unconfirmed (15) Not Working

MOTOR CAR (LH)

ACTION (AC)

- (1) Replace (✓) (2) Repair (R) (3) Check (C)
- (4) Not Consistent (NC)

Aug 2005

Left Portion

NAC	INC	Item	CON	AC	Qty
1255	995326	Frnt LH Door			
1256	995140	Frnt LH Door Protector			
1257	995104	Frnt LH Door Hinge			
1258	995142	Frnt LH Door Wing Mirror			
1259	995102	Frnt LH Door Garnish			
1260	991593	Frnt LH Door Glass Outer Moulding			
1261	991588	Frnt LH Door Glass Inner Moulding			
1262	995103	Frnt LH Door Glass			
1263	991595	Frnt LH Door Glass Regulator			
1264	991596	Frnt LH Door Glass Regulator Motor			
1265	991662	Frnt LH Door Rubber			
1266	991636	Frnt LH Door Outer Handle			
1267	991607	Frnt LH Door Inner Handle			
1268	991625	Frnt LH Door Lock w/Key			
1269	991624	Frnt LH Door Lock			
1270	991562	Frnt LH Door Central Lock			
1271	991675	Frnt LH Door Switch			
1272	991617	Frnt LH Door Inner Trim Board			
1273	991568	Frnt LH Door Checker			
1274	991575	Frnt LH Door Felt			
1275	991688	Frnt LH Door Wire Harness			
1276	991683	Frnt LH Door Window Glass Pillar			
1277	991640	Frnt LH Door Outer Pillar			
1278	991613	Frnt LH Door Inner Pillar			
1279	991646	Frnt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frnt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frnt Bumper		CUT ✓	
1006	991325	Frnt Bumper Bracket			
1007	991462	Frnt Bumper Side Retainer		BIS ✓	
1008	991433	Frnt Bumper Reinforcement			
1010	991468	Frnt Bumper Sponge			
1011	991427	Frnt Bumper Protector			
1014	991301	Frnt Bumper Moulding - LH Fog Lamp			
1015	991407	Frnt Bumper Lower Spoiler			
1029	995153	Frnt LH Headlamp Assy		CRA ✓	
1031	995088	Frnt LH Side Lamp			
1096	995070	Frnt LH Fender		DD ✓	
1098	995147	Frnt LH Fender Lamp Inner Shield		CRA ✓	
1099	995148	Frnt LH Fender Protector			
		Hybrid Logo		NECV ✓	

Vehicle No: **SLG 2135C**

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door			
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1163	993851	Rear LH Taillamp			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1136	990247	Sticker			

[Handwritten Signature]
18/10/18

No of Items: 4 Assessor: _____

Repair days 4

TGUM *[Signature]*

18/10/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Aug 2018 Edit Reg		08 Aug 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Main Claimant:	-		
Vehicle Reg. No.:	SLG2135C	Date of Loss:	08/08/2018 00:00 - :59 [22 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2776507768SG	Policy/Cover Note No.:	0999994790
Vehicle Reg. No. (Insured):	SLJ9958H	Policy No. (Claimant):	
		Excess:	
Repairer:	3 Motorwerkz Concepts Pte Ltd (HQ) 25 Kaki Bukit Road 4, Synergy @ KB #01-40, 417800 Kaki Bukit - Tel: 97972800		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Boyogan, Joane] Joane.Boyogan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/08/2018]		
Claimant's Solicitor:	RIAZ LLC - Tel: 65340110		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
<ul style="list-style-type: none"> AIG_SG (13/08/2018): Request To Upload TP GIA Report 			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

***SLG2135C (2776507768SG)
[SLJ9958H]**

TP

-

Aug 8 2018 12:00AM

[LCRF PTE LTD]

3 Motorwerkz Concepts Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser <input type="button" value="v"/>
Photos/Images						3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	14/08/18 12:20	General View	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
2	14/08/18 12:20	General View	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
3	14/08/18 12:20	General View	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
4	14/08/18 12:20	General View	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
5	14/08/18 12:20	General View	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
6	14/08/18 12:20	General View	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
7	14/08/18 12:20	General View	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
8	14/08/18 12:20	General View	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
9	14/08/18 12:20	General View	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
10	14/08/18 12:20	General View	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
11	14/08/18 12:20	General View	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
12	14/08/18 12:20	General View	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
13	14/08/18 12:20	General View	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
14	14/08/18 12:20	General View	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
15	14/08/18 12:20	General View	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
16	14/08/18 12:20	General View	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
17	14/08/18 12:20	General View	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
18	15/08/18 12:26	Photo After Spray	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
19	15/08/18 12:26	Photo After Spray	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
20	15/08/18 12:26	Photo After Spray	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
21	15/08/18 12:26	Photo After Spray	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
22	15/08/18 12:26	Photo After Spray	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
23	15/08/18 12:26	Photo After Spray	<input type="button" value="i"/>	Load JPG	<input checked="" type="checkbox"/>	
Documentation						1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print	
1	13/08/18 09:50	OI GIA REPORT	<input type="button" value="i"/>	Load PDF	<input type="checkbox"/>	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>	

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18014548/GZ4D3E2

Date: 30/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994790
Claimant Vehicle No : SLG2135C	Insured Vehicle No :	SLJ9958H
Date of Loss: 08/08/2018	Nature of Claim:	TP
		Claim No: 2776507768SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG2135C	Engine No:	2ZR6668572
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 S (A)	Chassis No:	ZVW506008397
Reg. Date:	23/09/2016 (Man. Year: 2016)	Odometer:	178829 km
Colour:	Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	08/08/2018		
Date Inspected:	10/08/2018	Inspected At:	3 Motorwerkz Concepts Pte Ltd (HQ) 25 KAKI BUKIT ROAD 4 SYNERGY @ KB #01-42 SINGAPORE 417800
Estimated Period of Repair:	4.0 days		

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cut	0.00 F	*- F
2	1		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
3	1		*FRT BUMPER REINFORCEMENT	* Check	0.00 F	*- F
4	1		*FRT BUMPER SPONGE	* Check	0.00 F	*- F
5	1		*FRT BUMPER LH FOG LAMP	* Check	0.00 F	*- F
6	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
7	1		*FRT LH FENDER	Dented	0.00 F	*- F
8	1		*FRT LH FENDER INNER SHIELD	Cracked	0.00 F	*- F
9	1		*HYBRID LOGO	Necessary	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >