

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/08/2018 16:38
Date Of Accident	10/08/2018 19:45
Exact Location Of Accident	JUNC OF MARYMOUNT RD AND SIN MING AVENUE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA9820G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MICRO CREDIT ( CAR LEASING ) PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90932248
Alternative Phone No	OFFICE-90932248

### Vehicle Particulars

Manufacturer	TOYOTA
Model	-
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	999994694
Cover Note Number	

### Driver

Name of Driver	LAI SHIN WEI DESMOND
NRIC No	S7118952Z
Date Of Birth	10/06/1971
Occupation	OUTDOOR
Date Of Driving Pass	18/08/2004
Driving Experience	13 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90932248
Fax Number	
Contact Number	OTHERS-90932248
Email Address	NOEMAIL

Address	102 HAIG ROAD #09-05
Postcode	438798
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : NIL GENDER: : MALE
Passenger 2	NAME: : NIL GENDER: : MALE
Passenger 3	NAME: : NIL GENDER: : MALE
Passenger 4	NAME: : NIL GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	THOMSON NPP 25 SIN MING ROAD
Police Station Address	<b>ROAD:</b> 25 SIN MING ROAD #01-180 , <b>POSTCODE:</b> 570025 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO: - FAX NO:</b>
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO THE POLICE REPORT : T/20180810/2147

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGV8998U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	LAI SHIN WEI DESMOND
Approximate Age	
Injuries Sustain	SLIGHT
Injured person in which vehicle?	SMA9820G
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Handwritten text across the accident description area: "Pls Refer to the Police Report 1/20180810/2147".

## DECLARATION

I/We declare the above particulars are true in every respect.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Handwritten signature and date: 11/8/2018



### Sketch Plan #3



**SINGAPORE  
POLICE FORCE**



T/20180810/2147

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

2 of 4

Report No: T/20180810/2147

#### CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	TAN KHOON HUI	ID No.	S1536238C
Related Vehicle	SGV8998U (Car)	Contact No.	98565582
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	LAI SHIN WEI DESMOND	ID No.	S7118952Z
Related Vehicle	SMA9820G (Car)	Contact No.	90932248
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	10/08/2018	Date Discharge	10/08/2018
No. of Days granted Medical Leave	05	Degree of Injury	NIL

#### Brief Details.

On 10th August 2018 at 7.45am, I was driving my vehicle registration number: SMA9820G along Marymount Road. I have 4 other passengers in my vehicle. (Grab IOS 3866340-4-032)

Upon reaching the junction of Marymount Road/Sin Ming Avenue, I was at the stationary position while waiting for arrow turning right. Then, there was a strong impact from my rear portion. I alighted and discovered that there was another vehicle registration number: SGV8998U (V2) had collided to my rear portion.

The driver told me to claim from my insurance company. I exchanged particulars with the other driver. I do have CCTV installed in my vehicle.

Due to the impact, I went to seek medical attention and was given 5 days MC. I am lodging this report for insurance claimed.

My passengers also claimed that they were in pain too

Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo





Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo





Accident Photo





Accident Photo



Accident Photo



Accident Photo





Accident Photo





Accident Photo




Accident Photo







Accident Photo



# Police Report



**SINGAPORE  
POLICE FORCE**



T/20180810/2147

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

1 of 4

Report No. T/20180810/2147

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/08/2018 21:39	Vide Report No.:	Station Diary No.: 33
--	------------------	--------------------------

### Informant's Particulars

Name of Informant: LAI SHIN WEI DESMOND			Address: 102 HAIG ROAD #09-05 SINGAPORE 438798	
ID Type / ID No.: NRIC NO / S7118952Z			Contact No.:	
Nationality: SINGAPORE CITIZEN			Home/Office:	Mobile: 90932248
			Email:	
Sex: Male	Age: 47	Date of Birth: 10/06/1971	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 3	Date of Expiry:

### General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 10/08/2018 07:45	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 MARYMOUNT ROAD SIN MING AVENUE At the junction				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow: Two Way	Traffic Control: Traffic Light - Working	Traffic Volume: No Traffic		
Type of Collision: Between Moving Vehicles - Head To Rear		Anyone conveyed by ambulance: No		

### Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGV8998U	Car	VOLVO	XC90 2.5T A/T ABS D/AB 4WD 5DR TC	Grey		0
SMA9820G	Car	TOYOTA	COROLLA ALTIS STANDARD AUTO	Black		4

# Police Report



**SINGAPORE  
POLICE FORCE**



T/20180810/2147

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

2 of 4

Report No. T/20180810/2147

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	TAN KHOON HUI	ID No.	S1536238C
Related Vehicle	SGV8998U (Car)	Contact No.	98565582
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	LAI SHIN WEI DESMOND	ID No.	S7118952Z
Related Vehicle	SMA9820G (Car)	Contact No.	90932248
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	10/08/2018	Date Discharge	10/08/2018
No. of Days granted Medical Leave	05	Degree of Injury	NIL

### Brief Details.

On 10th August 2018 at 7.45am, I was driving my vehicle registration number: SMA9820G along Marymount Road. I have 4 other passengers in my vehicle. (Grab IOS 3866340-4-032)

Upon reaching the junction of Marymount Road/Sin Ming Avenue, I was at the stationary position while waiting for arrow turning right. Then, there was a strong impact from my rear portion. I alighted and discovered that there was another vehicle registration number: SGV8998U (V2) had collided to my rear portion.

The driver told me to claim from my insurance company. I exchanged particulars with the other driver. I do have CCTV installed in my vehicle.

Due to the impact, I went to seek medical attention and was given 5 days MC. I am lodging this report for insurance claimed.

My passengers also claimed that they were in pain too



## Police Report



**SINGAPORE  
POLICE FORCE**



T/20180810/2147

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

3 of 4

Report No. T/20180810/2147

CONTINUATION OF REPORT

# Police Report



**SINGAPORE  
POLICE FORCE**



T/20180810/2147

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

4 of 4

Report No. T/20180810/2147

CONTINUATION OF REPORT

## Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
E /  
Sr Staff Sgt MOHAMAD FARID BIN JAMAL

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
10/08/2018 21:39

Officer In Charge Of Case:  
TP / AEIT /  
Sr Staff Sgt MOHAMAD ZULFAZDLI BIN  
ABDULLAH  
Contact No.: 65476367

Classification Of Case:

Authentication Stamp  
NP168

SINGAPORE  
POLICE

311 670