

ASS. REC. BY:

REF: CS/AGL18014623/Kvbnz

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Albert Hung of AGL Date/Time: 13082018 3pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJP 1398T Insured: SJZ 1522Z

at Workshop m/s Complete vms Tel: 6455 0012.

of Blk 176 Sin Ming Drive #03-14

Policy No: Claim No: C10001866

Sum Insured: Excess:

Make of Veh: D.O.A. 10082018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time: 13082018 3:05pm Person Contacted: Li Hui Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJP 1398T - X
	SJZ 1522Z - X
2:19	11 Sin @ 4000 Cabins (Red) 4059.40, 5019

ASS. REC. BY:

REF: AGZ/

### ASSIGNMENT

*Kenneth*

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s *Complex*

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)


Make of Veh: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: *8136*

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: *06* days Res.: Yes or No

Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: *STP 1398* Yr Regn: *03, 09*

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or \_\_\_\_\_

Make: *Honda Fit* c.g. *1.339*

Colour: *White* A/C:  Insured / Std / NI / NA

Sp. Reading: *93960* T/Radio:  Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: *626 1125729*

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  Inorder / Jammed / Leaked / Burnt or

Brake:  Inorder / Jammed / Leaked / Burnt or

Modl:  Nil / S/Rim / STD A/Rim or

Tyre Size: F: *195/60R15*

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *Continental*

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. *3* mm R/Bal. *7* mm

L/Bal. *3* mm L/Bal. *7* mm

D.O.A. *10/8/18* D.O.I. *13/8/18*

Survey held at \_\_\_\_\_

Des. of Damages:  Frt /  Rear /  O/S /  N/S /  UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<i>14/8</i>	<i>File pass to Catherine</i>

RECEIVED 24 SEP 2018

Date/Time, File Pass to?  : Prell. Report  : Final Report

1) \_\_\_\_\_  
2) *24/9 - typist*

Report Format: *TP*  
Lump Sum / I.B.I: (\$) *4000*

Days Of Repair: *6*  
Resurvey No. of Trlp: *1*

Add Fee:  : Site Insp (\$)  : Interview (\$)  : Tech Invs (\$)  : Weekend (\$)

Survey Fee:	
Transportation:	
S + P.S. \$	
Fees	
Others	
TOTAL	<b>250</b>

**Catherine Chong (LKK Auto)**

---

**From:** Albert Hong <albert.hong@budgetdirect.com.sg>  
**Sent:** Monday, 13 August, 2018 3:00 PM  
**To:** 'assignments'  
**Cc:** 'SUR'  
**Subject:** Appoint LKK to conduct TP survey; Our Ref: C10001866  
**Attachments:** FAX\_20180813\_1534125204\_25.pdf

Hi Team,

Please accept survey assignment and liaise with third party workshop.

Kenneth Kong was requested.

Thank you.

Regards,

**Albert Hong**  
**Senior Executive, Claims**

T +65 6540 2182  
F +65 6725 0853  
E [albert.hong@budgetdirect.com.sg](mailto:albert.hong@budgetdirect.com.sg)

**Budget  
Direct**  
insurance

**Customer Care:** +65 6221 2111  
**Claims:** +65 6221 2199  
**Claims (Int.):** +65 6540 2199

190 Clemenceau Avenue  
#03-01, Singapore Shopping Centre  
Singapore 239924  
[budgetdirect.com.sg](http://budgetdirect.com.sg)

Auto & General Insurance (Singapore) Pte. Limited (co. Reg. No. 201626103G) trading as Budget Direct Insurance.

**From:** Gan Li Hui <lihui@completevms.com.sg>  
**Sent:** Monday, 13 August, 2018 1:31 PM  
**To:** Albert Hong <albert.hong@budgetdirect.com.sg>  
**Subject:** Re: Your Ref: SJP1398T, Our Ref: C10001866 - List of surveyors

Without Prejudice

Dear OIC,

Please arrange  
Mr Kenneth Kong LKK Auto Consultants Pte Ltd to conduct survey.

Thank you & Best Regards,

Gan Li Hui (Ms)

**Complete VMS PTE LTD**

Tel: 6455 0012 Fax: 6554 0012

Block 176 Sin Ming Drive, #03-14

Sin Ming Autocare Complex, Singapore 575721

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

**Veron Chen (LKKAuto)**

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Monday, 24 September 2018 7:57 AM  
**To:** Lily Leow  
**Cc:** CS A Team; SUR  
**Subject:** FW: LOD - SDT1401S(LKK REF: CS/AGI18011735/Ktd3) & SJP1398T(LKK REF: CS/AGI18014623/Kvb)  
**Attachments:** img-922094832.pdf; img-922094614.pdf

**Without Prejudice**

Hi Lily,

Thank you for your email.

Kindly forward all the documents to AUTO & GENERAL INSURANCE (S) PL for their necessary action.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Lily Leow <lily@completevms.com.sg>  
**Sent:** Saturday, 22 September 2018 10:08 AM  
**To:** CS A Team <cs-a@lkkauto.com>  
**Subject:** LOD - SDT1401S & SJP1398T

WITHOUT PREJUDICE

Dear Officer In Charge,

With reference to above mentioned, please see attached LOD and advise offer asap.

Thank you and best regards

Lily Leow

Tel: 64550012

Complete VMS Pte Ltd

Blk 176 Sing Ming Drive #03-14

Sin Ming Autocare Complex

Singapore 575721

E-mail: [lily@completevms.com.sg](mailto:lily@completevms.com.sg)



> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6023C
Vehicle Details	
Vehicle No.:	SJP1398T
Vehicle to be Exported:	No
Intended De-registration Date:	16 Aug 2018
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	L13A4139237
Chassis No.:	GE61125729
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$13,047.00
Original Registration Date:	12 Mar 2009
First Registration Date:	12 Mar 2009
Transfer Count:	1
Actual ARF Paid:	\$13,047.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Mar 2019
PARF Rebate Amount:	\$6,523.00
Intended COE Rebate Details	
COE Expiry Date:	11 Mar 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$5,701.00
COE Rebate Amount:	\$282.00
<b>Total Rebate Amount:</b>	<b>\$6,805.00</b>

The information contained herein is correct as at 16 Aug 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/08/2018 13:43
Date Of Accident	10/08/2018 18:20
Exact Location Of Accident	CTE TO ANG MO KIO - EXIT TO MOULMEIN
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJP1398T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	THOE HUILIN (DU HUILIN)
NRIC No	S8316023C
Email Address	DENYSETHOE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91111805
Alternative Phone No	OFFICE-91111805
<b>Vehicle Particulars</b>	
Manufacturer	HONDA
Model	FIT-1.3 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5078867709-02
Cover Note Number	
<b>Driver</b>	
Name of Driver	THOE HUILIN (DU HUILIN)
NRIC No	S8316023C
Date Of Birth	18/05/1983
Occupation	OUTDOOR
Date Of Driving Pass	14/12/2009
Driving Experience	8 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91111805
Fax Number	
Contact Number	OFFICE-91111805
E-Mail Address	DENYSETHOE@GMAIL.COM

Address	BLK 101 JURONG EAST STREET 13 #12-172
Postcode	600101
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER ATTACHED

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SJZ1522Z
Vehicle Make/Model/Colour	M/BENZ
Details Of Properties	REAR AND FRONT
Vehicle Category	PRIVATE CAR
Name of Driver	CHAN
NRIC/Passport Number	
Contact Number	91771001
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number	SJZ7652S
Vehicle Make/Model/Colour	HONDA STREAM

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

FRONT PORTION

PRIVATE CAR

GANESAN S/O KARUNANITHY

S2617580A

97996597

## Sketch Plan #2

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the CTA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 2 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal information (information set out in this form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and to refer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (a liability) who have insured vehicle(s) involved in this accident and to collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigation relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or other forms which could involve disclosure of certain personal data, their use to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (c) above may be shared/disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature:  
Date & Time

11/08/18


Driver's Signature  
(if driver is not the policyholder)  
Date & Time

Reporting Centre's Signature  
Name  
NRIC/IN No.

11/8/2018

SKETCH

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Slowing down at the exit to Moulmein from CTE, suddenly hit from the car at the back. No car in front of mine. When I exited the car, there were 2 vehicles behind me involved in the collision.

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature  
Date & Time: 11/08/18

Driver's Signature:  
Telukok Centre (No. 1001, Telukok)

Reporting Centre Personnel's Signature  
Name: 11/8/2018



Email : darren@completevms.com.sg ( )  
 lily@completevms.com.sg ( )  
 lihui@completevms.com.sg ( )

THOE HUILIN  
 BLK 101 JURONG EAST STRET 13 #12-172  
 SINGAPORE 600101

Attention : THE OWNER  
 Contact : 91111805

Estimate : ES006418

Date : 11/08/2018  
 Vehicle Num. : SJP1398T  
 Make/Model : HONDA FIT 1.3G A-2009  
 Chassis/Eng#: GE61125729/L13A4139237  
 Accident Date : 10/08/2018  
 Claim No. :  
 Reference :  
 Policy No. :

*Not Authored*  
*Lily 8?*  
*Review After Paint*  
*5-6 days*

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	TAIL GATE		995.50
2.	1	TAIL GATE LOCK		204.80
3.	1	REAR W/SCREEN MOULDING		165.00
4.	1	TAIL GATE INNER TRIM BOARD		639.00
5.	2	TAIL LAMP	386.20	772.40
6.	2	TAIL LAMP CLIP	3.50	7.00
7.	1	BOOT WEATHERSTRIP		139.10
8.	1	REAR END PANEL		596.60
9.	1	REAR END PANEL TOP GARNISH		235.00
10.	1	REAR BUMPER		783.50
11.	6	REAR BUMPER CLIP	5.50	33.00
12.	2	REAR BUMPER BRACKET	48.80	97.60
13.	2	REAR BUMPER SIDE RETAINER	45.70	91.40
14.	1	REAR BUMPER TOW COVER		18.00
15.	1	SPARE TIRE PANEL		810.70
16.	1	REAR TOOL TRAY		281.90
List Total S\$ :				5,870.50
20.00% Discount S\$ :				1,174.10
				4,696.40

SPECIAL NETT ITEMS :				
1.	1	H LOGO		48.50
2.	1	FIT EMBLEM		46.50
3.	1	REAR W/SCREEN SEALANT		65.00
4.	1	REVERSE SENSOR		280.00
5.		REAR NUMBER PLATE		25.00
6.		REAR NUMBER PLATE HOLDER		33.00
Special Nett Total S\$ :				498.00

**LKK Auto Consultants** hence notify the Repairer of the following: CONTINUE / ...

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:



Email : darren@completevms.com.sg ( )  
 lily@completevms.com.sg ( )  
 lihui@completevms.com.sg ( )

THOE HUILIN  
 BLK 101 JURONG EAST STRET 13 #12-172  
 SINGAPORE 600101

Attention : THE OWNER  
 Contact : 91111805

**Estimate : ES006418**

Date : 11/08/2018  
 Vehicle Num. : SJP1398T  
 Make/Model : HONDA FIT 1.3G A-2009  
 Chassis/Eng# : GE61125729/L13A4139237  
 Accident Date : 10/08/2018  
 Claim No. :  
 Reference :  
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :				
		REMOVE & REINSTALL REAR W/SCREEN GLASS	120h	180.00
		TRANSFER TAILGATE COMPONENT TO NEW GATE	60h	150.00
		CHANGE TAIL LAMP AND CHECK LIGHTING	20h	65.00
		RUST PROOFING TREATMENT		100.00
		SPRAY PAINT DAMAGED AREA AFFECTED	Job	1,100.00
		TO CUT OFF REAR END PANEL, SPARE TIRE PANEL, KNOCK AND STRAIGHTEN REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS		1,300.00
		Labour Total S\$ :		2,895.00

SingDollars : Eight Thousand Eighty-Nine & Cents Forty Only

Total S\$ : 8,089.40  
 =====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



Email : darren@completevms.com.sg ( )  
 lily@completevms.com.sg ( )  
 lihui@completevms.com.sg ( )

THOE HUILIN  
 BLK 101 JURONG EAST STRET 13 #12-172  
 SINGAPORE 600101

Attention : THE OWNER  
 Contact : 91111805

Estimate : ES006418

Date : 11/08/2018  
 Vehicle Num. : SJP1398T  
 Make/Model : HONDA FIT 1.3G A-2009  
 Chassis/Eng# : GE61125729/L13A4139237  
 Accident Date : 10/08/2018  
 Claim No. :  
 Reference :  
 Policy No. :

*Not Authorized  
 21 by 8400d  
 Penny After Paint  
 6 days*

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$
		LIST ITEMS : <i>771.50</i>		
1.	1	TAIL GATE	<i>R</i> 995.50	<i>✓</i>
2.	1	TAIL GATE LOCK	<i>Ty</i> 204.80	<i>✓</i>
3.	1	REAR W/SCREEN MOULDING	<i>ru</i> 165.00	<i>✓</i>
4.	1	TAIL GATE INNER TRIM BOARD <i>234.50</i>	<i>ngom</i> 639.00	<i>✓</i>
5.	2	TAIL LAMP <i>e 286.20</i>	<i>ngom</i> 386.20	<i>✓</i>
6.	2	TAIL LAMP CLIP	3.50 <i>mc</i>	7.00 <i>✓</i>
7.	1	BOOT WEATHERSTRIP	<i>6P.55Sn</i> 139.10	<i>✓</i>
8.	1	REAR END PANEL <i>295.50</i>	<i>ng om</i> 596.60	<i>✓</i>
9.	1	REAR END PANEL TOP GARNISH <i>112.90</i>	<i>ng om</i> 235.00	<i>✓</i>
10.	1	REAR BUMPER <i>475.00</i>	<i>R</i> 783.50	<i>✓</i>
11.	6	REAR BUMPER CLIP	5.50 <i>ru</i>	33.00 <i>✓</i>
12.	2	REAR BUMPER BRACKET	48.80 <i>ru</i>	97.60 <i>X</i>
13.	2	REAR BUMPER SIDE RETAINER	45.70 <i>ru</i>	91.40 <i>✓</i>
14.	1	REAR BUMPER TOW COVER	<i>ru</i> 18.00	<i>✓</i>
15.	1	SPARE TIRE PANEL	<i>ru</i> 810.70	<i>X</i>
16.	1	REAR TOOL TRAY <i>180.00</i>	<i>CNA</i> 281.90	<i>✓</i>
		List TotalS\$ :		5,870.50
		20.00% Discount S\$ :		1,174.10
				4,696.40
		SPECIAL NETT ITEMS :		
1.	1	H LOGO	<i>ru</i> 48.50	<i>X</i>
2.	1	FIT EMBLEM	<i>ru</i> 46.50	<i>✓</i>
3.	1	REAR W/SCREEN SEALANT	<i>ru</i> 65.00	<i>✓</i>
4.	1	REVERSE SENSOR	<i>2005N</i> 280.00	<i>✓</i>
5.	1	REAR NUMBER PLATE	<i>CNA</i> 25.00	<i>✓</i>
6.	1	REAR NUMBER PLATE HOLDER	<i>CNA</i> 33.00	<i>✓</i>
		Special Nett Total S\$ :		498.00

CONTINUE / ...



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre  
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721  
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ( )  
lily@completevms.com.sg ( )  
lihui@completevms.com.sg ( )

THOE HUILIN  
BLK 101 JURONG EAST STRET 13 #12-172  
SINGAPORE 600101

Estimate : ES006418

Attention : THE OWNER  
Contact : 91111805

Date : 11/08/2018  
Vehicle Num. : SJP1398T  
Make/Model : HONDA FIT 1.3G A-2009  
Chassis/Eng# : GE61125729/L13A4139237  
Accident Date : 10/08/2018  
Claim No. :  
Reference :  
Policy No. :

S/N    Quantity    Particular    Unit Price    Amount S\$

LABOUR :  
REMOVE & REINSTALL REAR W/SCREEN GLASS  
TRANSFER TAILGATE COMPONENT TO NEW GATE  
CHANGE TAIL LAMP AND CHECK LIGHTING  
RUST PROOFING TREATMENT  
SPRAY PAINT DAMAGED AREA AFFECTED  
TO CUT OFF REAR END PANEL, SPARE TIRE PANEL, KNOCK AND  
STRAIGHTEN REAR CHASSIS FRAME AND CHANGE ALL NECESSARY  
PARTS

120h 180.00  
60h 150.00  
20h 65.00  
80h 1,100.00  
1,300.00  
2,895.00

Labour Total S\$ :

SingDollars : Eight Thousand Eighty-Nine & Cents Forty Only

Total S\$ : 8,089.40  
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 1398T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	TAIL GATE	BENT	995.50	771.50
1	TAIL GATE LOCK	JAMMED	204.80	204.80
1	REAR W/SCREEN MOULDING	NECESSARY	165.00	165.00
1	TAIL GATE INNER TRIM BOARD	MTG CRACKED	639.00	234.50
2	TAIL LAMP @\$386.20	MTG CRACKED	772.40	572.40
2	TAIL LAMP CLIP @\$3.50	NECESSARY	7.00	7.00
1	REAR END PANEL	BENT	596.60	295.50
1	REAR END PANEL TOP GARNISH	MTG DISTORTED	235.00	112.90
1	REAR BUMPER	BENT	783.50	475.00
6	REAR BUMPER CLIP @\$5.50	NECESSARY	33.00	33.00
2	REAR BUMPER BRACKET @\$48.80	SERVICEABLE	97.60	-
2	REAR BUMPER SIDE RETAINER @\$45.70	DISTORTED	91.40	91.40
1	REAR BUMPER TOW COVER	MISSING	18.00	18.00
1	SPARE TIRE PANEL	TO REPAIR SEE LABOUR	810.70	-
1	REAR TOOL TRAY	CRACKED	281.90	180.00
	LESS 20% DISCOUNT		-1,146.28	-632.20
			4,585.12	2,528.80
1	BOOT WEATHERSTRIP (50%)(SN)	DENTED / CUT	139.10	69.55
	LESS 20% DISCOUNT		-27.82	-
			111.28	69.55
<b>SPECIAL NETT ITEMS</b>				
1	H LOGO (SN)	NOT NECESSARY	48.50	-
1	FIT EMBLEM (SN)	NECESSARY	46.50	46.50
1	REAR W/SCREEN SEALANT (SN)	NECESSARY	65.00	40.00
1	REVERSE SENSOR (SN)	DENTED	280.00	200.00
1	REAR NUMBER PLATE HOLDER (SN) }	CRACKED	33.00	45.00
1	REAR NUMBER PLATE (SN) }	CRACKED	25.00	-
			498.00	331.50
<b>LABOUR</b>				
	REMOVE & REINSTALL REAR W/SCREEN GLASS.		180.00	120.00
	TRANSFER TAILGATE COMPONENT TO NEW GATE.		150.00	60.00

Report Ref No. CS/AGI18014623/Kvbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHANGE TAIL LAMP AND CHECK LIGHTING.		65.00	20.00
	RUST PROOFING TREATMENT.		100.00	60.00
	SPRAY PAINT DAMAGED AREA AFFECTED.		1,100.00	800.00
	TO CUT OFF REAR END PANEL, SPARE TIRE PANEL, KNOCK AND STRAIGHTEN REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS.		1,300.00	1,000.00
			2,895.00	2,060.00
	<b>GRAND TOTAL</b>		<b>8,089.40</b>	<b>4,989.85</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,000.00</b>

Report Ref No. CS/AGI18014623/Kvbn2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.