

ASS. REC. BY:

REF:

CS/AIG/18014 634/T19d3⁵²

Special Instruction:

Surveyor:

From (Person):

Mithoosingh

ASSIGNMENT (Office)

AIG

Date/Time: 7/8/18 @ 3:45pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIN 972C

Insured:

at Workshop m/s

Sinhien Seng

Tel:

6748 1231

of

10 Kallang Way

Policy No:

2100118528

Claim No:

466593660734

Sum Insured:

Excess:

TBA 600 16/8/18

Make of Veh:

D.O.A. 06/08/2018

(Client's Record)

14/8/18

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11/11/18 @ 13:18

Person Contacted:

said

Vehicle-IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SIN 972C-X

X policy number - comd.

15/8/18 @ 9:50pm Informed Said C/A & ex: TBA by email. (COR below BSK)

16/8/18 @ 11:07am Informed Said ex: \$ 600 by email.

06/9/18 @ 2:52pm confirmed with Said from fig to 3337.63, 6 days by email.
(Red to 1782.57, 75%)

Taufik

REF:

A/G

ASSIGNMENT

OPC

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s:

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

tkg

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

X	X
N/S	O/S

Bal. or Market Value:

\$8K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR: Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT
Sent

Veh No

SJN 972C

Yr Regn

2009 Feb.

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Daihatsu Sirio

C.C

1495

Colour:

Green

A/C

Insured / Std / NI / NA

Sp. Reading

59740

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

304M3039001002898

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65R15

R:

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

14/8/18 @ 3pm

Survey held at

Sin ten Sec

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6748/23

RECEIVED 12 SEP 2018.

Date/Time: File Pass to?

☐

Preli. Report

11/2/9 Taufik

☐

Final Report

Date/Time: File Return to?

3)

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Workand (\$

Report Format :

MER-09

Lump Sum / I.B.I: (\$

3337.63

TOTAL

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG18014634/T1qd3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 13-08-2018



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SJN 972C
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From MITHOOSINGH	Assign Date	13/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/08/2018	Inspection Date	14/08/2018
Survey held at	SIN TIEN SENG PTE LTD NO 10 KALLANG WAY SINGAPORE 349215		

5a. Remarks

- A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

FW: - OD New Assignment - SJN972C (OI) DOA 06/08/2018

From: Mithoosingh, Aashweenjeetkaur
To: admin-a@kkauto.com, assignments@kkauto.com
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Azlan, Syazairdina, Chan, Yoke Shi
Sent: 7/8/2018 3:45:19 PM
Attachments:  tmp8F73.tif

Hi,

Claim number : TO BE ADVISED

Case owner : TO BE ADVISED

Please be informed that the claim is currently pending for registration in system. We will advise the details as soon as possible.

Thanks and regards,

Aashweenjeet Kaur (Aashween)

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Distributor & Dealer for



DENSO PRIXMAX

新天成私人有限公司 SIN TIEN SENG PTE LTD

HEAD OFFICE & KALLANG CENTRE: Tel: 6748-1166

10 Kallang Way, Singapore 349215

Fax: 6748-6767 6840 1128

E-mail: admin@sin-tien-seng.com.sg

Co Reg No: 197000883D

JURONG CENTRE: Tel: 6584-0014

6 Teban Gardens Crescent, Singapore 600924

Fax: 6584-3558

BEN KENG SHOWROOM: Tel: 6298-1466

811-84 Whimpoor West #01-75/76, Singapore 330934

Your ref:
Our ref:
Date

06.08.2018

Dear Sir,

ESTIMATE FOR VEHICLE ACCIDENT REPAIR (DOA 06.08.2018)

VEHICLE DETAILS: -

REGISTRATION NUMBER : SJN972C

VEHICLE MODEL : D-M303RS-GQGEW

CHASSIS NUMBER : JDAM303S001002896

ENGINE NUMBER : 2030440

MILEAGE (KM) : KM

REGISTRATION DATE : 03.02.2009

INSURANCE DETAILS: -

INSURED'S NAME : SOH POH GEOK

INSURED'S ADDRESS : BLK 168 TOA PAYOH LOR 1

: #03-1024

SINGAPORE 310168

POLICY NUMBER : 2100118528-09000

EXPIRY DATE : 02.02.2019

EXCESS PAYMENT : \$600/-

We are pleased to enclose to you our estimate for your consideration and approval. Please send your surveyor to our Kallang Service Centre 10 Kallang Way, Singapore 349215 where the above mentioned vehicle is now stored. Kindly contact Mr SAID/ERIC LOH at telephone number 6-748 1231 or E-mail: accclaims@sin-tien-seng.com.sg or fax: 6-840 1128 for any clarification.

Yours faithfully

FOR MANAGER
SIN TIEN SENG PTE LTD
(Kallang Service Centre)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 6 September 2018 2:57 PM
To: 'ACCTCLAIM'
Subject: RE: VEHICLE SJN 972C (DOA: 06/08/2018) COR & PIC

Dear Said,

WITHOUT PREJUDICE

Confirm final fig \$3,337.63 before excess \$600.00 and 6 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ACCTCLAIM <acctclaim@sts.com.sg>
Sent: Monday, 27 August 2018 9:47 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: VEHICLE SJN 972C (DOA: 06/08/2018) COR & PIC

Hi Shiau Chan

Pls forward to Taufik. I appreciate Thank You Very Much.

Said

67481231

From: Shiau Chan (LKKAUTO)
Sent: Thursday, August 16, 2018 11:07 AM
To: ACCTCLAIM
Cc: SUR
Subject: RE: VEHICLE SJN 972C (DOA: 06/08/2018)

Dear Said,

Please be informed that the excess of above vehicle is \$600.00.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 15 August 2018 3:52 PM

Shiau Chan (LKKAUTO)


To: Rumli, Sharizah
Cc: Quek, Joyceline-CH; Paramchand, Varsha; Mutalip, Nurashikin; Admin A; SUR
Subject: RE: SID : 12863360 OC: 4665936607SG POLICY : 2100118528 (CTC INSD @ 96706955) *** LKK REF: CS/AIG18014634/T1qd3

Dear Shasha,

We have received the assignment on 07/08/2018 and contacted the repairer on the same day. We were informed by the repairer, the vehicle was not in the premises.

On 10/08/2018, we received an email and informed by Lee Ying (AIG) that the insured will be sending her vehicle in on 13/08/2018 (Monday).

We have called the repairer on 13/08/2018 morning to confirm the appointment but was told that the appointment will change to 14/08/2018.

Therefore, the vehicle was inspected on 14/08/2018 and authorise repair on 15/08/2018. 

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Rumli, Sharizah <Sharizah.Rumli@aig.com>
Sent: Thursday, 30 August 2018 11:29 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: Quek, Joyceline-CH <JoycelineCH.Quek@aig.com>; Paramchand, Varsha <Varsha.Paramchand@aig.com>; Mutalip, Nurashikin <Nurashikin.Mutalip@aig.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: SID : 12863360 OC: 4665936607SG POLICY : 2100118528 (CTC INSD @ 96706955) *** LKK REF: CS/AIG18014634/T1qd3

Hi Shiau Chan,

As spoken please assist urgently.

Sharizah Rumli (Shasha)
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120

Tel +(65) 6419-1087 | Fax +(65) 6835-7416
Sharizah.rumli@aig.com | www.aig.com.sg

Get up to 15% OFF your AIG vehicle insurance premium and stand a chance to win amazing prizes when you download AIG On the Go now!

IMPORTANT NOTICE:

We have contacted the repairer on 7/8/2018, the vehicle was not in the workshop and

We have received the assignment on 7/8/2018 and contacted the repairer on the same day. We will inform the vehicle is not in the workshop. On 10/8/2018, received email from Lee Ying ~~that~~ ^{that} ~~the insured~~ the repairer informed the insured ~~will send in the vehicle.~~ ^{will be sending her.} on ~~12/8/2018~~ Monday 13/8/2018.

Called repairer on the 13/8/2018 and was told that the vehicle will be in on 14/8/2018.

Please be informed that we have inspected the vehicle on 14/8/2018 and authorise the repair on 15/8/2018.

Dear Shasha,

We have checked with our colleague ^{agreed with} our surveyor had inspected the vehicle SJN 972C on 14/08/18 as the repairer had informed that the ~~insured~~ insured will send her vehicle to ~~workshop~~ workshop on 13/08/18. (We have ~~informed~~ informed repairer authorisation on 15/8/18 & update them the excess \$600 on 16/8/18 as informing by Mr. LOO Tony Shing on the same day.)

↓
Bryan said ok!

According to the repairer, the insured had drove off her vehicle from after reporting on 06/08/18.

~~We have review the ^{file} matter,~~

We have checked with our colleague, we had received this assignment on 07/08/18. At the same day, we had contacted the repairer & they informed that the insured had drove off her vehicle after reporting. ~~At the~~ So that, the said vehicle temporary not in the workshop & will updates as once the vehicle in the workshop.

On 10/08/18, we received email from Lee Yiny that the insured will sending her vehicle to workshop on 13/08/18.

We ~~have~~ had contacted the repairer on 13/08/18, the vehicle ~~has not yet in~~ workshop will send it to workshop on 14/08/18. So that we make the inspection arrangement on 14/08/18.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 16 August 2018 11:07 AM
To: ACCTCLAIM
Cc: SUR
Subject: RE: VEHICLE SJN 972C (DOA: 06/08/2018)

Dear Said,

Please be informed that the excess of above vehicle is \$600.00.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 15 August 2018 3:52 PM
To: ACCTCLAIM <acctclaim@sts.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: VEHICLE SJN 972C (DOA: 06/08/2018)

Dear Said,

As spoken with you.

Please proceed to repair the insured vehicle **SJN 972C (excess \$TBA/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 15 August 2018 3:52 PM
To: ACCTCLAIM
Cc: SUR
Subject: VEHICLE SJN 972C (DOA: 06/08/2018)

Dear Said,

As spoken with you.

Please proceed to repair the insured vehicle **SJN 972C (excess \$TBA/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	5370H

Vehicle Details

Vehicle No.:	SJN972C
Vehicle to be Exported:	No
Intended De-registration Date:	31 Aug 2018
Vehicle Make:	DAIHATSU
Vehicle Model:	M303RS-GQGEW
Primary Colour:	Green
Manufacturing Year:	2007
Engine No.:	2030440
Chassis No.:	JDAM303S001002898
Maximum Power Output:	76.0 kW (101 bhp)
Open Market Value:	\$13,789.00
Original Registration Date:	03 Feb 2009
First Registration Date:	03 Feb 2009
Transfer Count:	0
Actual ARF Paid:	\$0.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Feb 2019
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	02 Feb 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$0.00
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 14 Aug 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/08/2018 14:27
Date Of Accident	06/08/2018 07:00
Exact Location Of Accident	SLIP RD C'WEALTH AVE WEST TO NORTH BUONA VISTA RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN972C
Insured/Policyholder	
Name Of Registered Owner	SOH POH GEOK
NRIC No	S1535370H
Email Address	PGSOHTP@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96706955
Alternative Phone No	OTHERS-96706955

Vehicle Particulars

Manufacturer	DAIHATSU
Model	SIRION-1.5 SPORTS (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100118528-09
Cover Note Number	

Driver

Name of Driver	SOH POH GEOK
NRIC No	S1535370H
Date Of Birth	24/03/1962
Occupation	OUTDOOR
Date Of Driving Pass	13/01/2009
Driving Experience	9 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96706955
Fax Number	
Contact Number	OTHERS-96706955
EMail Address	PGSOHTP@GMAIL.COM

Address	BLK 168 LORONG 1 TOA PAYOH #03-1024
Postcode	310168
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WHILE STAYING IN QUEUE FOR TURNING INTO NORTH BUONA VISTA ROAD FROM COMMONWEALTH AVENUE WEST, STRING OF VEHICLES AHEAD STARTED MOVING. I ACCELERATED SLOWLY AND THE FRONT VEHICLE SJN9211G CAME TO A HALT AT THE DOTTED LINE, AND I STEPPED ON MY ACCELERATOR INSTEAD OF THE BRAKES AND BUMPED INTO THE REAR OF THE CAR.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJN9211G
Vehicle Make/Model/Colour	SILVER HONDA STREAM
Details Of Properties	MOTOR CAR
Vehicle Category	PRIVATE CAR
Name of Driver	CHIRNSIDE BRIAN JOHN
NRIC/Passport Number	S7081372F
Contact Number	91070211
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While staying in the queue for turning into North Buena Vista Drive from Commonwealth Ave. West, the string of vehicles ahead started moving. I accelerated slowly, and the front vehicle SSN 9211G came to a halt at the 'dotted' line, and I ~~stopped~~ ^{stepped} on my accelerator, instead of the brakes and bumped into the rear of the car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 6/8/2018 / 1109hs

Driver's Signature
(If driver is not the policyholder)
Date & Time: 6/8/2018 / 1109hs

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 6/8/2018

Driver's Signature
(If driver is not the policyholder)
Date & Time: 6/8/2018

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1535370H



Name

SOH POH GEOK

Race

CHINESE

Date of birth

24-03-1962

Sex

F

Country/Place of birth
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE



S1535370H

24 MAR 1962

19 JAN 2001



001697891E

5894811



NRIC No. S1535370H



Date of issue
20-03-2018

Address

APT BLK 168 LORONG 1 TOA PAYOH
#03-1024
SINGAPORE 310168

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 13 Jan 2009

NP 428A



Licence No. S1535370H



CERTIFICATE OF INSURANCE

DAIHATSU AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Soh Poh Geok
 Period of Insurance : 03 Feb 2018 To 02 Feb 2019
 Engine No. : 2030440
 Chassis No. : JDAM303S001002898

Vehicle No. : SJN972C
 Policy No. : 2100118528-09
 Endorsement No. :
 Issued Date : 05 Jan 2018

ABOUT THE COVER

Make/Model : DAIHATSU DAIHATSU SIRION M303R
 Engine Capacity/Tonnage : 1,495.00 CC Sum Insured : Market Value First Year of Registration : 2009
 Driver Restriction : NA Off Peak Car : Yes Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 169) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Soh Poh Geok - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Sin Tien Seng Kallang Centre Add: 10 Kallang Way, Singapore 349215 67481231 67486706

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 8200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES


Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 169), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500636010

SIN TIEN SENG PTE LTD
 10 KALLANG WAY KALLANG CENTRE
 SINGAPORE 349215

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.


 AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Distributor & Dealer for



DAIHATSU

DENSO PRIXMAX

新天成私人有限公司
SIN TIEN SENG PTE LTD

MOTOR CLAIM DEPARTMENT
AIG ASIA PACIFIC INSURANCE PL
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

HEAD OFFICE & KALLANG CENTRE: Tel: 6748-1166

10 Kallang Way, Singapore 349215

Fax: 6748-6707 6840 1128

E-mail: admin@sts.com.sg acclaim@sts.com.sg

Co Reg No: 197000883D

JURONG CENTRE: Tel: 6561-6611

6 Teban Gardens Crescent, Singapore 608921

Fax: 6561-9538

BOON KENG SHOWROOM: Tel: 6298-1466

Blk 34 Whampoa West #01-75/79, Singapore 330034

Fax: 6298-1462

Your ref.
Our ref.
Date

06.08.2018

Dear Sir

ESTIMATE FOR VEHICLE ACCIDENT REPAIR **(DOA 06.08.2018)**

VEHICLE DETAILS: -

REGISTRATION NUMBER : SJN972C
VEHICLE MODEL : D-M303RS-GQGEW
CHASSIS NUMBER : JDAM303S001002896
ENGINE NUMBER : 2030440
MILEAGE (KM) : 59740 KM
REGISTRATION DATE : 03.02.2009


INSURANCE DETAILS: -

INSURED'S NAME : SOH POH GEOK
INSURED'S ADDRESS : BLK 168 TOA PAYOH LOR 1
#03-1024
SINGAPORE 310168

POLICY NUMBER : 2100118528-09000
EXPIRY DATE : 02.02.2019
EXCESS PAYMENT : \$600/-

We are pleased to enclose to you our estimate for your consideration and approval. Please send your surveyor to our Kallang Service Centre 10 Kallang Way, Singapore 349215 where the above mentioned vehicle is now stored. Kindly contact **Mr SAID/ERIC LOH** at telephone number **6-748 1231** or E-mail: acclaim@sts.com.sg or fax: **6-840 1128** for any clarification.

Yours faithfully


for MANAGER
SIN TIEN SENG PTE LTD
(Kallang Service Centre)

VEHICLE REPAIR ESTIMATION FOR SJN972C

Parts Needed:

No.	PART DESC	PARTNO	QTY	U/LIST PR	TTL NET PR
1	REINFORCEMENT FRONT	52021 B1021	1	302.00	235.56 <i>bt / 100</i>
2	SUPPORT,FR BUMPER RH	52115 B1010	1	39.00	30.42 <i>X nn</i>
3	SUPPORT,FR BUMPER LH	52116 B1010	1	39.00	30.42 <i>bt /</i>
4	COVER,FR BUMPER [SP]	52119 B1090	1	484.00	377.52 <i>bt /</i>
5	BRCKT, FOG LAMP LH	52126 B1010	1	26.00	20.28 <i>X nn</i>
6	H-COVER FR BUMPER LH	52128 B1080	1	15.50	12.09 <i>bt / nn</i>
7	MOULD'G,FR BUMPER LH	52713 B1010	1	34.00	26.52 <i>bt /</i>
8	GRILLE,FR BUMPER UPP	53112 B1020	1	71.00	55.38 <i>bt / nn</i>
9	GRILLE,FR BUMPER LWR	53113 B1020	1	80.00	62.40 <i>bt / nn</i>
10	SUPPORT RADIATOR RH	53202 B1080	1	94.00	73.32 <i>X nn</i>
11	SUPPORT RADIATOR, LH	53203 B1010	1	93.00	72.54 <i>bt / nn</i>
12	SUPPORT RADIATOR TOP	53205 B1050	1	58.00	45.24 <i>bt / 20</i>
13	SUPPORT, HOOD LOCK	53215 B1010	1	21.00	16.38 <i>bt /</i>
14	HOOD	53301 B1021	1	333.00	259.74 <i>bt / 120</i>
15	LOCK HOOD	53510 B1010	1	78.00	60.84 <i>bt /</i>
16	SHIELD FENDER LH	53806 B1010	1	115.00	89.70 <i>X nn</i>
17	PANEL, FR FENDER, LH	53812 B1040	1	196.00	152.88 <i>bt /</i>
18	SEAL, FRT FENDER LH	53869 B1010	1	11.50	8.97 <i>bt /</i>
19	EMBLEM, HOOD	75311 B1010	1	63.00	49.14 <i>bt / nn</i>
20	HEADLAMP SET, LH	81150 B1030	1	427.00	333.06 <i>bt /</i>
21	CONDENSER W/RECEIVER	88450 B1020	1	382.00	297.96 <i>bt / 208.80</i>
22	HOSE, DISCHARGE	88711 B1050	1	378.00	294.84 <i>bt /</i>
23	TUBE, INLET	88716 B1050	1	309.00	241.02 <i>bt /</i>
24	R-COOLANT RCP 1L	PM-02 1654	1	29.00	29.00 <i>bt / 14.40</i>
25	SUNDRIES	WSS-01	1	80.00	80.00 <i>bt / 14.40</i>
Total (1) :			25		\$2,955.22

Labour Charges:

1 R&R/ REPLACE FRONT HEADLAMP & REFOCUS HEADLIGHT	\$30.00 /
2 R&R RADIATOR TO FACILITATE REPAIR	\$40.00 /
3 R&R/ REPLACE AIRCON CONDENSER & REFILL GAS	\$120.00 /
4 CUT & WELD FRONT SUPPORT PANEL/ PANEL BEAT <i>320</i>	\$900.00 <i>800</i>
REPLACE FRONT BUMPER/ HOOD ETC.	
5 SPRAY PAINT ON AFFECTED AREAS <i>200</i>	\$900.00 <i>800</i>
6 RENEW FRONT NUMBER PLATE	\$40.00 <i>bt /</i>
7 LTA DOCUMENTATION FOR OPC NUMBER PLATE	\$120.00 /
8 OPC NUMBER PLATE SEAL	<i>not</i> \$15.00 <i>/ 20</i>
TOTAL (2)	\$2,165.00
TOTAL (1) & (2)	\$5,120.20 <i>5125.22</i>

PREPARED BY SAID

TEL : 6-7481231 FAX : 6-8401128 E-mail : acctclaim@sts.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjil 97495749

6 days

Ex: to be advise

14/8/18 @ 3pm

Resurvey before paint

sur@lkkauto.com

Revert, Not the flame

VEHICLE REPAIR ESTIMATION FOR SJN972C

Parts Needed:

No.	PART DESC	PARTNO	QTY	U/LIST PR	TTL NET PR	
1	REINFORCEMENT FRONT	52021 B1021	1	302.00	235.56	bt / 100 ✓ Used Part
2	SUPPORT,FR BUMPER RH	52115 B1010	1	39.00	30.42	X n
3	SUPPORT,FR BUMPER LH	52116 B1010	1	39.00	30.42	2x /
4	COVER,FR BUMPER [SP]	52119 B1090	1	484.00	377.52	de /
5	BRCKT, FOG LAMP LH	52126 B1010	1	26.00	20.28	X
6	H-COVER FR BUMPER LH	52128 B1080	1	15.50	12.09	de X
7	MOULD'G,FR BUMPER LH	52713 B1010	1	34.00	26.52	2x /
8	GRILLE,FR BUMPER UPP	53112 B1020	1	71.00	55.98	de X
9	GRILLE,FR BUMPER LWR	53113 B1020	1	80.00	62.40	cm X
10	SUPPORT RADIATOR RH	53202 B1080	1	94.00	73.32	X
11	SUPPORT RADIATOR, LH	53203 B1010	1	93.00	72.54	bt X
12	SUPPORT RADIATOR TOP	53205 B1050	1	58.00	45.24	bt / 20 ✓ Used Part
13	SUPPORT, HOOD LOCK	53215 B1010	1	21.00	16.38	bt /
14	HOOD	53301 B1021	1	333.00	259.74	bt / 120 ✓ Used Part
15	LOCK HOOD	53510 B1010	1	78.00	60.84	bt ✓
16	SHIELD FENDER LH	53806 B1010	1	115.00	89.70	X
17	PANEL, FR FENDER, LH	53812 B1040	1	196.00	152.88	bt /
18	SEAL,FRT FENDER LH	53869 B1010	1	11.50	8.97	net ✓
19	EMBLEM, HOOD	75311 B1010	1	63.00	49.44	net X
20	HEADLAMP SET, LH	81150 B1030	1	427.00	333.06	cm ✓
21	CONDENSER W/RECEIVER	88450 B1020	1	382.00	297.96	? 208.80 net
22	HOSE, DISCHARGE	88711 B1050	1	378.00	294.84	X
23	TUBE, INLET	88716 B1050	1	309.00	241.02	X
24	R-COOLANT RCP 1L	PM-02 1654	1	29.00	29.00	2x / 14.40 net
25	SUNDRIES	WSS-01	1	80.00	80.00	✓ 73.50 net
Total (1):			25		\$2,955.22	1543.29

Labour Charges:

1 R&R/ REPLACE FRONT HEADLAMP & REFOCUS HEADLIGHT	\$30.00	/
2 R&R RADIATOR TO FACILITATE REPAIR	\$40.00	/
3 R&R/ REPLACE AIRCON CONDENSER & REFILL GAS	\$120.00	/
4 CUT & WELD FRONT SUPPORT PANEL/ PANEL BEAT 320	\$900.00	800 ✓
5 REPLACE FRONT BUMPER/ HOOD ETC.		
6 SPRAY PAINT ON AFFECTED AREAS 200	\$900.00	800 ✓
7 RENEW FRONT NUMBER PLATE	\$40.00	bt /
8 LTA DOCUMENTATION FOR OPC NUMBER PLATE	\$120.00	/
8 OPC NUMBER PLATE SEAL (Vicem Revised Fee)	\$15.00	/ 20 ✓
TOTAL (2)	\$2,165.00	1970
TOTAL (1) & (2)	\$5,120.20	3513.29 COR

PREPARED BY SAID

TEL : 6-7481231 FAX : 6-8401128 E-mail : acctclaim@sts.com.sg

Less 520 175.66 Tanjiluh 97495749
 Less Excess 600
 2737.63

6 days
 Ex: to be advise
 14/8/18 @ 3pm.
 Reserving before print.
 sur@tukaauto.com
 Revert, Not An Answer

Distributor & Dealer for



DAIHATSU

DENSO PRIXMAX

新天成私人有限公司
SIN TIEN SENG PTE LTD

MOTOR CLAIM DEPARTMENT

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

HEAD OFFICE & KALLANG CENTRE: Tel: 6748-1166

10 Kallang Way, Singapore 349215 Fax: 6748-6767 68401175

E-mail: admin@sts.com.sg Co Reg No: 197000883D

JURONG CENTRE: Tel: 6561-6611

8 Teban Gardens Crescent, Singapore 608921 Fax: 6561-9538

SIN MING CENTRE: Tel: 6453-1166

Blk 1 Sector C Sin Ming Ind Est #01-111/117, Singapore 675606

Fax: 6454-5134

BOON KENG SHOWROOM: Tel: 6298-1466

Blk 34 Whampoa West #01-75/79, Singapore 330034

Fax: 6298-1482

Your ref:
Our ref:
Date

07.09.2018

Dear Sir

VEHICLE ACCIDENT REPAIR

VEHICLE NUMBER: **SJN972C** ✓

REFERENCE NUMBER:

Please refer to our estimate dated 07.08.2018. We wish to inform that the repair has been completed and the following are attached for your necessary action.

Workshop Repair Bill No:882194 for \$2,929.26

Owner's Discharge Voucher dated 21.08.2018

2 We look forward to your early remittance.

Yours faithfully

for MANAGER
SIN TIEN SENG PTE LTD



Innovation for Tomorrow

CUSTOMER'S NAME & ADDRESS:
 AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 AIG BUILDING
 SINGAPORE 079120

REF #	MR205160	DATE	20180817
ISSUE CODE	59	ISSUE TIME	16:01:43
VEH # / DO # / PO# / COMP #		ACCOUNT #	A33458

ITEM	PART NUMBER	PART NAME	QTY	NET PRICE	TOTAL (\$\$)
1	52116-B1010-	SUPPORT, FR BUMPER	1	30.45	30.45
2	52119-B1090-	COVER,FR BUMPER [SP]	1	377.55	377.55
3	52713-B1010-	MOULDING, FR BMP [SP]	1	26.55	26.55
4	53215-B1010-	SUPPORT, HOOD LOCK	1	16.40	16.40
5	53510-B1010-	LOCK HOOD	1	60.85	60.85
6	53812-B1020-	PANEL, FR SIDE, LH	1	152.90	152.90
7	53869-B1010-	SEAL,FRT FDR TO COWL	1	9.00	9.00
8	81150-B1030-	HEADLAMP SET, LH	1	333.10	333.10
9	90044-67517-	CLIP	3	1.10	3.30
10	90044-67529-	CLIP (FOR FENDER)	4	1.10	4.40
11	90044-67530-	CLIP	4	1.20	4.80
12	90044-67555-	CLIP	4	1.90	7.60
13	90044-68280-	CLIP (7)	4	1.20	4.80
14	90044-68320-	CLIP	4	1.50	6.00
15	44776-00250	CORE, CONDENSER	1	208.80	208.80

SUB-TOTAL 1,246.50

ADD: GOODS & SERVICES TAX (7%) -

TOTAL (\$\$) 1,246.50

RECEIVED GOODS IN GOOD CONDITION	CHECKED BY	ATTENDED BY	MECHANIC	VEHICLE #	REPAIR ORDER#
		CHEWPW	TANKS	SJN972C	200194

PARTS CENTRE:
 KALLANG 10 KALLANG WAY SINGAPORE 349215 FAX 6741 1735 TEL 6748 1253



Innovation for Tomorrow

CUSTOMER'S NAME & ADDRESS:

AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 AIG BUILDING
 SINGAPORE 079120

REF #	MR205181	DATE	20180823
ISSUE CODE	59	ISSUE TIME	14:50:59
VEH # / DO # / PO# / COMP #	ACCOUNT # A33458		

ITEM	PART NUMBER	PART NAME	QTY	NET PRICE	TOTAL (S\$)
1	01240-00300	RAD COOLANT (RED)	1	14.40	14.40
2	CH-20-1976	BULB YELLOW OFFS	2	8.00	16.00
3	90981-11059-000	BULB 12-18W	1	5.55	5.55
4	CH-20-1756	B-BULB 12V-21/5W	1	5.80	5.80
5	90044-80392-	GROMMET	1	3.45	3.45
6	90467-07071-22	CLIP	2	4.85	9.70
7	90044-67526-	CLIP	1	1.20	1.20
8	90044-67383-	CLIP	1	0.90	0.90

SUB-TOTAL 57.00

ADD: GOODS & SERVICES TAX (7%) -

TOTAL (S\$) 57.00

RECEIVED GOODS IN GOOD CONDITION	CHECKED BY	ATTENDED BY	MECHANIC	VEHICLE #	REPAIR ORDER#
		CHEWPW	TANKS	SJN972C	200194

PARTS CENTRE:
 KALLANG 10 KALLANG WAY SINGAPORE 349215 FAX: 6741 1735 TEL: 6748 1253

AUTHORISATION LETTER

(Repair of Vehicles Involving Insurance Claims)

Date : 14.08.2018
Name of Owner : SOH POH GEOK
Address : BLK 168
LORONG 1 TOA PAYOH
#03-1024
SINGAPORE 310168

Vehicle Registration No : SJN972C
Insurer : AIG ASIA PACIFIC INSURANCE PTE LTD
Insurance Policy No. : 2100118528-09000
Date & Time of Incident : 06.08.2018 @ 0700HRS
Accident Claim No. :

I/We hereby authorise Sin Tien Seng Pte Ltd to carry out the repairs to my/our vehicle and agree to pay the bill in full to Sin Tien Seng Pte Ltd in case of repudiation by the Insurer.

Yours faithfully



(SIGNATURE OF INSURED)
(COMPANY'S STAMP)

Name : Soh Poh Geok
NRIC No.: S5353704



Innovation for Tomorrow

CUSTOMER'S NAME & ADDRESS	VEHICLE'S & TRANSACTION'S INFORMATION	
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #07-16 AIG BUILDING SINGAPORE 079120	VEHICLE REG # SJN972C	DATE/TIME OF INVOICE 2018-09-07 15:00
	MODEL D-M303RS-GQGEW	ACCOUNT # A33458
	ODOMETER READING 59740 KM	SERVICE ADVISOR/EXECUTIVE SAID
	REPAIR ORDER # 200194	PAYMENT DETAILS CREDIT

DESCRIPTION OF REPAIRS PERFORMED


ITEM	DETAILS		CHARGES(S\$)
1	R&R/ REPLACE HEADLAMP & REFOCUS HEADLIGHT	30.00	
2	R & RADIATOR TO FACILITATE REPAIR	40.00	
3	R&R/ AIRCOND CONDENSER & REFILL GAS	120.00	
4	CUT & WELD/ REPAIR FRONT SUPPORT PANEL	800.00	
5	PANEL BEAT & REPLACE DAMAGED PARTS	0.00	
6	SPRAY PAINT ON AFFECTED AREAS	800.00	
7	LTA DOCUMENTATION FOR OPC NUMBER PLATE	120.00	1,910.00
	SUBLET REPAIR ...		
8	RENEW FRONT NUMBER PLATE		40.00
	OTHERS ...		
9	OPC NUMBER PLATE SEAL	20.00	
10	USED FRONT REINFORCEMENT	100.00	
11	USED TOP SUPPORT, RADIATOR	20.00	
12	USED HOOD	120.00	
13	LESS ROUND UP DISCOUNT	-0.21	259.79
	SPARE PARTS USED ...		
14	MR205160, MR205181		1,303.50
	SUB-TOTAL:		3,513.29
	LESS SPECIAL DISCOUNT @ 5%		(175.66)
	LESS BILL# 882141 INSURANCE EXCESS PAYMENT		(600.00)
	SUB-TOTAL:		\$2,737.63
	ADD: GOODS & SERVICES TAX (7%)		\$191.63
	GRAND TOTAL:		\$2,929.26
	DOLLARS TWO THOUSAND NINE HUNDRED TWENTY NINE AND CENTS TWENTY SIX ONLY		

CUSTOMER'S ACKNOWLEDGEMENT OF REPAIRS/CHARGES

NAME

NRIC #

SIGNATURE

for  SIN TIEN SENG PTE LTD

Interest at 1% per month will be levied on overdue amount

GST REG #: M2-0011219-9 CO REG #: 197000883D

SERVICE CENTRE:

KALLANG : 10 KALLANG WAY SINGAPORE 349215 TEL: 6748 1231 FAX: 6748 1128

DISCHARGE VOUCHER

VEHICLE OWNER: SOH POH GEOK

ADDRESS: BLK 168
LORONG 1 TOA PAYOH
#03-1024
SINGAPORE 440001

DATE: 21.08.2018

Dear Sir

VEHICLE REGISTRATION NO. : SJN972C
INSURER : AIG ASIA PACIFIC INSURANCE PTE LTD
INSURANCE POLICY NO. : 2100118528-09000
ACCIDENT CLAIM NO. :
DATE & TIME OF ACCIDENT : 06.08.2018 @ 0700 HRS

I/We hereby certify that the repair to my/our motor vehicle involved in the accident on the above mentioned date and time has been completed by Sin Tien Seng Pte Ltd to my/our entire satisfaction and agree that payment of their account for such repair shall be in full satisfaction and discharge of all claims under this policy.

Yours faithfully



(SIGNATURE OF INSURED)
(COMPANY'S STAMP)

Name : Soh Poh Geok
NRIC No.: R1535370 H

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Aug 2018		15 Aug 2018 14:15 Edit Adj Rpt	S\$3,513.29 Edit Estimates	S\$3,513.29 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SOH POH GEOK, ID: S1535370H, Tel: +6596706955, Email: PGSOHTP@GMAIL.COM		
Vehicle Reg. No.:	SJN972C	Date of Loss:	06/08/2018 00:00 - :59 [114 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 4665936607SG	Policy/Cover Note No.:	2100118528 (Comprehensive)
		Excess:	S\$600.00
Repairer:	Sin Tien Seng Pte Ltd (Kallang) 10 Kallang Way, 349215 Kallang - Tel: 6748 1231		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 27/08/2018]		
Driver/Custodian:	SOH POH GEOK (56 / Female), NRIC: S1535370H, Tel: +6596706955		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJN972C (4665936607SG)**

OD

Aug 6 2018 12:00AM

[SOH POH GEOK]

Sin Tien Seng Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images											3 per page			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	06/09/18 15:07	Odometer Reading										Load JPG		
2	06/09/18 15:07	General View										Load JPG		
3	06/09/18 15:07	General View										Load JPG		
4	06/09/18 15:07	General View										Load JPG		
5	06/09/18 15:07	General View										Load JPG		
6	06/09/18 15:07	General View										Load JPG		
7	06/09/18 15:07	General View										Load JPG		
8	06/09/18 15:07	General View										Load JPG		
9	06/09/18 15:07	General View										Load JPG		
10	06/09/18 15:07	General View										Load JPG		
11	06/09/18 15:07	General View										Load JPG		
12	06/09/18 15:07	General View										Load JPG		
13	06/09/18 15:07	General View										Load JPG		
14	06/09/18 15:07	General View										Load JPG		
15	06/09/18 15:07	General View										Load JPG		
16	06/09/18 15:07	General View										Load JPG		
17	06/09/18 15:07	General View										Load JPG		
18	06/09/18 15:07	General View										Load JPG		
19	06/09/18 15:07	General View										Load JPG		
20	06/09/18 15:07	General View										Load JPG		
21	06/09/18 15:07	General View										Load JPG		
22	06/09/18 15:07	General View										Load JPG		
23	06/09/18 15:07	General View										Load JPG		
24	06/09/18 15:07	General View										Load JPG		
25	06/09/18 15:07	General View										Load JPG		
26	06/09/18 15:07	General View										Load JPG		
27	06/09/18 15:07	General View										Load JPG		
28	06/09/18 15:07	General View										Load JPG		
29	06/09/18 15:07	General View										Load JPG		
30	06/09/18 15:07	General View										Load JPG		
31	06/09/18 15:07	General View										Load JPG		
32	06/09/18 15:07	General View										Load JPG		
33	06/09/18 15:07	General View										Load JPG		
34	06/09/18 15:07	General View										Load JPG		
35	06/09/18 15:07	General View										Load JPG		
36	06/09/18 15:07	General View										Load JPG		

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	06/09/18 15:07	General View	Load JPG	✓
38	06/09/18 15:07	General View	Load JPG	✓
39	06/09/18 15:07	General View	Load JPG	✓
40	06/09/18 15:07	General View	Load JPG	✓
41	06/09/18 15:07	General View	Load JPG	✓
42	06/09/18 15:07	General View	Load JPG	✓
43	06/09/18 15:07	General View	Load JPG	✓
44	06/09/18 15:07	General View	Load JPG	✓
45	06/09/18 15:07	General View	Load JPG	✓
46	06/09/18 15:08	Reinspection Photo	Load JPG	✓
47	06/09/18 15:08	Reinspection Photo	Load JPG	✓
48	06/09/18 15:08	Reinspection Photo	Load JPG	✓
49	06/09/18 15:08	Reinspection Photo	Load JPG	✓
50	06/09/18 15:08	Reinspection Photo	Load JPG	✓

Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/08/18 15:39	ESTIMATE	Load PDF	
2	15/08/18 16:10	Certificate of Insurance	Load PDF	
3	15/08/18 16:10	Driver's Driving License	Load PDF	
4	03/10/18 10:27	DISCHARGE VOUCHER	Load PDF	
5	03/10/18 10:27	WORKSHOP INVOICE	Load PDF	

Linked Accident Report Documents

View

View in Browser

Assessment Reports			1 per page	
No	Finalized On	Sin Tien Seng Pte Ltd (Kallang)	Thumbnail	Print
1	06/08/18 14:53	Accident Statement	1 Load HTM	

Photos/Images			3 per page	
No	Finalized On	Sin Tien Seng Pte Ltd (Kallang)	Thumbnail	Print
1	06/08/18 14:49	Accident Photo	1 Load JPG	
2	06/08/18 14:49	Accident Photo	1 Load JPG	
3	06/08/18 14:49	Accident Photo	1 Load JPG	
4	06/08/18 14:49	Accident Photo	1 Load JPG	
5	06/08/18 14:49	Accident Photo	1 Load JPG	

Documentation			1 per page	
No	Finalized On	Sin Tien Seng Pte Ltd (Kallang)	Thumbnail	Print
1	06/08/18 14:50	Sketch Plan	1 Load TIF	
2	06/08/18 14:50	Sketch Plan #2	1 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG18014634/T1QD3S2

Date: 03/10/2018

REFERENCE

Insured/Claimant:	SOH POH GEOK	Policy No:	2100118528	
Date of Loss:	06/08/2018	Nature of Claim:	OD	Claim No: 4665936607SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN972C		
Make & Model:	DAIHATSU SIRION, 1.5 Sports (A)		
Reg. Date:	03/02/2009 (Man. Year: 2007)	Engine No:	2030440
Colour:	Green	Chassis No:	JDAM303S001002898
Engine Capacity:	1495 cc	Odometer:	59740 km
Market Value/New Car Price:	S\$8,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,015.22	1,603.29	1,411.93	46.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,110.00	1,910.00	200.00	9.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,125.22	3,513.29	1,611.93	31.45
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	4,525.22	2,913.29	1,611.93	35.62
+ GST 7.00/7.00% (S\$)	316.77	203.93	112.84	35.62
Nett Amount (S\$)	4,841.99	3,117.22	1,724.77	35.62

INSPECTION

Date of Assignment:	15/08/2018		
Date Inspected:	14/08/2018	Inspected At:	Sin Tien Seng Pte Ltd (Kallang) 10 Kallang Way Singapore 349215
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REINFORCEMENT FRONT	Bent	235.56 F	*100.00 F
2	1		*SUPPORT, FR BUMPER RH	Not Necessary	30.42 F	*- F
3	1		*SUPPORT, FR BUMPER LH	Necessary	30.42 F	*30.42 F
4	1		*COVER, FR BUMPER (SP)	Deformed	377.52 F	*377.52 F
5	1		*BRCKT, FOG LAMP LH	Not Necessary	20.28 F	*- F
6	1		*H-COVER FR BUMPER LH	Not Necessary	12.09 F	*- F
7	1		*MOULDG, FR BUMPER LH	Cut	26.52 F	*26.52 F
8	1		*GRILLE, FR BUMPER UPP	Not Necessary	55.38 F	*- F
9	1		*GRILLE, FR BUMPER LWR	Not Necessary	62.40 F	*- F
10	1		*SUPPORT RADIATOR RH	Not Necessary	73.32 F	*- F
11	1		*SUPPORT RADIATOR LH	Not Necessary	72.54 F	*- F
12	1		*SUPPORT RADIATOR TOP	Bent	45.24 F	*20.00 F
13	1		*SUPPORT, HOOD LOCK	Bent	16.38 F	*16.38 F
14	1		*HOOD	Bent	259.74 F	*120.00 F
15	1		*LOCK HOOD	Bent	60.84 F	*60.84 F
16	1		*SHIELD FENDER LH	Not Necessary	89.70 F	*- F
17	1		*PANEL, FR FENDER, LH	Bent	152.88 F	*152.88 F
18	1		*SEAL, FRT FENDER LH	Necessary	8.97 F	*8.97 F
19	1		*EMBLEM, HOOD	Not Necessary	49.14 F	*- F
20	1		*HEADLAMP SET, LH	Cracked	333.06 F	*333.06 F
21	1		*CONDENSER W/RECEIVER	Bent	297.96 F	*208.80 F
22	1		*HOSE, DISCHARGE	Not Necessary	294.84 F	*- F
23	1		*TUBE, INLET	Not Necessary	241.02 F	*- F
24	1		*R-COOLANT RCP 1L	Necessary	29.00 F	*14.40 F
25	1		*SUNDRIES	Necessary	80.00 FS	*73.50 FS
26	1		*FRONT NUMBER PLATE	Bent	40.00 FS	*40.00 FS
27	1		*OPC NUMBER PLATE SEAL	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	3,015.22	1,603.29
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R / REPLACE FRONT HEADLAMP & REFOCUS HEADLIGHT.	New	30.00	30.00
2	R&R RADIATOR TO FACILITATE REPAIR.	New	40.00	40.00
3	R&R / REPLACE AIRCON CONDENSER & REFILL GAS.	New	120.00	120.00
4	CUT & WELD FRONT SUPPORT PANEL / PANEL BEAT REPLACE FRONT BUMPER / HOOD ETC.	New	900.00	800.00
5	SPRAY PAINT ON AFFECTED AREAS.	New	900.00	800.00
6	LTA DOCUMENTATION FOR OPC NUMBER PLATE.	New	120.00	120.00
Gross Labour Cost (\$\$)			2,110.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >