

ASS. REC. BY:

REF: CS3/FWD18014638/Gpad3^{sr} Social Instruction: ✓

Survivor's

ASSIGNMENT (Office)

From (Person):

GO
Jokey Teh

of

FWD

Date/Time: 10/8/2018 @ 4:28pm

Estimated Cost:

Bill to:

OD / EP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

G1BE 9131X

Insured:

FBG 1281M

at Workshop m/s

N-51 Automotive

Tel:

68420051

of

Blk 2 Kaki Bkt Ave 2 # 01-17/18

Policy No:

Claim No:

PNMC2018 - 00001133

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 09/08/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

9:27am @ 13/8/18

Person Contacted:

eileen

Vehicle IN/OUT

Date/Time

Action/Instruction (x) Estimate

G1BE 9131X - NA / INC18014537 / KA

DOA: 9/8/18

FBG 1281M - NA / INC18014537 / KA

DOA: 9/8/18

13/8/18 -

called melody vehicle still not in yet.

3/1/18 Dismantled

15/8/18 -

called melody vehicle still not in yet

3/1/18 After Repair

17/8/18 -

called weep elaine said not yet

18/8/18 -

Vehicle still not in (eileen)

PAS
XLR

REF:

FWD

B 5126J /

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

N-51

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

QBE931X

Yr Regn:

01 Apr 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Regins

Ace Super
C.C. 2982

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

87963

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KPH/2010183659

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

31-08-18

Survey held at

W/S

11AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$35.00 - \$45.00

4/9/18

submit PRS Repy.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S * RS, SI

Photos

Others

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FWD SINGAPORE PTE LTD		Ref : CS3/FWD18014638/Gz4d3	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4 SINGAPORE 038986		Date : 13-08-2018	
		Code : FWD	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	FBG 1281M	Veh. Inspected	GBE 9131X
Policy No.		Coverage (\$)	0.00
Claim No.	PNMC2018-00001133	Excess (\$)	0.00
Assign From	JOSEY LOH	Assign Date	13/08/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c		
Engine No.	Year of Reg.		
Chassis No.	Colour		
Odometer	Steering		
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/08/2018	Inspection Date	
Survey held at			
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Nivitha (LKK Auto)

From: motorclaims.sg@fwd.com
Sent: Friday, 10 August 2018 4:28 PM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: FW: GBE9131X & FBG1281M - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS (FWD Ref: PNMC2018-00001133)
Attachments: 10082018152456-0001.pdf

Hi LKK team,

Please refer to the email below and liaise with TP repairer for PRS.

Attached is the TP GIA report.

Please create the case in Merimen.

Thank you.

Kind Regards

Josey Loh

Executive, Claims


FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872

E josey.loh@fwd.com

W fwd.com.sg



From: Motor Claims SG - SG Common

Sent: Friday, 10 August, 2018 4:24 PM

To: Chin Hui Xin

Cc: Motor Claims SG - SG Common

Subject: RE: GBE9131X & FBG1281M - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS (FWD Ref: PNMC2018-00001133)

WITHOUT PREJUDICE

Dear Melody,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s LKK Auto Consultants Pte Ltd, to conduct the pre-repair survey (PRS) on your client's vehicle, GBE9131X. We seek your cooperation to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

Thank you.


****Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.***

Kind Regards

Josey Loh
Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872
E josey.loh@fwd.com
W fwd.com.sg



From: Chin Hui Xin [<mailto:huixin@n51.com.sg>]

Sent: Friday, 10 August, 2018 3:49 PM

To: Motor Claims SG - SG Common

Subject: Re: GBE9131X & FBG1281M - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS (FWD Ref: PNMC2018-00001133)

Dear Sir/Madam,


We refer to your list of motor surveyors proposed.

We do not agree to your list of motor surveyors.

Please see attached.

Thank you

Regards,
Melody Chin
N-51 Automotive Pte Ltd
Office : 6842 0051
Fax : 6741 0510
www.n51.com.sg



On Fri, Aug 10, 2018 at 3:38 PM, <motorclaims.sg@fwd.com> wrote:

WITHOUT PREJUDICE

Dear Melody,

We refer to your letter dated 10 August 2018 of the PRI Notice of your client's vehicle GBE9131X.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. Appraisals Associates Pte Ltd
5. VICOM Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.*

Kind Regards

Josey Loh

Executive, Claims


FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872

E josey.loh@fwd.com

W fwd.com.sg



From: Chin Hui Xin [<mailto:huixin@n51.com.sg>]

Sent: Friday, 10 August, 2018 3:29 PM

To: Motor Claims SG - SG Common

Subject: GBE9131X & FBG1281M - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors.

Thank you...

Regards,


Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

www.n51.com.sg



ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please

notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub,
2 Kaki Bukit Ave 2, #01-18
Singapore 417921
Tel No. : +65 6842 0051 / 6744 0510 Fax No. : +65 6741 0510
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

Our Ref: **GBE 9131 X**
Your ref: **FBG 1281 M**

10 August 2018

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER FOUR
SINGAPORE 038986
Attn: Motor Claims Department

BY EMAIL motorclaims.sg@fwd.com ONLY

Dear Sir/Madam,

DATE OF ACCIDENT : 09 Aug 2018
NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS
PURSUANT TO PARAGRAPH 2.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

We are instructed by **TRUST FUNERAL SERVICES** to notify you of a road traffic accident on **09 Aug 2018** at about **12:55 HOURS** At **YISHUN AVE 4 SLIP RD INTO YISHUN AVE 1** involving our client's vehicle **GBE 9131 X & FBG 1281 M** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be inform that we don't excess to Merimen System and kindly reply to us by Email / Fax.

Yours faithfully,



N-51 AUTOMOTIVE PTE LTD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/08/2018 17:29
Date Of Accident	09/08/2018 12:55
Exact Location Of Accident	YISHUN AVE 4 SLIP RD INTO YISHUN AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE9131X
Insured/Policyholder	
Name Of Registered Owner	TRUST FUNERAL SERVICES
Co Reg No	53235126J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91319131
Alternative Phone No	OFFICE-91319131
Vehicle Particulars	
Manufacturer	TOYOTA
Model	REGIUS ACE SUPER GL DARK PRIME
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5089034583-01
Cover Note Number	

Driver

Name of Driver	LIM TAO JANG (LIN DAOZHANG)
NRIC No	S7337075B
Date Of Birth	14/10/1973
Occupation	OUTDOOR
Date Of Driving Pass	18/04/2001
Driving Experience	17 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91319131
Fax Number	
Contact Number	OTHERS-91319131
Email Address	NOEMAIL

Address	BLK 850 YISHUN STREET 81 #05-104
Postcode	760850
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - SELF-EMPLOYED
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBG1281M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


3. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

10/8/2018

Sketch Plan #2

SKETCH PLAN



(A) GBE 9131X
(A) GBE 9131X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 09/08/18 at 06:25 hrs, I stopped my vehicle (GBE 9131X) along Yichuan Ave 4 slip road onto Yichuan Ave 1 to give way to the traffic on the main road. Suddenly, a motorcycle (FRG 1281M) from behind collided into the rear portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policy Officer's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name
NRIC/ID No.

10/8/2018

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	5126J
Vehicle Details	
Vehicle No.:	GBE9131X
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	REGIUS ACE SUPER GL DARK PRIME
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	1KD2570926
Chassis No.:	KDH2010183659
Maximum Power Output:	-
Open Market Value:	\$38,511.00
Original Registration Date:	01 Apr 2016
First Registration Date:	01 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$1,926.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$40,889.00
COE Rebate Amount:	\$30,974.00
Total Rebate Amount:	\$30,974.00

The information contained herein is correct as at 03 Sep 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Aug 2018 Edit Reg		10 Aug 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Ng Pui Koon, ID: S7926573Z		
Main Claimant:	-		
Vehicle Reg. No.:	GBE9131X	Date of Loss:	09/08/2018 00:00 - :59 [28 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1201800010129	Policy/Cover Note No.:	PNMC2018-00001133 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	FBG1281M	Policy No. (Claimant):	
		Excess:	
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 31/08/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBE9131X (1201800010129)**
[FBG1281M]




































TP

-

Aug 9 2018 12:00AM

[Ng Pui Koon]

N-51 Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
2	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
3	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
4	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
5	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
6	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
7	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
8	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
9	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
10	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
11	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
12	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
13	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
14	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
15	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
16	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
17	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
18	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
19	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
20	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
21	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
22	04/09/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
23	04/09/18 11:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
24	04/09/18 11:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
25	04/09/18 11:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
26	04/09/18 11:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
27	04/09/18 11:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
28	04/09/18 11:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	04/09/18 11:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	04/09/18 11:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	04/09/18 11:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	04/09/18 11:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	04/09/18 11:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
34	04/09/18 11:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	04/09/18 11:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	04/09/18 11:07	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
37	04/09/18 11:07	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
38	04/09/18 11:07	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
39	04/09/18 11:07	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
40	04/09/18 11:07	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
41	04/09/18 11:07	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
42	04/09/18 11:07	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
43	04/09/18 11:07	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
44	04/09/18 11:07	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
45	04/09/18 11:07	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
46	04/09/18 11:07	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
47	04/09/18 11:07	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
48	04/09/18 11:07	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
49	04/09/18 11:07	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
50	04/09/18 11:08	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
51	04/09/18 11:08	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
52	04/09/18 11:08	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
53	04/09/18 11:08	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
54	04/09/18 11:08	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
55	04/09/18 11:08	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
56	04/09/18 11:08	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
57	04/09/18 11:08	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
58	04/09/18 11:08	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
59	04/09/18 11:08	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
60	04/09/18 11:08	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
61	04/09/18 11:08	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
62	04/09/18 11:08	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
63	04/09/18 11:08	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
64	04/09/18 11:08	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	21/08/18 15:01	OI GIA Report	Load PDF	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD18014638/GZ4D3S2

Date: 05/09/2018

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNMC2018-00001133
 Claimant Vehicle No: GBE9131X Insured Vehicle No: FBG1281M
 Date of Loss: 09/08/2018 Nature of Claim: TP Claim No: 1201800010129

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE9131X
 Make & Model: TOYOTA REGIUS ACE, 3.0 SUPER GL DARK PRIME (A) Engine No: 1KD2570926
 Reg. Date: 01/04/2016 (Man. Year: 2015) Chassis No: KDH2010183659
 Colour: Grey Odometer: 87963 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/08/2018
 Date Inspected: 31/08/2018 Inspected At: N-51 Automotive Pte Ltd (HQ)
 Estimated Period of Repair: 5.0 days BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB
 Singapore 417921

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 - \$4,500.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 05 Sep 2018)

Parts: N/A TOYOTA REGIUS ACE 3.0 SUPER GL DARK PRIME (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBE9131X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >