

Your Ref: CMTD1704383

Date: 16th August 2018

Our Ref: CS1/SMO18014643/Brd3s2

M/s Sampo Insurance Singapore Pte Ltd

50 Raffles Place

#05-01/06 Singapore Land Tower

Singapore 048623

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:

SG 5344M

INSURED VEHICLE: GBF 5278C

ACCIDENT DATE: 04/12/2017

We thank you for your instruction on 13/08/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SG 5344M from M/s Vicom Ltd.
- b) Singapore Accident Statement of Vehicles SG 5344M and GBF 5278C.
- c) Colour damaged vehicle photographs of SG 5344M.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SG 5344M
Make & Model	: VOLVO B9TL 9.4L
Year of Registration	: 2016
Chassis Number	: YV3S4P927GA177192
Engine Capacity	: 9364 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.