

ASS. REC. BY:

REF:

CS3/SPF18014646/NibSP

Special Instruction:

Surveyor:

NAZ

ASSIGNMENT (Office)

From (Person):

Abdul Rahman

of

SPF

Date/Time:

13082018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 9825Y

Insured:

QX 5626

at Workshop m/s

Wei Car Spray Painting

Tel:

9638 3306

of

Blk 1017 Yishun Ind Park A #01-242

Policy No:

Claim No:

AEMD/105/009/2018/095

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21072018

(Client's Record)

14.082018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

13082018 5:40pm

Person Contacted:

Ah Wei

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLL 9825Y - X

QX 5626 - X

Surveyor

NAZ

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLL 9825Y Yr Regn: 24 FEB 2010Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA CERADO RTTE KOUT C.C. 1.9LColour: RED A/C: Insured / Std / NI / NASp. Reading: 144,679 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAEW611MA520-3305Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/40R18R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CONTINENTAL

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 21/7/18 D.O.I. 14/08/18 1730Survey held at WEI CARDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

04/08/18 Submit L/S \$ 1,300/- @ 3 days, checked by Simon.

Submit DAR Report

DAR (with pricing)
No. of days

RECEIVED 4 SEP 2018

Date/Time, File Pass to?

04/08/18

1)

Typist

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

) \$ + RS \$

) Photos

) Others

)

TOTAL

Report Format: DARLump Sum / I.B.I. (\$) 1,300/- L/S



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS3/SPF18014646/Nz4b

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE)

1 MOUNT PLEASANT ROAD

BLK 8 OLD POLICE ACADEMY SINGAPORE 298333

Date : 13-08-2018



Code : SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	QX 562S	Veh. Inspected	SLL 9825Y
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/095	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	13/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	21/07/2018	Inspection Date	14/08/2018
Survey held at	WEI CAR SPRAY PAINTING BLK 1017 YISHUN INDUSTRIAL PARK A #01-242 SINGAPORE 768759		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : SLL 9825 Y

Our Ref : AEMD/105/009/2018/095

Tel: 64784840

Fax: 64784848

Date : 13 Aug 2018

LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 # 01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir,

**ACCIDENT INVOLVING GOVT VEHICLE QX 562 S AND OTHER VEHICLE SLL 9825 Y ON
21 July 2018**

We refer to the above matter.

- 2 Kindly arrange for an inspection of vehicle no. **SLL 9825 Y** at Wei Car Spray Painting Pte Ltd,
Blk 1017 Yishun Industrial Park A # 01-242, Singapore 768759.
- 3 For appointment kindly contact Mr Ah Wei at Tel: 96383306.
- 4 Estimates were provided by the workshop.
- 5 Thank you.

Yours faithfully,

Frankie Thay
Safe Driving Manager
for ASST DIRECTOR

A FORCE FOR THE NATION

K. K. CHENG & CO

Advocates & Solicitors
101 Upper Cross Street #05-21
People's Park Centre
Singapore 058357
Tel: 6227 1272 Fax: 6227 5563

Our Ref: WC/SLL 9825Y
Your Ref: QX 562S
(Please quote our reference number when replying)

13 August 2018

SPF Accident Claims Section
Automotive Engineering and Management Division
Police logistics Department
1 Mount Pleasant Road
Block 8 Old Police Academy
Singapore 298333

BY FAX : 6478-4848 ONLY

LKK Auto Consultants Pte Ltd
Singapore 408933

BY FAX : 6741-4108 ONLY

Attention: Claims Department

Dear Sirs

NOTICE OF ACCIDENT

Claimant: NUR AFIDZA BINTE MOHD GHAZALI

Pre-action Protocol for Non-injury Motor Accident Cases involving motor accident occurring on or after 1st April 2016 ["Protocol"]

We refer to your letter dated 13 August 2018.

Firstly, we object to the appointment of any of the motor surveyors proposed by in your List as a single joint expert. We have already stated this at para 4 of our Notice of Accident dated 13 August 2018.

Secondly, we have also given you our proposed list of proposed motor surveyors at para 4 of our Notice of Accident dated 13 August 2018.

Thirdly, if you object to our proposed list of proposed motor surveyors, this matter shall proceed on the basis of para 2.9 of the Protocol. Accordingly, our client shall appoint a surveyor of his choice to conduct the pre-repair survey. And our client shall have his motor vehicle repaired after the pre-repair survey had been done by your appointed surveyor.

Fourthly, *for the sake of clarity, we do not agree to your appointed surveyor conducting the Pre-Repair Survey as the single joint expert.*

If you wish to conduct a post-repair inspection, please instruct your appointed surveyor to inform our client's repairer of the same during the pre-repair survey.

Finally, the location and contact person of the workshop are as follows:

Name of Workshop	:	Wei Car Spray Painting Pte Ltd
Address	:	Blk 1017 Yishun Industrial Park A #01-242 Singapore 768759
Contact person	:	Ah Wei
Telephone No	:	9638-3306

Yours faithfully

CHENG KIM KUAN

cc Workshop (REF: SLL 9825Y)



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/07/2018 11:03
Date Of Accident	21/07/2018 15:15
Exact Location Of Accident	ALONG PIONEER RD NORTH (FILTER LANE EXITING PIE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL9825Y
Insured/Policyholder	
Name Of Registered Owner	NUR AFIDZA BINTE MOHD GHAZALI
NRIC No	S8821833G
Email Address	MSFIDOD@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96541414
Alternative Phone No	OTHERS-96541414

Vehicle Particulars

Manufacturer	KIA
Model	CERATO FORTE KOUP 1.6 AT SX ABS D/AB SR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5090422393
Cover Note Number	

Driver

Name of Driver	MUHAMMAD ZULFADHLI BIN ZULKAFLY
NRIC No	S8700890H
Date Of Birth	08/01/1987
Occupation	OUTDOOR
Date Of Driving Pass	27/10/2016
Driving Experience	1 YEAR AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93294525
Fax Number	
Contact Number	
EEmail Address	ZOOLFADHLI@GMAIL.COM

Address	BLK 709 JURONG WEST STREET 71 #05-32
Postcode	640709
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	NANYANG N.P.C
Police Station Address	ROAD: 2 JURONG WEST AVE 5 , POSTCODE: 649482 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7929999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX562S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	SGT. ARINA
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


Yvonne Toh

Accident Sketch Plan Pg. 1

SKETCH PLAN

A > 8LL 9825 y

B → QX 562 E



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident Date & Time : 21 July 2018 , 1515 hrs

Accident Location : Along fitter lane of Pioneer Rd North exiting PIC

As per police report.

☐ Reporting Only ☐ Own Damage ☐ Third Party ☒ Claim at other workshop (OD/TP)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*** IMPORTANT NOTE:**

IMPORTANT NOTE:
You have been advised by the workshop that in the event that you wish to claim against your own policy (Car Damage Claim) there is a **FOURTEEN (14) days** clause whereby the claim must be made within the stipulated timeframe from the day of completion.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____ 11/8

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Yvonne Tob



**SINGAPORE
POLICE FORCE**



T/20180724/2134

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

1 of 3

Report No. T/20180724/2134

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/07/2018 18:14	Vide Report No.: J/20180721/0158	Station Diary No.: 172
--	-------------------------------------	---------------------------

Informant's Particulars

Name of Informant: MUHAMMAD ZULFADHLI BIN ZULKAFLY			Address: APT BLK 709 JURONG WEST STREET 71 #05-32 SINGAPORE 640709	
ID Type / ID No.: NRIC NO / S8700890H			Contact No.:	Mobile: 93294525
Nationality: SINGAPORE CITIZEN			Home/Office:	
			Email:	
Sex: Male	Age: 31	Date of Birth: 08/01/1987	Type of Informant: Driver	
Race: Malay			Language: English	Institution / School Name:
Occupation: CONTAINER HANDLING			Driving Licence Information: Class: 2B,2A,3	
			Date of Expiry:	

General information of the Accident

Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 21/07/2018 15:15	Type of Location: Filter Lane
Location: Along Road 1 PIONEER ROAD NORTH				
Along Pioneer Road North towards NTU, at the filter lane exiting PIE				
Weather: Clear	Road Surface: Dry		Road Speed Limit:	
Traffic Flow: One Way	Traffic Control: Not Controlled		Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear	Anyone conveyed by ambulance: No			

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX562S	Car	HYUNDAI		White	Slightly Damaged	2
SLL9825Y	Car	KIA		Red	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180724/2134

2 of 2

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

Report No. T/20180724/2134

CONTINUATION OF REPORT

Driver			
Name	MUHAMMAD ZULFADHLI BIN ZULKAFLY	ID No.	S8700890H
Related Vehicle	SLL9825Y (Car)	Contact No.	93294525
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 21/07/18 at about 1515hrs, I was driving my car (SLL9825Y) at the filter lane exiting PIE, going towards Pioneer Road North in the direction of NTU. My wife was in the Police car (QX562S) as previously my wife was searching for her handphone on the expressway thus the officer asked her to board the car and she will then bring my wife to the side.

While exiting PIE, at the filter lane, I had stopped my car as there were oncoming vehicles from Pioneer Road North going towards NTU. I suddenly felt a hard impact to the rear. I then move out of the filter lane and the driver's partner then told me to wait while the officer drive the car and parked it in front of my car in order not to block the traffic.

The officer then informed me that she has to report the matter to her supervisor and Traffic Police. She had also taken photos of the damage. My car sustained a dent and scratches to the rear bumper. Traffic Police officer and her supervisor then came down. The Traffic Police officer then advised me to lodge a Traffic Accident Report under TP IO Sharulnizam Tel: 65476904 vide incident J/20180721/0158.

There is a camera in the Police car. I am not sure if there are any traffic camera at the vicinity.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999



T/20180724/2134

3 of 2

Report No. T/20180724/2134

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Staff Sgt NORIMAWATI BINTI ABDULLAH

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476451



Authentication Stamp

SN 127

Signature :

Singapore Police Force

Signature Of Informant:

Date/Time:

24/07/2018 18:14

Classification Of Case:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1833G
Vehicle Details	
Vehicle No.:	SLL9825Y
Vehicle to be Exported:	No
Intended De-registration Date:	24 Aug 2018
Vehicle Make:	KIA
Vehicle Model:	CERATO FORTE KOUP 1.6 AT SX ABS D/AB SR
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	G4FCAH365928
Chassis No.:	KNAFW611MA5203305
Maximum Power Output:	92.7 kW (124 bhp)
Open Market Value:	\$15,754.00
Original Registration Date:	24 Feb 2010
First Registration Date:	24 Feb 2010
Transfer Count:	1
Actual ARF Paid:	\$15,754.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Feb 2020
PARF Rebate Amount:	\$8,664.00
Intended COE Rebate Details	
COE Expiry Date:	23 Feb 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$18,150.00
COE Rebate Amount:	\$2,725.00
Total Rebate Amount:	\$11,389.00

The information contained herein is correct as at 24 Aug 2018

OK

Accident Photo



Accident Photo



Accident Photo



Accident Photo



MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	✓		
1142	993085	Rear Bumper Upper	✓		
1143	993017	Rear Bumper Lower	✓		
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	✓		
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SL 98254

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			
		Labour			
1		Painting of rear bumper			200.00
2		R.R.R. the rear bumper			400.00
		Total			
		Repair days		3	

No of Items: 3

Assessor: Wm

31/8/18

31/8/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref: CS3/SPF18014646/Nsbs2

ACCIDENT CLAIM SECTION (SINGAPORE POLICE Date: 05-09-2018

FORCE)1 MOUNT PLEASANT ROAD BLK 8 OLD

POLICE ACADEMYSINGAPORE 298333



ATTN: ABDUL RAHMAN

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	QX 562S	Veh. Inspected	SLL 9825Y
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/095	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	13/08/2018

2. Vehicle Particulars & Condition

Make & Model	KIA CERATO FORTE KOUP	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	KNAFW611MA5203305	Colour	RED
Odometer	144679 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40R18	CONTINENTAL	5 mm
L/H Front Tyre	225/40R18	CONTINENTAL	5 mm
R/H Rear Tyre	225/40R18	CONTINENTAL	5 mm
L/H Rear Tyre	225/40R18	CONTINENTAL	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	21/07/2018	Inspect Date / Time	14/08/2018 (05:30 PM)
Survey held at	WEI CAR SPRAY PAINTING BLK 1017 YISHUN INDUSTRIAL PARK A #01-242 SINGAPORE 768759		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SLL 9825Y

Qty	Description of Parts	Condition	Recommended (\$)
REPLACEMENT OF PARTS			
1	REAR BUMPER	CUT	685.00
1	REAR BUMPER LOWER	CUT	150.00
1	REAR BUMPER CLIPS (@ \$45.00 DISC 10%)	NECESSARY	40.50
1	REAR BUMPER SPONGE	DENTED	151.00
			1,026.50
LABOUR			
	PAINTING OF REAR BUMPER.		200.00
	RNR THE REAR BUMPER.		400.00
			600.00
GRAND TOTAL			1,626.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,300.00

Report Ref No. CS3/SPF18014646/Nsbs2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.