

ASS. REC. BY:

REF: CS3/CT#18014647/T124d3/2

Special Instruction:

Survivor:  
Monmen

Talkrich

ASSIGNMENT (Office)

From (Person):

Irene fuy

of

CTI

Date/Time:

13/8/18 @ 4:43pm

Estimated Cost:

Bill to:

OD  TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJF 7258C

Insured:

GBG 4197D

at Workshop m/s

N-SI Automotive

Tel:

68420051

of

2 kcalci St Ave 2 #01-18

Policy No:

DMCKSN 1753261801

Claim No:

SNM18D03903C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/05/2018

CA / REV / REP. / REV 24 HRS

lup

14/8/18

H.O.D. Endorsement:

Date/Time:

5:35pm @ 13/8/18

Person Contacted:

Melody

Vehicle  IN /  OUT

Date/Time	Action/Instruction ( X ) Estimate
	SJF 7258C - X
	GBG 4197D - X
	Dismantle: 15/8/2018
	After repair: 21/8/2018

REF: *Tanpin*

REF: *071*

*WE 2023 June*

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S
	<i>XX</i>

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rport: \_\_\_\_\_ Consistent? : **Yes or No**

GIA / PR Seen: \_\_\_\_\_ Consistent? : **Yes or No**

Est. Repairs: \_\_\_\_\_ days Res.: **Yes or No**

Lum Sum: \_\_\_\_\_ % 3 Val.: **Yes or No**

CA / REV / REP. / 24 HRS *PRS*

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: **IN / OUT**

Veh No: *SJF 7258C* Yr Regn: *2008 June*

Type:  Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: *Honda Airwave* C.C. *1496*

Colour: *sil/wh* A/C: **Insured / Std / NI / NA**

Sp Reading: *143396* T/Radio: **Insured / Std / NI / NA**

Eng/No: \_\_\_\_\_

C/No: *6 9J11209477*

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  Inorder / Jammed / Leaked / Burnt or

Brake:  Inorder / Jammed / Leaked / Burnt or

Modi:  Nil / S/Rim / STD A/Rim or

Tyre Size: *F: 145/65R15*

R: *4 -*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or *Dayton*

Front *6* mm R/Bal. *6* mm

Rear *6* mm L/Bal. *6* mm

D.O.A. *14/8/18 @ 1140*

Survey held at *N-51 Noto*

Des. of Damages: Frt /  Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction	Range + No. of days
	<i>Estimated repair range \$6,500 - \$7,800</i>	<i>2 hrs total Ave 2 #01-17/18</i>
<i>30/8/18</i>	<i>submit PRS report</i>	<i>30/8/2018</i>

Date/Time. File Pass to?  : **Preli. Report**  : **Final Report**

1) \_\_\_\_\_

Date/Time. File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format : \_\_\_\_\_

Lump Sum / I.B.I. (\$) *PRS -*

Days Of Repair: *7*

Resurvey No. of Trip: *2*

Survey Fee: *150*

Transportation: \_\_\_\_\_

Add Fee:  Site Insp (\$ )  S+RS, SI

Interview (\$ )  Photos

Tech. Invs (\$ )  Others

Weekend (\$ )

TOTAL *150*

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Aug 2018		13 Aug 2018 16:43 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	CHUA YU HAN		
Vehicle Reg. No.:	SJF7258C	Date of Loss:	10/08/2018 00:00 - :59
Claim Type:	TP / SNM18D03903C02	Policy/Cover Note No.:	DMCVSN1753261801
Vehicle Reg. No. (Insured):	GBG4197D	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	N-51automotive Pte Ltd (HQ) KAKI BUKIT AUTOHUB, 2 KAKI BUKIT AVE 2 #01-18, 417921 Kaki Bukit - Tel: 6842 0051 /67440510		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/08/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS3/CTI18014647/T1z4d3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 13-08-2018	
		Code : CTI	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	GBG 4197D	Veh. Inspected	SJF 7258C
Policy No.	DMCVSN1753261801	Coverage (\$)	0.00
Claim No.	SNM18D03903C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	13/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	10/08/2018	Inspection Date	14/08/2018
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	0023E
<b>Vehicle Details</b>	
Vehicle No.:	SJF7258C
Vehicle to be Exported:	No
Intended De-registration Date:	21 Aug 2018
Vehicle Make:	HONDA
Vehicle Model:	AIRWAVE 1.5M A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	L15A5161229
Chassis No.:	GJ11209477
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$13,713.00
Original Registration Date:	09 Jun 2008
First Registration Date:	09 Jun 2008
Transfer Count:	4
Actual ARF Paid:	\$12,104.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	08 Jun 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$19,107.00
COE Rebate Amount:	\$18,339.00
<b>Total Rebate Amount:</b>	<b>\$18,339.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 21 Aug 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/08/2018 13:51
Date Of Accident	10/08/2018 19:40
Exact Location Of Accident	JURONG TOWN HALL RD TOWARDS BUKIT BATOK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJF7258C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHUA YU HAN
NRIC No	S8570023E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93259756
Alternative Phone No	OFFICE-93259756

### Vehicle Particulars

Manufacturer	HONDA
Model	AIRWAVE 1.5M A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10789949
Cover Note Number	

### Driver

Name of Driver	TEO KAI YUNN
NRIC No	S8574336H
Date Of Birth	11/04/1985
Occupation	INDOOR
Date Of Driving Pass	18/10/2011
Driving Experience	6 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93259754
Fax Number	
Contact Number	
EMail Address	TEOKAIYUNN@YAHOO.COM

Address	APT BLK 416 SAUJANA ROAD #10-60
Postcode	670416
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHUA YU HAN GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS DRIVING ALONG JURONG TOWN HALL TOWARDS BUKIT BATOK. I WAS SAW TRAFFIC INFRONT WAS YELLOW LIGHT, THEN I WAS SLOW DOWN MY VEHICLE FOR READY TO STOP. SUDDENLY VEHICLE B AT BEHIND OF ME COLLIDED ONTO MY REAR OF MY VEHICLE NO INJURIES INVOLVED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WILL UPLOAD TO MERIMEN AFTER INSURED SEND
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG4197D
Vehicle Make/Model/Colour	TOYOTA / DYNA 3.0 M
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ALAGAPPAN GANESAN
NRIC/Passport Number	G7756306M
Contact Number	90510240
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

# Sketch Plan


**IMPORTANT NOTICE**

1. Please read carefully the details of the accident to assist in the claims process.
2. The form must be completed by the Policyholder or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may cause immediate termination or rescission of policy liability.
4. The fees and conditions of the form by individual companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be furnished by the insured to the GSA Records Management Centre established by the General Insurance Association of Singapore (GIAS) for auditing and that copies of this report will be made available upon request by interested parties.
7. By the submission of this report to the insurer, you hereby consent to the auditing of the report at the centre and to copies of the report being made available upon request.
8. Consent under the Personal Data Protection Act (PDPA)
  - (a) I understand, acknowledge, agree and consent that:
    - (i) My insurer, my solicitor and the General Insurance Association of Singapore ("GIAS") may be permitted to collect, use, disclose and/or process my personal information contained and out in the form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicles involved in the accident (or insurer(s) who have insured vehicles) involved in the accident and be conclusively referred to as the "insurer(s)", the insurers' lawyers/law firms, the Ministry of Transport of Singapore and any relevant governmental agencies/authority (such as the police), for the purposes of:
      - (1) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
      - (2) investigating the accident and/or my claims;
      - (3) carrying out and/or dealing with my instructions or responding to any enquiries by me;
      - (4) administering my claims (including the settling of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the car as well as on the external cover of envelope/mail packages); and/or
      - (5) complying with applicable law in administering, processing, handling and/or dealing with my claims.
  - (b) all insurer(s) who have insured vehicle(s) involved in the accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above purposes; and
  - (c) my Personal Information may/will be disclosed by any of the insurers' service CIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above purposes.

**VERIFIED BY AJAX MARS  
REPORTING OFFICER  
Jun Keat**

Policyholder's Signature / Date & Time      Driver's Signature (if driver is not the policyholder) / Date & Time      Witnessed by Reporting Centre Personnel

**Sketch Plan**



ACCIDENT STATEMENT (2000 characters)

I WAS DRIVING ALONG JURONG TOWN HALL TOWARDS BUKIT BATOK. I WAS SAW TRAFFIC INFRONT WAS YELLOW LIGHT, THEN I WAS SLOW DOWN MY VEHICLE FOR READY TO STOP. SUDDENLY VEHICLE B AT BEHIND OF ME COLLIDED ONTO MY REAR OF MY VEHICLE NO INJURIES INVOLVED.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
WONG JUN KEAT

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

11 August 2018 at 1:04 PM

Date/Time:

11 August 2018 at 1:04 PM

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Aug 2018		13 Aug 2018 16:43 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [\[Created by insurer\]](#)

Insured: -, Co. Reg. No.: -

Main Claimant: **CHUA YU HAN**

Vehicle Reg. No.: <b>SJF7258C</b>	Date of Loss: 10/08/2018 00:00 - :59 <b>[122 Months and 1 Days From LTA Reg Date (Man Yr)]</b>
Claim Type: <b>TP / SNM18D03903C02</b>	Policy/Cover Note No.: <b>DMCVSN1753261801</b>
Vehicle Reg. No. (Insured): <b>GBG4197D</b>	Policy No. (Claimant):
	Excess: <b>S\$0.00</b>

Repairer: **N-51automotive Pte Ltd (HQ)** KAKI BUKIT AUTOHUB, 2 KAKI BUKIT AVE 2 #01-18, 417921 Kaki Bukit - Tel: 6842 0051 /67440510

Handling Insurer: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 ... [Handled by **Irene Tay Hui Ping** - 638986192]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **MOHD TAUFIKH BIN HAMID**] ... **[Final Rpt due 23/08/2018]**

Adj Asg. Remarks: NO EST, CASE W/O SJE.

---

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

---

**ALL ASSOCIATED TASKS**  [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

### Claim Documents

**\*SJF7258C (SNM18D03903C02)**  
**[GBG4197D]**  
**TP**  
**CHUA YU HAN**  
**Aug 10 2018 12:00AM**  
**[-]**  
**N-51automotive Pte Ltd**

Upload Documents		Upload Photos	Compose New Letter	<b>View</b> View in Browser <input type="checkbox"/>
<b>Photos/Images</b>				3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		<b>Thumbnail</b> <b>Print</b>
1	21/08/18 12:51	<b>General View</b>	Load PDF	
2	21/08/18 12:51	<b>Photographs of Damaged Parts</b>	Load PDF	
3	27/08/18 12:29	<b>Photo After Spray</b>	Load PDF	
<b>Documentation</b>				1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		<b>Thumbnail</b> <b>Print</b>
1	13/08/18 16:42	<b>PRS WITH TP GIA</b>	Load PDF	

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**Our File No: CS3/CTI18014647/T1Z4D3E2  
Date: 03/09/2018REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1753261801
Claimant Vehicle No :	SJF7258C	Insured Vehicle No :	GBG4197D
Date of Loss:	10/08/2018	Nature of Claim:	TP
		Claim No:	SNM18D03903C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJF7258C</b>	Engine No:	L15A5161229
Make & Model:	HONDA AIRWAVE, 1.5 M (A)	Chassis No:	GJ11209477
Reg. Date:	09/06/2008 (Man. Year: 2008)	Odometer:	143396 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dayton 6 mm	Rear Left Side:	Dayton 6 mm
Front Right Side:	Dayton 6 mm	Rear Right Side:	Dayton 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment:	13/08/2018	
Date Inspected:	14/08/2018 Inspected At:	N-51automotive Pte Ltd (HQ) KAKI BUKIT AUTOHUB, 2 KAKI BUKIT AVE 2 #01-18 Singapore 417921
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Ho Zhao Tian

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,500.00 -\$7,800.00

## REPAIR DETAILS

Reference	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 31 Aug 2018)
<b>Parts:</b> M1-MPV	HONDA AIRWAVE 1.5 M (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJF7258C)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >